

LIST OF KSRTC BUSES AS ON 9.8.2017

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1	RAC741	KL-15	7894	LL	CFP	AFP	14-Aug-2009	PPD	53	52	ALPSV 4/89 EURO II	JVH 224995	KXE 672580	26
2	RNC528	KL-15	8786	TATA	CFP	AFP	4-Nov-2010	CTY	53	52	LP 1512 TC/59 BSIII	62337437	MAT412088A0H14677	28
3	RNC532	KL-15	8788	TATA	CFP	AFP	6-Nov-2010	CTY	53	52	LP 1512 TC/59 BSIII	01H62916341	MAT412088A0H14676	28
4	RNC536	KL-15	8807	LL	CFP	AFP	12-Nov-2010	CTY	53	52		NAE129930Z	MB1PBEHC1AEND4993	28
5	RNC624	KL-15	8889	TATA	CFP	AFP	3-Dec-2010	CTY	53	52	LP 1512 TC/59 BSIII	01J62924066	MAT412088A0J15682	28
6	RNC625	KL-15	8894	TATA	CFP	AFP	6-Dec-2010	CTY	53	52	LP 1512 TC/59 BSIII	01J62924063	MAT412088A0J15684	28
7	RRC375	KL-15	6536	TATA	CFP	AFP	15-Jan-2008	VKBN	53	52	697 NA	JSZ 143055	KSZ 016680	29
8	RRC650	KL-15	6811	TATA	CFP	AFP	28-Mar-2008	VKBN	53	52	697 TCIC	ARZ 105632	BRZ 002965	29
9	RRA315	KL-15	6479	TATA	CFP	AFP	29-Dec-2007	VKBN	53	52	697 TCIC	GSZ 134927	HSZ 012586	29
10	RRA316	KL-15	6500	TATA	CFP	AFP	4-Jan-2008	PKDA	53	52	697 TCIC	697 TC55 HSZ 136553	436062 HSZ 013353	81
11	RT 856	KL-15	6034	TATA	CFP	AFP	9-Aug-2005	VJMD	53	52	1512	50C62393766	412071CUZ110106	16
12	RT 919	KL-15	6097	TATA	CFP	AFP	19-Sep-2005	CTY	53	52	1512 TATA CUMMINS	H62349941	CUZ 110105	28
13	RT 728	KL-15	5906	TATA	CFP	AFP	2-May-2005	CTY	53	52	1512 TC CUMMINS	50B62388694	AUZ 103580	28
14	RT 729	KL-15	5907	TATA	CFP	AFP	2-May-2005	VZM	53	52	1512 TC CUMMINS	62140955	AUZ 103290	24
15	RT 761	KL-15	5939	TATA	CFP	AFP	2-Jun-2005	CTY	53	52	1512 TC CUMMINS	62394672	BUZ 107321	28
16	RT 861	KL-15	6039	TATA	CFP	AFP	12-Aug-2005	CTY	53	52	1512 TC CUMMINS	62343552	CUZ 110774	28
17	RT 864	KL-15	6042	TATA	CFP	AFP	19-Aug-2005	CTY	53	52	1512 TC CUMMINS	50C 62389354	CUZ 109829	28
18	RAA707	KL-15	7864	TATA	CFP		9-Jul-2009	PPD	53	52	CUMMINS 1512 TCIC	0162843877	412081CQZ002635	26
19	RT 887	KL-15	6065	LL	CFP	AFP	27-Aug-2005	CTY	53	52	ALPSV 4/19 HINO W06E BSI	ZBH 150982	UDE 551838	28
20	RT 713	KL-15	5891	LL	CFP	AFP	25-May-2005	CTY	53	52	ALPSV 4/19 HINO W06E BSII	10VHX7806	DWA 046435	28
21	RT 716	KL-15	5894	LL	CFP	AFP	2-May-2005	CTY	53	52	ALPSV 4/19 HINO W06E BSII	MWH279477	DWA 046473	28
22	RT 717	KL-15	5895	LL	CFP	AFP	2-May-2005	CTY	53	52	ALPSV 4/19 HINO W06E BSII	OO 264488	DWA 046572	28
23	RT 924	KL-15	6102	LL	CFP	AFP	17-Oct-2005	CTY	53	52	ALPSV 4/19 HINO W06E BSII	TDH 311125	TDE 553640	28
24	RT 742	KL-15	5920	TATA	CFP	AFP	16-May-2005	NTA	53	52	ALPSV 4/19 HINO W06E/16	0062143088	AUZ 103553	22
25	RT 748	KL-15	5926	LL	CFP	AFP	23-May-2005	CTY	53	52	ALPSV 4/19 HINO W06E/16	HNI 3656	WDA 047355	28
26	RT 749	KL-15	5927	LL	CFP	AFP	23-May-2005	NTA	53	52	ALPSV 4/19 HINO W06E/16	MNH519507	DWA 046358	22
27	RT 752	KL-15	5930	LL	CFP	AFP	24-May-2005	CTY	53	52	ALPSV 4/19 HINO W06E/16	DBH 146565	WDA 047352	28
28	RNC539	KL-15	8791	LL	CFP	AFP	8-Nov-2010	PPD	53	52	ALPSV 4/89 BSII HINO	MAE131285Z	MB1PBEHC7AEND6437	26
29	RNC537	KL-15	8804	LL	CFP	AFP	10-Nov-2010	VKBN	53	52	6HEIT HINO	MAE 131201Z	MB1PBEHC4AEND6363	29
30	RNC538	KL-15	8805	LL	CFP	AFP	10-Nov-2010	PPD	53	52	ALPSV 4/89 BSII	NAE130543Z	MB1PBEHC1AEND5803	26
31	RAC188	KL-15	7341	LL	CFP	AFP	6-Jan-2009	VLND	53	52	ALPSV 4/89 HINO EURO BSII TIC	CNH 560718	BNE 665244	20
32	RAC189	KL-15	7342	LL	CFP	AFP	6-Jan-2009	VLND	53	52	ALPSV 4/89 HINO EURO BSII TIC	CNH 561020	BNE 665241	20
33	RAC190	KL-15	7343	LL	CFP	AFP	6-Jan-2009	VLND	53	52	ALPSV 4/89 HINO EURO BSII TIC	BNE 103641Z	BNE 665337	20
34	RAC187	KL-15	7336	LL	CFP	AFP	5-Jan-2009	VLND	53	52	ALPSV 4/89 HINO EURO BSII TIC	BNE 103628Z	BNE 665340	20
35	RAC900	KL-15	8067	LL	CFP	AFP	13-Nov-2009	VLND	53	52	ALPSV 4/89 HINO EURO BSII TIC	VXH 585952	MB1PBEHC09EBA7397	20
36	RAC907	KL-15	8077	LL	CFP	AFP	17-Nov-2009	VLND	53	52	ALPSV 4/89 HINO EURO BSII TIC	BXE 109552Z	MB1PBEHC9EBA6970	20
37	RAC913	KL-15	8080	LL	CFP	AFP	18-Nov-2009	VLND	53	52	ALPSV 4/89 HINO EURO BSII TIC	BXE 109686Z	MB1PBEHC89EBA7227	20
38	RRK320	KL-15	6475	LL	CFP		28-Dec-2007	PKDA	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	WPH 482573	WPE 628656	81
39	RAC108	KL-15	7258	LL	CFP	AFP	3-Dec-2008	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	CNH 565269	BNE 664843	28
40	RAC166	KL-15	7326	LL	CFP	AFP	1-Jan-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	CNH 560892	CNE 663378	28

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
41	RAC167	KL-15	7328	LL	CFP	AFP	1-Jan-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	IOUHD1066	CNE 663486	28
42	RAC168	KL-15	7327	LL	CFP	AFP	1-Jan-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	JXH 578313	BNE 665252	28
43	RAC169	KL-15	7334	LL	CFP	AFP	3-Jan-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	LXH 572702	BNE 665222	28
44	RAC170	KL-15	7318	LL	CFP	AFP	29-Dec-2008	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	WAE 119186Z	BNE 665486	28
45	RAC856	KL-15	8033	LL	CFP	AFP	5-Nov-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	BXH 585798	MBIPBEHC29EBA7148	28
46	RAC872	KL-15	8034	LL	CFP	AFP	5-Nov-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	BXE 109745Z	MBIPBEHC29EBA7353	28
47	RAC874	KL-15	8035	LL	CFP	AFP	5-Nov-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	BXE 109681Z	MBIPBEHCX9EBA7228	28
48	RAC873	KL-15	8036	LL	CFP	AFP	7-Nov-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	BXH 585949	MB1PBEHC49EBA7399	28
49	RAC876	KL-15	8037	LL	CFP	AFP	7-Nov-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	BXE 109972Z	MBIPBEHC89EBA7857	28
50	RAC878	KL-15	8038	LL	CFP	AFP	7-Nov-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	JXH 576659	MBIPBEHCX9EBA7214	28
51	RAC875	KL-15	8039	LL	CFP	AFP	9-Nov-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	ZNE 104364Z	MBIPBEHC79EBA7154	28
52	RAC877	KL-15	8040	LL	CFP	AFP	9-Nov-2009	CTY	53	52	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	BXE 109966Z	MBIPBEHC39EBA7815	28
53	RAM126	KL-15	7344	LL	CFP	AFP	8-Jan-2009	VLND	53	52	ALPSV 4/89 HINO HA6ETI	BNE 103711Z	BNE 665510	20
54	RAM 78	KL-15	7338	LL	CFP	AFP	6-Jan-2009	VLND	53	52	ALPSV 4/89 HINO HA6ETI	BNE 103477Z	BNE 665187	20
55	RAM125	KL-15	7337	LL	CFP	AFP	6-Jan-2009	VLND	53	52	ALPSV 4/89 HINO HA6ETI	BNE 103613Z	BNE 665308	20
56	RRC752	KL-15	6918	LL	CFP	AFP	26-Apr-2008	PPD	53	52	ALPSV 4/89 VIKING	LNH 524553	LNE 648541	26
57	RAC 89	KL-15	7246	LL	CFP	AFP	27-Nov-2008	VKBN	53	52	HINO EURO II	JNE 101397Z	JNE 655805	29
58	RAC107	KL-15	7271	LL	CFP	AFP	11-Dec-2008	PPD	53	52	ALPSV 4/89 VIKING	DNE 102734Z	CNE 663382	26
59	RAC110	KL-15	7272	LL	CFP	AFP	11-Dec-2008	PPD	53	52	ALPSV 4/89 VIKING	JOVHB3340	CNE 663453	26
60	RAC191	KL-15	7354	LL	CFP	AFP	9-Jan-2009	PPD	53	52	ALPSV 4/89 VIKING	BNE 103716Z	BNE 665509	26
61	RAC192	KL-15	7355	LL	CFP	AFP	9-Jan-2009	PPD	53	52	ALPSV 4/89 VIKING	CNH 561035	BNE 665234	26
62	RAC200	KL-15	7361	LL	CFP	AFP	12-Jan-2009	PPD	53	52	ALPSV 4/89 VIKING	CNE 103246Z	CNE 664139	26
63	RAC201	KL-15	7362	LL	CFP	AFP	12-Jan-2009	PPD	53	52	ALPSV 4/89 VIKING	BNE 103685Z	BNE 665485	26
64	RAM128	KL-15	7371	LL	CFP	AFP	15-Jan-2009	PPD	53	52	ALPSV 4/89 VIKING	BNE 103636Z	BNE 665334	26
65	RAM122	KL-15	7330	LL	CFP	AFP	2-Jan-2009	PPD	53	52	ALPSV 4/89 VIKING	BNH 568435	BNE 665183	26
66	RAM123	KL-15	7331	LL	CFP	AFP	2-Jan-2009	PPD	53	52	ALPSV 4/89 VIKING	TPH 49947Z	CNE 663423	26
67	RAC186	KL-15	7335	LL	CFP	AFP	5-Jan-2009	PPD	53	52	ALPSV 4/89 VIKING	KNH 533476	CNE 664127	26
68	RAC915	KL-15	8081	LL	CFP	AFP	18-Nov-2009	PPD	53	52	ALPSV 4/89 VIKING	BXE 109733Z	MB1PBEHC49EBA7340	26
69	RAC916	KL-15	8082	LL	CFP	AFP	19-Nov-2009	PPD	53	52	ALPSV 4/89 VIKING	BXE 110462Z	MB1PBEHC39EZA9682	26
70	RAC917	KL-15	8083	LL	CFP	AFP	19-Nov-2009	PPD	53	52	ALPSV 4/89 VIKING	ZXE 111642Z	MB1PBEHC49E2B0677	26
71	RAC919	KL-15	8087	LL	CFP	AFP	20-Nov-2009	PPD	53	52	ALPSV 4/89 VIKING	ZXE 110896Z	MB1PBEHC39EZA9486	26
72	RAC920	KL-15	8088	LL	CFP	AFP	20-Nov-2009	PPD	53	52	ALPSV 4/89 VIKING	ZXE 111570Z	MB1PBEHC79EZB0544	26
73	RAC921	KL-15	8093	LL	CFP	AFP	21-Nov-2009	PPD	53	52	ALPSV 4/89 VIKING	ZXE 110887Z	MB1PBEHC29EZA9477	26

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
74	RAC918	KL-15	8092	LL	CFP	AFP	21-Nov-2009	PPD	53	52	ALPSV 4/89 VIKING	ZXE 111186Z	MB1PBEHC49EZ0534	26
75	RAA118	KL-15	7268	LL	CFP	AFP	11-Dec-2008	CTY	53	52	ALPSV 4/89 VIKING HINO BSII	DNE 102433Z	CNE 663383	28
76	RAC 91	KL-15	7247	LL	CFP	AFP	27-Nov-2008	VLND	53	52	ALPSV 4/89 VIKING HINO EURO BSII TIC	CNH 560894	CNE 663424	20
77	RAC 87	KL-15	7245	LL	CFP	AFP	27-Nov-2008	CTY	53	52	ALPSV 4/89 VIKING HINO EURO II TURBO INTER COOLER	JNH 543089	JNE 655803	28
78	RAC 94	KL-15	7259	LL	CFP	AFP	4-Dec-2008	CTY	53	52	ALPSV 4/89 VIKING HINO EURO II TURBO INTER COOLER	CNH 561148	BNE 665224	28
79	RAC 95	KL-15	7257	LL	CFP	AFP	2-Dec-2008	CTY	53	52	ALPSV 4/89 VIKING HINO EURO II TURBO INTER COOLER	BNH 568444	BNE 665160	28
80	RRK275	KL-15	6443	LL	CFP	AFP	17-Dec-2007	PPD	53	52	ALPSV 4/89 VIKING HINO EUROII TIC	VHG1753	WPE 628614	26
81	RAC 88	KL-15	7240	LL	CFP	AFP	25-Nov-2008	PKDA	53	52	ALPSV 4/89 VIKING LL HINO BSII	JNH 543972	JNE 655862	81
82	RAC 93	KL-15	7255	LL	CFP	AFP	2-Dec-2008	PKDA	53	52	ALPSV 4/89 VIKING LL HINO BSII	CNH 559582	CNE 663448	81
83	RAC 92	KL-15	7251	LL	CFP	AFP	28-Nov-2008	PKDA	53	52	ALPSV 4/89 VIKING LL HINO BSII	CNH 559410	CNE 663370	81
84	RAC 90	KL-15	7250	LL	CFP	AFP	28-Nov-2008	PKDA	53	52	ALPSV 4/89 VIKING LL HINO BSII	CNH 560413	CNE 663372	81
85	RAA117	KL-15	7260	LL	CFP	AFP	5-Dec-2008	PKDA	53	52	ALPSV 4/89 VIKING LL HINO BSII	BNE 103604Z	BNE 665276	81
86	RAC 96	KL-15	7269	LL	CFP	AFP	11-Dec-2008	PKDA	53	52	ALPSV 4/89 VIKING LL HINO BSII	CNH 560610	BNE 665159	81
87	RAC 97	KL-15	7270	LL	CFP	AFP	11-Dec-2008	PKDA	53	52	ALPSV 4/89 VIKING LL HINO BSII	CNH 560764	BNE 665251	81
88	RT 731	KL-15	5909	TATA	CFP	AFP	2-May-2005	VKBN	53	52	CUMMINS 1512 TC	50A62384412	AVZ 103784	29
89	RT 732	KL-15	5910	TATA	CFP	AFP	2-May-2005	VKBN	53	52	CUMMINS 1512 TC	50A62384072	AVZ 104308	29
90	RT 733	KL-15	5911	TATA	CFP	AFP	2-May-2005	VKBN	53	52	CUMMINS 1512 TC	50A62382577	AUZ 103337	29
91	RT 734	KL-15	5912	TATA	CFP	AFP	2-May-2005	VKBN	53	52	CUMMINS 1512 TC	50A62384948	AUZ 104307	29
92	RT 735	KL-15	5913	TATA	CFP	AFP	2-May-2005	VKBN	53	52	CUMMINS 1512 TC	50A62384946	AUZ 104048	29
93	RT 736	KL-15	5914	TATA	CFP	AFP	2-May-2005	VKBN	53	52	CUMMINS 1512 TC	50A62384292	AUZ 104304	29
94	RT 756	KL-15	5934	TATA	CFP	AFP	2-Jun-2005	VKBN	53	52	CUMMINS 1512 TC	50A62384724	AUZ 103878	29
95	RT 757	KL-15	5935	TATA	CFP	AFP	2-Jun-2005	VKBN	53	52	CUMMINS 1512 TC	50B62389479	BUZ 107035	29
96	RT 758	KL-15	5936	TATA	CFP	AFP	2-Jun-2005	VKBN	53	52	CUMMINS 1512 TC	50B62389652	BUZ 107322	29
97	RT 804	KL-15	5982	TATA	CFP	AFP	8-Jul-2005	VKBN	53	52	CUMMINS 1512 TC	50C62394557	CUZ 110849	29
98	RT 851	KL-15	6029	TATA	CFP	AFP	5-Aug-2005	VKBN	53	52	CUMMINS 1512 TC	50A62380071	CUZ 109590	29
99	RT 857	KL-15	6035	TATA	CFP	AFP	9-Aug-2005	VKBN	53	52	CUMMINS 1512 TC	50A62380937	CUZ 109831	29
100	RT 866	KL-15	6044	TATA	CFP	AFP	19-Aug-2005	VKBN	53	52	CUMMINS 1512 TC	50C62392822	CUZ 109672	29
101	RT 891	KL-15	6069	TATA	CFP	AFP	1-Sep-2005	VKBN	53	52	CUMMINS 1512 TC	50B62389349	BUZ 107033	29
102	RT 730	KL-15	5908	TATA	CFP	AFP	2-May-2005	CTY	53	52	CUMMINS 1512 TC	623440026	AUZ 103782	28
103	RT 759	KL-15	5937	TATA	CFP	AFP	2-Jun-2005	CTY	53	52	CUMMINS 1512 TC	OOE 62150498	BUZ 106918	28
104	RT 872	KL-15	6050	TATA	CFP	AFP	22-Aug-2005	CTY	53	52	CUMMINS 1512 TC	50A 62384726	AUZ 103880	28
105	RT 873	KL-15	6051	TATA	CFP	AFP	22-Aug-2005	CTY	53	52	CUMMINS 1512 TC	62380074	CUZ 110771	28
106	RT 874	KL-15	6052	TATA	CFP	AFP	22-Aug-2005	VZM	53	52	CUMMINS 1512 TC	00E62149550	AUZ 104049	24
107	RT 911	KL-15	6089	TATA	CFP	AFP	12-Sep-2005	CTY	53	52	CUMMINS 1512 TC	50A62384223	AUZ 103762	28
108	RNC531	KL-15	8784	TATA	CFP	AFP	3-Nov-2010	PKDA	53	52	LP 1512 TC/59 BSIII	01H62916343	MAT412088A0H14675	81
109	RNC534	KL-15	8806	TATA	CFP	AFP	12-Nov-2010	PKDA	53	52	LP 1512 TC/59 BSIII	01H62916352	MAT412088A0H14680	81
110	RNC544	KL-15	8831	TATA	CFP	AFP	19-Nov-2010	PKDA	53	52	LP 1512 TC/59 BSIII	01J62923522	MAT412088A0J15620	81
111	RNC576	KL-15	8840	TATA	CFP	AFP	22-Nov-2010	PKDA	53	52	LP 1512 TC/59 BSIII	01H62922886	MAT412088A0J15641	81
112	RNC577	KL-15	8841	TATA	CFP	AFP	22-Nov-2010	PKDA	53	52	LP 1512 TC/59 BSIII	01J62924120	MAT412088A0J15675	81
113	RNC578	KL-15	8853	TATA	CFP	AFP	24-Nov-2010	VKBN	53	52	LP 1512 TC/59 BSIII	01J62924067	MAT412088A0J15678	29
114	RAM127	KL-15	7345	LL	CFP	AFP	8-Jan-2009	VKBN	53	52	HINO 6ETI	BNE 103644Z	BNE 665332	29
115	RT 723	KL-15	5901	LL	CFP	AFP	2-May-2005	PKDA	53	52	HINO EURO	DWH 292254	WDA 047243	81

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
116	RT 724	KL-15	5902	LL	CFP	AFP	2-May-2005	PKDA	53	52	HINO EURO	DWH 292218	WDA 047241	81
117	RT 725	KL-15	5903	LL	CFP	AFP	2-May-2005	PKDA	53	52	HINO EURO	DWH 289862	WDA 047248	81
118	RT 726	KL-15	5904	LL	CFP	AFP	2-May-2005	PKDA	53	52	HINO EURO	DWH 292074	WDA 047246	81
119	RT 753	KL-15	5931	LL	CFP	AFP	24-May-2005	VJMD	53	52	HINO EURO	PWA 289860	WDA 047252	16
120	RT 754	KL-15	5932	LL	CFP	AFP	24-May-2005	VJMD	53	52	HINO EURO	DWH 291950	WDA 047244	16
121	RT 923	KL-15	6101	LL	CFP	AFP	17-Oct-2005	PKDA	53	52	HINO EURO	TDH 311114	TDE 553825	81
122	RT 926	KL-15	6104	LL	CFP	AFP	17-Oct-2005	VLND	53	52	HINO EURO	UDH 308932	TDE 553970	20
123	RAC185	KL-15	7349	LL	CFP	AFP	8-Jan-2009	VKBN	53	52	HINO EURO II	BNE 103629Z	BNE 665330	29
124	RAC193	KL-15	7350	LL	CFP	AFP	8-Jan-2009	VKBN	53	52	HINO EURO II	CNH 561151	BNE 665223	29
125	RAC194	KL-15	7351	LL	CFP	AFP	8-Jan-2009	VKBN	53	52	HINO EURO II	CNE 561786	CNE 663390	29
126	RAC202	KL-15	7363	LL	CFP	AFP	12-Jan-2009	VKBN	53	52	HINO EURO II	ZNE 104005Z	ZNE 666159	29
127	RAC203	KL-15	7364	LL	CFP	AFP	12-Jan-2009	VKBN	53	52	HINO EURO II	BNE 103710Z	BNE 665495	29
128	RAC204	KL-15	7365	LL	CFP	AFP	12-Jan-2009	VKBN	53	52	HINO EURO II	BNE 103713Z	BNE 665518	29
129	RAC205	KL-15	7374	LL	CFP	AFP	15-Jan-2009	VKBN	53	52	HINO EURO II	BNE 103708Z	BNE 665514	29
130	RAC879	KL-15	8041	LL	CFP	AFP	10-Nov-2009	VKBN	53	52	HINO EURO II	BXE 109683Z	MB1PBEHC29EBA7241	29
131	RAC880	KL-15	8042	LL	CFP	AFP	10-Nov-2009	VKBN	53	52	HINO EURO II	CXE 108728Z	MB1PBEHC19ECA5256	29
132	RAC881	KL-15	8050	LL	CFP	AFP	11-Nov-2009	VKBN	53	52	HINO EURO II	BXE 109554Z	MB1PBEHC49EBA6978	29
133	RAC898	KL-15	8051	LL	CFP	AFP	11-Nov-2009	VKBN	53	52	HINO EURO II	BXH 584575	MB1PBEHC79EBA6988	29
134	RAC901	KL-15	8068	LL	CFP	AFP	13-Nov-2009	VKBN	53	52	HINO EURO II	BXE 109743Z	MB1PBEHC49EBA7354	29
135	RAC914	KL-15	8078	LL	CFP	AFP	17-Nov-2009	VKBN	53	52	HINO EURO II	BXE 109689Z	MB1PBEHC19EBA7229	29
136	RAC899	KL-15	8062	LL	CFP	AFP	12-Nov-2009	VKBN	53	52	HINO EURO II	BXH 585795	MB1PBEHC39EBA7152	29
137	RAC109	KL-15	7274	LL	CFP	AFP	15-Dec-2008	PKDA	53	52	HINO EURO II TURBO INTER COOLER	JNH 543302	JNE 665863	81
138	RAC902	KL-15	8063	LL	CFP	AFP	12-Nov-2009	PKDA	53	52	HINO EURO II TURBO INTER COOLER	BXH 585796	MBIPREHC59EBA7153	81
139	RAC904	KL-15	8074	LL	CFP	AFP	16-Nov-2009	PKDA	53	52	HINO EURO II TURBO INTER COOLER	BXE 109679Z	MBIPBEHC09EBA7240	81
140	RAC905	KL-15	8075	LL	CFP	AFP	16-Nov-2009	PKDA	53	52	HINO EURO II TURBO INTER COOLER	BXE 109548Z	MBIPBEHC39EBA6969	81
141	RAC906	KL-15	8076	LL	CFP	AFP	16-Nov-2009	PKDA	53	52	HINO EURO II TURBO INTER COOLER	BXH 584572	MBIPBEHC49EBA6981	81
142	RAM 76	KL-15	7296	LL	CFP	AFP	23-Dec-2008	CTY	53	52	HINO HA6 ETI 2	10UHD302	BNE 665170	28
143	RAM 77	KL-15	7297	LL	CFP	AFP	23-Dec-2008	CTY	53	52	HINO HA6 ETI 2	CNH 103248Z	CNE 664132	28
144	RAM458	KL-15	7748	TATA	CFP	AFP	27-May-2009	CTY	53	52	HINO HA6ETI 2	80M62726280	AQZ 000296	28
145	RRE129	KL-15	6344	LL	CFP	AFP	17-Nov-2007	PPD	53	52	HINO W06ETI BSII	IOBH B4627	XPE 626782	26
146	RRC251	KL-15	6421	LL	CFP	AFP	10-Dec-2007	PPD	53	52	HINO W06ETI BSII	VPH 490322	VPE 631960	26
147	RRC392	KL-15	6550	LL	CFP	AFP	18-Jan-2008	PPD	53	52	HINO W06ETI BSII	BXH585894	TPE 637138	26
148	RRC393	KL-15	6556	LL	CFP	AFP	21-Jan-2008	PPD	53	52	HINO W06ETI BSII	BNE 103709	TPE 637224	26
149	RAM 74	KL-15	7264	LL	CFP	AFP	6-Dec-2008	CTY	53	52	HINO W06ETI BSII	IOVHC 3156	CNE 664143	28
150	RAM 75	KL-15	7265	LL	CFP	AFP	6-Dec-2008	CTY	53	52	HINO W06ETI BSII	CNH 560606	BNE 665188	28
151	RAA119	KL-15	7280	LL	CFP	AFP	17-Dec-2008	PKDA	53	52	LL HINO BSII	CNE 102816Z	CNE 663447	81
152	RAA120	KL-15	7279	LL	CFP	AFP	17-Dec-2008	PKDA	53	52	LL HINO BSII	DNE 102714Z	CNE 663500	81
153	RRC585	KL-15	6751	TATA	ORD		13-Mar-2008	PPD	48	60	697 TCIC	BRZ 1115324	ARZ 000903	26
154	RRC736	KL-15	6902	TATA	CFP	AFP	22-Apr-2008	VKBN	53	52	697 TCIC	BRZ 108664	BRZ 003591	29
155	RRC 77	KL-15	6251	TATA	CFP	AFP	14-Sep-2007	VKBN	53	52	697 TCIC	FSZ 130857	FSZ 010556	29
156	RRC 78	KL-15	6253	TATA	CFP	AFP	19-Sep-2007	VKBN	53	52	697 TCIC	FSZ 130746	FSZ 010557	29
157	RRC 79	KL-15	6254	TATA	CFP	AFP	19-Sep-2007	VKBN	53	52	697 TCIC	FSZ 131091	FSZ 010558	29
158	RRM 96	KL-15	6255	TATA	CFP	AFP	19-Sep-2007	VLND	53	52	697 TCIC	697 TC55 FSZ 130747	436062 FSZ 010464	20
159	RRC 82	KL-15	6260	TATA	CFP	AFP	26-Sep-2007	VKBN	53	52	697 TCIC	FSZ 130760	FSZ 010463	29
160	RRC 80	KL-15	6259	TATA	CFP	AFP	24-Sep-2007	PKDA	53	52	697 TCIC	697 TC55 FSZ 130764	436062 FSZ 010458	81

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
161	RRM103	KL-15	6262	TATA	CFP		27-Sep-2007	VLND	53	52	697 TCIC	697 TC55 FSZ 130506	436062 FSZ 010446	20
162	RRA107	KL-15	6267	TATA	CFP	AFP	1-Oct-2007	PKDA	53	52	697 TCIC	697 TC55 FSZ 130501	436062 FSZ 010457	81
163	RRC 86	KL-15	6269	TATA	CFP	AFP	1-Oct-2007	VKBN	53	52	697 TCIC	FSZ 130938	FSZ 010519	29
164	RRC 89	KL-15	6270	TATA	CFP	AFP	1-Oct-2007	VLND	53	52	697 TCIC	697 TC55 FSZ 130832	436062 FSZ 010526	20
165	RRM105	KL-15	6266	TATA	CFP	AFP	1-Oct-2007	PKDA	53	52	697 TCIC	697 TC55 FSZ 130660	436062 FSZ 010460	81
166	RRM104	KL-15	6271	TATA	CFP	AFP	3-Oct-2007	PKDA	53	52	697 TCIC	697 TC55 FSZ 130534	436062 FSZ 010455	81
167	RRC 87	KL-15	6272	TATA	CFP	AFP	3-Oct-2007	VLND	53	52	697 TCIC	697 TC55 FSZ 130659	436062 FSZ 010523	20
168	RRC 94	KL-15	6276	TATA	CFP	AFP	3-Oct-2007	VKBN	53	52	697 TCIC	FSZ 130955	FSZ 010560	29
169	RRC 92	KL-15	6279	TATA	CFP	AFP	6-Oct-2007	PKDA	53	52	697 TCIC	697 TC55 FSZ 130738	436062 FSZ 010553	81
170	RRM117	KL-15	6283	TATA	CFP	AFP	10-Oct-2007	PKDA	53	52	697 TCIC	697 TC55 FSZ 130834	436062 FSZ 010531	81
171	RRC113	KL-15	6285	TATA	CFP	AFP	11-Oct-2007	PKDA	53	52	697 TCIC	697 TC55 GSZ 132217	436062 HSZ 012585	81
172	RRC111	KL-15	6292	TATA	CFP	AFP	16-Oct-2007	VKBN	53	52	697 TCIC	FSZ 130954	FSZ 010521	29
173	RRC112	KL-15	6291	TATA	CFP	AFP	15-Oct-2007	PKDA	53	52	697 TCIC	697 TC55 GSZ 132645	436062 GSZ 011447	81
174	RRC114	KL-15	6294	TATA	ORD	AFP	19-Oct-2007	PKDA	48	60	697 TCIC	697 TC55 GSZ 135484	436062 HSZ 012702	81
175	RRM135	KL-15	6322	TATA	CFP	AFP	2-Nov-2007	PKDA	53	52	697 TCIC	697 TC55 GSZ 134910	436062 HSZ 012428	81
176	RRM163	KL-15	6336	TATA	CFP	AFP	12-Nov-2007	VKBN	53	52	697 TCIC	GSZ 132852	GSZ 011451	29
177	RRM164	KL-15	6339	TATA	CFP	AFP	13-Nov-2007	VKBN	53	52	697 TCIC	697 TC55	HSZ 012717	29
178	RRM165	KL-15	6342	TATA	CFP	AFP	16-Nov-2007	PKDA	53	52	697 TCIC	697 TC55 GSZ 135238	436062 HSZ 012472	81
179	RRM162	KL-15	6356	TATA	CFP	AFP	20-Nov-2007	VKBN	53	52	697 TCIC	GSZ 134915	GSZ 013362	29
180	RRA173	KL-15	6360	TATA	CFP	AFP	23-Nov-2007	VKBN	53	52	697 TCIC	697 TC55	HSZ 012718	29
181	RRA240	KL-15	6366	TATA	CFP	AFP	26-Nov-2007	VKBN	53	52	697 TCIC	GSZ 35634	HSZ 013073	29
182	RRM136	KL-15	6335	TATA	CFP	AFP	12-Nov-2007	PKDA	53	52	697 TCIC	697 TC55 GSZ 134911	436062 HSZ 012429	81
183	RRC125	KL-15	6299	TATA	CFP	AFP	23-Oct-2007	PKDA	53	52	697 TCIC	697 TC55 GSZ 135699	436062 HSZ 012716	81
184	RRC 83	KL-15	6261	TATA	CFP	AFP	26-Sep-2007	CTY	53	52	697 TCIC	JSZ 139611	436062 FSZ 010466	28
185	RRC 84	KL-15	6265	TATA	CFP	AFP	28-Sep-2007	CTY	53	52	697 TCIC	697 TC55 FSZ 130227	436062 FSZ 010467	28
186	RRC 88	KL-15	6273	TATA	CFP	AFP	3-Oct-2007	CTY	53	52	697 TCIC	697 TC55 FSZ 130953	436062 FSZ 010522	28
187	RRC 91	KL-15	6280	TATA	CFP	AFP	8-Oct-2007	CTY	53	52	697 TCIC	BUZ 104286	436062 FSZ 010532	28
188	RRC 93	KL-15	6281	TATA	CFP	AFP	9-Oct-2007	CTY	53	52	697 TCIC	62101185	436062 FSZ 010555	28
189	RRC116	KL-15	6293	TATA	CFP	AFP	18-Oct-2007	CTY	53	52	697 TCIC	697 TC55 FSZ 130763	436062 HSZ 012711	28
190	RRC122	KL-15	6295	TATA	CFP	AFP	22-Oct-2007	CTY	53	52	697 TCIC	BRZ 111517	436062 HSZ 012705	28
191	RRC124	KL-15	6296	TATA	CFP	AFP	22-Oct-2007	CTY	53	52	697 TCIC	697 TC55 JSZ 139615	436062 HSZ 012714	28
192	RRC121	KL-15	6309	TATA	CFP	AFP	29-Oct-2007	CTY	53	52	697 TCIC	697 TE55 LSZ152743	436062 HSZ 012588	28
193	RRC123	KL-15	6321	TATA	CFP	AFP	2-Nov-2007	CTY	53	52	697 TCIC	697 TC55 GSZ 135634	436062 HSZ 012712	28
194	RRC467	KL-15	6632	TATA	CFP	AFP	11-Feb-2008	VKBN	53	52	697 TCIC	MSZ 154119	MSZ 020850	29
195	RNC529	KL-15	8767	TATA	CFP	AFP	2-Nov-2010	VLND	53	52	LP 1512 TC/59 BSIII	01H62915679	MAT412088A0H14492	20
196	RNC530	KL-15	8768	TATA	CFP	AFP	2-Nov-2010	VLND	53	52	LP 1512 TC/59 BSIII	01H62915684	MAT412088A0H14500	20
197	RNC533	KL-15	8790	TATA	CFP	AFP	8-Nov-2010	PPD	53	52	LP 1512 TC/59 BSII	01H62916339	MAT412088A0H14678	26
198	RRC224	KL-15	6364	TATA	CFP	AFP	24-Nov-2007	VKBN	53	52	LP 59 BSII	GSZ 134928	HSZ 012701	29
199	RT 860	KL-15	6038	TATA	CFP	AFP	12-Aug-2005	CTY	53	52	TATA 1512 TC CUMMINS	50A62382577	CUZ 110773	28
200	TP 926	KL-15	5104	LL	CTY		19-Dec-2003	PKDA	53	49	HINO EURO	XVH 247128	XVE 516304	81
201	RT 76	KL-15	5254	LL	CTY		5-Mar-2004	VLND	53	49	HINO EURO	BMH 206333	WVE 599212	20
202	RT 316	KL-15	5494	LL	CTY		1-Jul-2004	VLND	53	49	HINO EURO	FBH 145141	SWA 042567	20
203	RT 331	KL-15	5509	LL	CTY		13-Jul-2004	PKDA	53	49	HINO EURO	YBH 153030	SWA 042496	81
204	RT 573	KL-15	5751	LL	CTY		23-Dec-2004	PKDA	53	49	HINO EURO	10VHX2483	KWA 045123	81
205	RT 627	KL-15	5804	LL	CTY		15-Feb-2005	VLND	53	49	HINO EURO	LBH 163096	FWA 046245	20

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
206	RT 630	KL-15	5807	LL	CTY		15-Feb-2005	PKDA	53	49	HINO EURO	FWH 288497	DWA 046445	81
207	RT 893	KL-15	6071	LL	CTY		1-Sep-2005	PKDA	53	49	HINO EURO	VHP 16495	UDE 551208	81
208	RN 765	KL-15	9050	LL	DD		26-Feb-2011	CTY	53	96		KNH 535419	KXG048854	28
209	RN 766	KL-15	9051	LL	DD		26-Feb-2011	ANK	53	96	HINO BSII	KNH 535418	KXG048855	57
210	RAE180	KL-15	7367	LL	ORD		13-Jan-2009	EDT	48	60	HINO W06ETI BSII	BNE 103714Z	BNE 665494	98
211	RAE182	KL-15	7375	LL	ORD		16-Jan-2009	KKLM	48	60	HINO W06ETI BSII	LXH 572186	ZNE 666670	108
212	RAC247	KL-15	7390	LL	ORD		22-Jan-2009	CHRY	48	60	HINO BSII TURBO INTER COOLER	ZNH 567906	ZNE 666688	44
213	RAC228	KL-15	7391	LL	ORD		22-Jan-2009	PSL	48	60	HINO BSII	ZNE 104145Z	ZNE 666669	21
214	RAC226	KL-15	7394	LL	ORD		23-Jan-2009	VLRD	48	60	HINO BSII TURBO INTER COOLER	ZNH 566887	ZNE 666576	93
215	RAC227	KL-15	7395	LL	ORD		23-Jan-2009	PSL	48	60	HINO BSII	ZNE 104117Z	ZNE 666659	21
216	RAE249	KL-15	7396	LL	ORD		24-Jan-2009	KTP	48	60	HINO W06ETI BSII	ZNE 104138Z	ZNE 666660	14
217	RAE328	KL-15	7501	LL	ORD		2-Mar-2009	KMY	48	60	WXE 114818Z	ZNE 104358Z	YNE 667278	05
218	RAC486	KL-15	7622	LL	ORD		15-Apr-2009	VLND	48	60	HINO BSII TURBO INTER COOLER	LXH 573279	LXE 670239	20
219	RAE515	KL-15	7682	LL	ORD		4-May-2009	CTLA	48	60	HINO W06ETI BSII	NXE 105298Z	NXE 669321	46
220	RAC487	KL-15	7623	LL	ORD		15-Apr-2009	VLND	48	60	HINO BSII TURBO INTER COOLER	LXH 572760	LXE 669883	20
221	RAE469	KL-15	7638	LL	ORD		20-Apr-2009	VLND	48	60	HINO W06ETI BSII	NXE 105270Z	NXE 669245	20
222	RAE491	KL-15	7639	LL	ORD		20-Apr-2009	CTLA	48	60	HINO W06ETI BSII	NXH 571761	NXE 669227	46
223	RAE492	KL-15	7640	LL	ORD		20-Apr-2009	CTLA	48	60	HINO W06ETI BSII	LXH 572215	LXE 669906	46
224	RAM535	KL-15	7763	TATA	ORD		1-Jun-2009	CLDY	48	60		90A62728338	BQZ 001058	58
225	RAA636	KL-15	7783	TATA	ORD		8-Jun-2009	CLDY	48	60		90A62726990	BQZ 001115	58
226	RAA638	KL-15	7794	TATA	ORD		20-Jun-2009	CLDY	48	60		90G62768499	BQZ 001246	58
227	RAE685	KL-15	7820	LL	ORD		23-Jun-2009	MLTM	48	60	HINO EURO III	LXH 572529	LXE 669908	54
228	RAE596	KL-15	7775	LL	ORD		3-Jun-2009	VJMD	48	60	HINO W06ETI BSII	LXH 572218	LXE 670020	16
229	RAE598	KL-15	7776	LL	ORD		3-Jun-2009	PVR	48	60	HINO W06ETI BSII	LXH 572225	LXE 657665	23
230	RAE600	KL-15	7786	LL	ORD		17-Jun-2009	CHRY	48	60	HINO W06ETI BSII	LXH 573585	LXE 670594	44
231	RAA710	KL-15	7881	TATA	ORD		24-Jul-2009	CLDY	48	60		90B62734402	CQZ 002639	58
232	RAC721	KL-15	7906	LL	ORD		25-Aug-2009	MLTM	48	60	HINO W06ETI BSII	NXE 105345Z	NXE 669327	54
233	RAE773	KL-15	7913	LL	ORD		26-Aug-2009	MLTM	48	60	HINO EURO BSII	JXH 576189	MB1PBEHC99EJA0557	54
234	RAA715	KL-15	7952	TATA	ORD		25-Sep-2009	CTY	48	60		90C62737581	CQZ 003375	28
235	RAC810	KL-15	7982	LL	ORD		15-Oct-2009	VDCY	48	60		JXE 1070247	MP1PBEHC89EJA1053	82
236	RAC871	KL-15	8023	LL	ORD		3-Nov-2009	VLND	48	60	HINO BSII TURBO INTER COOLER	BXE 109736Z	MB1PBEHC79EBA7364	20
237	RAC855	KL-15	8024	LL	ORD		4-Nov-2009	VLND	48	60	HINO BSII TURBO INTER COOLER	BXE 109742Z	MB1PBEHC09EBA7352	20
238	RAC869	KL-15	8025	LL	ORD		4-Nov-2009	VLND	48	60	HINO BSII TURBO INTER COOLER	BXH 585894	MB1PBEHC29EBA7398	20
239	RAC930	KL-15	8113	LL	ORD		3-Dec-2009	CLDY	48	60		ZXE110994Z	MB1PBEHC99EZA9511	58
240	RAC933	KL-15	8116	LL	ORD		3-Dec-2009	VDCY	48	60		ZXE 111463Z	MB1PBEHC09E2B0322	82
241	RAC937	KL-15	8146	LL	ORD		30-Dec-2009	KTDA	48	60		ZXE 11653Z	MB1PBEHC69E2B0678	25
242	RAC951	KL-15	8150	LL	ORD		1-Jan-2010	CLDY	48	60		BXE110663Z	MB1PBEHC49EZA9478	58
243	RNE211	KL-15	8453	LL	ORD		8-Jul-2010	TDP	48	60	EURO BSII	WAE119339Z	MB1PBEHC9AEWC2996	53
244	RNE276	KL-15	8548	LL	ORD		10-Aug-2010	CLDY	48	60		VAE121705Z	MB1PBEHC8AEVC6129	58
245	RNE372	KL-15	8585	LL	ORD		21-Jun-2010	PLR	48	60	ALPSV 4/89 VIKING BSII	VAE120706Z	MB1PBEHC3AEVC4773	36
246	RNE370	KL-15	8590	LL	ORD		27-Aug-2010	NTA	48	60	ALPSV 4/89 VIKING BSII	VAE121587Z	MB1PBEHC4AEVC6113	22
247	RNE371	KL-15	8594	LL	ORD		1-Sep-2010	KGD	48	60	ALPSV 4/89 VIKING BSII	VAE120674Z	MB1PBEHC9AEVC4678	84
248	RNE373	KL-15	8605	LL	ORD		3-Sep-2010	VJMD	48	60		VAE120726Z	MB1PBEHC1AEVC4769	16
249	RNE402	KL-15	8606	LL	ORD		3-Sep-2010	MDY	48	60	ALPSV 4/89 VIKING BSII	VAE122023Z	MB1PBEHC6AEVC6632	76
250	RNE403	KL-15	8611	LL	ORD		4-Sep-2010	ARND	48	60	ALPSV 4/89 VIKING BSII	VAE121544Z	MB1PBEHC8AEVC5885	19

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
251	RNE405	KL-15	8633	LL	ORD		15-Sep-2010	PNKM	48	60	ALPSV 4/89 VIKING BSII	YPH470437	MB1PBEHC1AEVC5632	49
252	RNE406	KL-15	8634	LL	ORD		15-Sep-2010	VTRA	48	60	ALPSV 4/89 VIKING BSII	VAE121444Z	MB1PBEHCXAEVC5760	17
253	RNE407	KL-15	8644	LL	ORD	VND	16-Sep-2010	KTDA	48	60	ALPSV 4/89 VIKING BSII	VAE121769Z	MB1PBEHC6AEVC6212	25
254	RNK409	KL-15	8654	LL	ORD		22-Sep-2010	TDY	48	60	ALPSV 4/89 VIKING BSII	WAE120653Z	MB1PBEHC1AEVC4643	79
255	RNE418	KL-15	8655	LL	ORD		22-Sep-2010	PTA	48	60	ALPSV 4/89 VIKING BSII	MAE131101Z	MB1PBEHC7AEVD6180	37
256	RNE420	KL-15	8656	LL	ORD		22-Sep-2010	NTA	48	60	ALPSV 4/89 VIKING BSII	NAE130542Z	MB1PBEHC6AEND5671	22
257	RNE421	KL-15	8661	LL	ORD		25-Sep-2010	NTA	48	60	ALPSV 4/89 VIKING BSII	VAE121349Z	MB1PBEHC3AEVC5633	22
258	RNE422	KL-15	8662	LL	ORD		25-Sep-2010	NDD	48	60	ALPSV 4/89 VIKING BS11	WAE120021Z	MB1PBEHC7AEWC3841	31
259	RNK413	KL-15	8674	LL	ORD		29-Sep-2010	VJMD	48	60	ALPSV 4/89 VIKING BSII	VAE121873Z	MB1PBEHC9AEVC6365	16
260	RNK451	KL-15	8744	LL	ORD		20-Oct-2010	KDLR	48	60		NAE129697Z	MB1PBEHC6AEND4990	90
261	RNA496	KL-15	8753	TATA	ORD		28-Oct-2010	PTA	48	60	LP 1512 TC/59 BSII	01G62908004	MAT412088A0H13960	37
262	RNA499	KL-15	8787	TATA	ORD		4-Nov-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01G62908229	MAT412088A0H13951	90
263	RNE524	KL-15	8789	LL	ORD		8-Nov-2010	NTA	48	60		MAE131099Z	MB1PBEHC9AEVD6178	22
264	RNK484	KL-15	8800	LL	ORD		10-Nov-2010	CLDY	48	60		NAE130506Z	MB1PBEHC3AEND5675	58
265	RNK486	KL-15	8802	LL	ORD		10-Nov-2010	CLDY	48	60		NAE129879Z	MB1PBEHC7AEND4982	58
266	RNE598	KL-15	8872	LL	ORD		30-Nov-2010	PLD	48	60	EURO BSII	NAE130091Z	MB1PBEHC1AEND5187	32
267	RNM594	KL-15	8887	TATA	ORD		2-Dec-2010	CLDY	48	60	LP 1512 TC/59 BSIII	01H62915614	MAT412088A0H14686	58
268	RNC818	KL-15	9269	LL	ORD		28-Nov-2011	PLD	48	66	HINO 6ETI3K BSIII	BNHZ101630	MB1PBEYC1BENG3931	32
269	RNE806	KL-15	9270	LL	ORD		28-Nov-2011	PLD	48	66	HINO 6ETI3K BSIII	NBE158588Z	MB1PBEYC9BENG3692	32
270	RNC817	KL-15	9272	LL	ORD		29-Nov-2011	PNR	48	66	HINO 6ETI3K BSIII	BPHZ101069	MB1PBEYCXBENG3930	78
271	RNE822	KL-15	9286	LL	ORD		7-Dec-2011	PTA	48	66	HINO 6ETI3K BSIII	BMEZ400091	MB1PBEYC6BEMG5140	37
272	RNK833	KL-15	9287	LL	ORD		9-Dec-2011	PTA	48	66	HINO 6ETI3K BSIII	NBE159547Z	MB1PBEYC2BEMG4762	37
273	RNC872	KL-15	9306	LL	ORD		19-Dec-2011	NDD	48	66	HINO 6ETI3K BSIII	BMEZ400719	MB1PCEYCBENG5639	31
274	RNC866	KL-15	9308	TATA	ORD		20-Dec-2011	IJK	48	66	LP 1512 TC/59 BSIII	11K84025242	MAT412021B0N20828	89
275	RNA850	KL-15	9309	LL	ORD		20-Dec-2011	TPLM	48	66	HINO 6ETI3K BSIII	MBE159636Z	MB1PBEYC6BENG5204	94
276	RNM819	KL-15	9273	LL	ORD		29-Nov-2011	PNR	48	66	HINO 6ETI3K BSIII	NBE158609Z	MB1PBEYC6BENG3682	78
277	RNC914	KL-15	9360	TATA	ORD		31-Jan-2012	VKM	48	66	LP 1512 TC/59 BSIII	11L63199700	MAT412021B0N21336	51
278	RNC934	KL-15	9383	TATA	ORD		14-Feb-2012	IJK	48	66	LP 1512 TC/59 BSIII	11L84028089	MAT412021BON21383	89
279	RNE888	KL-15	9387	LL	ORD		14-Feb-2012	MLTM	48	66	HINO 6ETI3K BSIII	BMEZ400726	MB1PBEYC0BECG6457	54
280	RNC952	KL-15	9392	TATA	ORD		18-Feb-2012	GVR	48	66	LP 1512 TC/59 BSIII	11L63206158	MAT412021BON22057	66
281	RNK926	KL-15	9395	LL	ORD		21-Feb-2012	EKM	48	66	HINO 6ETI3K BSIII	6MEZ400598	MB1PBE7C2BEMG5670	56
282	RNA980	KL-15	9397	TATA	ORD		24-Feb-2012	KLM	48	66	LP 1512 TC/59 BSIII	11L63199697	MAT412021B0N21526	34
283	RNC953	KL-15	9399	TATA	ORD		27-Feb-2012	MKD	48	66	LP 1512 TC/59 BSIII	11L84030104	MAT412021BON22056	08
284	RNC983	KL-15	9403	TATA	ORD		1-Mar-2012	PMNA	48	66	LP 1512 TC/59 BSIII	11L84028095	MAT412021BON21379	68
285	RNK927	KL-15	9406	LL	ORD		3-Mar-2012	KGD	48	66	HINO 6ETI3K BSIII	BMEZ400012	MB1PBEYC3BEMG5208	84
286	RNM901	KL-15	9341	TATA	ORD		10-Jan-2012	KNPY	48	66	LP 1512 TC/59 BSIII	11K84025370	MAT412021B0N20826	87
287	RAM463	KL-15	7753	TATA	ORD		27-May-2009	EMLY	48	60	6BT CUMMINS BSII	90A 62728317	412081 BQZ001109	95
288	RAM619	KL-15	7831	TATA	ORD		26-Jun-2009	GVR	48	60	6BT CUMMINS BSII	90B 62734410	412081 CQZ002644	66
289	RAM760	KL-15	8057	TATA	ORD		11-Nov-2009	CTY	48	60	6BT CUMMINS BSII	80L 62722219	LRZ 19496	28
290	RNC155	KL-15	8323	TATA	ORD		19-May-2010	PALA	48	60	LP 1512 TC/59 BSIII	01C62855473	MAT412088A0C06868	50
291	RNA566	KL-15	8818	TATA	ORD		16-Nov-2010	VKBN	48	60	LP 1512 TC/59 BSII	01G62908006	MAT412266A0J16464	29
292	RNM635	KL-15	8949	TATA	ORD		3-Jan-2011	ALP	48	60	LP 1512 TC/59 BSII	01H62922025	MAT412088A0J15473	45
293	RNM749	KL-15	9107	TATA	ORD		28-Mar-2011	PALA	48	60	LP 1512 TC/59 BSIII	01H62921312	MAT412088A0J15574	50
294	RNC864	KL-15	9305	TATA	ORD		17-Dec-2011	ALP	48	66	LP 1512 TC/59 BSIII	11K84025257	MAT412021B0N20829	45
295	RNC867	KL-15	9317	TATA	ORD		27-Dec-2011	ALP	48	66	LP 1512 TC/59 BSIII	11K84025245	MAT412021B0N20827	45

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
296	RNA915	KL-15	9344	TATA	ORD		13-Jan-2012	KNPY	48	60	LP 1512 TC/59 BSIII	11K63194733	MAT412021B0N20826	87
297	RAA570	KL-15	7730	TATA	ORD		16-May-2009	KPM	48	60	1512 CUMMINS TCIC		AQZ 000295	91
298	RAA575	KL-15	7758	TATA	ORD		29-May-2009	MALA	48	60	1512 CUMMINS TCIC		BQZ 001112	85
299	RNM592	KL-15	8863	TATA	ORD		27-Nov-2010	CTNR	48	60	LP 1512 TC/59 BSII	01G62908483	MAT412088A0H13948	97
300	RNM907	KL-15	9396	TATA	ORD		23-Feb-2012	PNI	48	66	LP 1512 TC/59 BSIII	31A84094621	MAT412021B0N21824	67
301	RAA642	KL-15	7841	TATA	ORD		30-Jun-2009	CTLA	48	60	1512 TC BSII	90462726965	BQZ 001330	46
302	RAM622	KL-15	7842	TATA	ORD		1-Jul-2009	CTLA	48	60	1512 TC BSII	90B62734419	CQZ 002642	46
303	RAA643	KL-15	7854	TATA	ORD		4-Jul-2009	CTLA	48	60	1512 TC BSII	90462728242	BQZ 001066	46
304	RAM620	KL-15	7845	TATA	ORD		2-Jul-2009	KYLM	48	60	1512 TC BSII		412081CQZ003376	41
305	RAM679	KL-15	7875	TATA	ORD		18-Jul-2009	PNKM	48	60	1512 TC BSII	62737588	412081CQZ003380	49
306	RAM677	KL-15	7869	TATA	ORD		16-Jul-2009	KDLR	48	60	1512 TC BSII	90B62734420	CQZ 002647	90
307	RAA713	KL-15	7933	TATA	ORD		14-Sep-2009	HPD	48	60	1512 TC BSII	90C62737212	412081CQZ003371	42
308	RAA716	KL-15	7970	TATA	ORD		8-Oct-2009	HPD	48	60	1512 TC BSII	90B62734415	412081CQZ002648	42
309	RAM857	KL-15	8058	TATA	ORD		11-Nov-2009	CTLA	48	60	1512 TC BSII	80L62722589	LRZ 019550	46
310	RAM756	KL-15	8054	TATA	ORD		11-Nov-2009	KYLM	48	60	1512 TC BSII		412081LRZ019516	41
311	RAM858	KL-15	8059	TATA	ORD		11-Nov-2009	KYLM	48	60	1512 TC BSII		412081MRZ019184	41
312	RAM890	KL-15	8102	TATA	ORD		8-Dec-2009	HPD	48	60	1512 TC BSII	90F62759692	MAT41208190F08996	42
313	RAA910	KL-15	8112	TATA	ORD		2-Dec-2009	HPD	48	60	1512 TC BSII	90E62757083	MAT41208190F08982	42
314	RAA959	KL-15	8138	TATA	ORD		21-Dec-2009	CTNR	48	60	1512 TC BSII	90G62768367	MAT41208190G11184	97
315	RNC 61	KL-15	8239	TATA	ORD		3-Apr-2010	KLM	48	60	LP 1512 TC/59 BSIII	90F62761150	MAT41208190F09627	34
316	RNA 76	KL-15	8250	TATA	ORD		12-Apr-2010	KLM	48	60	LP 1512 TC/59 BSIII	01A62829030	MAT412081A0B02624	34
317	RNC 69	KL-15	8255	TATA	ORD		13-Apr-2010	KLM	48	60	LP 1512 TC/59 BSIII	01A62829747	MAT412081A0B02620	34
318	RNC 95	KL-15	8257	TATA	ORD		17-Apr-2010	KYLM	48	60	LP 1512 TC/59 BSII	01A62830352	MAT412081A0B02621	41
319	RNC 97	KL-15	8266	TATA	ORD		21-Apr-2010	KYLM	48	60	LP 1512 TC/59 BSII	01A62829026	MAT412081A0B02625	41
320	RNC100	KL-15	8269	TATA	ORD		23-Apr-2010	CTLA	48	60	LP 1512 TC/59 BSII	01B62840566	MAT412081A0B03378	46
321	RNA114	KL-15	8271	TATA	ORD		24-Apr-2010	CTLA	48	60	LP 1512 TC/59 BSII	01B62840622	MAT412081A0B03325	46
322	RNC120	KL-15	8279	TATA	ORD		28-Apr-2010	KPM	48	60	LP 1512 TC/59 BSIII	01B62843875	MAT412081A0B03637	91
323	RNC147	KL-15	8333	TATA	ORD		24-May-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01B62841371	MAT412081A0B03387	90
324	RNA 56	KL-15	8518	TATA	ORD		28-Jul-2010	KYLM	48	60	LP 1512 TC/59 BSII	01A62829980	MAT412085AAA01664	41
325	RNA494	KL-15	8747	TATA	ORD		25-Oct-2010	NPR	48	60	LP 1512 TC/59 BSII	01G62908442	MAT412088A0H13954	62
326	RNA569	KL-15	8852	TATA	ORD		24-Nov-2010	HPD	48	60	LP 1512 TC/59 BSII	01H62915691	MAT412088A0H14497	42
327	RNC865	KL-15	9307	TATA	ORD		19-Dec-2011	HPD	48	66	LP 1512 TC/59 BSIII	11K84025252	MAT412021B0N20830	42
328	RNC879	KL-15	9327	TATA	ORD		4-Jan-2012	KYLM	48	66	LP 1512 TC/59 BSIII	11K84024967	MAT412021B0N21330	41
329	RNA899	KL-15	9328	TATA	ORD		5-Jan-2012	KYLM	48	66	LP 1512 TC/59 BSIII	11K63196945	MAT412021B0N20821	41
330	RNC880	KL-15	9343	TATA	ORD		12-Jan-2012	CTLA	48	66	LP 1512 TC/59 BSIII	11K63194789	MAT412021B0N21069	46
331	RNC909	KL-15	9352	TATA	ORD		19-Jan-2012	KLM	48	60	LP 1512 TC/59 BSIII	11L84028078	MAT412021B0N21384	34
332	RNA615	KL-15	8867	TATA	ORD		29-Nov-2010	GVR	48	60	LP 1512 TC/59 BSIII	01H62918620	MAT412088A0J15983	66
333	RNM595	KL-15	8892	TATA	ORD		6-Dec-2010	CTY	48	60	LP 1512 TC/59 BSIII	01H62915350	MAT412088A0H14684	28
334	RAA635	KL-15	7774	TATA	ORD		2-Jun-2009	KPM	48	60	1512 TCIC		412081BQZ001114	91
335	RAM678	KL-15	7891	TATA	ORD		13-Aug-2009	PVR	48	60	1512 TCIC	90C62737042	412081CQZ003379	23
336	RAM680	KL-15	7955	TATA	ORD		25-Sep-2009	PVR	48	60	1512 TCIC	90C62735586	412081CQZ003378	23
337	RAM681	KL-15	7956	TATA	ORD		25-Sep-2009	PVR	48	60	1512 TCIC	90C62735577	412081CQZ003377	23
338	RAM754	KL-15	8052	TATA	ORD		11-Nov-2009	KNPY	48	60	LP 1512 TC/59 BSII	80L62722353	LRZ 019531	87
339	RAA912	KL-15	8118	TATA	ORD		9-Dec-2009	PVR	48	60	1512 TCIC	90E62752287	MAT41208190F08854	23
340	RAM938	KL-15	8126	TATA	ORD		10-Dec-2009	PVR	48	60	1512 TCIC	90F62759506	MAT41208190F09052	23

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
341	RNA117	KL-15	8306	TATA	ORD		10-May-2010	VZM	48	60	LP 1512 TC/59 BSII	01B62840577	MAT412081A0B03329	24
342	RNC157	KL-15	8330	TATA	ORD		21-May-2010	PVR	48	60	LP 1512 TC/59 BSII	01C62854425	MAT412088A0C06160	23
343	RAA568	KL-15	7709	TATA	ORD		12-May-2009	KPM	48	60	1512 TCIC BSII	62726349	AQZ 000170	91
344	RAA641	KL-15	7835	TATA	ORD		27-Jun-2009	KLM	48	60	1512 TCIC BSII	62729829	BQZ 001260	34
345	RAA709	KL-15	7874	TATA	ORD		17-Jul-2009	ATL	48	60	1512 TCIC BSII			33
346	RAM676	KL-15	7862	TATA	ORD		9-Jul-2009	ATL	48	60	1512 TCIC BSII			33
347	RAM755	KL-15	8053	TATA	ORD		11-Nov-2009	ATL	48	60	1512 TCIC BSII			33
348	RAM757	KL-15	8055	TATA	ORD		11-Nov-2009	KNPY	48	60	1512 TCIC BSII			87
349	RAA828	KL-15	8043	TATA	ORD		10-Nov-2009	ATL	48	60	1512 TCIC BSII			33
350	RAA829	KL-15	8079	TATA	ORD		17-Nov-2009	VZM	48	60	1512 TCIC BSII	62734377	MAT41208190F08850	24
351	RAM861	KL-15	8094	TATA	ORD		24-Nov-2009	ATL	48	60	1512 TCIC BSII			33
352	RAA909	KL-15	8104	TATA	ORD		30-Nov-2009	ATL	48	60	1512 TCIC BSII			33
353	RAM891	KL-15	8103	TATA	ORD		28-Nov-2009	ATL	48	60	1512 TCIC BSII			33
354	RAA911	KL-15	8117	TATA	ORD		4-Dec-2009	KYLM	48	60	1512 TCIC BSII		MAT41208190F08852	41
355	RAM892	KL-15	8125	TATA	ORD		10-Dec-2009	KPM	48	60	1512 TCIC BSII			91
356	RNC 58	KL-15	8223	TATA	ORD		9-Mar-2010	ATL	48	60	LP 1512 TC/59 BSII	90G62767722	MAT41208190G11174	33
357	RNC 59	KL-15	8224	TATA	ORD		9-Mar-2010	PKDA	48	60	LP 1512 TC/59 BSII	90G62767783	MAT41208190G11175	81
358	RNC 60	KL-15	8227	TATA	ORD		15-Mar-2010	ATL	48	60	LP 1512 TC/59 BSII	90F62761576	MAT41208190F09628	33
359	RNM 30	KL-15	8234	TATA	ORD		26-Mar-2010	ATL	48	60	LP 1512 TC/59 BSII	01A62831012	MAT412085A01663	33
360	RNM 31	KL-15	8238	TATA	ORD		30-Mar-2010	KYLM	48	60	LP 1512 TC/59 BSIII	01A62829975	MAT412085A01661	41
361	RNC 67	KL-15	8241	TATA	ORD		3-Apr-2010	ATL	48	60	LP 1512 TC/59 BSII	01A62735336	MAT412081A0B02777	33
362	RNA 77	KL-15	8242	TATA	ORD		3-Apr-2010	ATL	48	60	LP 1512 TC/59 BSII	01A62835348	MAT412081A0B02776	33
363	RNC 68	KL-15	8256	TATA	ORD		17-Apr-2010	ATL	48	60	LP 1512 TC/59 BSII	01B62840818	MAT412081A0B03381	33
364	RNA495	KL-15	8748	TATA	ORD		25-Oct-2010	CDLM	48	60	LP 1512 TC/59 BSIII	01G62907922	MAT412088A0H13957	80
365	RNA497	KL-15	8763	TATA	ORD		1-Nov-2010	ATL	48	60	LP 1512 TC/59 BSII	01G62915677	MAT412088A0H14494	33
366	RNA501	KL-15	8793	TATA	ORD		9-Nov-2010	CDLM	48	60	LP 1512 TC/59 BSIII	01G62907999	MAT412088A0H13956	80
367	RNA565	KL-15	8812	TATA	ORD		15-Nov-2010	VKBN	48	60	LP 1512 TC/59 BSII	01G62907920	MAT412088A0H13958	29
368	RNM593	KL-15	8886	TATA	ORD		2-Dec-2010	MVK	48	60	LP 1512 TC/59 BSII	01H62915351	MAT412088A0H14683	88
369	RNM596	KL-15	8902	TATA	ORD		19-Dec-2010	VZM	48	60	LP 1512 TC/59 BSII	01H62921281	MAT412088A0J15479	24
370	RNM631	KL-15	8907	TATA	ORD		13-Dec-2010	MVK	48	60	LP 1512 TC/59 BSII	01H62916342	MAT412088A0H14682	88
371	RNM637	KL-15	8993	TATA	ORD		25-Jan-2011	ATL	48	60	LP 1512 TC/59 BSII	01H62915338	MAT412088A0J14685	33
372	RNA890	KL-15	9318	TATA	ORD		28-Dec-2011	ATL	48	66	LP 1512 TC/59 BSIII	11K63194775	MAT412B2B0N20822	33
373	RAA708	KL-15	7865	TATA	ORD		13-Jul-2009	KLM	48	60	1512 TCIC CUMMINS BSII	62734427	CQZ 002637	34
374	RNM591	KL-15	8857	TATA	ORD		26-Nov-2010	PVR	48	60	LP 1512 TC/59 BSII	01G62908482	MAT412088A0H13950	23
375	RNA645	KL-15	8920	TATA	ORD		17-Dec-2010	CLDY	48	60	LP 1512 TC/59 BSIII	01H62915675	MAT412088AOJ15981	58
376	RNC 66	KL-15	8240	TATA	ORD		3-Apr-2010	KLM	48	60	LP 1512 TC/59 BSIII	01A62830545	MAT412081A0B02619	34
377	RNC787	KL-15	9229	LL	ORD		8-Nov-2011	PNKM	48	60	HINO 6ETI3K BSIII	NBE158145Z	MB1PB EYC3BENG3221	49
378	RNE796	KL-15	9250	LL	ORD		19-Nov-2011	KTP	48	60	HINO 6ETI3K BSIII	GYEZ414192	MB1PB EYC1BENG3282	14
379	RNC843	KL-15	9288	LL	ORD		9-Dec-2011	TDP	48	66	HINO 6ETI3K BSIII	MBE159647Z	MB1PB EYC3BEMG5273	53
380	RNC844	KL-15	9289	LL	ORD		9-Dec-2011	TDP	48	60	HINO 6ETI3K BSIII	BMHZ103123	MB1PB EYC1BEMG5207	53
381	RNE823	KL-15	9290	LL	ORD		9-Dec-2011	TPLM	48	66	HINO 6ETI3K BSIII	BMHZ103119	MB1PB EYC1BEMG5143	94
382	RNE842	KL-15	9325	LL	ORD		30-Dec-2011	MDY	48	66	HINO 6ETI3K BSIII	BMEZ400386	MB1PB EYC0BEMG5277	76
383	RNC876	KL-15	9331	LL	ORD		6-Jan-2012	PVM	48	66	HINO 6ETI3K BSIII	BMEZ400887	MB1PB EYC9BEMG5813	83
384	RNE859	KL-15	9340	LL	ORD		9-Jan-2012	ARK	48	66	HINO 6ETI3K BSIII	BMEZ400721	MB1PB EYC6BEMG5638	06
385	RAC865	KL-15	8017	LL	ORD		31-Oct-2009	KTDA	48	60	6ETI BSII	JXE107066Z	MB1PB EHC39EJA1140	25

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
386	RNC788	KL-15	9236	LL	ORD		14-Nov-2011	ETPA	48	66	HINO 6ET13K BSIII	BNHZ101505	MB1PBEYC5BENG3270	48
387	RNC791	KL-15	9237	LL	ORD		14-Nov-2011	ETPA	48	66	HINO 6ET13K BSIII	NBE158151Z	MB1PBEYC7BENG3223	48
388	RNE812	KL-15	9276	LL	ORD		30-Nov-2011	ETPA	48	66	HINO 6ET13K BSIII	NBE158585Z	MB1PBEYC1BENG3766	48
389	RNE783	KL-15	9238	LL	ORD		14-Nov-2011	KTM	48	66	HINO 6ET13K BSIII	BNHZ101114	MB1PBEYC9BENG3269	47
390	RNC790	KL-15	9240	LL	ORD		15-Nov-2011	VKM	48	66	HINO 6ET13K BSIII	NBE158310Z	MB1PBEYC6BENG3360	51
391	RNC793	KL-15	9241	LL	ORD		15-Nov-2011	KTM	48	66	HINO 6ET13K BSIII	BPHZ101114	MB1PBEYC8BENG3201	47
392	RNC846	KL-15	9283	LL	ORD		6-Dec-2011	PVM	48	66	HINO 6ET13K BSIII	BMHZ403263	MB1PBEYC4BEMG4861	83
393	RNC849	KL-15	9294	LL	ORD		12-Dec-2011	KTM	48	66	HINO 6ET13K BSIII	BMEZ400385	MB1PBEYC1BEMG5272	47
394	RNC929	KL-15	9382	LL	ORD		14-Feb-2012	KTM	48	66	HINO 6ET13K BSIII	BMEZ400896	MB1PBEYC6BEMG5817	47
395	RNC848	KL-15	9293	LL	ORD		12-Dec-2011	PDM	48	66	HINO 6ET13K BSIII	MBE159650Z	MB1PBEYC9BEMG5276	39
396	RNE620	KL-15	8899	LL	ORD		7-Dec-2010	KGD	48	60	ALPSV 4/100 W06ETI BSII	NAE130046Z	MB1PBEHC9AEND5177	84
397	RNE860	KL-15	9364	LL	ORD		2-Feb-2012	NBR	48	66	HINO 6ET13K BSIII	BMEZ400727	MB1PBEYC6BEMG5669	86
398	RNE841	KL-15	9324	LL	ORD		29-Dec-2011	KGD	48	66	HINO 6ET13K BSIII	BMHZ103109	MB1PBEYC8BEMG5205	84
399	RNE891	KL-15	9390	TATA	ORD		16-Feb-2012	MPM	48	60	LP 1512 TC/59 BSIII	BMEZ400833	MAT4126217BEMG5812	71
400	RAE519	KL-15	7699	LL	ORD		8-May-2009	VZM	48	60	ALPSV 4/89 BSII HINO	LXH 573060	LXE 670127	24
401	RNE277	KL-15	8532	LL	ORD		3-Aug-2010	KGD	48	60	ALPSV 4/89 BSII HINO CUMMINS 6BT 5.9	WAE119337Z	MB1PBEHC7AEWC2964	84
402	RNE522	KL-15	8779	LL	ORD		3-Nov-2010	KTDA	48	60	ALPSV 4/89 BSII	NAE129988Z	MB1PBEHC8AEND5087	25
403	RNE106	KL-15	8328	LL	ORD		20-May-2010	TDP	48	60	ALPSV 4/89 EURO BSII VIKING	WAE120110Z	MB1PBEHC4AEWC3991	53
404	RAC703	KL-15	7897	LL	ORD		18-Aug-2009	VLND	48	60	ALPSV 4/89 HINO EURO BSII TIC	KXE 106097Z	KXE 671178	20
405	RAE736	KL-15	7884	LL	ORD		30-Jul-2009	VKBN	48	60	ALPSV 4/89 HINO EURO BSII VIKING	LXH 572527	KXE 671075	29
406	RAE739	KL-15	7907	LL	ORD		26-Aug-2009	TDP	48	60	ALPSV 4/89 HINO EURO BSII VIKING	KXE 106224Z	KXE 671495	53
407	RAE761	KL-15	7908	LL	ORD		26-Aug-2009	TDP	48	60	ALPSV 4/89 HINO EURO BSII VIKING	JXE 107099Z	MB1PBEHC89EJA1263	53
408	RNC127	KL-15	8290	LL	ORD		3-May-2010	VTRA	48	60	ALPSV 4/89 HINO EURO II	WAE 119652Z	MB1PBEHC9AEWC3355	17
409	RAC558	KL-15	7695	LL	ORD		6-May-2009	KMR	48	60	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	LXH 573039	LXE 670040	30
410	RAE693	KL-15	7872	LL	ORD		17-Jul-2009	KMGH	48	60	ALPSV 4/89 HINO EURO VIKING 2F	KXH 574308	KXE 671907	55
411	RAC852	KL-15	8009	LL	ORD		26-Oct-2009	PTA	48	60	ALPSV 4/89 HINO EUROII TI	CXE 108780Z	MB1PBEHC59ECA4983	37
412	RAC742	KL-15	7915	LL	ORD		26-Aug-2009	TDP	48	60	ALPSV 4/89 HINO EUROII TIC	KXH 574383	KXE 671513	53
413	RAC853	KL-15	8010	LL	ORD		27-Oct-2009	TDP	48	60	ALPSV 4/89 HINO EUROII TIC	CXE 108941Z	MB1PBEHC19ECA5435	53
414	RNC124	KL-15	8280	LL	ORD		29-Apr-2010	TDP	48	60	ALPSV 4/89 HINO EUROII TIC	WAH 615979	MB1PBEHC2AEWC3925	53
415	RAE517	KL-15	7697	LL	ORD		8-May-2009	MDY	48	60	ALPSV 4/89 HINO W06ETI BSII	LXH 572345	LXE 670128	76
416	RAE551	KL-15	7712	LL	ORD		15-May-2009	MKD	48	60	ALPSV 4/89 HINO W06ETI BSIW	LXH 573312	LXE 670239	08
417	RAE834	KL-15	8015	LL	ORD		30-Oct-2009	NBR	48	60	ALPSV 4/89 VIKING	JXE 107095Z	MB1PBEHC89EJA1215	86
418	RAC932	KL-15	8115	LL	ORD		3-Dec-2009	TDP	48	60	ALPSV 4/89 VIKING	ZXE 111068Z	MB1PBEHC19EZA9681	53
419	RNE213	KL-15	8497	LL	ORD		19-Jul-2010	MNR	48	60	ALPSV 4/89 VIKING	WAE119742Z	MB1PBEHC7AEWC3435	60
420	RNE619	KL-15	8898	LL	ORD		7-Dec-2010	CLDY	48	60	ALPSV 4/89 VIKING	ZNE103991Z	MB1PBEHC6AEND4732	58
421	RNE886	KL-15	9373	LL	ORD		4-Feb-2012	MPM	48	60	HINO 6ET13K BSIII	BMEZ400831	MB1PBEYC6BEMG5915	71
422	RNE887	KL-15	9377	LL	ORD		6-Feb-2012	MPM	48	60	HINO 6ET13K BSIII	BMEZ400766	MB1PBEYC7BEMG5714	71
423	RAE329	KL-15	7502	LL	ORD		2-Mar-2009	MKD	48	60	ALPSV 4/89HINO W06ETI BSII	XNE 104648Z	XNE 667968	08
424	RNA851	KL-15	9291	LL	ORD		12-Dec-2011	MDY	48	60	HINO 6ET13K BSIII	NBE159558Z	MB1PBEYC9BEMG4760	76
425	RNE857	KL-15	9334	LL	ORD		9-Jan-2012	PLKD	48	60	HINO 6ET13K BSIII	BMHZ103111	MB1PBEYCXBEMG5206	69
426	RAE179	KL-15	7366	LL	ORD		19-Jan-2009	NTA	48	60	BSII	JNE 101450Z	JNE 655894	22
427	RAC556	KL-15	7717	LL	ORD		15-May-2009	NTA	48	60	BSII	LXE 105718Z	LXE 670492	22
428	RAC847	KL-15	8003	LL	ORD		23-Oct-2009	NTA	48	60	BSII	CXE 108775Z	MB1PBEHC99EC44985	22
429	RNE105	KL-15	8296	LL	ORD		5-May-2010	NTA	48	60	BSII	BNE103517Z	MB1PBEHCXAEVC4642	22

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
430	RNC128	KL-15	8297	LL	ORD		5-May-2010	NTA	48	60	BSII	WAE 120024Z	MB1PBEHC7AEWC3838	22
431	RNC792	KL-15	9247	LL	ORD		17-Nov-2011	NTA	48	60	HINO 6ETI3K BSIII	NBE158148Z	MB1PBEYC7BENG3268	22
432	RNE885	KL-15	9369	LL	ORD		2-Feb-2012	TLY	48	60	HINO 6ETI3K BSIII	BMEZ400556	MB1PBEYC4BEMG5735	18
433	RNC828	KL-15	9275	LL	ORD		30-Nov-2011	MVPA	48	60	HINO 6ETI3K BSIII	NBE159542Z	MB1PBEYC8BEMG4765	52
434	RNC826	KL-15	9278	LL	ORD		2-Dec-2011	NTA	48	60	HINO 6ETI3K BSIII	NBE159551Z	MB1PBEYC3BEMG4799	22
435	RNC827	KL-15	9279	LL	ORD	PINK	2-Dec-2011	ATL	48	60	HINO 6ETI3K BSIII	NBE158606Z	MB1PBEYC5BENG3768	33
436	RNC856	KL-15	9303	LL	ORD		16-Dec-2011	TPLM	48	60	HINO 6ETI3K BSIII	BMEZ400582	MB1PBEYC6BEMG5641	94
437	RNM820	KL-15	9297	LL	ORD		13-Dec-2011	SBY	48	60	HINO 6ETI3K BSIII	BNHZ102721	MB1PBEYC6BEMG4764	75
438	RNK836	KL-15	9322	LL	ORD		29-Dec-2011	SBY	48	60	HINO 6ETI3K BSIII	BMHZ103168	MB1PBEYC7BEMG5275	75
439	RAM538	KL-15	7766	TATA	ORD		1-Jun-2009	KLM	48	60	CUMMINS 1512 BSII	62728315	BQZ 001111	34
440	RAA574	KL-15	7743	TATA	ORD		27-May-2009	ANK	48	60	CUMMINS 1512 BSII	90A62728143	412081BQZ001106	57
441	RAA573	KL-15	7742	TATA	ORD		25-Jun-2009	KPM	48	60	CUMMINS 1512 BSII	90A62727795	412081BQZ001067	91
442	RAA571	KL-15	7737	TATA	ORD		20-May-2009	KPM	48	60	CUMMINS 1512 BSII	90A62728457	412081BQZ001064	91
443	RAM531	KL-15	7744	TATA	ORD		27-May-2009	PKDA	48	60	CUMMINS 1512 BSII	90A62726987	412081 BQZ 001060	81
444	RAM533	KL-15	7746	TATA	ORD		27-May-2009	CTLA	48	60	CUMMINS 1512 BSII	90A62728243	MAT412081BQZ001057	46
445	RAM532	KL-15	7745	TATA	ORD		27-May-2009	CTLA	48	60	CUMMINS 1512 BSII	90A62728244	MAT412081BQZ001110	46
446	RAM752	KL-15	7975	TATA	ORD		12-Oct-2009	KLM	48	60	CUMMINS 1512 BSII	62737579	CQZ 003372	34
447	RAM751	KL-15	7980	TATA	ORD		14-Oct-2009	KLM	48	60	CUMMINS 1512 BSII	62737577	CQZ 003373	34
448	RAM753	KL-15	7995	TATA	ORD		20-Oct-2009	ARK	48	60	CUMMINS 1512 BSII	90C62737209	412081 CQZ 003370	06
449	RAM889	KL-15	8131	TATA	ORD		14-Dec-2009	KLM	48	60	CUMMINS 1512 BSII	62725088	MRZ 020008	34
450	RAM617	KL-15	7806	TATA	ORD		22-Jun-2009	EKM	48	60	CUMMINS 1512 BSII LP 1512 TC	90B62734044	412081CQZ002646	56
451	RAM614	KL-15	7782	TATA	ORD		8-Jun-2009	KTM	48	60	CUMMINS 1512 BSII TCIC	90A62727015	412081BQZ001061	47
452	RAM615	KL-15	7804	TATA	ORD		22-Jun-2009	CGNR	48	60	CUMMINS 1512 BSII TCIC	90A62726992	412081BQZ001107	40
453	RAM616	KL-15	7805	TATA	ORD		22-Jun-2009	KTM	48	60	CUMMINS 1512 BSII TCIC	90B62734340	412081CQZ002645	47
454	RAA712	KL-15	7888	TATA	ORD		31-Jul-2009	KTM	48	60	CUMMINS 1512 BSII TCIC	90C62737592	412081CQZ003369	47
455	RNC 94	KL-15	8259	TATA	ORD		19-Apr-2010	KTM	48	60	LP 1512 TC/59 BSII	01A62830433	MAT412081A0B02622	47
456	RNM 71	KL-15	8260	TATA	ORD		21-Apr-2010	KKLM	48	60	LP 1512 TC/59 BSII	01A62829975	MAT412081A0B02623	108
457	RNM 72	KL-15	8261	TATA	ORD		21-Apr-2010	KMGM	48	60	LP 1512 TC/59 BSII	01A62835312	MAT412081A0B02775	55
458	RNA118	KL-15	8311	TATA	ORD		12-May-2010	KTM	48	60	LP 1512 TC/59 BSII	01B62840584	MAT412081A0B03332	47
459	RNC163	KL-15	8337	TATA	ORD		25-May-2010	KTM	48	60	LP 1512 TC/59 BSII	01C62854421	MAT412088A0C06159	47
460	RNA567	KL-15	8829	TATA	ORD		19-Nov-2010	KTM	48	60	LP 1512 TC/59 BSII	01H62915685	MAT412088A0H14493	47
461	RNM590	KL-15	8846	TATA	ORD		23-Nov-2010	KTM	48	60	LP 1512 TC/59 BSII	01G62908446	MAT412088A0H13949	47
462	RNA616	KL-15	8878	TATA	ORD		1-Dec-2010	KTDA	48	60	LP 1512 TC/59 BSII	01H62922452	MAT412088A0J15468	25
463	RNA617	KL-15	8879	TATA	ORD		1-Dec-2010	ALP	48	60	LP 1512 TC/59 BSII	01J62923525	MAT412088A0J15575	45
464	RNM702	KL-15	9071	TATA	ORD		14-Mar-2011	KKLM	48	60	LP 1512 TC/59 BSII	01H62922469	MAT412088A0J15470	108
465	RNM744	KL-15	9079	TATA	ORD		16-Mar-2011	KTM	48	60	LP 1512 TC/59 BSII	01H62922472	MAT412088A0J15472	47
466	RNA648	KL-15	8940	TATA	ORD		29-Dec-2010	TPLM	48	60	LP 1512 TC/59 BSIII	01H62922902	MAT41208A0J15482	94
467	RNA649	KL-15	8941	TATA	ORD		29-Dec-2010	TPLM	48	60	LP 1512 TC/59 BSIII	01H62921044	MAT41208A0J15483	94
468	RNA650	KL-15	8944	TATA	ORD		31-Dec-2010	VKBN	48	60	LP 1512 TC/59 BSII TURBO INTER COOLER	01C62855143	MAT412088A0D08746	29
469	RNA456	KL-15	8730	TATA	ORD		12-Oct-2010	HPD	48	60	LP 1512 TC/59 BSII	01G62906807	MAT412088A0G13538	42
470	RNC 96	KL-15	8268	TATA	ORD		23-Apr-2010	KTR	48	60	LP1512TC/59BSII	01B62839371	MAT412081A0B03384	35
471	RNM 33	KL-15	8270	TATA	ORD		24-Apr-2010	KTR	48	60	LP 1512 TC/59 BSII	90L62808141	MAT41208590P23184	35
472	RNC101	KL-15	8277	TATA	ORD		26-Apr-2010	KTR	48	60	LP1512TC/59BSII	01B62841280	MAT412081A0B03386	35
473	RNC119	KL-15	8278	TATA	ORD		24-Apr-2010	KTR	48	60	LP1512TC/59BSII	01B62843877	MAT412081A0B03638	35
474	RNC 98	KL-15	8272	TATA	ORD		24-Apr-2010	TVL	48	60	LP 1512 TC/59 BSIII	01A62831510	MAT412081A0B03009	43

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
475	RNC122	KL-15	8289	TATA	ORD		3-May-2010	VZM	48	60	LP 1512 TC/59 BSII	01B62841373	MAT412081A0B03388	24
476	RNC158	KL-15	8324	TATA	ORD		19-May-2010	VLND	48	60	LP 1512 TC/59 BSIII	01C62854427	MAT412088A0C06158	20
477	RNA492	KL-15	8732	TATA	ORD		15-Oct-2010	CTY	48	60	LP 1512 TC/59 BSIII	01C62856911	MAT412088A0H13953	28
478	RNA498	KL-15	8785	TATA	ORD		3-Nov-2010	CLDY	48	60	LP 1512 TC/59 BSIII	01G62915675	MAT412088A0H14496	58
479	RNA570	KL-15	8855	TATA	ORD		26-Nov-2010	VZM	48	60	LP 1512 TC/59 BSII	01H62922821	MAT412088A0J15615	24
480	RNA618	KL-15	8908	TATA	ORD		13-Dec-2010	VZM	48	60	LP 1512 TC/59 BSII	62883265	MAT412088A0J15617	24
481	RNA646	KL-15	8924	TATA	ORD		18-Dec-2010	ALP	48	60	LP 1512 TC/59 BSIII	01G62908006	MAT41208A0J15478	45
482	RNC931	KL-15	9371	TATA	ORD		4-Feb-2012	VZM	48	66	LP 1512 TC/59 BSIII	11L84028910	MAT412021B0N21530	24
483	RAA569	KL-15	7722	TATA	ORD		15-May-2009	ADR	48	60	CUMMINS 1512 TCIC BSII	80M62726335	AQZ 000176	38
484	RAA717	KL-15	7993	TATA	ORD		16-Oct-2009	KLM	48	60	CUMMINS 1512 TCIC BSII	62736339	CQZ 003368	34
485	RAA826	KL-15	8007	TATA	ORD		26-Oct-2009	KLM	48	60	CUMMINS 1512 TCIC BSII	62757081	90F 08848	34
486	RAA827	KL-15	8021	TATA	ORD		2-Nov-2009	KLM	48	60	CUMMINS 1512 TCIC BSII	62734392	CQZ 002636	34
487	RAA958	KL-15	8134	TATA	ORD		17-Dec-2009	KLM	48	60	CUMMINS 1512 TCIC BSII	62768500	90G 11182	34
488	RNC121	KL-15	8288	TATA	ORD		3-May-2010	ADR	48	60	LP 1512 TC/59 BSII	01B62840811	MAT412081A0B03389	38
489	RNM520	KL-15	8844	TATA	ORD		23-Nov-2010	ATL	48	60	LP 1512 TC/59 BSII	01G62908476	MAT412088A0H13947	33
490	RNM521	KL-15	8845	TATA	ORD		23-Nov-2010	ATL	48	60	LP 1512 TC/59 BSII	01G62907386	MAT412088A0G13677	33
491	RNC161	KL-15	8335	TATA	ORD		24-May-2010	CGNR	48	60	LP 1512 TC/59 BSII	01C62857058	MAT412088A0C06838	40
492	RNC912	KL-15	9370	TATA	ORD		4-Feb-2012	ATL	48	60	LP 1512 TC/59 BSIII	11K84026262	MAT412021B0N21332	33
493	RNC883	KL-15	9347	TATA	ORD		16-Jan-2012	MALA	48	66	LP 1512 TC/59 BSIII	11L84028082	MAT412021B0N21381	85
494	RNC881	KL-15	9350	TATA	ORD		17-Jan-2012	MALA	48	66	LP 1512 TC/59 BSIII	11K84026266	MAT412021B0N21333	85
495	RNM900	KL-15	9332	TATA	ORD		6-Jan-2012	HPD	48	66	LP 1512 TC/59 BSIII	11K84025372	MAT412021B0N20825	42
496	RNC882	KL-15	9339	TATA	ORD		1-Jan-2012	HPD	48	66	LP 1512 TC/59 BSIII	11L84030467	MAT412021B0N21337	42
497	RNC169	KL-15	8338	TATA	ORD		25-May-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62855953	MAT412081A0B06576	56
498	RNC878	KL-15	9323	TATA	ORD		31-Dec-2011	HPD	48	66	LP 1512 TC/59 BSIII	11K63194774	MAT412021B0N21329	42
499	RNC913	KL-15	9359	TATA	ORD		31-Jan-2012	KNR	48	66	LP 1512 TC/59 BSIII	11K84024976	MAT412021B0N21334	77
500	RNC932	KL-15	9361	TATA	ORD		1-Feb-2012	KNR	48	66	LP 1512 TC/59 BSIII	11L84028092	MAT412021B0N21616	77
501	RNA935	KL-15	9362	TATA	ORD		1-Feb-2012	KNR	48	66	LP 1512 TC/59 BSIII	11K84028849	MAT412021B0N21452	77
502	RNA948	KL-15	9378	TATA	ORD		8-Feb-2012	KNR	48	66	LP 1512 TC/59 BSIII	11K84026261	MAT412021B0N21453	77
503	RNM904	KL-15	9363	TATA	ORD		31-Jan-2012	VKBN	48	66	LP 1512 TC/59 BSIII	11L63204990	MAT412021B0N21614	29
504	RAA639	KL-15	7807	TATA	ORD		22-Jun-2009	EMLY	48	60	CUMMINS BSII	90B62729823	BQZ 001247	95
505	RAM621	KL-15	7846	TATA	ORD		2-Jul-2009	ALP	48	60	CUMMINS BSII	90C62737578	412081CQZ003381	45
506	RAM759	KL-15	8056	TATA	ORD		11-Nov-2009	ALP	48	60	CUMMINS BSII	80L62721990	412081LRZ019514	45
507	RAM758	KL-15	8086	TATA	ORD		19-Nov-2009	ALP	48	60	CUMMINS BSII	80L62721986	412081LRZ019515	45
508	RAA908	KL-15	8095	TATA	ORD		25-Nov-2009	ALP	48	60	CUMMINS BSII	90E62757820	MAT41208190F08853	45
509	RAM888	KL-15	8130	TATA	ORD		14-Dec-2009	ALP	48	60	CUMMINS BSII	80L62721309	412081MRZ019750	45
510	RNC160	KL-15	8334	TATA	ORD		24-May-2010	KYLM	48	60	LP 1512 TC/59 BSII	01C62856398	MAT412088A0C06906	41
511	RNC933	KL-15	9374	TATA	ORD		7-Feb-2012	PBVR	48	66	LP 1512 TC/59 BSIII	11L84030459	MAT412021B0N22055	59
512	RAA566	KL-15	7707	TATA	ORD		8-May-2009	CTNR	48	60	CUMMINS BSII 1512	M 62725127	MRZ 020046	97
513	RNC247	KL-15	8515	TATA	ORD		27-Jul-2010	ALP	48	60	LP 1512 TC/59 BSIII	01C62853521	MAT412088A0C06257	45
514	RNC246	KL-15	8517	TATA	ORD		28-Jul-2010	ALP	48	60	LP 1512 TC/59 BSIII	01C62853518	MAT412088A0C06753	45
515	RNE332	KL-15	8549	LL	ORD		10-Aug-2010	PDM	48	60	EURO BSII	WAE120013Z	MB1PBEHC6AEW3930	39
516	RNE459	KL-15	8681	LL	ORD	VND	1-Oct-2010	KTDA	48	60	EURO BSII	NAE130331Z	MB1PBEHCXAEND5432	25
517	RNE481	KL-15	8729	LL	ORD		12-Oct-2010	ETPA	48	60	EURO BSII	WAE120107Z	MB1PBEHCXAEW3994	48
518	RNE458	KL-15	8746	LL	ORD		21-Oct-2010	MALA	48	60	EURO BSII	NAE130544Z	MB1PBEHC4AEND5670	85
519	RNE513	KL-15	8762	LL	ORD		1-Nov-2010	VJMD	48	60	EURO BSII	NAE129927Z	MB1PBEHC9AEND4997	16

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
520	RNE572	KL-15	8827	LL	ORD		19-Nov-2010	PALA	48	60	EURO BSII	MAE131289Z	MB1PBEHC1AEMD6451	50
521	RNE209	KL-15	8431	LL	ORD		3-Jul-2010	KTDA	48	60	EURO BSII ALPSV 4/89 VIKING	WAE120127Z	MB1PBEHE6AEWC4026	25
522	RNE335	KL-15	8566	LL	ORD		16-Feb-2010	KTDA	48	60	EURO BSII ALPSV 4/89 VIKING	VAE121548Z	MB1PBEHC3AEVC5941	25
523	RNK786	KL-15	9242	LL	ORD		15-Nov-2011	KPA	48	66	HINO 6ETI3K BSIII	NBE158142Z	MB1PBEYCXBENG3281	74
524	RNK808	KL-15	9265	LL	ORD		25-Nov-2011	KPA	48	66	HINO 6ETI3K BSIII	BPHZ100845	MB1PBEYC7BENG3285	74
525	RAE271	KL-15	7416	LL	ORD	VND	2-Feb-2009	RNI	48	60	HINO BSII	ZNE 104283Z	YNE 667282	101
526	RAC561	KL-15	7719	LL	ORD		15-May-2009	MDY	48	60	HINO BSII	LXH 572925	LXE 670272	76
527	RAE518	KL-15	7698	LL	ORD		8-May-2009	MDY	48	60	HINO BSII	NXE 105180Z	NXE 669318	76
528	RAE555	KL-15	7734	LL	ORD		20-May-2009	KTR	48	60	HINO BSII	NXH 571845	NXE 669329	35
529	RAE599	KL-15	7777	LL	ORD		3-Jun-2009	PTA	48	60	HINO BSII	XPH 474880	NXE 669275	37
530	RAE654	KL-15	7818	LL	ORD		23-Jun-2009	VLND	48	60	HINO BSII	LXH 573759	LXE 670599	20
531	RAE656	KL-15	7787	LL	ORD		18-Jun-2009	KTR	48	60	HINO BSII	LXE 105729Z	LXE 670496	35
532	RAE691	KL-15	7867	LL	ORD		14-Jul-2009	PALA	48	60	HINO BSII	NXE 105300Z	NXE 669319	50
533	RAE692	KL-15	7868	LL	ORD		14-Jul-2009	VTRA	48	60	HINO BSII	LXH 572509	LXE 670597	17
534	RAE687	KL-15	7876	LL	ORD		22-Jul-2009	PTA	48	60	HINO BSII	LXH 573073	LXE 670267	37
535	RAC706	KL-15	7902	LL	ORD		20-Aug-2009	PTPM	48	60	HINO BSII	LXE 105837Z	LXE 670558	15
536	RAC705	KL-15	7901	LL	ORD		20-Aug-2009	PALA	48	60	HINO BSII	KXH 574581	KXE 672074	50
537	RAC719	KL-15	7903	LL	ORD		21-Aug-2009	PALA	48	60	HINO BSII	KXH 574010	KXE 671494	50
538	RAC720	KL-15	7905	LL	ORD		22-Aug-2009	PALA	48	60	HINO BSII	LXH 572836	KXE 670793	50
539	RAE762	KL-15	7909	LL	ORD		26-Aug-2009	PTA	48	60	HINO BSII	JNH 541677	MB1PBEHC49EJA1051	37
540	RAE790	KL-15	7945	LL	ORD		18-Sep-2009	PTA	48	60	HINO BSII	CXE 108761Z	MB1PBEHC69ECA4992	37
541	RAC784	KL-15	7947	LL	ORD		19-Sep-2009	PTA	48	60	HINO BSII	ZNE 104196Z	MB1PBEHCX9EJA0146	37
542	RAC809	KL-15	7963	LL	ORD		3-Oct-2009	VJMD	48	60	HINO BSII EURO	JXE 107065Z	MB1PBEHC79EJA1139	16
543	RAC807	KL-15	7972	LL	ORD		12-Oct-2009	KTR	48	60	HINO BSII	JXH 576221	MB1PBEHC79EJA0556	35
544	RAC812	KL-15	7973	LL	ORD		12-Oct-2009	RNI	48	60	HINO BSII	CXH 581828	MB1PBEHC69ECA5026	101
545	RAE819	KL-15	7991	LL	ORD		16-Oct-2009	RNI	48	60	HINO BSII	CXE 108956Z	MB1PBEHCX9ECA5515	101
546	RAE795	KL-15	7962	LL	ORD		3-Oct-2009	PALA	48	60	HINO BSII	CXE 108907Z	ECA 5437	50
547	RAC863	KL-15	8013	LL	ORD		29-Oct-2009	PTA	48	60	HINO BSII	DXE 108464Z	MB1PBEHC69HCA5740	37
548	RAE836	KL-15	8090	LL	ORD		20-Nov-2009	PTA	48	60	HINO BSII	JXE 107096Z	MB1PBEHC69EJA1214	37
549	RAK894	KL-15	8091	LL	ORD		20-Nov-2009	PTA	48	60	HINO BSII	CXH 583003	MB1PBEHC29ECA5704	37
550	RAE884	KL-15	8105	LL	ORD		1-Dec-2009	KTR	48	60	HINO BSII	BXE 11012AZ	MB1PBEHC09EBA8047	35
551	RAK844	KL-15	8065	LL	ORD		13-Nov-2009	KTM	48	60	HINO BSII	CXH 583009Z	MB1PBEHC69ECA5723	47
552	RAK897	KL-15	8101	LL	ORD		26-Nov-2009	KNPY	48	60	HINO BSII	BXE 109550Z	MB1PBEHC69EBA6979	87
553	RAC936	KL-15	8145	LL	ORD		30-Dec-2009	KTR	48	60	HINO BSII	ZXE 111560Z	MB1PBEHC59EVB0512	35
554	RAC948	KL-15	8147	LL	ORD		30-Dec-2009	PALA	48	60	HINO BSII	ZXE 111372Z	EZB 0175	50
555	RAC953	KL-15	8152	LL	ORD		1-Jan-2010	PALA	48	60	HINO BSII	ZXE 111449Z	EZB 0324	50
556	RNC 29	KL-15	8215	LL	ORD		19-Feb-2010	KPZA	48	60	HINO BSII	WXE 114805Z	EWB 5619	07
557	RNC 23	KL-15	8216	LL	ORD		20-Feb-2010	PALA	48	60	HINO BSII	WXE 114633Z	EWB 5515	50
558	RNC 28	KL-15	8217	LL	ORD		20-Feb-2010	PALA	48	60	HINO BSII	WXE 114555Z	EWB 5537	50
559	RNK 63	KL-15	8247	LL	ORD		12-Apr-2010	MPLY	48	60	HINO BSII	WXE114531Z	MB1PBHEC69EWB5516	96
560	RNK 64	KL-15	8248	LL	ORD		12-Apr-2010	CGNR	48	60	HINO BSII	WXE114769Z	MB1PBHEC99EWB5560	40
561	RNK 65	KL-15	8249	LL	ORD		12-Apr-2010	CGNR	48	60	HINO BSII	WXE114690Z	MB1PBHEC29EWB5514	40
562	RNE102	KL-15	8285	LL	ORD		3-May-2010	PALA	48	60	HINO BSII	WAE120039Z	MB1PBEHC9AEWC3887	50
563	RNE205	KL-15	8395	LL	ORD		16-Jun-2010	PALA	48	60	HINO BSII	VAE121354Z	MB1PBEHXA9EVC5631	50
564	RNE206	KL-15	8398	LL	ORD		18-Jun-2010	PALA	48	60	HINO BSII	WAE119842Z	MB1PBEHE9AEWC3601	50

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
565	RNE368	KL-15	8580	LL	ORD		20-Aug-2010	MDY	48	60	HINO BSII	WAH614241	MB1PBEHC1AEWC4029	76
566	RNE369	KL-15	8581	LL	ORD		20-Aug-2010	PTA	48	60	HINO BSII	WAE120198Z	MB1PBEHC6AEWC4088	37
567	RNK410	KL-15	8673	LL	ORD		29-Sep-2010	ETPA	48	60	HINO BSII	WAE120630Z	MB1PBEHC9AEVC4633	48
568	RNK414	KL-15	8694	LL	ORD		6-Oct-2010	KTR	48	60	HINO BSII	VAE120764Z	MB1PBEHC1AEVC4805	35
569	RNK415	KL-15	8695	LL	ORD		21-Oct-2010	KMR	48	60	HINO BSII	WAE120650Z	MB1PBEHC8AEVC4641	30
570	RNK416	KL-15	8696	LL	ORD		21-Oct-2010	KMR	48	60	HINO BSII	VAE121955Z	MB1PBEHC2AEVC6479	30
571	RNK450	KL-15	8751	LL	ORD		26-Oct-2010	KTR	48	60	HINO BSII	NAE129738Z	MB1PBEHC9AEND4840	35
572	RNK482	KL-15	8752	LL	ORD		26-Oct-2010	PTA	48	60	HINO BSII	NAE129666Z	MB1PBEHCXAEND4765	37
573	RNK483	KL-15	8766	LL	ORD		2-Nov-2010	ETPA	48	60	HINO BSII	NAE130031Z	MB1PBEHC3AEND5238	48
574	RNK487	KL-15	8814	LL	ORD		23-Nov-2010	KMR	48	60	HINO BSII	MAE132177Z	MB1PBEHC1AEMD7308	30
575	RNK489	KL-15	8816	LL	ORD		16-Nov-2010	KTR	48	60	HINO BSII	MAE132329Z	MB1PBEHC2AEMD7429	35
576	RNK554	KL-15	8877	LL	ORD		1-Dec-2010	CTR	48	60	HINO BSII	MAE132354Z	MB1PBEHC9AEMD7492	70
577	RNE600	KL-15	8885	LL	ORD		2-Dec-2010	KTR	48	60	HINO BSII	NAE129665Z	MB1PBEHC8AEND4764	35
578	RNE601	KL-15	8890	LL	ORD		4-Dec-2010	KTR	48	60	HINO BSII	NAE129655Z	MB1PBEHC4AEND4731	35
579	RNE602	KL-15	8891	LL	ORD		4-Dec-2010	KTR	48	60	HINO BSII	NAE129941Z	MB1PBEHCXAEND5012	35
580	RNK835	KL-15	9300	LL	ORD		15-Dec-2011	KMY	48	66	HINO 6ETI3K BSIII	NBE159541Z	MB1PBEYC0BEMG4761	05
581	RNE824	KL-15	9301	LL	ORD		17-Dec-2011	PBVR	48	66	HINO 6ETI3K BSIII	BMEZ400094	MB1PBEYCXBEMG5139	59
582	RNK839	KL-15	9342	LL	ORD		13-Jan-2012	KMR	48	66	HINO 6ETI3K BSIII	NBE 159634Z	MB1PBEYCBENG3780	30
583	RAE274	KL-15	7434	LL	ORD		9-Feb-2009	VLRD	48	60	HINO BSII 6ETI	YNE 104620Z	XNE 667933	93
584	RAC783	KL-15	7946	LL	ORD		18-Sep-2009	VLRD	48	60	HINO BSII 6ETI	KXE 106720Z	MB1PBEHC09EJA0110	93
585	RNC815	KL-15	9267	LL	ORD		26-Nov-2011	MDY	48	66	HINO 6ETI3K BSIII	NBE158616Z	MB1PBEYC0BENG3693	76
586	RAC814	KL-15	7974	LL	ORD		12-Oct-2009	KTDA	48	60	HINO BSII ALPSV 41/89	MNH 519956 LLBS11	MB1PBEHC79ECA4984	25
587	RAC704	KL-15	7898	LL	ORD		18-Aug-2009	KTDA	48	60	HINO BSII ALPSV 4189	KXH 574569	KXE 671913	25
588	RAC722	KL-15	7918	LL	ORD		9-Sep-2009	CDLM	48	60	HINO BSII TCIC	JNH 543731	JNE 656174	80
589	RAC811	KL-15	7968	LL	ORD		6-Oct-2009	CDLM	48	60	HINO BSII TCIC	JXE 107101	MB1PBEHC79EJA1223	80
590	RAC823	KL-15	7994	LL	ORD		19-Oct-2009	CDLM	48	60	HINO BSII TCIC	CXH 581825	MB1PBEHC09ECA5023	80
591	RAC862	KL-15	8012	LL	ORD		28-Oct-2009	CDLM	48	60	HINO BSII TCIC	LXE 108953Z	MB1PBEHC89ECA5514	80
592	RNE527	KL-15	8819	LL	ORD		18-Nov-2010	CDLM	48	60	HINO BSII TCIC	NAE130122Z	MB1PBEHC1AEND5237	80
593	RNA 70	KL-15	8235	LL	ORD		27-Mar-2010	TVL	48	60	HINO BSII TCIC VIKING	WXE 114635Z	MB1PBEHC19EWB5620	43
594	RNC383	KL-15	8589	LL	ORD		26-Aug-2010	KTM	48	60	HINO BSIII	PAH636760	MB1PBEJC3AEPD3117	47
595	RNC360	KL-15	8598	LL	ORD		1-Sep-2010	KNPY	48	60	HINO BSIII	PAH636761	MB1PBEJC9AEPB3056	87
596	RNC799	KL-15	9252	LL	ORD		21-Nov-2011	CGNR	48	66	HINO 6ETI3K BSIII	BNHZ101716	MB1PBEYC1BENG3847	40
597	RNC800	KL-15	9253	LL	ORD		21-Nov-2011	CGNR	48	66	HINO 6ETI3K BSIII	BNHZ101504	MB1PBEYC3BENG3204	40
598	RNK809	KL-15	9255	LL	ORD		23-Nov-2011	PALA	48	66	HINO 6ETI3K BSIII	NBE158152Z	MBIPBEYC9BENG3224	50
599	RNC802	KL-15	9258	LL	ORD		23-Nov-2011	PLD	48	66	HINO 6ETI3K BSIII	BPHZ101139	MB1PBEYC3BENG3932	32
600	RNC803	KL-15	9259	LL	ORD		24-Nov-2011	EKM	48	66	HINO 6ETI3K BSIII	BNHZ101916	MB1PBEYCXBENG3846	56
601	RNE805	KL-15	9264	LL	ORD		25-Nov-2011	EKM	48	66	HINO 6ETI3K BSIII	BPHZ101113	MB1PBEYC5BENG3219	56
602	RNC814	KL-15	9266	LL	ORD		26-Nov-2011	PALA	48	66	HINO 6ETI3K BSIII	NBE158724Z	MB1PBEYC0BENG3872	50
603	RNK834	KL-15	9298	LL	ORD		14-Dec-2011	KTR	48	66	HINO 6ETI3K BSIII	MBE159653Z	MB1PBEYC8BEMG4801	35
604	RNC854	KL-15	9299	LL	ORD		14-Dec-2011	KTR	48	66	HINO 6ETI3K BSIII	BMEZ400374	MB1PBEYC1BEMG5224	35
605	RNC873	KL-15	9310	LL	ORD		21-Dec-2011	CGNR	48	66	HINO 6ETI3K BSIII	BMEZ400510	MB1PCEYC7BEMG5504	40
606	RNM821	KL-15	9320	LL	ORD		30-Dec-2011	KTR	48	66	HINO 6ETI3K BSIII	BNHZ101626	MB1PBEYC2BENG3856	35
607	RNE863	KL-15	9367	LL	ORD		2-Feb-2012	ARND	48	66	HINO 6ETI3K BSIII	BMEZ400718	MB1PBEYC1BEMG5711	19
608	RNK785	KL-15	9233	LL	ORD		10-Nov-2011	CDLM	48	66	HINO 6ETI3K BSIII	NBE158141Z	MB1PBEYCXBENG3202	80
609	RNC789	KL-15	9234	LL	ORD		11-Nov-2011	CDLM	48	66	HINO 6ETI3K BSIII	NBE158158Z	MB1PBEYC5BENG3864	80

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
610	RNE795	KL-15	9246	LL	ORD		17-Nov-2011	TPLM	48	66	HINO 6ET13K BSIII	NBE158159Z	MB1PBEYC3BENG3283	94
611	RAK786	KL-15	7966	LL	ORD		5-Oct-2009	IJK	48	60	HINO EURO BS11	JXE 107016Z	MB1PBEHC29EJA1050	89
612	RAE683	KL-15	7819	LL	ORD		23-Jun-2009	TVL	48	60	HINO EURO 222 NB VIKING BSII	LXH 572160	LXE 670051	43
613	RAE184	KL-15	7379	LL	ORD		20-Jan-2009	KTDA	48	60	HINO EURO BSII	JNH 543302	ZNE 666218	25
614	RAC530	KL-15	7674	LL	ORD		30-Apr-2009	NDM	48	60	HINO EURO BSII	LXH 572186	LXE 670086	110
615	RAE595	KL-15	7755	LL	ORD		27-May-2009	TLY	48	60	HINO EURO BSII	LXH 572400	LXE 670153	18
616	RAE658	KL-15	7833	LL	ORD		27-Jun-2009	MVPA	48	60	HINO EURO BSII	KXH 574038	KXE 672041	52
617	RAE688	KL-15	7839	LL	ORD		29-Jun-2009	ARND	48	60	HINO EURO BSII	CNH 565269	LXE 670593	19
618	RAE774	KL-15	7916	LL	ORD		31-Aug-2009	CGNR	48	60	HINO EURO BSII	JXE 107020Z	MB1PBEHC19EJA1010	40
619	RAE763	KL-15	7910	LL	ORD		26-Aug-2009	KPM	48	60	HINO EURO BSII	KXH 575721	MB1PBEHC49EJA0126	91
620	RAC779	KL-15	7934	LL	ORD		15-Sep-2009	EDT	48	60	HINO EURO BSII		MB1PBEHC59EJA0149	98
621	RAC780	KL-15	7937	LL	CFP		16-Sep-2009	PPD	53	66	HINO EURO BSII	BVH 237291	MB1PBEHC89EJA0128	26
622	RAK734	KL-15	7941	LL	ORD		18-Sep-2009	CTLA	48	60	HINO EURO BSII	LXH 573484	KXE671076	46
623	RAK735	KL-15	7942	LL	ORD		18-Aug-2009	PVM	48	60	HINO EURO BSII	KXH 574476	KXE 672003	83
624	RAE776	KL-15	7943	LL	ORD		18-Sep-2009	PLR	48	60	HINO EURO BSII	LXH 572703	LXE 667117	36
625	RAC797	KL-15	7949	LL	ORD		23-Sep-2009	CGNR	48	60	HINO EURO BSII	JXE 107017Z	MB1PBEHC09EJA0995	40
626	RAC800	KL-15	7957	LL	ORD		26-Sep-2009	MVPA	48	60	HINO EURO BSII	VHX 102216	MB1PBEHC09EJA0351	52
627	RAC822	KL-15	7998	LL	ORD		20-Oct-2009	ADR	48	60	HINO BSII	CXE 108846Z	MB1PBEHC59ECA5213	38
628	RAE818	KL-15	7978	LL	ORD		12-Oct-2009	PVM	48	60	HINO EURO BSII	CXE 108786Z	MB1PBEHCX9ECA5255	83
629	RAC824	KL-15	7999	LL	ORD		21-Oct-2009	ADR	48	60	HINO BSII	CXH 581820	59ECA 5020	38
630	RAC864	KL-15	8016	LL	ORD		31-Oct-2009	CGNR	48	60	HINO EURO BSII	CXE 108759Z	MB1PBEHC39ECA4982	40
631	RAK896	KL-15	8099	LL	ORD		25-Nov-2009	CTNR	48	60	HINO EURO BSII	BXE 109479Z	MB1PBEHC19EBA6968	97
632	RAE882	KL-15	8096	LL	ORD		25-Nov-2009	VTRA	48	60	HINO EURO BSII	BXE 109988Z	MB1PBEHC19EBA7859	17
633	RNE103	KL-15	8286	LL	ORD		3-May-2010	CTNR	48	60	HINO EURO BSII	WAE120028Z	MB1PBEHC5AEWC3837	97
634	RNE208	KL-15	8410	LL	ORD		25-Jun-2010	KTP	48	60	HINO EURO BSII TURBO INTERCOOLER	EF10707	MB1PBEHC3AEWC3979	14
635	RNE212	KL-15	8485	LL	ORD		15-Jul-2010	PVM	48	60	HINO EURO BSII	WAE120112Z	MB1PBEHE1AEWC3978	83
636	RNE214	KL-15	8512	LL	ORD		26-Jul-2010	KMY	48	60	HINO EURO BSII	WAE119345Z	MB1PBEHE7EWC2978	05
637	RNE331	KL-15	8560	LL	ORD		13-Aug-2010	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	VHG 1653	MB1PBEHC2AEWC4024	14
638	RNE514	KL-15	8761	LL	ORD		1-Nov-2010	NDD	48	60	HINO EURO BSII	NAE130297Z	MB1PBEHC9AEND5423	31
639	RNE523	KL-15	8780	LL	ORD		3-Nov-2010	TSR	48	60	HINO EURO BSII	MAE131103Z	MB1PBEHC0AEMD6179	63
640	RNE525	KL-15	8792	LL	ORD		9-Nov-2010	PKDA	48	60	HINO EURO BSII	NAE130547Z	MB1PBEHC8AEND5672	81
641	RNK485	KL-15	8801	LL	ORD		10-Nov-2010	TSR	48	60	HINO EURO BSII	MAE132278Z	MB1PBEHC4AEMD7416	63
642	RNE526	KL-15	8808	LL	ORD		15-Nov-2010	PKDA	48	60	HINO EURO BSII	MAE131216Z	MB1PBEHC2AEMD6362	81
643	RNK488	KL-15	8815	LL	ORD		16-Nov-2010	CTY	48	60	HINO EURO BSII	WAE120017Z	MB1PBEHC3AEMD7424	28
644	RNK551	KL-15	8851	LL	ORD		24-Nov-2010	ADR	48	60	HINO BSII	MAE132176Z	MB1PBEHC1AEMD7311	38
645	RNK552	KL-15	8875	LL	ORD		1-Dec-2010	NTA	48	60	HINO EURO BSII	MAE132285Z	MB1PBEHC6AEMD7420	22
646	RNK555	KL-15	8884	LL	ORD		2-Dec-2010	MDY	48	60	HINO EURO BSII	NAE130090Z	MB1PBEHCXAEND5186	76
647	RNE622	KL-15	8922	LL	ORD		18-Dec-2010	TSR	48	60	HINO EURO BSII	NAE129975Z	MB1PBEHC6AEND5086	63
648	RNK491	KL-15	8850	LL	ORD		24-Nov-2010	PNI	48	60	HINO EURO BSII TCIC	MAE132348Z	MB1PBEHC7AEMD7491	67
649	RAE694	KL-15	7879	LL	ORD		23-Jul-2009	MVPA	48	60	HINO EURO BSII TURBO INTER COOLER	VAE 121874Z	LXE670039	52
650	RAE738	KL-15	7887	LL	ORD		31-Jul-2009	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	LXH 573510	KXE 671175	14
651	RAE765	KL-15	7912	LL	ORD		26-Aug-2009	MVPA	48	60	HINO EURO BSII TURBO INTER COOLER	JXH 576225	MB1PBEHC19EJA0553	52
652	RAC820	KL-15	7997	LL	ORD		20-Oct-2009	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	WXE 113984Z	MB1PBEHCX9ECA4994	14
653	RAC851	KL-15	8008	LL	ORD		26-Oct-2009	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	CXE 108843Z	MB1PBEHC49ECA 5168	14
654	RNE404	KL-15	8619	LL	ORD		9-Sep-2010	KPZA	48	60	HINO EURO BSII TURBO INTER COOLER	VAE121441Z	MB1PBEHC8AEVC5756	07

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
655	RNE423	KL-15	8645	LL	ORD		16-Sep-2010	KPZA	48	60	HINO EURO BSII TURBO INTER COOLER	VAE121704Z	MB1PBEHCXAEVC6133	07
656	RAE330	KL-15	7503	LL	ORD		2-Mar-2009	CDLM	48	60	HINO EURO BSII TURBO INTERCOLLER	XNE 104647	XNE 667962	80
657	RAC225	KL-15	7388	LL	ORD		21-Jan-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER		ZNE 666566	07
658	RAE775	KL-15	7935	LL	ORD		16-Sep-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER			07
659	RAC806	KL-15	7971	LL	ORD		8-Oct-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER			07
660	RNC126	KL-15	8282	LL	ORD		30-Apr-2010	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER	WAE 120022Z	MB1PBEHC3AEWC3836	07
661	RAE737	KL-15	7885	LL	ORD		30-Jul-2009	TVL	48	60	HINO EURO BSII VIKING	KXE 106229Z	KXE 671479	43
662	RAK731	KL-15	7914	LL	ORD		26-Aug-2009	TVL	48	60	HINO EURO BSII VIKING	KXH 573899	KXE 671071	43
663	RNE460	KL-15	8698	LL	ORD		6-Oct-2010	TSY	48	60	HINO EURO BSII VIKING	NAE129990Z	MB1PBEHC5AEND5094	73
664	RNK784	KL-15	9228	LL	ORD		8-Nov-2011	ADR	48	66	HINO 6ET13K BSIII	NBE158316Z	MB1PBEYCXBENG3359	38
665	RNC830	KL-15	9281	LL	ORD		6-Dec-2011	TSY	48	66	HINO 6ET13K BSIII	MBE159643Z	MB1PBEYC1BEMG5045	73
666	RNC831	KL-15	9282	LL	ORD		6-Dec-2011	TSY	48	66	HINO 6ET13K BSIII	BMEZ400372	MB1PBEYC5BEMG5226	73
667	RNE889	KL-15	9380	LL	ORD		9-Feb-2012	KTP	48	66	HINO 6ET13K BSIII TURBO INTER COOLER	BMEZ401404	MB1PBEYC2BECG6458	14
668	RAC230	KL-15	7399	LL	ORD	VND	27-Jan-2009	VTRA	48	60	HINO EURO II	ZNH 567934	ZNE 666673	17
669	RAC231	KL-15	7400	LL	ORD		27-Jan-2009	VTRA	48	60	HINO EURO II	BNE 103686Z	BNE 665489	17
670	RAK787	KL-15	7977	LL	ORD		12-Oct-2009	CGNR	48	60	HINO EURO II	JXE 107019Z	MB1PBEHC29EJA0996	40
671	RAC928	KL-15	8110	LL	ORD		2-Dec-2009	VTRA	48	60	HINO EURO II	ZXE 111458Z	MB1PBEHC19EZB0331	17
672	RNE511	KL-15	8759	LL	ORD		1-Nov-2010	KMY	48	60	HINO EURO II	NAE130296Z	MB1PBEHC7AEND5422	05
673	RNE512	KL-15	8760	LL	ORD		1-Nov-2010	KMY	48	60	HINO EURO II	NAE129926Z	MB1PBEHC7AEND4996	05
674	RNC874	KL-15	9321	LL	ORD		30-Dec-2011	KLM	48	60	HINO 6ET13K BSIII	BMEZ400632	MB1PBEYC2BEMG5507	34
675	RNE862	KL-15	9366	LL	ORD		2-Feb-2012	VTRA	48	66	HINO 6ET13K EUROIII	BMEZ400724	MB1PBEYC1BEMG5644	17
676	RAC799	KL-15	7951	LL	ORD		24-Sep-2009	PDM	48	60	HINO EURO II BSII	JXE 107027	MB1PBEHC69EJA1052	39
677	RAC803	KL-15	7953	LL	ORD		25-Sep-2009	PDM	48	60	HINO EURO II BSII	XE 106918Z	MB1PBEHC49EJA0837	39
678	RAC935	KL-15	8120	LL	ORD		9-Dec-2009	PNI	48	60	HINO EURO II	EZXE116637	MB1PBEHC09EZB0675	67
679	RAC782	KL-15	7948	LL	ORD		19-Sep-2009	PLR	48	60	HINO EURO II TIC	KXH 57444Z	KXE 671711	36
680	RAC798	KL-15	7950	LL	ORD		23-Sep-2009	PLR	48	60	HINO EURO II TIC	KXE 106731Z	MB1PBEHC49EJA0143	36
681	RAC802	KL-15	7959	LL	ORD		30-Sep-2009	PLR	48	60	HINO EURO II TIC	JXE 107064Z	MB1PBEHC59EJA1141	36
682	RAC805	KL-15	7967	LL	ORD		5-Oct-2009	PLR	48	60	HINO EURO II TIC	JXE 107108Z	MB1PBEHCX9EJ1264	36
683	RAC866	KL-15	8018	LL	ORD		31-Oct-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	KXH 575724	MB1PBEHC59EJA0104	47
684	RAC929	KL-15	8111	LL	ORD		2-Dec-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	ZXE 110991Z	MB1PBEHC59EJA9487	47
685	RAE835	KL-15	8064	LL	ORD		13-Nov-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	JXE 107098Z	MB1PBEHC39EJA1221	47
686	RAC950	KL-15	8149	LL	ORD		1-Jan-2010	KTM	48	60	HINO EURO II TURBO INTER COOLER	ZXE 111542Z	MB1PBEHC89EZB0536	47
687	RAC952	KL-15	8151	LL	ORD		1-Jan-2010	KTM	48	60	HINO EURO II TURBO INTER COOLER	ZXE 111385Z	MB1PBEHC19EZB0233	47
688	RNK 62	KL-15	8221	LL	ORD		8-Mar-2010	KLM	48	60	HINO EURO II TURBO INTER COOLER	WXE114311Z	MB1PBHEC09EWB5513	34
689	RAC931	KL-15	8114	LL	ORD		3-Dec-2009	VKM	48	60	HINO EURO II W06ETI BSII	VHG 1104	MB1PBEHC99EZA9492	51
690	RNC798	KL-15	9251	LL	ORD		19-Nov-2011	KMY	48	66	HINO 6ET13K BSIII	NBE158580Z	MB1PBEYC8BENG3683	05
691	RNK837	KL-15	9336	LL	ORD		6-Jan-2012	KMY	48	66	HINO 6ET13K BSIII	MBE159649Z	MB1PBEYC5BEMG5274	05
692	RNK838	KL-15	9337	LL	ORD		6-Jan-2012	NDM	48	66	HINO 6ET13K BSIII	BMEZ400236	MB1PBEYC3BEMG5144	110
693	RNE884	KL-15	9368	LL	ORD		2-Feb-2012	KTDA	48	66	HINO 6ET13K BSIII	BMEZ400545	MB1PBEYCXBEMG5643	25
694	RAE308	KL-15	7472	LL	ORD		21-Feb-2009	PLD	48	60	HINO W06ETI BSII	ZNH 568015	YNE 667275	32
695	RNC129	KL-15	8291	LL	ORD		4-May-2010	PLD	48	60	HINO EURO TIC BSII	WAE 120040Z	MB1PBEHC0AEWC3888	32
696	RAK732	KL-15	7924	LL	ORD		14-Sep-2009	KMGH	48	60	HINO EURO VIKING BSII	LXH 573478	KXE 671073	55
697	RAK733	KL-15	7925	LL	ORD		14-Sep-2009	KMGH	48	60	HINO EURO VIKING BSII	KXH 573934	KXE 671173	55
698	RAE 85	KL-15	7356	LL	ORD		12-Jan-2009	TVL	48	60	HINO EURO W06ETT BSII	10HB 504130	CNE 664131	43
699	RAC854	KL-15	8011	LL	ORD		27-Oct-2009	EKM	48	60	HINO EUROII ALPSV 4/89	CXE 108904Z	MB1PBEHC39ECA5436	56

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
700	RAC934	KL-15	8119	LL	ORD		9-Dec-2009	EKM	48	60	HINO EUROII ALPSV 4/89	ZXE 11370Z	MB1PBEHC09EZBB0174	56
701	RAC744	KL-15	7919	LL	ORD		9-Sep-2009	MVPA	48	60	HINO EUROII TURBO INTER COLLER	KXH 573972	KXE 671510	52
702	RAC743	KL-15	7921	LL	ORD		10-Sep-2009	PNKM	48	60	HINO EUROII TURBO INTER COOLER	KXH 574090	KXE 671764	49
703	RAC771	KL-15	7936	LL	ORD		16-Sep-2009	PVM	48	60	HINO EUROII TURBO INTER COOLER	KXH 575715	MB1PBEHC29EJA0111	83
704	RAC949	KL-15	8148	LL	ORD		1-Jan-2010	MVPA	48	60	HINO EUROII TURBO INTER COOLER	ZXE 111650Z	MB1PBEHC29E2B0676	52
705	RNC125	KL-15	8281	LL	ORD		29-Apr-2010	MVPA	48	60	HINO EUROII TURBO INTER COOLER	WAE 119180Z	MB1PBEHC2AEWC2998	52
706	RAC867	KL-15	8019	LL	ORD		2-Nov-2009	KLM	48	60	HINO EUROII TURBO INTERCOOLER	581834	ECA 5027	34
707	RAC868	KL-15	8020	LL	ORD		2-Nov-2009	KLM	48	60	HINO EUROII TURBO INTERCOOLER	109737Z	EBA 7363	34
708	RAC870	KL-15	8022	LL	ORD		3-Nov-2009	KLM	48	60	HINO EUROII TURBO INTERCOOLER	583004	ECA 5700	34
709	RAC955	KL-15	8154	LL	ORD		2-Jan-2010	KLM	48	60	HINO EUROII TURBO INTERCOOLER	1114602	EZB 0323	34
710	RAC209	KL-15	7378	LL	ORD		19-Jan-2009	EKM	48	60	HINO EUROII W06ETI BSII	ZNE 104043Z	ZNE 666222	56
711	RNC877	KL-15	9338	LL	ORD		9-Jan-2012	KNR	48	66	HINO 6ET13K BSIII	BMEZ400888	MB1PBEYC0BEMG5814	77
712	RNA 75	KL-15	8243	LL	ORD		6-Apr-2010	CDLM	48	60	HINO EURO BSII	WXE 114835Z	MBIPBBHCX9EWB6149	80
713	RAC246	KL-15	7389	LL	ORD		22-Jan-2009	KMR	48	60	HINO W06ETI BSII	ZNH 567936	ZNE 666661	30
714	RAE250	KL-15	7404	LL	ORD		29-Jan-2009	TVL	48	60	HINO W06ETI BSII	ZNH 567899	ZNE 666761	43
715	RAE251	KL-15	7408	LL	ORD		30-Jan-2009	TVL	48	60	HINO W06ETI BSII	CNH 561049	ZNE 666671	43
716	RAE252	KL-15	7410	LL	ORD		30-Jan-2009	TVL	48	60	HINO W06ETI BSII	CNH 561131	ZNE 666573	43
717	RAE272	KL-15	7417	LL	ORD		5-Feb-2009	KMR	48	60	HINO W06ETI BSII	ZNE 104345Z	YNE 667324	30
718	RAE273	KL-15	7433	LL	ORD		9-Feb-2009	PTPM	48	60	HINO W06ETI BSII	10UHC 1649	YNE 667386	15
719	RAE332	KL-15	7518	LL	ORD		7-Mar-2009	NDD	48	60	HINO W06ETI BSII	ZNE 104004Z	NXE 668474	31
720	RAC562	KL-15	7720	LL	ORD		15-May-2009	MNR	48	60	HINO W06ETI BSII	LXH 105766Z	LXE 670491	60
721	RAE520	KL-15	7700	LL	ORD		8-May-2009	CTR	48	60	HINO W06ETI BSII	LXH572546	LXE 669920	70
722	RAE493	KL-15	7680	LL	ORD		4-May-2009	CTLA	48	60	HINO W06ETI BSII	LXE105568	LXE 669882	46
723	RAE494	KL-15	7681	LL	ORD		4-May-2009	CTLA	48	60	HINO W06ETI BSII	VAE121874Z	LXE 670039	46
724	RAE516	KL-15	7683	LL	ORD		4-May-2009	CTLA	48	60	HINO W06ETI BSII	LXH572909	LXE 669899	46
725	RAE552	KL-15	7713	LL	ORD		15-May-2009	ETPA	48	60	HINO W06ETI BSII	LXH573040	LXE 670088	48
726	RAE553	KL-15	7714	LL	ORD		15-May-2009	KPM	48	60	HINO W06ETI BSII	LXH572617	LXE 670021	91
727	RAE554	KL-15	7723	LL	ORD		16-May-2009	NDD	48	60	HINO W06ETI BSII	LXH573288	LXE 670038	31
728	RAE594	KL-15	7741	LL	ORD		22-May-2009	KPA	48	60	HINO W06ETI BSII			74
729	RAE597	KL-15	7756	LL	ORD		18-Jul-2009	KPA	48	60	HINO W06ETI BSII			74
730	RAE740	KL-15	7886	LL	ORD		30-Jul-2009	EMLY	48	60	HINO W06ETI BSII	KXH 574379	KXE 671509	95
731	RAC747	KL-15	7920	LL	ORD		9-Sep-2009	KLM	48	60	HINO W06ETI BSII	KXE 1066582	MB1PBEHC49EJA0112	34
732	RAC748	KL-15	7922	LL	ORD		10-Sep-2009	ARND	48	60	HINO W06ETI BSII	KXE 106733	MBHPBEHC69EJA0141	19
733	RAC769	KL-15	7931	LL	ORD		14-Sep-2009	KMR	48	60	HINO W06ETI BSII	KXE 106667Z	MB1PBEHCX9EJA0101	30
734	RAC770	KL-15	7932	LL	ORD		14-Sep-2009	KMR	48	60	HINO W06ETI BSII	UHF 2675	MB1PBEHC59EJA0121	30
735	RAC768	KL-15	7930	LL	ORD		14-Sep-2009	NDD	48	60	HINO W06ETI BSII	KXE 106730Z	MB1PBEHC19EJA0147	31
736	RAE764	KL-15	7911	LL	ORD		26-Aug-2009	PNKM	48	60	HINO W06ETI BSII	JXH 576218	MB1PBEHCX9EJA0552	49
737	RAC778	KL-15	7940	LL	ORD		17-Sep-2009	PTPM	48	60	HINO W06ETI BSII	KXH 575725	MB1PBEHC39EJA0103	15
738	RAK785	KL-15	7954	LL	ORD		25-Sep-2009	PTPM	48	60	HINO W06ETI BSII	JXE1070252	MBIPBEHC29EJA1016	15
739	RAC804	KL-15	7960	LL	ORD		1-Oct-2009	PTPM	48	60	HINO W06ETI BSII	JXH 576035	MB1PBEHC59EJA0555	15
740	RAC808	KL-15	7969	LL	ORD		7-Oct-2009	NDD	48	60	HINO W06ETI BSII	KXH 575718	MB1PBEHC79EJA0122	31
741	RAC813	KL-15	7992	LL	ORD		16-Oct-2009	NDD	48	60	HINO W06ETI BSII	CXE 108751	MB1PBEHC89ECA4993	31
742	RAK788	KL-15	7976	LL	ORD		12-Oct-2009	PMNA	48	60	HINO W06ETI BSII	JXE 107021Z	MB1PBEHC59EJA1009	68
743	RAC849	KL-15	8000	LL	ORD		21-Oct-2009	EMLY	48	60	HINO W06ETI BSII	KXE 106735Z	MB1PBEHC69EJA0144	95
744	RAE833	KL-15	7996	LL	ORD		20-Oct-2009	KMR	48	60	HINO W06ETI BSII	BXH 585887	MB1PBEHC79EBA7400	30

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
745	RAC825	KL-15	8002	LL	ORD		22-Oct-2009	PNKM	48	60	HINO W06ETI BSII	JXE 10695ZZ	MB1PBEHC29EJAQ836	49
746	RAC848	KL-15	8005	LL	ORD		24-Oct-2009	PNKM	48	60	HINO W06ETI BSII	KXE 106724Z	MB1PBEHC79EJA0105	49
747	RAC850	KL-15	8006	LL	ORD		24-Oct-2009	PNKM	48	60	HINO W06ETI BSII	JXE 106909Z	MB1PBEHC39EJA0814	49
748	RAE794	KL-15	7981	LL	ORD		14-Oct-2009	VTRA	48	60	HINO W06ETI BSII	CXH582972	MB1PBEHC09HCA1942	17
749	RAE791	KL-15	7961	LL	ORD		3-Oct-2009	VLND	48	60	HINO W06ETI BSII	KXH574706	MB1PBEHC09HCA1925	20
750	RAE792	KL-15	7964	LL	ORD		5-Oct-2009	ARND	48	60	HINO W06ETI BSII	CXH582971	MB1PBEHC79HCA1968	19
751	RAE796	KL-15	7965	LL	ORD		5-Oct-2009	KPA	48	60	HINO W06ETI BSII	CXE108958Z	MB1PBEHC59ECA5518	74
752	RAE793	KL-15	8001	LL	ORD		22-Oct-2009	VLND	48	60	HINO W06ETI BSII	JXH577566	MB1PBEHC49HCA1894	20
753	RAE815	KL-15	8004	LL	ORD		24-Oct-2009	PVM	48	60	HINO W06ETI BSII	CXH582970	MB1PBEHC19HCA1951	83
754	RAE816	KL-15	8014	LL	ORD		30-Oct-2009	CHRY	48	60	HINO W06ETI BSII	CXH582974	MB1PBEHC69HCA2089	44
755	RAE839	KL-15	8071	LL	ORD		16-Nov-2009	CTY	48	60	HINO W06ETI BSII	CXH582975	MB1PBEHC59HCA1970	28
756	RAK831	KL-15	8044	LL	ORD		10-Nov-2009	MVK	48	60	HINO W06ETI BSII	CXH 581832	MB1PBEHC49ECA5025	88
757	RAK832	KL-15	8045	LL	ORD		10-Nov-2009	TDP	48	60	HINO W06ETI BSII	CXE 108709Z	MB1PBEHC39ECA5467	53
758	RAK842	KL-15	8046	LL	ORD		10-Nov-2009	ARND	48	60	HINO W06ETI BSII	CXE 108908Z	MB1PBHL19ECA5466	19
759	RAE837	KL-15	8070	LL	ORD		24-Nov-2009	KMR	48	60	HINO W06ETI BSII	BXE 109978Z	MB1PBEHC19EBA7814	30
760	RAE840	KL-15	8084	LL	ORD		19-Nov-2009	CTY	48	60	HINO W06ETI BSII	MWH277495	MB1PBEHCX9HCA1902	28
761	RAK843	KL-15	8047	LL	ORD		10-Nov-2009	ANK	48	60	HINO W06ETI BSII	CXH 581836	99ECA5019	57
762	RAE838	KL-15	8049	LL	ORD		10-Nov-2009	MLPY	48	60	HINO W06ETI BSII	BXE 109980Z	MB1PBEHCX9EBA7858	96
763	RAE841	KL-15	8100	LL	ORD		26-Nov-2009	CTR	48	60	HINO W06ETI BSII	JXH578314	MB1PBEHC99HCA1891	70
764	RAE883	KL-15	8097	LL	ORD		25-Nov-2009	PMNA	48	60	HINO W06ETI BSII	BXE 109999Z	MB1PBEHC49EBA7886	68
765	RAK895	KL-15	8098	LL	ORD		25-Nov-2009	PMNA	48	60	HINO W06ETI BSII	JXE 107060Z	MB1PBEHC09EJA1208	68
766	RNC131	KL-15	8300	LL	ORD		6-May-2010	KMR	48	60	HINO W06ETI BSII	WAE 120105Z	MB1PBEHCXAEW3980	30
767	RNC130	KL-15	8302	LL	ORD		7-May-2010	VKM	48	60	HINO W06ETI BSII	WAE 119637Z	MB1PBEHC2AEWC3357	51
768	RNE104	KL-15	8316	LL	ORD		14-May-2010	PTPM	48	60	HINO W06ETI BSII	WAH61298Z	MB1PBEHC4AEWC3926	15
769	RNE367	KL-15	8578	LL	ORD		19-Aug-2010	PPD	48	60	HINO W06ETI BSII	WAE120621Z	MB1PBEHC3AEVC4613	26
770	RAC208	KL-15	7370	LL	ORD		16-Jan-2009	ARND	48	60	HINO W06ETI BSII ALPSV 4/89	BNE 103720Z	BNE 665512	19
771	RAE181	KL-15	7368	LL	ORD		16-Jan-2009	CDLM	48	60	HINO BSII TCIC	BNE 103709Z	BNE 665516	80
772	RAE306	KL-15	7462	LL	ORD		19-Feb-2009	KTDA	48	60	HINO W06ETI BSII ALPSV 4/89	YNE 104587Z	XNE 667900	25
773	RNC801	KL-15	9257	LL	ORD		23-Nov-2011	PLD	48	66	HINO 6ETI3K BSIII	BNHZ101636	MB1PBEYC3BENG3929	32
774	RNE813	KL-15	9285	LL	ORD		7-Dec-2011	PTPM	48	66	HINO 6ETI3K BSIII	BNHZ101506	MB1PBEYC1BENG3203	15
775	RNC875	KL-15	9319	LL	ORD		29-Dec-2011	TPLM	48	60	HINO 6ETI3K BSIII	BMEZ400547	MB1PBEYC8BEMG5642	94
776	RNK925	KL-15	9381	LL	ORD		10-Feb-2012	PTPM	48	66	HINO 6ETI3K BSIII	BMEZ400723	MB1PBEYC4BEMG5640	15
777	RNC816	KL-15	9268	LL	ORD		28-Nov-2011	PNKM	48	60	HINO 6ETI3K BSIII	NBE158587Z	MB1PBEYC3BENG3767	49
778	RNC847	KL-15	9292	LL	ORD		12-Dec-2011	CTY	48	60	HINO 6ETI3K BSIII	NBE159375Z	MB1PBEYC5BEMG5209	28
779	RNC855	KL-15	9302	LL	ORD		16-Dec-2011	NTA	48	66	HINO 6ETI3K BSIII	BMHZ103100	MB1PBEYC2BEMG4860	22
780	RNE825	KL-15	9304	LL	ORD		17-Dec-2011	PNKM	48	60	HINO 6ETI3K BSIII	BNHZ102731	MB1PBEYC4BEMG4763	49
781	RAC821	KL-15	7979	LL	ORD		13-Oct-2009	NDD	48	60	HINO W06ETI BSII	CXH 581821	MB1PBEHC79ECA5021	31
782	RNK 78	KL-15	8262	LL	ORD		21-Apr-2010	NDD	48	60	HINO W06ETI BSII	VHG0268	MB1PBEHC7AEWC2995	31
783	RNK811	KL-15	9277	LL	ORD		1-Dec-2011	PSL	48	66	HINO 6ETI3K BSIII	BNHZ101913	MB1PBEYC3BENG3848	21
784	RNC845	KL-15	9284	LL	ORD		7-Dec-2011	PSL	48	66	HINO 6ETI3K BSIII	BMEZ400375	MB1PBEYC3BEMG5225	21
785	RNC797	KL-15	9249	LL	ORD		18-Nov-2011	PLR	48	66	HINO 6ETI3K BSIII	NBE158160Z	MB1PBEYCXBENG3264	36
786	RNE804	KL-15	9256	LL	ORD		23-Nov-2011	PLR	48	66	HINO 6ETI3K BSIII	NBE158605Z	MB1PBEYC7AEWC3691	36
787	RNK810	KL-15	9271	LL	ORD		28-Nov-2011	PLR	48	66	HINO 6ETI3K BSIII	NBE158607Z	MB1PBEYCXBENG3684	36
788	RNC829	KL-15	9280	LL	ORD		3-Dec-2011	PLR	48	66	HINO 6ETI3K BSIII	NBE158157Z	MB1PBEYC0BENG3225	36
789	RNE419	KL-15	8697	LL	ORD		6-Oct-2010	KYLM	48	60	LL BSII	NAE129981Z	MB1PBEHC1AEND5089	41

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
790	RNE334	KL-15	8650	LL	ORD		20-Sep-2010	MVPA	48	60	LL BSII 222	WAE120019Z	MB1PBEHC5AEWC3840	52
791	RNE457	KL-15	8680	LL	ORD		1-Oct-2010	MVPA	48	60	LL BSII 222	NAE129989Z	MB1PBEHCXAEND5088	52
792	RNC794	KL-15	9230	LL	ORD		8-Nov-2011	EDT	48	66	HINO 6ETI3K BSIII	BPHZ401391	MB1PBEYC8BENG3361	98
793	RNK807	KL-15	9248	LL	ORD		18-Nov-2011	EDT	48	66	HINO 6ETI3K BSIII	NBE158580Z	MB1PBEYCXBENG3782	98
794	RNA832	KL-15	9274	LL	ORD		30-Nov-2011	PDM	48	66	HINO 6ETI3K BSIII	NBE158725Z	MB1PBEYCXBENG3877	39
795	RNE573	KL-15	8835	LL	ORD		22-Nov-2010	ALP	48	60	LL EURO BSII	MAE131287Z	MB1PBEHC0AEMD6439	45
796	RNE599	KL-15	8873	LL	ORD		30-Nov-2010	CHRY	48	60	LL HINO EURO BSII	BNE103714	MB1PBEHC1AEND5013	44
797	RAC210	KL-15	7383	LL	ORD		20-Jan-2009	CHRY	48	60	LL HINO BSII	KNH 535555	BNE 665511	44
798	RAC267	KL-15	7430	LL	ORD		6-Feb-2009	CHRY	48	60	LL HINO BSII	ZNE104209Z	YNE 667389	44
799	RAC772	KL-15	7939	LL	ORD		17-Sep-2009	PSL	48	60	LL HINO BSII	KXH 575722	MB1PBEHC69EJA0127	21
800	RAE777	KL-15	7944	LL	ORD		18-Sep-2009	KTDA	48	60	LL HINO BSII	KXE 106718Z	MB1PBEHC99EJA0106	25
801	RAC801	KL-15	7958	LL	ORD		29-Sep-2009	PSL	48	60	LL HINO BSII	JXH 576296	MB1PBEHC99EJA0106	21
802	RAK789	KL-15	8048	LL	ORD		10-Nov-2009	PSL	48	60	LL HINO BSII	KXE 106743Z	MB1PBEHC39EJA0148	21
803	RNK553	KL-15	8876	LL	ORD		1-Dec-2010	GVR	48	60	LL HINO BSII	NAE129936Z	MB1PBEHC3AEND4994	66
804	RNK490	KL-15	8817	LL	ORD		16-Nov-2010	CHRY	48	60	LL HINO EURO BSII	BNE103714	MB1PBEHCXAEMD5802	44
805	RNE571	KL-15	8826	LL	ORD		19-Nov-2010	CHRY	48	60	LL HINO EURO BSII	MAE132178Z	MB1PBEHCXAEMD7310	44
806	RNK840	KL-15	9356	LL	ORD		24-Jan-2012	TSY	48	66	HINO 6ETI3K BSIII	MBE159634Z	MB1PBEYCXBEMG5044	73
807	RAE684	KL-15	7834	LL	ORD		27-Jun-2009	ETPA	48	60	LL HINO W06ETI BSII	KXH 574068	KXE 672040	48
808	RAE655	KL-15	7843	LL	ORD		2-Jul-2009	ETPA	48	60	LL HINO W06ETI BSII	KXH 574837	KXE 672117	48
809	RAE660	KL-15	7844	LL	ORD		2-Jul-2009	ETPA	48	60	LL HINO W06ETI BSII	LXH 572496	LXE 670595	48
810	RAE657	KL-15	7785	LL	ORD		17-Jun-2009	ETPA	48	60	LL HINO W06ETI BSII	KXH 574841	KXE 672073	48
811	RAE689	KL-15	7853	LL	ORD		3-Jul-2009	ETPA	48	60	LL HINO W06ETI BSII	VWH 255989	LXE 659115	48
812	RAE690	KL-15	7859	LL	ORD		8-Jul-2009	ETPA	48	60	LL HINO W06ETI BSII	LXH 573575	LXE 670598	48
813	RAE659	KL-15	7870	LL	ORD		17-Jul-2009	ETPA	48	60	LL HINO W06ETI BSII	LXE 105674Z	LXE 670600	48
814	RAE686	KL-15	7871	LL	ORD		17-Jul-2009	ETPA	48	60	LL HINO W06ETI BSII	LXH 572701	LXE 669871	48
815	RAC927	KL-15	8109	LL	ORD		2-Dec-2009	CHRY	48	60	LL HINO/E BSII	ZXE11557Z	MB1PBEHC39EZB0542	44
816	RNK924	KL-15	9372	LL	ORD		3-Feb-2012	TDY	48	66	HINO 6ETI3K BSIII	BMEZ400763	MB1PBEYC9BEMG5715	79
817	RAC954	KL-15	8153	LL	ORD		2-Jan-2010	CHRY	48	60	LL HINO/E BSII ALPSV 4/89	ZXE11368Z	MB1PBEHC09EZB0188	44
818	RNE207	KL-15	8401	LL	ORD		19-Jun-2010	CHRY	48	60	LL HINO/E BSII ALPSV 4/89 VIKING	VAE12002Z	MB1PBEHE3AEVC4692	44
819	RAM540	KL-15	7781	TATA	ORD		8-Jun-2009	MALA	48	60	LP 1512 BSII	90A62727796	412081B22001055	85
820	RAA634	KL-15	7770	TATA	ORD		1-Jun-2009	TLY	48	60	LP 1512 BSII	90A62726850	BQZ 001113	18
821	RNM903	KL-15	9355	TATA	ORD		24-Jan-2012	PVR	48	66	LP 1512 TC/59 BSIII	11L63203382	MAT412021B0N21907	23
822	RAA640	KL-15	7823	TATA	ORD		24-Jun-2009	VKM	48	60	LP 1512 TC 59 BSII	90B62729827	BQZ 001259	51
823	RNM902	KL-15	9351	TATA	ORD		17-Jan-2012	NPR	48	66	LP 1512 TC/59 BSIII	11K63195044	MAT412021B0N20824	62
824	RNC910	KL-15	9357	TATA	ORD		31-Jan-2012	KPM	48	66	LP 1512 TC/59 BSIII	11L84028083	MAT412021B0N21387	91
825	RAM464	KL-15	7696	TATA	ORD		8-May-2009	VKM	48	60	LP 1512 TC BSII	90A62726972	BQZ 001059	51
826	RAM539	KL-15	7767	TATA	ORD		1-Jun-2009	ANK	48	60	LP 1512 TC BSII	90A62728421	412081BQZ001062	57
827	RAA714	KL-15	7938	TATA	ORD		17-Sep-2009	ANK	48	60	LP 1512 TC BSII	90C62737597	CQZ 003374	57
828	RAM860	KL-15	8061	TATA	ORD		11-Nov-2009	ANK	48	60	LP 1512 TC BSII	80L62723816	MRZ019752	57
829	RNM633	KL-15	8928	TATA	ORD		22-Dec-2010	ANK	48	60	LP 1512 TC/59 BSII	01H62922877	MAT412088A0J15481	57
830	RNA647	KL-15	8931	TATA	ORD		22-Dec-2010	ANK	48	60	LP 1512 TC/59 BSII	01H62922901	MAT41208A0J15480	57
831	RNM634	KL-15	8933	TATA	ORD		23-Dec-2010	ANK	48	60	LP 1512 TC/59 BSII	01H62921758	MAT412088A0J15475	57
832	RNC868	KL-15	9326	TATA	ORD		4-Jan-2012	PKD	48	66	LP 1512 TC/59 BSIII	11K84025182	MAT412021B0N21331	65
833	RNC911	KL-15	9358	TATA	ORD		31-Jan-2012	GVR	48	66	LP 1512 TC/59 BSIII	11L84028080	MAT412021B0N21380	66
834	RAM536	KL-15	7764	TATA	ORD		1-Jun-2009	VTRA	48	60	LP 1512 TC/59 BSII	90A62728418	412081BQZ001054	17

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
835	RAA637	KL-15	7788	TATA	ORD		19-Jun-2009	PKD	48	60	LP 1512 TC/59 BSII			65
836	RAM618	KL-15	7830	TATA	ORD		26-Jun-2009	ALV	48	60	LP 1512 TC/59 BSII	90B62734361	412081CQZ002649	61
837	RAA830	KL-15	8089	TATA	ORD		20-Nov-2009	PKD	48	60	LP 1512 TC/59 BSII			65
838	RNC156	KL-15	8329	TATA	ORD		21-May-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62855523	MAT412088A0C06903	61
839	RNC162	KL-15	8331	TATA	ORD		21-May-2010	VKM	48	60	LP 1512 TC/59 BSII	01C62857067	MAT412088A0C06840	51
840	RNA493	KL-15	8738	TATA	ORD		19-Oct-2010	VKBN	48	60	LP 1512 TC/59 BSII	01G62908000	MAT412086AOCO6754	29
841	RNA500	KL-15	8847	TATA	ORD		23-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01G62908440	MAT412088A0H13952	56
842	RAA474	KL-15	7659	TATA	ORD		25-Apr-2009	ALP	48	60	LP 1512 TC/59 BSII 1512 TCIC	80M62726339	AQZ 000171	45
843	RAA476	KL-15	7689	TATA	ORD		5-May-2009	CTNR	48	60	LP 1512 TC/59 BSII CUMMINS TC	80M62726312	AQZ 000177	97
844	RAA572	KL-15	7738	TATA	ORD		21-May-2009	VKM	48	60	LP 1512 TC/59 BSII CUMMINS TCIC	90A62728237	BQZ 001065	51
845	RNA928	KL-15	9354	TATA	ORD		23-Jan-2012	ALV	48	66	LP 1512 TC/59 BSII	11K63195079	MAT412021B0N21335	61
846	RNC950	KL-15	9388	TATA	ORD		16-Feb-2012	PTA	48	66	HINO 6ETI3K BSIII	11L63199966	MAT412021B0N21527	37
847	RAA567	KL-15	7708	TATA	ORD		12-May-2009	ALV	48	60	LP 1512 TC/59/BSII	80M62726266	412081 AQZ 000169	61
848	RAA957	KL-15	8132	TATA	ORD		14-Dec-2009	KNPY	48	60	LP 1512 TC/59/BSII	62718425	MAT41208190G11181	87
849	RNM906	KL-15	9385	TATA	ORD		14-Feb-2012	ALV	48	60	LP 1512 TC/59 BSIII	11L84028097	MAT412021B0N21528	61
850	RNE858	KL-15	9335	LL	ORD		3-Jan-2012	PLKD	48	66	HINO 6ETI3K BSIII	MBE159645Z	MB1PBEEYCXBEMG4802	69
851	RNE861	KL-15	9365	LL	ORD		2-Feb-2012	NBR	48	66	HINO 6ETI3K BSIII	BMEZ400634	MB1PBEEYC9BEMG5505	86
852	RNC 99	KL-15	8273	TATA	ORD		24-Apr-2010	PVM	48	60	LP 1512 TC/59 BSII	01A62831754	MAT412081A0B03014	83
853	RNC159	KL-15	8325	TATA	ORD		19-May-2010	PVM	48	60	LP 1512 TC/59 BSII	01C62857072	MAT412088A0C06837	83
854	RAM859	KL-15	8060	TATA	ORD		11-Nov-2009	MVK	48	60	TATA 1512 TC BSII	80L62723636	412081LRZ019789	88
855	RAM534	KL-15	7747	TATA	ORD		27-May-2009	KMR	48	60	TATA 1512 BSII	90A 62728419	412081BQZ001056	30
856	RNA115	KL-15	8283	TATA	ORD		30-Apr-2010	PVR	48	60	LP 1512 TC/59 BSIII	01B62841225	MAT412081A0B03327	23
857	RNM 90	KL-15	8298	TATA	ORD		6-May-2010	MVK	48	60	LP 1512 TC/59 BSII	01B62841425	MAT412081A0B03632	88
858	RNA116	KL-15	8287	TATA	ORD		3-May-2010	ARND	48	60	LP 1512 TC/59 BSII	A 62829979	MAT412081A0B03328	19
859	RNA614	KL-15	8860	TATA	ORD		26-Nov-2010	PLR	48	60	LP 1512 TC/59 BSIII	01J62926469	MAT412088A0J15975	36
860	RNA704	KL-15	8951	TATA	ORD		4-Jan-2011	KGD	48	60	LP 1512 TC/59 BSIII	01H62922458	MAT412266A0J15466	84
861	RNA705	KL-15	8958	TATA	ORD		6-Jan-2011	VJMD	48	60	LP 1512 TC/59 BSIII	01J62923791	MAT412266A0J15572	16
862	RNM636	KL-15	8961	TATA	ORD		7-Jan-2011	VJMD	48	60	LP 1512 TC/59 BSIII	01H62915615	MAT412088A0J14688	16
863	RNM699	KL-15	8962	TATA	ORD		7-Jan-2011	KGD	48	60	LP 1512 TC/59 BSIII	01H62922661	MAT412088A0J15471	84
864	RNA706	KL-15	8963	TATA	ORD		10-Jan-2011	KGD	48	60	LP 1512 TC/59 BSIII	01H62922819	MAT412266A0J15613	84
865	RNM632	KL-15	8919	TATA	ORD		17-Dec-2010	VZM	48	60	LP 1512 TC/59 BSIII	01H62915613	MAT412088A0H14687	24
866	RNC949	KL-15	9384	TATA	ORD		14-Feb-2012	KTDA	48	66	LP 1512 TC/59 BSIII	11L63205005	MAT412021BON21338	25
867	RNC951	KL-15	9386	LL	ORD		15-Feb-2012	ALP	48	66	HINO 6ETI3K BSIII	11L84028855	MB1PBEE7C1B0N21615	45
868	RNA568	KL-15	8839	TATA	ORD		22-Nov-2010	KNPY	48	60	LP 1512 TC/59 BSII	01H62915680	MAT412088A0H14495	87
869	RNA455	KL-15	8713	TATA	ORD		8-Oct-2010	PVR	48	60	LP 1512 TC/59 BSII	01G62906907	MAT412088A0G13537	23
870	RNM748	KL-15	9098	TATA	ORD		23-Mar-2011	CTNR	48	60	LP 1512 TC/59 BSIII	01H62922660	MAT412088A0J15467	97
871	RNM905	KL-15	9379	TATA	ORD		9-Feb-2012	CTNR	48	66	LP 1512 TC/59 BSIII	11L84028097	MAT412021B0N21531	97
872	RNA707	KL-15	8983	TATA	ORD		20-Jan-2011	VKBN	48	60	LP 1512 TC/59 BSIII	01J62924093	MAT412088A0J15674	29
873	RNM 73	KL-15	8267	TATA	ORD		22-Apr-2010	VJMD	48	60	LP 1512 TC/59 BSII	01B62840578	MAT412081A0B03331	16
874	RNE574	KL-15	8858	LL	ORD		26-Nov-2010	TVL	48	60	VIKING BSII 222"	MAE131290Z	MB1PBEHC9AEMD6438	43
875	RNE597	KL-15	8859	LL	ORD		26-Nov-2010	TVL	48	60	VIKING BSII 222"	MAE129987Z	MB1PBEHC2AEMD5084	43
876	RNE275	KL-15	8526	LL	ORD		30-Jul-2010	MLPY	48	60	W06ETI BSII	FXE108074Z	MB1PBEHC8AEWC3590	96
877	RNC984	KL-15	9402	TATA	ORD		29-Feb-2012	CTLA	48	66	LP 1512 TC/59 BSIII	11L84028857	MAT412021BON21524	46
878	RNM969	KL-15	9407	TATA	ORD		1-Mar-2012	IJK	48	66	LP 1512 TC/59 BSIII	11L84028843	MAT412021BON21825	89
879	RNM970	KL-15	9408	TATA	ORD		5-Mar-2012	PNI	48	66	LP 1512 TC/59 BSIII	11M63216639	MAT412021COA00017	67

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
880	RNA981	KL-15	9412	TATA	ORD		9-Mar-2012	ALP	48	66	LP 1512 TC/59 BSIII	11L84028088	MAT412021BON21382	45
881	RNC985	KL-15	9413	TATA	ORD		12-Mar-2012	NTA	48	66	LP 1512 TC/59 BSIII	11L63199966	MAT412021BON21533	22
882	RNK999	KL-15	9414	LL	ORD		12-Mar-2012	PSL	48	66	LL HINO BSIII	BMEZ400891	MB1PBCEYC2BEMG5815	21
883	RNM971	KL-15	9415	TATA	ORD		12-Mar-2012	HPD	48	66	LP 1512 TC/59 BSIII	11M63216641	MAT412021COA00015	42
884	RNC988	KL-15	9425	LL	ORD	VND	22-Mar-2012	KTR	48	60	HINO 6ETI3K BSIII	BMEZ400828	MB1PBCEYC8BEMG5916	35
885	RNC986	KL-15	9417	TATA	ORD		13-Mar-2012	PNI	48	66	LP 1512 TC/59 BSIII	21K84081911	MAT412021BON21532	67
886	RNM972	KL-15	9418	TATA	ORD		15-Mar-2012	ALP	48	66	LP 1512 TC/59 BSIII	11M63216640	MAT412021COA00016	45
887	16000	KL-15	9422	LL	ORD		19-Mar-2012	KPA	48	66	HINO 6ETI3K BSIII	BMEZ400889	MB1PBCEYC4BEMG5816	74
888	RNA982	KL-15	9424	TATA	ORD		22-Mar-2012	ARK	48	66	LP 1512 TC/59 BSIII	11L84028855	MAT412021BON21385	06
889	RNM973	KL-15	9423	TATA	ORD		2-Mar-2012	KTM	48	66	LP 1512 TC 59	11M63216294	MAT412021COA00018	47
890	RSC 18	KL-15	9436	LL	ORD	RR	3-Apr-2012	KKD	48	60	6ETI3KBSIII	BCHZ105255	MB1PBCEYC8BECG7047	72
891	RNE920	KL-15	9437	LL	ORD	RR	3-Apr-2012	VJMD	48	60	HINO EURO BSIII	BCEZ402304	MB1PBCEYCXBECG7423	16
892	RSK 1	KL-15	9438	LL	ORD	RR	3-Apr-2012	VJMD	48	60	HINO EURO BSIII	BCEZ401556	MB1PBCEYC3BECG6579	16
893	RNM974	KL-15	9439	TATA	ORD	RR	3-Apr-2012	CTY	48	60		21A84037091	MAT412021COA01074	28
894	RSC 8	KL-15	9440	LL	ORD	RR	3-Apr-2012	MDY	48	60	6ETI 3K BSIII	BCEZ401557	MB1PBCEYC2BECG6590	76
895	RSC 10	KL-15	9441	LL	ORD	RR	3-Apr-2012	SBY	48	60	6ETI3K BSIII	BCHZ105513	MB1PBCEYC2BECG7299	75
896	RNM975	KL-15	9442	TATA	ORD	RR	4-Apr-2012	KGD	48	60		11M8403698	MAT412021COA00704	84
897	RSK 2	KL-15	9447	LL	ORD	RR	7-Apr-2012	VJMD	48	60	HINO EURO BSIII	BCEZ401642	MB1PBCEYC3BECG6677	16
898	RSK 3	KL-15	9450	LL	ORD	RR	9-Apr-2012	SBY	48	60	HINO BSIII	BCEZ401605	MB1PBCEYC1BECG6645	75
899	RNE921	KL-15	9451	LL	ORD	RR	9-Apr-2012	VJMD	48	60	HINO EURO BSIII	BCEZ105198	MB1PBCEYC5BECG7068	16
900	RSA 16	KL-15	9430	TATA	ORD		27-Mar-2012	TDP	48	60		11M63217648	MAT412021COA00019	53
901	RSC 6	KL-15	9448	LL	ORD	RR	7-Apr-2012	VLRD	48	60	BS III	BMEZ400635	MB1PBCEYC2BEMG5734	93
902	RSC 20	KL-15	9449	TATA	ORD	RR	7-Apr-2012	VLRD	48	60	1512 TC BS III	11K84024953	MAT412021BOK19322	93
903	RNM976	KL-15	9452	TATA	ORD	RR	10-Apr-2012	NTA	48	60	LP 1512 TC/59	11M84036854	MAT412021COA00702	22
904	RSC 41	KL-15	9464	TATA	ORD		19-Apr-2012	KDLR	48	60	LP 1512 TC/59 BSIII	11L63205025	MAT412021BON21905	90
905	RNE936	KL-15	9467	LL	ORD		19-Apr-2012	NTA	48	60		BCEZ402070	MB1PBCEYC7BECG7296	22
906	RNE937	KL-15	9468	LL	ORD	VND	20-Apr-2012	MVK	48	60		BCHZ106102	MBIPBCEYCXBECG7860	88
907	RSK 36	KL-15	9471	LL	ORD	VND	24-Apr-2012	KTR	48	60	HINO 6ETI3K BSIII	BCHZ105423	MB1PBCEYC7BECG7153	35
908	RSA 51	KL-15	9472	TATA	ORD		24-Apr-2012	CGNR	48	66		11M84036434	MAT412021COA00877	40
909	RNE938	KL-15	9473	LL	ORD		23-Apr-2012	TPLM	48	66		BCHZ105319	MB1PBCEYC7BECG7072	94
910	RSC 42	KL-15	9477	TATA	ORD		27-Apr-2012	VKM	48	66	CUMMINS BSIII	11L84028850	MAT412021BON21529	51
911	RSK 37	KL-15	9478	LL	ORD		28-Apr-2012	PLKD	48	66	HINO BSIII	NBE158686Z	MB1PBCEYC8BENG3781	69
912	RNE939	KL-15	9480	LL	ORD		26-Apr-2012	KMR	48	66	LL HINO BSIII	BCEZ402901	MBIPBCEYC5BECG8124	30
913	RSA 52	KL-15	9481	TATA	ORD		30-Apr-2012	PKD	48	66		21A84038651	MAT412021COB02554	65
914	RNE940	KL-15	9482	LL	ORD		27-Apr-2012	TVL	48	66	BSIII 222	BGHZ106182	MB1PBCEYC5BECG8012	43
915	RSC 46	KL-15	9484	LL	ORD		2-May-2012	KTM	48	66	HINO 6ETI3K BSIII	BCHZ105655	MB1PBCEYC0BECG7365	47
916	RSK 38	KL-15	9485	LL	ORD		2-May-2012	CHRY	48	66	LL HINO BSIII	BCHZ105652	MB1PBCEYC7BECG7363	44
917	RNE941	KL-15	9486	LL	ORD	VND	30-Apr-2012	KTR	48	60	HINO 6ETI 3K BSIII	BCEZ402899	MB1PBCEYC1BECG8119	35
918	RSM 22	KL-15	9487	TATA	ORD		30-Apr-2012	ATL	48	60	1512 BSIII	21A84037148	MAT412021COA01077	33
919	RSA 53	KL-15	9488	TATA	ORD		3-May-2012	ANK	48	60	CUMMINS 1512C BSIII	11M84036931	MAT412021COA01031	57
920	RSC 49	KL-15	9491	LL	ORD		7-May-2012	MVPA	48	60	6ETI3K BSIII	BCEZ402303	MB1PBCEYC8BECG7422	52
921	RSA 54	KL-15	9492	TATA	ORD		7-May-2012	KPM	48	60	LP 1512 TC/59 BSIII	21A84038671	MAT412021COB02442	91
922	RNE942	KL-15	9493	LL	ORD		4-May-2012	ARND	48	60	6ET BSIII	BCHZ105425	MB1PBCEYC6BEMG7158	19
923	RSC 48	KL-15	9494	LL	ORD		8-May-2012	VTRA	48	60	HINO EURO BSIII	BCHZ105418	MB1PBCEYC5BECG7152	17
924	RSM 23	KL-15	9495	TATA	ORD		7-May-2012	TDY	48	60	BSIII	21A84037065	MAT412021COA01072	79

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
925	RSC 50	KL-15	9496	LL	ORD		9-May-2012	TSY	48	60		BCEZ402392	MB1PB EYC2BECG7258	73
926	RSA 55	KL-15	9497	TATA	ORD		10-May-2012	TSY	53	60		21A84039694	MAT412021COB02456	73
927	RSC 59	KL-15	9498	LL	ORD		10-May-2012	TSR	48	60		BCEZ402279	MB1PB EYC6BECG7452	63
928	RNE943	KL-15	9499	LL	ORD		8-May-2012	VJMD	48	60	HINO EURO BSIII	BCEZ402305	MB1PB EYC2BECG7450	16
929	RSK 39	KL-15	9501	LL	ORD		11-May-2012	TSY	53	60		BCEZ401560	MB1PB EYC3BECG6582	73
930	RNE944	KL-15	9502	LL	ORD		10-May-2012	TSY	53	60		BCEZ402812	MB1PB EYC7BECG8058	73
931	RSA 56	KL-15	9504	TATA	ORD		14-May-2012	CTNR	53	60		21A84037870	MAT412021COB02458	97
932	RSC 61	KL-15	9505	TATA	ORD		15-May-2012	ATL	53	60	1512 BSIII	11L84028091	MAT412021BON21378	33
933	RSA 57	KL-15	9509	TATA	ORD		18-May-2012	KNPY	53	60	LP 1512 TC/59 BSIII	21A84037869	MAT412021COB02454	87
934	RSM 24	KL-15	9510	TATA	ORD		17-May-2012	KYLM	53	60	1512TCBS III	21A84037182	MAT412021COA01079	41
935	RSK 40	KL-15	9511	LL	ORD		19-May-2012	CTY	53	60	HINO BSIII	BCEZ402193	MBIPB EYC5BECG7362	28
936	RSC 60	KL-15	9512	LL	ORD		19-May-2012	PLR	53	60		BCEZ402307	MB1PB EYC1BECG7424	36
937	RSM 25	KL-15	9514	TATA	ORD		19-May-2012	VKM	53	60	LP 1512 TC 59 BSIII	11K63194789	MAT412021COA01068	51
938	RSA 58	KL-15	9515	TATA	ORD		21-May-2012	ANK	48	60	CUMMINS 1512C BSIII	11M63216016	MAT412021COA00020	57
939	RSK 70	KL-15	9519	LL	ORD		23-May-2012	KMGM	48	60	HINO EURO BSIII ALPSV 4/186	BCHZ105535	MB1PB EYC4BECG7367	55
940	RSM 26	KL-15	9524	TATA	ORD		25-May-2012	VZM	53	66	TC BSIII	21A84037381	MAT412021COA01077	24
941	RSA 76	KL-15	9525	TATA	ORD		26-May-2012	CTR	53	66	LP 1512 TC/59 BSIII	11M63216023	MAT412021COA00021	70
942	RSK 71	KL-15	9526	LL	ORD		26-May-2012	ETPA	53	66	HINO BS 111	BMEZ401004	MB1PB EYCXBEMG5917	48
943	RSA 77	KL-15	9531	TATA	ORD		30-May-2012	PVR	53	66	1512 TC BSIII	11M84036907	MAT412021COA00713	23
944	RSA 78	KL-15	9532	TATA	ORD		31-May-2012	PVR	53	66	1512 TC BSIII	21A84037165	MAT412021COA00875	23
945	RSM 27	KL-15	9535	TATA	ORD		31-May-2012	KNPY	53	66	LP 1512 TC/59 BSIII	21A84038680	MAT412021COB02562	87
946	RSM 28	KL-15	9538	TATA	ORD		1-Jun-2012	VZM	53	66	TC BSIII	21A84039685	MAT412021COB02689	24
947	RSA 79	KL-15	9541	TATA	ORD		4-Jun-2012	CTR	53	66	LP 1512 TC/59 BSIII	11M84033570	MAT412021COA00876	70
948	RNE922	KL-15	9453	LL	ORD	RR	11-Apr-2012	KKD	53	66	LL 6ETI BSIII	BCEZ4021631	MBIPB EYC8BECG7856	72
949	RSC 21	KL-15	9461	TATA	ORD	RR	17-Apr-2012	KPM	53	66	TATA CUMMINS 6BT 5.9	11L63200401	MAT412021BON21906	91
950	RNE923	KL-15	9457	LL	ORD	RR	13-Apr-2012	KKD	53	66	LL 6ETI BSIII	BCHZ1055317	MBIPB EYC6BECG7046	72
951	RSC 19	KL-15	9459	LL	ORD	RR	13-Apr-2012	KPM	53	66	6ETI 3K BSIII	BCHZ105208	MAT412021COA00019	91
952	RSC 86	KL-15	9542	TATA	ORD		5-Jun-2012	MALA	53	66	LP 1512 TC/59 BSIII	11L63206077	MATA12021B0P22204	85
953	RSC 85	KL-15	9546	TATA	ORD		8-Jun-2012	KLM	53	66	BSIII	11L63199964	MAT412021BON21525	34
954	RSC 90	KL-15	9553	LL	ORD		12-Jun-2012	MVPA	53	66	LL BS 111	BCHZ105321	MB1PB EYC5BECG7071	52
955	RSC 91	KL-15	9555	LL	ORD		14-Jun-2012	VLRD	53	66	BS III	BCEZ402495	MB1PB EYC3BECG7778	93
956	RSK 4	KL-15	9456	LL	ORD	RR	13-Apr-2012	SBY	53	66		BMEZ400767	MB1PB EYC3BEMG5712	75
957	RSC 87	KL-15	9544	TATA	ORD		6-Jun-2012	ALV	53	66	6BT 5.9 BSIII	11L84030467	MAT412021BOP22249	61
958	RSC 88	KL-15	9548	TATA	ORD		11-Jun-2012	ARK	53	66	LP 1512 TC/59 BSIII	11L63206171	MAT412021BOP22201	06
959	RSC 89	KL-15	9549	TATA	ORD		11-Jun-2012	ALV	48	60	6BT 5.9 BSIII	11L63205747	MAT412021BOP22202	61
960	RSA106	KL-15	9550	TATA	ORD		11-Jun-2012	CTLA	48	60	TATA 1512 TC BSIII	21A84037138	MAT412021COA00878	46
961	RSM 29	KL-15	9554	TATA	ORD		11-Jun-2012	CTNR	53	66		21A84037973	MAT412021COB02647	97
962	RSA107	KL-15	9556	TATA	ORD		14-Jun-2012	KLM	48	60	BSII	21A84037106	MAT412021COA01030	34
963	RSC110	KL-15	9557	TATA	ORD		15-Jun-2012	KNPY	48	60	LP 1512 TC/59 BSIII	11L63206164	MAT412021BOP22203	87
964	RSC111	KL-15	9558	LL	ORD		15-Jun-2012	KTDA	53	66	6ETI3K BSIII	BCEZ402492	MB1PB EYCXBECG7776	25
965	RSM 30	KL-15	9560	TATA	ORD		15-Jun-2012	PVR	53	66	1512 TC BSIII	21A84037867	MAT412021COB02688	23
966	RSC112	KL-15	9561	LL	ORD		18-Jun-2012	TDP	53	66	BSIII	BCEZ402391	MB1PB EYC4BECG7529	53
967	RSC113	KL-15	9563	LL	ORD		19-Jun-2012	KKLM	53	66		BCEZ402810	MB1PB EYC8BECG8019	108
968	RSC114	KL-15	9565	LL	ORD		21-Jun-2012	NTA	53	66	BSIII	BCEZ402800	MB1PB EYC9BECG8014	22
969	RSM 92	KL-15	9572	TATA	ORD		22-Jun-2012	CLDY	53	66		21L84086261	MAT412021COB02447	58

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
970	RSA108	KL-15	9574	TATA	ORD		25-Jun-2012	NPR	53	66	LP 1512 TC/59 BSIII	21A84039689	MAT412021COB02455	62
971	RSA109	KL-15	9577	TATA	ORD		27-Jun-2012	KYLM	53	66	1512 BSIII	21A84037864	MAT412021C0B02457	41
972	RSM 93	KL-15	9582	TATA	ORD		26-Jun-2012	ATL	53	66	1512 BSIII	21A84038665	MAT412021COB02574	33
973	RSA141	KL-15	9586	TATA	ORD		29-Jun-2012	RWM	53	66		21A84038663	MAT412021C0B02443	10
974	RSA142	KL-15	9587	TATA	ORD		29-Jun-2012	ALP	53	66	BSIII	21B84044641	MAT412021C0C04359	45
975	RSC139	KL-15	9590	LL	ORD		30-Jun-2012	KTDA	53	66	BS III	BCEZ402900	MB1PBEYCXBECG8121	25
976	RSM 94	KL-15	9589	TATA	ORD		10-Jul-2012	PBVR	53	66	TATA LP 1512 TC 59 BSIII	21A84040553	MAT412021COB02573	59
977	RSA143	KL-15	9591	TATA	ORD		2-Jul-2012	PVR	53	66	1512 TC BSIII	21B84045133	MAT412021C0C04394	23
978	RSC140	KL-15	9592	LL	ORD		2-Jul-2012	ETPA	53	66	HE BS III	BCEZ402395	MBIPBEYC3BECG7537	48
979	RSC151	KL-15	9594	TATA	ORD		2-Jul-2012	KPM	53	66	TATA CUMMINS BSIII	11L63205739	MAT412021BOP22200	91
980	RSM 95	KL-15	9595	TATA	ORD		2-Jul-2012	CLDY	53	66		21A84038684	MAT412021COB02508	58
981	RSC152	KL-15	9596	TATA	ORD		3-Jul-2012	ALP	53	66	BSIII	11L63205020	MAT412021BON21617	45
982	RSC153	KL-15	9597	TATA	ORD		3-Jul-2012	KNPY	53	66	LP 1512 TC/59 BSIII	11M84036900	MAT412021COA00712	87
983	RSA144	KL-15	9603	TATA	ORD		5-Jul-2012	ANK	53	66	CUMMINS 1512C BSIII	21A84038695	MAT412021COB02466	57
984	RSC150	KL-15	9604	LL	ORD		5-Jul-2012	KMR	53	66	LL HINO BS III	BECZ402191	MB1PBEYC5BECG7815	30
985	RNM977	KL-15	9458	TATA	ORD	RR	13-Apr-2012	KPM	53	66	1512 BSIII	11M84033583	MAT412021COA01028	91
986	RSK 5	KL-15	9460	LL	ORD	RR	16-Apr-2012	MDY	53	66		BCEZ402046	MB1PBEYC1BECG7150	76
987	RNM978	KL-15	9462	TATA	ORD	RR	18-Apr-2012	KPM	53	66	1512 BSIII	11M84036860	MAT412021COA00705	91
988	RSM 96	KL-15	9605	TATA	ORD		5-Jul-2012	CLDY	53	66		21A84038854	MAT412021COB02575	58
989	RSC154	KL-15	9606	TATA	ORD		6-Jul-2012	CTLA	53	66	TATA 1512 TC BSIII	11M84036511	MAT412021COA00610	46
990	RSC155	KL-15	9607	TATA	ORD		6-Jul-2012	KLM	53	66	BSIII	11M84036912	MAT412021COA00708	34
991	RSA170	KL-15	9612	TATA	ORD		9-Jul-2012	ALP	53	66		21A84040178	MAT412021COB02648	45
992	RSC156	KL-15	9613	TATA	ORD		9-Jul-2012	NPR	53	66	LP 1512 TC/59 BSIII	11M84036883	MAT412021COA00703	62
993	RSC157	KL-15	9614	TATA	ORD		9-Jul-2012	VKM	53	66	CUMMINS BSIII	11M63216023	MAT412021COA00701	51
994	RSC158	KL-15	9615	TATA	ORD	VND	9-Jul-2012	PVR	48	60	1512 TC BSIII	11M84036896	MAT412021COA00700	23
995	RSC159	KL-15	9618	TATA	ORD		10-Jul-2012	CTNR	48	60		11M84036509	MAT412021COA00612	97
996	RSA171	KL-15	9619	TATA	ORD		10-Jul-2012	HPD	53	66	LP 1512 TC/159 BSIII	21B63235736	MAT412021COCO4571	42
997	RSM 97	KL-15	9608	TATA	ORD		6-Jul-2012	CLDY	53	66		21A84038675	MAT412021COB02444	58
998	RSC187	KL-15	9627	TATA	ORD		12-Jul-2012	HPD	53	66	LP 1512 TC/159 BSIII	11M84036890	MAT412021COA00711	42
999	RSC181	KL-15	9628	LL	ORD		13-Jul-2012	NTA	53	66	BSIII	BCEZ402804	MB1PBEYC9BECG7994	22
1000	RSA172	KL-15	9631	TATA	ORD		16-Jul-2012	KNPY	48	60	LP 1512 TC/59 BSIII	21B84045135	MAT412021C0C04393	87
1001	RSA173	KL-15	9632	TATA	ORD		16-Jul-2012	ALV	48	60	HINO W06ETI TC BSIII	21B63237522	MAT412021COCO4572	61
1002	RSC188	KL-15	9633	TATA	ORD		16-Jul-2012	CTLA	53	66	TATA 1512 TC BSIII	11M84036804	MAT412021COA00336	46
1003	RSC189	KL-15	9634	TATA	ORD		16-Jul-2012	CTLA	53	66	TATA 1512 BSIII	11M84036909	MAT412021COA00707	46
1004	RSC182	KL-15	9635	LL	ORD		16-Jul-2012	VJMD	53	66	HINO EURO BSIII	BCEZ402848	MB1PBEYC8BECG8120	16
1005	RSC183	KL-15	9636	LL	ORD		16-Jul-2012	KTDA	53	66	BS 111	BCEZ402747	MB1PBEYC1BECG7990	25
1006	RSM 98	KL-15	9638	TATA	ORD		16-Jul-2012	ALP	53	66	BSIII	21A84038679	MAT412021COB02510	45
1007	RSC190	KL-15	9643	TATA	ORD		19-Jul-2012	MVK	53	66		11M84036887	MAT412021COA00709	88
1008	RSA175	KL-15	9648	TATA	ORD		20-Jul-2012	KLM	53	66	BSIII	21B84044971	MAT412021COCO4392	34
1009	RSC215	KL-15	9653	TATA	ORD		23-Jul-2012	KNPY	48	60	LP 1512 TC/59 BSIII	21B63235735	MAT412021COCO4338	87
1010	RSA174	KL-15	9654	TATA	ORD		23-Jul-2012	ATL	53	66	1512 BSIII	21B84044641	MAT412021COCO4395	33
1011	RSM 99	KL-15	9649	TATA	ORD		19-Jul-2012	VKM	53	66	LP 1512 TC 59 BSIII	21A84040546	MAT412021COB02559	51
1012	RSC210	KL-15	9656	TATA	ORD		24-Jul-2012	CTNR	48	60		11M84036456	MAT412021COA00338	97
1013	RSM100	KL-15	9662	TATA	ORD		24-Jul-2012	KTM	53	66	LP 1512 TC BSIII	21A84037154	MAT412021COB02445	47
1014	RSA218	KL-15	9663	LL	ORD		26-Jul-2012	ALV	48	60	HINO W06ETI TC BSIII	21B63235746	MAT412021COCO4424	61

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1015	RSC211	KL-15	9664	TATA	ORD		26-Jul-2012	MVK	53	66		11M84036470	MAT412021COA00335	88
1016	RSM101	KL-15	9667	TATA	ORD		26-Jul-2012	KLM	53	66	BSIII	21A84038694	MAT412021COB02446	34
1017	RSA219	KL-15	9675	TATA	ORD		30-Jul-2012	VZM	53	66	TC BSIII	21B84044651	MAT412021COCO4358	24
1018	RSC213	KL-15	9676	TATA	ORD		30-Jul-2012	KYLM	53	66	1512TC BS III	11M84036862	MAT412021COA00706	41
1019	RSC214	KL-15	9677	TATA	ORD		30-Jul-2012	CTLA	53	66	TATA 1512 TC BSIII	11M84036508	MAT412021COA00611	46
1020	RSA220	KL-15	9681	TATA	ORD		31-Jul-2012	HPD	53	66	LP 1512 TC/159 BSIII	21B84044652	MAT412021COCO4349	42
1021	RSC248	KL-15	9683	TATA	ORD	VND	1-Aug-2012	PVR	48	60	1512 TC BSIII	11M84036454	MAT412021COA00339	23
1022	RSC249	KL-15	9684	TATA	ORD		1-Aug-2012	KPM	53	66	TATA CUMMINS BSIII	21A84037105	MAT412021COA01070	91
1023	RSC212	KL-15	9672	TATA	ORD		28-Jul-2012	KTM	53	66	LP 1512 TC BSIII	11M84036796	MAT412021COA00337	47
1024	RSM102	KL-15	9687	TATA	ORD		31-Jul-2012	KTM	53	66	LP 1512 TC BSIII	21A84039693	MAT412021COB02462	47
1025	RSM103	KL-15	9688	TATA	ORD		31-Jul-2012	CTNR	53	66		21B63235736	MAT412021COCO4335	97
1026	RSC250	KL-15	9691	TATA	ORD		3-Aug-2012	CLDY	53	66		21A84037063	MAT412021COA01071	58
1027	RSC251	KL-15	9693	TATA	ORD		4-Aug-2012	KYLM	53	66	1512TC BS III	21A84037379	MAT412021COA01076	41
1028	RSA221	KL-15	9697	TATA	ORD		6-Aug-2012	PVM	53	66	LP 1512 TC/59 BSIII	21B84037796	MAT412021COB02460	83
1029	RSA222	KL-15	9702	TATA	ORD		9-Aug-2012	KTM	53	66	LP 1512TC BSIII	21A84040554	MAT412021COB02567	47
1030	RSM104	KL-15	9703	TATA	ORD		8-Aug-2012	PVM	53	66	LP 1512 TC 59 BSIII	21B63235179	MAT412021COCO4337	83
1031	RSA224	KL-15	9707	TATA	FP		14-Aug-2012	MVK	53	66		21B04044649	MAT412021COCO4351	88
1032	RSC252	KL-15	9708	TATA	FP		14-Aug-2012	VJMD	53	66	CUMMINS 6BT BSIII	21A84037376	MAT412021COA01073	16
1033	RSC253	KL-15	9709	TATA	FP		14-Aug-2012	PKD	53	66		21A84037118	MAT412021COA01069	65
1034	RSM105	KL-15	9712	TATA	FP		14-Aug-2012	IJK	53	66	LP 1512 TC BS III	21B63235393	MAT412021COCO4340	89
1035	RSC273	KL-15	9715	TATA	FP		16-Aug-2012	CTR	53	66	LP1512 TV/59 BSIII	21A84040760	MAT412021COB02568	70
1036	RSC274	KL-15	9716	TATA	FP		16-Aug-2012	ATL	53	66	1512 BSIII	21A84040537	MAT412021COB02558	33
1037	RSC275	KL-15	9717	TATA	FP		16-Aug-2012	ATL	53	66	1512 BSIII	21A84038696	MAT412021COB02557	33
1038	RSC276	KL-15	9718	TATA	FP		16-Aug-2012	KYLM	53	66	1512TC BS III	21A84040538	MAT412021COB02564	41
1039	RSC254	KL-15	9720	TATA	FP		16-Aug-2012	MVK	53	66		21A84037121	MAT412021COA01027	88
1040	RSC272	KL-15	9721	TATA	FP		16-Aug-2012	VZM	53	66	TC BSIII	21B63235175	MAT412021COA01078	24
1041	RSK240	KL-15	9722	LL	FP		14-Aug-2012	CGNR	53	66	HINO BSIII	CBHZ100747	MB1PB EYC6CEBG9703	40
1042	RSC277	KL-15	9724	TATA	FP		17-Aug-2012	CTLA	53	66	TATA 1512 TC BSIII	11M84036897	MAT412021COB02461	46
1043	RSC278	KL-15	9725	TATA	FP		17-Aug-2012	TSR	53	66	CUMMINS 6BT BSIII	21A84040763	MAT412021COB02566	63
1044	RSA225	KL-15	9728	TATA	FP		18-Aug-2012	ALP	53	66	BSIII	21A84039507	MAT412021COB02536	45
1045	RSC279	KL-15	9729	TATA	ORD		18-Aug-2012	KNPY	48	60	LP 1512 TC/59 BSIII	11M84036430	MAT412021COA01029	87
1046	RSA223	KL-15	9706	TATA	FP		13-Aug-2012	ALV	53	66	HINO W06ETI TC BSIII	21A84040749	MAT412021COB02569	61
1047	RSA226	KL-15	9736	TATA	FP		22-Aug-2012	ALV	53	66	HINO W09ETI TC BSIII	21A84037791	MAT412021COB02463	61
1048	RSC294	KL-15	9737	TATA	ORD		22-Aug-2012	CTLA	48	60	TATA 1512 TC BSIII	21A84038852	MAT412021COB02459	46
1049	RSK241	KL-15	9735	LL	FP		17-Aug-2012	PSL	53	66	HINO BSIII	CBHZ400603	MB1PB EYC2CEBG9634	21
1050	RSC296	KL-15	9738	LL	FP		23-Aug-2012	VLRD	53	66	BSIII	CBEZ401693	MB1PB EYC1CEBH0578	93
1051	RSK242	KL-15	9742	LL	FP		18-Aug-2012	PLKD	53	66	BS III	BMEZ400790	MB1PB EYC5BECC8060	69
1052	RSK243	KL-15	9746	LL	FP		23-Aug-2012	PLKD	53	66	BS III	CBEZ401228	MB1PB EYC1CEBH0113	69
1053	RSM227	KL-15	9734	LL	FP		17-Aug-2012	TSR	53	66	LP 1512 TC/59	21A84039507	MAT412021COCO4341	63
1054	RSC293	KL-15	9743	TATA	ORD		24-Aug-2012	KTR	48	60	LP 1512 TC/59 BSIII	21A84038852	MAT412021COB02560	35
1055	RSA312	KL-15	9745	TATA	FP		24-Aug-2012	KYLM	53	66	BSIII	21B84045115	MAT412021COCO4425	41
1056	RSC292	KL-15	9750	TATA	FP		25-Aug-2012	PLR	53	66		21A84037865	MAT412021COB02467	36
1057	RSK244	KL-15	9753	LL	FP		25-Aug-2012	NDD	53	66	BSIII	CBEZ401047	MB1PB EYC6CEBG9877	31
1058	RSK245	KL-15	9754	LL	FP		27-Aug-2012	KPA	53	66		CBHZ400610	MB1PB EYC8CEBG9654	74
1059	RSA313	KL-15	9755	TATA	FP		4-Sep-2012	PSL	53	66	1512 BSIII	21B84045116	MAT412021COCO4426	21

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1060	RSA314	KL-15	9756	TATA	FP		4-Sep-2012	ADR	53	66	TATA CUMMINS BSIII	21B63235392	MAT412021COCO4410	38
1061	RSC318	KL-15	9758	TATA	FP		4-Sep-2012	CGNR	53	66	TATA CUMMINS 6BT 5.9 BSIII	21A84038672	MAT412021COB02563	40
1062	RSC317	KL-15	9763	TATA	FP		5-Sep-2012	PLR	53	66		21A84040541	MAT412021COB02572	36
1063	RSM228	KL-15	9764	TATA	FP		25-Aug-2012	KTDA	53	66		21B63235175	MAT412021COCO4413	25
1064	RSM229	KL-15	9765	TATA	FP		4-Sep-2012	MALA	53	66	LP 1512 TC/59 BSIII	21B84045112	MAT412021COCO4416	85
1065	RSC319	KL-15	9767	TATA	ORD		6-Sep-2012	PTA	48	60	CUMMINS 6BT 5.9 BSIII	21A84038677	MAT412021COB02561	37
1066	RSC321	KL-15	9768	TATA	FP		6-Sep-2012	PALA	53	66		21A84040539	MAT412021COB02565	50
1067	RSM230	KL-15	9770	TATA	FP		6-Sep-2012	CHRY	53	66	LP 1512 TC/59 BSIII	21B63236577	MATA12021COCO4343	44
1068	RSC320	KL-15	9773	TATA	FP		7-Sep-2012	ETPA	53	66	TC BS III	21A84040746	MAT412021COB02571	48
1069	RSC322	KL-15	9774	TATA	ORD		7-Sep-2012	PTA	48	60	CUMMINS 6BT 5.9 BSIII	21A84038850	MAT412021COB02511	37
1070	RSM231	KL-15	9775	TATA	FP		7-Sep-2012	PLR	53	66		21B63235183	MAT412021COCO4412	36
1071	RSA316	KL-15	9776	TATA	FP		10-Sep-2012	MVPA	53	66	TATA BS 111	21P84045123	MAT412021COCO4355	52
1072	RSC323	KL-15	9777	TATA	FP		10-Sep-2012	PLR	53	66	1512 TCIC	21B63235172	MAT412021COCO4396	36
1073	RSC324	KL-15	9778	TATA	FP		10-Sep-2012	CGNR	53	66	CUMMINS 6BT 5.9 BSIII	21B63235737	MAT412021COCO4397	40
1074	RSC336	KL-15	9780	TATA	FP		10-Sep-2012	KPM	53	66	TC BS III	21B63234712	MAT412021COCO4346	91
1075	RSC337	KL-15	9781	TATA	FP		10-Sep-2012	KYLM	53	66	1512TC BS III	21B84044643	MAT412021COCO4352	41
1076	RSC338	KL-15	9782	TATA	FP		11-Sep-2012	KNPY	53	66		21B84044647	MAT412021COCO4353	87
1077	RSE262	KL-15	9783	LL	FP		7-Sep-2012	TSY	53	66		CBHZ101867	MB1PBEYC6CEAH1058	73
1078	RSC339	KL-15	9784	TATA	FP		12-Sep-2012	VKM	53	66	BSIII	21A84040554	MAT412021COCO4357	51
1079	RSK246	KL-15	9785	LL	ORD		11-Sep-2012	SBY	53	66	HINO BSIII	CBEZ401124	MB1PBEYC4CEBG9957	75
1080	RSC340	KL-15	9786	TATA	FP		13-Sep-2012	KNPY	53	66	LP 1512 TC/59 BSIII	21B63236579	MAT412021COCO4344	87
1081	RSC341	KL-15	9787	TATA	FP		13-Sep-2012	PNKM	53	66	CUMMINS 6BT 5.9	21B63235193	MAT412021COCO4411	49
1082	RSE263	KL-15	9788	LL	FP		10-Sep-2012	PMNA	53	66	HINO 6ETI3K BSIII	CAEZ402728	MB1PBEYC4CEAH1723	68
1083	RSK247	KL-15	9789	LL	FP		13-Sep-2012	PNKM	53	66	HINO BSIII	BMHZ103128	MB1PBEYCXBEM5142	49
1084	RSC342	KL-15	9790	TATA	FP		17-Sep-2012	ANK	53	66	CUMMINS 1512C BSIII	21B84044639	MAT412021COCO4350	57
1085	RSC343	KL-15	9791	TATA	FP		17-Sep-2012	KTM	53	66	LP 1512 TC BSIII	21B63235760	MAT412021COCO4342	47
1086	RSC344	KL-15	9792	TATA	FP		17-Sep-2012	CGNR	53	66	CUMMINS 6BT 5.9 BSIII	21B84045102	MAT412021COCO4414	40
1087	RSC345	KL-15	9793	TATA	FP		17-Sep-2012	ALP	53	66	BSIII	21B84045105	MAT412021COCO4399	45
1088	RSA358	KL-15	9794	TATA	FP		17-Sep-2012	KMR	53	66	TATA 1512 BSIII	21B84045118	MAT412021COCO4418	30
1089	RSM232	KL-15	9795	TATA	FP		13-Sep-2012	CHRY	53	66		21B84040203	MAT412021COA00710	44
1090	RSC346	KL-15	9796	TATA	FP		18-Sep-2012	PTPM	53	66		21B63235751	MAT412021COCO4336	15
1091	RSE264	KL-15	9797	LL	FP		13-Sep-2012	PLKD	53	66	BS III	CAEZ402438	MB1PBEYC3CEAH1390	69
1092	RSE265	KL-15	9798	LL	FP		14-Sep-2012	TDY	53	66	BSIII	CAEZ402877	MB1PBEYC7CEAH1862	79
1093	RSC347	KL-15	9799	TATA	FP		19-Sep-2012	PSL	53	66	1512 TC BSIII	21B63235751	MAT412021COCO4356	21
1094	RSK326	KL-15	9800	LL	FP		18-Sep-2012	ARK	53	66	HINO BSIII	CBHZ100846	MB1PBEYC4CEBG9635	06
1095	RSA359	KL-15	9801	TATA	FP		20-Sep-2012	NTA	53	66		21B63236580	MAT412021COCO4421	22
1096	RSK327	KL-15	9811	LL	FP		20-Sep-2012	MNR	53	66	HINO EURO BSIII	CBEZ401233	MB1PBEYC6CEBH0222	60
1097	RSE267	KL-15	9815	LL	FP		20-Sep-2012	ARK	53	66	6ETI BSIII	CAEZ402566	MB1PBEYC9CEAH1524	06
1098	RSK328	KL-15	9822	LL	FP		24-Sep-2012	MNR	53	66	HINO EURO BSIII	CBHZ401207	MB1PBEYCXCEBH0224	60
1099	RSK329	KL-15	9829	LL	FP		27-Sep-2012	NDD	53	66	BSIII	CBHZ401545	MB1PBEYC6CEVH0365	31
1100	RSK330	KL-15	9830	LL	FP		28-Sep-2012	EKM	53	66	BSIII	CBHZ101274	MB1PBEYC6CEBH0110	56
1101	RSE269	KL-15	9833	LL	FP		27-Sep-2012	EKM	53	66	BSIII	CAEZ402833	MB1PBEYC2CEAH1879	56
1102	RSE270	KL-15	9834	LL	FP		29-Sep-2012	KKD	53	66	6ETI BSIII	CBEZ402101	MB1PBEYC3CEAH1132	72
1103	RSK331	KL-15	9835	LL	FP		1-Oct-2012	TLY	53	66	HINO 6ETI3K BSIII	CBEZ401379	MB1PBEYCXLEBH0580	18
1104	RSC376	KL-15	9848	TATA	FP		15-Oct-2012	VZM	53	66	TC BSIII	21B63237526	MAT412021COCO4570	24

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1105	RSM373	KL-15	9851	TATA	FP		15-Oct-2012	VZM	53	66	TC BSIII	90C62735662	MATA12021COBO2509	24
1106	RSM374	KL-15	9852	TATA	FP		16-Oct-2012	VZM	53	66	TC BSIII	70C62552483	MAT412021COCO4575	24
1107	RSK332	KL-15	9836	LL	FP		1-Oct-2012	EMLY	53	66	HINO 6ETI 3K BSIII	CBEZ401892	MB1PBEYCICEBH0855	95
1108	RSM371	KL-15	9837	TATA	FP		1-Oct-2012	TSR	53	66	1512 TC BSIII	21B63235752	MAT412021COCO4334	63
1109	RSA387	KL-15	9838	LL	FP		3-Oct-2012	ETPA	53	66	HINO BSIII	CBEZ400946	MB1PBEYC2CEBG9729	48
1110	RSA388	KL-15	9845	LL	FP		10-Oct-2012	NBR	53	66	HINO EURO BSIII	CAEZ402172	MB1PBEYC3CEAH1129	86
1111	RSE302	KL-15	9840	LL	FP		5-Oct-2012	MVPA	53	66	HINO EURO LL BSIII	CAEZ402552	MB1PBEYC7CEAH1523	52
1112	RSE271	KL-15	9839	LL	FP		1-Oct-2012	MLTM	53	66	HINO EURO BSIII	CAEZ402730	MB1PBEYC2CEAH1719	54
1113	RSM372	KL-15	9841	TATA	FP		5-Oct-2012	KNPY	53	66		21B84045144	MAT412021COCO4576	87
1114	RSM235	KL-15	9832	TATA	FP		25-Sep-2012	KMGGM	53	66		21B84045110	MAT412021COCO4417	55
1115	RSC377	KL-15	9831	TATA	FP		29-Sep-2012	ALP	53	66		21A84037806	MAT412021COBO2448	45
1116	RSA389	KL-15	9847	LL	FP		15-Oct-2012	MDY	53	66	BARATH III MODELS	CBEZ402058	MB1PBEYC8CEAH1059	76
1117	RSM234	KL-15	9821	TATA	FP		22-Sep-2012	ALP	53	66		21B63237082	MAT412021COCO4574	45
1118	RSC365	KL-15	9819	TATA	FP		25-Sep-2012	PALA	53	66		21B63235743	MAT412021COCO4339	50
1119	RSC366	KL-15	9820	TATA	FP		25-Sep-2012	HPD	53	66		21B63237098	MAT412021COCO4568	42
1120	RSA315	KL-15	9772	TATA	ORD		7-Sep-2012	KNPY	48	60	LP 1512 TC/59 BSIII	21B63235177	MAT412021COCO4345	87
1121	RSM233	KL-15	9802	TATA	FP		18-Sep-2012	ALP	53	66		21B63235390	MAT412021COCO4420	45
1122	RSC363	KL-15	9817	TATA	FP		25-Sep-2012	MVPA	53	66	TATA BS 111	21C84049843	MAT412021CODO5796	52
1123	RSC364	KL-15	9818	TATA	FP		25-Sep-2012	NPR	53	66		21B84044640	MAT412021COCO4927	62
1124	RSA360	KL-15	9823	TATA	FP		26-Sep-2012	KTM	53	66	LP 1512 TC BSIII	21B63236585	MAT412021COCO4422	47
1125	RSE268	KL-15	9824	LL	FP		24-Sep-2012	CHRY	53	66	LL HINO BSIII	CAEZ402170	MB1PBETCICEAH1131	44
1126	RSC367	KL-15	9825	TATA	FP		28-Sep-2012	EKM	53	66	BSIII	21B63234875	MAT412021COCO4419	56
1127	RSC368	KL-15	9826	TATA	FP		28-Sep-2012	EKM	53	66	BSIII	21B84094642	MAT412021COCO4348	56
1128	RSC369	KL-15	9827	TATA	FP		28-Sep-2012	EKM	53	66	BSIII	21B63237529	MAT412021COCO4569	56
1129	RSC370	KL-15	9828	TATA	FP		28-Sep-2012	PALA	53	66		21B84045123	MAT412021COCO4398	50
1130	RSC325	KL-15	9779	TATA	ORD		10-Aug-2012	KDLR	53	66	CUMMINS 6BT 5.9	21B63235166	MAT412021COCO4347	90
1131	RSC361	KL-15	9812	TATA	FP		24-Sep-2012	PALA	53	66	CUMMINS 6BT 5.9	21B84044653	MAT412021COCO4354	50
1132	RSC362	KL-15	9813	TATA	FP		24-Sep-2012	HPD	53	66	CUMMINS 6BT 5.9	21B63235745	MAT412021COCO4423	42
1133	RSC295	KL-15	9816	TATA	FP		25-Sep-2012	ATL	53	66	1512 BSIII	21A84040214	MAT412021COBO2465	33
1134	RSK333	KL-15	9842	LL	FP		6-Oct-2012	MVPA	53	66	LL BSIII	CBHZ400682	MB1PBEYCICEBG9706	52
1135	RSE266	KL-15	9814	LL	FP		18-Sep-2012	MNR	53	66	HINO EURO BSIII	CBEZ401342	MB1PBEYC8CEAH0142	60
1136	RSA390	KL-15	9853	LL	FP		19-Oct-2012	MPM	53	66		CBEZ401694	MB1PBEYC4CEBH0722	71
1137	RSK399	KL-15	9854	LL	FP		18-Oct-2012	NPR	53	66	HINO BSIII	CBEZ401498	MB1PBEYC4CEBH0364	62
1138	RSC378	KL-15	9856	TATA	FP		22-Oct-2012	KLM	53	66		21C84049844	MAT412021C0D05797	34
1139	RSC379	KL-15	9857	LL	FP		22-Oct-2012	NPR	53	66		CAEZ403042	MB1PBEYC9CEAH2043	62
1140	RSK400	KL-15	9858	LL	FP		22-Oct-2012	VTRA	53	66	HINO 6ET13KN BSIII	CBEZ401439	MB1PBEYC1CEBH0290	17
1141	RSM375	KL-15	9859	TATA	FP		22-Oct-2012	KYLM	53	66	1512T BS111	21B63237089	MAT412021C0C04573	41
1142	RSC381	KL-15	9860	LL	ORD		25-Oct-2012	KPZA	48	60	HINO 6ET13K BSIII	CAEZ402743	MB1PBEYC2CEAH1722	07
1143	RSA391	KL-15	9861	LL	FP		25-Oct-2012	MDY	53	66		CBEZ401902	MB1PBEYCXCEBH0854	76
1144	RSC380	KL-15	9862	LL	FP		25-Oct-2012	VDCY	53	66		BCEZ402713	MB1PBEYC3BECG8011	82
1145	RSC382	KL-15	9863	LL	FP		29-Oct-2012	NTA	53	66		CAEZ402318	MB1PBEYC6CEAH1321	22
1146	RSC383	KL-15	9864	LL	FP		30-Oct-2012	KTM	53	66	HINO 6ET13K BSIII	CAEZ402551	MB1PBEYC4CEAH1530	47
1147	RSC384	KL-15	9865	LL	FP		1-Nov-2012	PNKM	53	66	LL BSIII	BCEZ401555	MB1PBEYC6BECG6589	49
1148	RSE306	KL-15	9866	LL	FP		30-Oct-2012	PALA	53	66	ALPSV 4/186 6ETI BSIII	CBEZ401743	MB1PBEYC2CEAH0721	50
1149	RSE307	KL-15	9867	LL	FP		30-Oct-2012	NDD	53	66	ALPSV 4/186 6ETI BSIII	CAEZ402176	MB1PBEYCXCEAH1130	31

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1150	RSC392	KL-15	9870	TATA	FP		2-Nov-2012	PBVR	53	66	TATA 1512 TC BS111	21A84040181	MAT412021C0B02570	59
1151	RSE308	KL-15	9871	LL	FP		1-Nov-2012	VLRD	53	66	BS III	CAEZ403044	MB1PBEYC3CEAH2040	93
1152	RSK401	KL-15	9872	LL	FP		2-Nov-2012	KMR	53	66	LL HINO BS 111	CBEZ401126	MB1PBEYC4CEBG9974	30
1153	RSE309	KL-15	9873	LL	FP		3-Nov-2012	KMY	53	66		CAEZ403033	MB1PBEYC5CEAH2041	05
1154	RSK402	KL-15	9874	LL	FP		6-Nov-2012	PNKM	53	66	HINO BSIII	CAEZ402201	MB1PBEYC5CEAH1133	49
1155	RSE310	KL-15	9876	LL	FP		6-Nov-2012	VDCY	53	66		CAEZ402401	MB1PBEYC7CEAH1392	82
1156	RSK403	KL-15	9877	LL	FP		9-Nov-2012	PTPM	53	66		CAEZ402424	MB1PBEYC1CEBH1386	15
1157	RSE311	KL-15	9878	LL	FP		12-Nov-2012	NBR	53	66	HINO 6ETI BSIII	CAEZ402883	MB1PBEYC9CEAH1880	86
1158	RSE348	KL-15	9880	LL	FP		15-Nov-2012	TVL	53	66		CAEZ402886	MB1PBEYQCCEAH1878	43
1159	RSC355	KL-15	9882	LL	ORD		17-Nov-2012	KPZA	48	60		CAEZ402414	MB1PBEYC4CEAH1351	07
1160	RSC385	KL-15	9883	LL	FP		17-Nov-2012	RNI	53	66	HINO 6ETI3K BSIII	CAEZ402850	MB1PBEYC9CEAH1863	101
1161	RSC386	KL-15	9884	LL	FP		17-Nov-2012	RNI	53	66	HINO 6ETI3K BSIII	CAEZ403045	MB1PBEYC7CEAH2042	101
1162	RSC393	KL-15	9885	LL	FP		17-Nov-2012	KMGH	53	66	HINO EURO BSIII	CAEZ403031	MB1PBEYC0CEAH2044	55
1163	RSC394	KL-15	9886	LL	FP		17-Nov-2012	PTA	53	66	6ETI3K LL BSIII	CYEZ405689	MB1PBEYC7CEYH5026	37
1164	RSC352	KL-15	9887	LL	FP		19-Nov-2012	KMY	53	66		CAEZ402412	MB1PBEYC5CEAH1391	05
1165	RSC353	KL-15	9888	LL	FP		19-Nov-2012	KTP	53	66		CAEZ402732	MBIPBEYC0CEAH1721	14
1166	RSC354	KL-15	9889	LL	FP		19-Nov-2012	TDY	53	66	BSIII	CAEZ402994	MB1PBEYC6CEAH2064	79
1167	RSE349	KL-15	9890	LL	FP		16-Nov-2012	TDY	53	66	6ETI BSIII	CBEZ402103	MB1PBEYC3CEAH1051	79
1168	RSK404	KL-15	9891	LL	FP		17-Nov-2012	KMR	53	66	HINO BSIII	CBHZ400689	MB1PBEYC5CEBG9708	30
1169	RSC357	KL-15	9892	LL	FP		21-Nov-2012	TSR	53	66		CAEZ402842	MB1PBEYC6CEAH1870	63
1170	RSC398	KL-15	9893	LL	FP		21-Nov-2012	PBVR	53	66	LL BSIII	CAEZ402834	MB1PBEYC1CEAH1873	59
1171	RSK405	KL-15	9894	LL	FP		20-Nov-2012	MLPY	53	66	6ETI 3K BSIII	CBEZ400717	MB1PBEYC8CEBG9637	96
1172	RSE350	KL-15	9895	LL	FP		26-Nov-2012	SBY	53	66	6ETI BSIII	CAEZ402838	MB1PBEYXCCEAH1872	75
1173	RSA420	KL-15	9896	LL	FP		5-Feb-2013	PNR	53	66	LL BS111	CPEZ417009	MB1PBEYC5CERJ8440	78
1174	RSA422	KL-15	9898	LL	FP		6-Feb-2013	TLY	53	66	HINO BS111	CPEZ416894	MBIPBEYCOCEPJ8443	18
1175	RSE406	KL-15	9899	LL	ORD		12-Feb-2013	PNR	48	60	ALPSV 4/186 6ETI BSIII	CRHZ416505	MBIPBEYC6CERJ6699	78
1176	RSE407	KL-15	9900	LL	FP		12-Feb-2013	KGD	53	66		CREZ415241	MB1PBEYC3CERJ6286	84
1177	RSA421	KL-15	9901	LL	FP		12-Feb-2013	TLY	53	66		CPEZ416762	MB1PBEYC7CEPJ8682	18
1178	RSC411	KL-15	9902	LL	FP		12-Feb-2013	KGD	53	66	ALPSV 4/186 6ETI BSIII	CREZ415966	MB1PBEYC6CERJ7206	84
1179	RSC412	KL-15	9903	LL	FP		12-Feb-2013	KGD	53	66	ALPSV 4/186 6ETI3K BSIII	CNEZ418645	MB1PBEYC2CENK0284	84
1180	RSC413	KL-15	9904	LL	ORD		12-Feb-2013	KHD	53	66	ALPSV 4/186 6ETI BSIII	CREZ416565	MB1PBEYC3CEPJ8064	106
1181	RSC414	KL-15	9905	LL	FP		12-Feb-2013	KHD	53	66		CREZ415597	MB1PBEYC7CERJ6694	106
1182	RSC415	KL-15	9906	LL	FP		12-Feb-2013	KHD	53	66		CPEZ416800	MB1PBEYC3CEPJ8288	106
1183	RSC416	KL-15	9907	LL	FP		12-Feb-2013	KHD	53	66		CRHZ116374	MB1PBEYOCERJ7492	106
1184	RSC417	KL-15	9908	LL	FP		12-Feb-2013	KHD	53	66	BS 111	CREZ415219	MB1PBEYC7CERJ6324	106
1185	RSC418	KL-15	9909	LL	FP		12-Feb-2013	PNR	53	66		CREZ415297	MB1PBEYC0CERJ6326	78
1186	RSC419	KL-15	9910	LL	FP		12-Feb-2013	KGD	53	66		CRHZ116297	MB1PBEYC1CERJ6917	84
1187	RSC430	KL-15	9912	LL	FP		12-Feb-2013	KHD	53	66	BSIII 6ETI 3K	CRHZ115936	MB1PBEYC6CERJ6931	106
1188	RSC431	KL-15	9911	LL	ORD		12-Feb-2013	KHD	48	60	BSIII 6ETI 13K	CRHZ116368	MB1PBEYC7CERJ7490	106
1189	RSK440	KL-15	9913	LL	FP		13-Feb-2013	TVL	53	66		CPEZ417189	MB1PBEYC9CEPJ8683	43
1190	RSE408	KL-15	9916	LL	FP		14-Feb-2013	MLPY	53	66	6ETI 3K BSIII	CREZ415840	MB1PBEYC3CERJ7046	96
1191	RSE410	KL-15	9917	LL	FP		14-Feb-2013	TVM	53	66	ALPSV4/1866ETI BSIII	CREZ415312	MBIPBEYC3CERJ6322	27
1192	RSC432	KL-15	9918	LL	FP		16-Feb-2013	ETPA	53	66	HINO BS III	CPEZ416892	MB1PBEYC6CEPJ8363	48
1193	RSC433	KL-15	9919	LL	FP		16-Feb-2013	NDD	53	66		CPEZ416765	MB1PBEYC4CEPJ8364	31
1194	RSA424	KL-15	9920	LL	FP		16-Feb-2013	ANK	53	66	ALPSV4/186 222 BSIII	CPEZ417168	MBIPBEYCOGEPJ8877	57

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1195	RSK441	KL-15	9921	LL	FP		18-Feb-2013	CLDY	53	66		CRHZ116510	MB1PBEYC7CERJ7487	58
1196	RSM450	KL-15	9922	LL	FP		19-Feb-2013	PVM	53	66	BSIII	11L84028082	MB1PBEYC8CEPJ8285	83
1197	RSK442	KL-15	9923	LL	FP		23-Feb-2013	KTDA	53	66	BS 111	CPEZ417410	MBIPBEYC6CEPJ883	25
1198	RSA423	KL-15	9924	LL	FP		23-Feb-2013	TSR	53	66		CRH116319	MB1PBEYC8CERJ6932	63
1199	RSM451	KL-15	9925	LL	FP		22-Feb-2013	TPLM	53	66		CREZ415229	MB1PBEYC4CERJ6331	94
1200	RSE409	KL-15	9926	LL	FP		19-Feb-2013	CGNR	53	66		CREZ415836	MB1PBEYXCERJ7045	40
1201	RSE425	KL-15	9927	LL	FP		26-Feb-2013	VTRA	53	66	HINO EURO BSIII	CREZ415215	MB1PBEYC9CERJ6325	17
1202	RSK443	KL-15	9928	LL	FP		28-Feb-2013	PMNA	53	66	HINO BSIII	CPEZ417008	MB1PBEYC3CEPJ8906	68
1203	RSK444	KL-15	9933	LL	FP		7-Mar-2013	KPA	53	66		CPEZ417412	MB1PBEYC7CEPJ8911	74
1204	RSM452	KL-15	9934	LL	FP		7-Mar-2013	NTA	53	66		CREZ415841	MB1PBEYC4CERJ7074	22
1205	RSM453	KL-15	9935	LL	FP		11-Mar-2013	KNR	53	66	BSIII	CRHZ115912	MB1PBEYCCOCERJ7316	77
1206	RSA461	KL-15	9936	TATA	FP		8-Mar-2013	MVK	53	66		21L84086257	MAT412021DOA00043	88
1207	RSA462	KL-15	9937	TATA	FP		14-Mar-2013	MVK	53	66		21L84086253	MAT412021DOA00044	88
1208	RSC434	KL-15	9938	LL	FP		18-Mar-2013	ARND	53	66		CRHZ116500	MB1PBEYC2CERJ7476	19
1209	RSC435	KL-15	9939	LL	FP		18-Mar-2013	CHRY	53	66	HINO BSIII	CRHZ116250	MB1PBEYC6CERJ7156	44
1210	RSM454	KL-15	9940	LL	FP		18-Mar-2013	MDY	53	66		CPEZ417195	MB1PBEYC5CEPJ8681	76
1211	RSC436	KL-15	9941	LL	FP		20-Mar-2013	PLD	53	66	6ETI 13K(BSIII)	CRHZ116514	MB1PBEYC0CERJ7475	32
1212	RSC437	KL-15	9942	LL	FP		20-Mar-2013	TVM	53	66	ALPSV 4/186 6ETI BSIII	CNEZ419026	MB1PBEYC9CENK0704	27
1213	RSE426	KL-15	9944	LL	FP		23-Mar-2013	PLR	53	66		CPEZ417069	MB1PBEYC9CEPJ8666	36
1214	RSK445	KL-15	9945	LL	FP		26-Mar-2013	TVL	53	66		CRHZ116363	MB1PBEYC9CERJ7491	43
1215	RSC438	KL-15	9946	LL	FP		9-Apr-2013	TLY	53	66	6ETI 13K BSIII	CPEZ417064	MB1PBEYC8CEPJ8626	18
1216	RSC439	KL-15	9947	LL	FP		9-Apr-2013	KHD	53	66	6ETI 13K BSIII	CPEZ419022	MB1PBEYC8CENK0709	106
1217	RSC467	KL-15	9948	LL	FP		9-Apr-2013	KHD	53	66		CRHZ116942	MB1PBEYC3CERJ7485	106
1218	RSC468	KL-15	9949	LL	FP		9-Apr-2013	PNI	53	66	6ETI BSIII	CPEZ417411	MBIPBEYC8CEPJ8884	67
1219	RSC469	KL-15	9950	LL	ORD		9-Apr-2013	KGD	48	60	BSIII 6ETI 3K	CREZ 41577	MB1PBEYC1CEPJ8290	84
1220	RSC470	KL-15	9951	LL	FP		9-Apr-2013	PLD	53	66		CSHZ115616	MB1PBEYC6CERJ7075	32
1221	RSC471	KL-15	9952	LL	FP		9-Apr-2013	KMR	53	66	LL HINO BS III	CPEZ416774	MB1PBEYC1CEPJ8284	30
1222	RSA541	KL-15	9953	TATA	FP		9-Apr-2013	MPM	53	66		21K84081852	MAT412021DOA00467	71
1223	RSA463	KL-15	9954	TATA	FP		8-Apr-2013	CTLA	53	66		21L84086253	MAT412021DOA00045	46
1224	RSC476	KL-15	9955	TATA	FP		10-Apr-2013	NPR	53	66	LP 1512 TC/59 BSIII	21K84081849	MAT412021DOA00059	62
1225	RSC479	KL-15	9956	LL	FP		10-Apr-2013	TVL	53	66		CNEZ418917	MB1PBEYC4CENK0528	43
1226	RSC477	KL-15	9957	LL	FP		11-Apr-2013	KTM	53	66	HINO 6ETI3K BSIII	CNEZ419075	MB1PBEYC9CENK0735	47
1227	RSM536	KL-15	9958	TATA	FP		11-Apr-2013	NBR	53	66	LP 1512 TCIC BSIII	21L84086047	MAT412021DOA00051	86
1228	RSC478	KL-15	9962	LL	FP		16-Apr-2013	ADR	53	66	6ETI3K(BSIII)	CNEZ419144	MB1PBEYC6CEMK0708	38
1229	RSC473	KL-15	9960	TATA	FP		16-Apr-2013	KTM	53	66	LP 1512 TC BSIII	21L84086250	MAT412021DOA00054	47
1230	RSC474	KL-15	9961	TATA	FP		16-Apr-2013	KGD	53	66		21L84086267	MAT412021DOA00053	84
1231	RSC472	KL-15	9963	TATA	FP		17-Apr-2013	KGD	53	66		21L84084959	MAT412021DOA00056	84
1232	RSC475	KL-15	9964	TATA	FP		22-Apr-2013	KGD	53	66		21K84082643	MAT412021DOA00060	84
1233	RSC480	KL-15	9965	TATA	FP		23-Apr-2013	SBY	53	66		21L84084966	MAT412021DOA00055	75
1234	RSC481	KL-15	9966	TATA	FP		24-Apr-2013	KGD	53	66		21L84084965	MAT412021DOA00057	84
1235	RSC482	KL-15	9967	TATA	FP		26-Apr-2013	SBY	53	66		21I84086008	MAT412021DOA00058	75
1236	RSC483	KL-15	9968	TATA	FP		26-Apr-2013	KGD	53	66		21L84086099	MAT412021DOA000414	84
1237	RSM537	KL-15	9970	TATA	FP		25-Apr-2013	KGD	53	66		21L84086097	MAT412021DOA00052	84
1238	RSC484	KL-15	9977	TATA	FP		13-May-2013	EKM	53	66	BSIII	21L84086091	MAT412021DOA00433	56
1239	RSC485	KL-15	9978	TATA	FP		13-May-2013	MKD	53	66	CUMMINS 6BT 5.9 BSIII	31A84090617	MAT412021DOA00456	08

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1240	RSM538	KL-15	9979	TATA	FP		14-May-2013	MKD	53	66	LP 1512 TC/IC BSIII	21L84081842	MAT412021DOA00050	08
1241	RSM539	KL-15	9981	TATA	FP		20-May-2013	ALP	53	66		21L84086255	MAT412021DOA00048	45
1242	RSE456	KL-15	9997	LL	FP		30-May-2013	KTP	53	66		CPEZ417171	MB1PBCEYC1CEPJ8905	14
1243	RSM540	KL-15-A	3	TATA	FP		4-Jun-2013	MALA	53	66	LP 1512 TC/59 BSIII	21K84081911	MAT412021DOA00049	85
1244	RSC486	KL-15	9990	TATA	FP		3-Jun-2013	PTA	53	66	CUMMINS 6BT 59 BSIII	21K84082636	MAT412021DOA00430	37
1245	RSC487	KL-15	9991	TATA	FP		3-Jun-2013	ADR	53	66	CUMMINS 6BT 5.9 BSIII	21L84086002	MAT412021DOA00436	38
1246	RSC489	KL-15-A	7	TATA	FP		7-Jun-2013	ALP	53	66		21L84086045	MAT412021DOA00431	45
1247	RSE457	KL-15-A	8	LL	FP		4-Jun-2013	KTP	53	66		CREZ416046	MB1PBCEYC4CERJ7351	14
1248	RSE458	KL-15-A	9	LL	FP		6-Jun-2013	MVPA	53	66	LL BS 111	CPEZ417412	MB1PBCEYC0CEPJ8913	52
1249	RSC488	KL-15-A	10	TATA	FP		10-Jun-2013	PSL	53	66		21L84086004	MAT412021DOA00417	21
1250	RSC490	KL-15-A	11	TATA	FP		10-Jun-2013	TSR	53	66		21L84086261	MAT412021DOA00409	63
1251	RSA571	KL-15-A	17	TATA	FP		11-Jun-2013	IJK	53	66	BSIII TATA CUMMINS 1512 TC/BS III	31A84093896	MAT412021DOB00991	89
1252	RSA573	KL-15-A	18	TATA	FP		11-Jun-2013	PALA	53	66	1512 TC BSIII	31A84094662	MAT412021DOB01099	50
1253	RSM561	KL-15-A	20	TATA	FP		13-Jun-2013	ETPA	53	66	TC BS 111	21L84086269	MAT412021DOA00408	48
1254	RSM562	KL-15-A	21	TATA	FP		13-Jun-2013	GVR	53	66		21L84086049	MAT412021DOA00420	66
1255	RSC491	KL-15-A	22	TATA	FP		15-Jun-2013	TDP	53	66		21L84086263	MAT412021DOA00062	53
1256	RSA464	KL-15-A	25	TATA	FP		14-Jun-2013	PNI	53	66	LP 1512 TC BSIII	21L84086251	MAT412021DOA00046	67
1257	RSC492	KL-15-A	26	TATA	FP		17-Jun-2013	VLND	53	66	LP 1512 TC/59 BSIII	21K84082640	MAT412021DOA00412	20
1258	RSM563	KL-15-A	30	TATA	FP		17-Jun-2013	IJK	53	66	LP 1512 TC BS111	21L84085922	MAT412021DOA00432	89
1259	RSA465	KL-15-A	31	TATA	FP		18-Jun-2013	PBVR	53	66	LP 1512 TC/59 BSIII	21L84086248	MAT412021DOA00047	59
1260	RSM564	KL-15-A	33	TATA	FP		18-Jun-2013	HPD	53	66		21L84086061	MAT412021DOA00435	42
1261	RSC494	KL-15-A	37	TATA	FP		21-Jun-2013	ATL	53	66	1512 BSIII	21K84082639	MAT412021DOA00413	33
1262	RSA542	KL-15-A	39	TATA	FP		21-Jun-2013	EKM	53	66	1512 TC BSIII	21L84037363	MAT412021DOA00469	56
1263	RSA545	KL-15-A	40	TATA	FP		21-Jun-2013	ANK	53	66	21K 84081848	21K84081848	MAT412021DOA00466	57
1264	RSC493	KL-15-A	41	TATA	FP		24-Jun-2013	PVR	53	66		21K84086258	MAT412021DOA00061	23
1265	RSC506	KL-15-A	42	TATA	FP		24-Jun-2013	KPM	53	66	TATA CUMMINS BSIII	21L84086822	MAT412021DOA00463	91
1266	RSM565	KL-15-A	46	TATA	FP		24-Jun-2013	KNPY	53	66		21L84086063	MAT412021DOA00437	87
1267	RSA609	KL-15-A	47	TATA	FP		25-Jun-2013	ARK	53	66	1512 TC BSIII	31A84093897	MAT412021DOB01038	06
1268	RSC507	KL-15-A	48	TATA	FP		27-Jun-2013	VZM	53	66	LP 1512/TC/59 BSIII	21L84086012	MAT412021DOA00462	24
1269	RSC508	KL-15-A	49	TATA	FP		27-Jun-2013	PLR	53	66		21L84087851	MAT412021DOA00471	36
1270	RSC589	KL-15-A	50	LL	FP		27-Jun-2013	MVPA	53	66	LL BS 111	CDEZ419660	MB1PBCEYC3CEDK1344	52
1271	RSA544	KL-15-A	55	TATA	FP		27-Jun-2013	PALA	53	66	1512 TC BSIII	21L84087849	MAT412021DOA00470	50
1272	RSA543	KL-15-A	56	TATA	FP		28-Jun-2013	ETPA	53	66	TC BS III	21A84092327	MAT412021DOA00472	48
1273	RSM566	KL-15-A	57	TATA	FP		28-Jun-2013	KTDA	53	66	BS 111	21L84086055	MAT412021DOA00418	25
1274	RSC510	KL-15-A	58	TATA	FP		1-Jul-2013	PALA	53	66	CUMMINS 6BT 5.9	31A84090615	MAT412021DOA00457	50
1275	RSA610	KL-15-A	63	TATA	FP		2-Jul-2013	CLDY	53	66		31A84093889	MAT412021DOB00939	58
1276	RSC509	KL-15-A	64	TATA	FP		5-Jul-2013	KLM	53	66		21L84086891	MAT412021DOA00411	34
1277	RSC514	KL-15-A	65	TATA	FP		5-Jul-2013	KLM	53	66		31A84090611	MAT412021DOA00460	34
1278	RSM567	KL-15-A	66	TATA	FP		4-Jul-2013	TVL	53	66		21L84086011	MAT412021DOA00434	43
1279	RSC515	KL-15-A	69	LL	FP		8-Jul-2013	CTNR	53	66	6BT 59 CUMMINS	31A84090766	MAT412021DOA00458	97
1280	RSC516	KL-15-A	72	TATA	FP		9-Jul-2013	MLPY	53	66	LP 1512 TC/59 BSIII	31A84090618	MAT412021DOA00459	96
1281	RSA611	KL-15-A	73	TATA	FP		8-Jul-2013	MALA	53	66	LP 1512 TC/59 BSIII	31A84094619	MAT412021DOB01087	85
1282	RSA612	KL-15-A	74	TATA	FP		8-Jul-2013	MALA	53	66	LP 1512 TC/59 BSIII	31A84093897	MAT412021DOB00996	85
1283	RSM568	KL-15-A	75	TATA	FP		11-Jul-2013	NBR	53	66		31A84092165	MAT412021DOA00461	86
1284	RSM659	KL-15-A	77	TATA	FP		12-Jul-2013	PMNA	53	66	LP 1512 TC 159 BSIII	21M84090394	MAT412021DOA00455	68

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1285	RSA613	KL-15-A	78	TATA	FP		12-Jul-2013	ANK	53	66	LP 1512 TC/59 BSIII	31A84093585	MAT412020DOB00984	57
1286	RSA669	KL-15-A	81	TATA	FP		18-Jul-2013	KNR	53	66	TT LP 1512 TC BSII	31A84093887	MAT412021DOB01033	77
1287	RSA670	KL-15-A	83	TATA	FP		22-Jul-2013	KYLM	53	66	LP 1512 TC/59 BSIII	31A84093654	MAT412021DOB00987	41
1288	RSM660	KL-15-A	84	TATA	FP		22-Jul-2013	NTA	53	66		21K84083056	MAT412002DOA00465	22
1289	RSC517	KL-15-A	88	TATA	FP		26-Jul-2013	VKM	53	66		21L84085998	MAT412021DOA00415	51
1290	RSC599	KL-15-A	91	LL	FP		29-Jul-2013	NBR	53	66		CDEZ419631	MB1PBEEYC9CEDK1106	86
1291	RSC597	KL-15-A	94	LL	FP		31-Jul-2013	KTP	53	66		CDEZ419538	MB1PBEEYC0CEDK1169	14
1292	RSA671	KL-15-A	92	TATA	FP		25-Jul-2013	NBR	53	66		31A84094310	MAT412021DOB01037	86
1293	RSA673	KL-15-A	96	TATA	FP		30-Jul-2013	PTPM	53	66		31A84094625	MAT412021DOB01101	15
1294	RSM661	KL-15-A	97	TATA	FP		30-Jul-2013	KTDA	53	66		31A84093653	MAT412021DOB00978	25
1295	RSC598	KL-15-A	98	LL	FP		1-Aug-2013	ETPA	53	66	HINO BS III	CDEZ419631	MB1PBEEYC4CEDK1269	48
1296	RSA672	KL-15-A	101	TATA	FP		1-Aug-2013	PALA	53	66		31A84094628	MAT412021DOB01100	50
1297	RSC518	KL-15-A	103	TATA	FP		7-Aug-2013	PTA	53	66	CUMMINS 6BT 5.9 BSIII	21L84086048	MAT412021DOA00416	37
1298	RSC519	KL-15-A	110	TATA	FP		12-Aug-2013	PLR	53	66	TT TC BSIII	21K84081865	MAT41202100A00468	36
1299	RSA683	KL-15-A	111	TATA	FP		5-Aug-2013	VZM	53	66	TC BSIII	31A84093642	MAT412021DOB00944	24
1300	RSA684	KL-15-A	115	TATA	FP		13-Aug-2013	ETPA	53	66	TC BSIII	31A84093590	MAT412021DOB00986	48
1301	RSC520	KL-15-A	135	TATA	FP		30-Aug-2013	ALV	53	66	LP 1512 TC/59 BSIII	21K84078567	MAT412021DOA00464	61
1302	RSC521	KL-15-A	136	TATA	FP		30-Aug-2013	PALA	53	66		21K84086827	MAT412021DOA00410	50
1303	RSC529	KL-15-A	137	TATA	FP		30-Aug-2013	CTLA	53	66		31A84093955	MAT412021DOB00941	46
1304	RSM666	KL-15-A	138	TATA	FP		29-Aug-2013	CTY	53	66		31A84093438	MAT412021DOB00992	28
1305	RSC530	KL-15-A	139	TATA	FP		31-Aug-2013	NBR	53	66		31A84091671	MAT412021DOB00829	86
1306	RSA686	KL-15-A	141	TATA	FP		30-Aug-2013	MVK	53	66		31A84093951	MAT412021DOB00940	88
1307	RSA687	KL-15-A	142	TATA	FP		30-Aug-2013	ALV	53	66		31A84093945	MAT412021DOB00997	61
1308	RSM667	KL-15-A	143	TATA	FP		3-Sep-2013	HPD	53	66	LP 1512 TC/59 BSIII	31A84093895	MAT412021DOB00919	42
1309	RSA736	KL-15-A	146	TATA	FP		5-Sep-2013	PSL	53	66		31A84093900	MAT412021DOB00999	21
1310	RSC531	KL-15-A	151	TATA	FP		10-Sep-2013	ALV	53	66	LP 1512 TC /59 BSIII	31A84093950	MAT412021DOB00945	61
1311	RSM668	KL-15-A	158	TATA	FP		12-Sep-2013	VZM	53	66	TC BS 111	21A84037095	MAT412021DOB00832	24
1312	RSA685	KL-15-A	123	TATA	FP		23-Aug-2013	CLDY	53	66	LP 1512 TC/59 BSIII	31A84093592	MAT412021DOB01035	58
1313	RSM664	KL-15-A	124	TATA	FP		24-Aug-2013	CLDY	53	66	LP 1512 TC/59 BSIII	31A84091675	MAT412021DOB00833	58
1314	RSM665	KL-15-A	125	TATA	FP		26-Aug-2013	KLM	53	66	LP 1512 TC/59 BSIII	31A84093587	MAT412021DOB00979	34
1315	RSM663	KL-15-A	113	TATA	FP		13-Aug-2013	ETPA	53	66	1512 TC 159 BSIII	31A84093890	MAT412021DOB00920	48
1316	RSM726	KL-15-A	161	TATA	FP		23-Sep-2013	KNPY	53	66	LP 1512 TC/59 BSIII	31A84093884	MAT412021DOB00921	87
1317	RSM727	KL-15-A	163	TATA	FP		27-Sep-2013	VTRA	53	66	BSIII	31A84091658	MAT412021DOB00826	17
1318	RSA738	KL-15-A	164	TATA	FP		27-Sep-2013	PALA	53	66		31A84094616	MAT412021DOB01085	50
1319	RSA739	KL-15-A	167	TATA	FP		30-Sep-2013	CGNR	53	66		31A84093886	MAT412021DOB01039	40
1320	RSA737	KL-15-A	157	TATA	FP		10-Sep-2013	PVM	53	66	LP 1512 TC BSIII	31A84094652	MAT412021DOB01086	83
1321	RSM728	KL-15-A	168	TATA	FP		3-Oct-2013	TVL	53	66		31A84091665	MAT412021DOB00827	43
1322	RSC532	KL-15-A	169	TATA	FP		5-Oct-2013	CTNR	53	66		31A84093656	MAT412021DOB00985	97
1323	RSE620	KL-15-A	179	LL	FP		21-Oct-2013	PTA	53	66	6ETI3K LL BSIII	CDEZ419903	MB1PBEEYC2CEDK1562	37
1324	RSM731	KL-15-A	181	TATA	FP		24-Oct-2013	VTRA	53	66	BSIII	31A84094312	MAT412021DOB00980	17
1325	RSE621	KL-15-A	184	LL	FP		25-Oct-2013	PTA	53	66	6ETI3K LL BSIII	CNEZ419027	MB1PBEEYC2CENK0706	37
1326	RSC533	KL-15-A	185	TATA	FP		29-Oct-2013	TVL	53	66		31A84093586	MAT412021DOB00983	43
1327	RSA632	KL-15-A	186	TATA	FP		30-Oct-2013	MLPY	53	66	LP 1512 TC/59 BSIII	31A84094620	MAT412021DOB01091	96
1328	RSM732	KL-15-A	187	TATA	FP		30-Oct-2013	PLR	53	66	TT TC BSIII	31A84092328	MAT412021DOB00824	36
1329	RSE622	KL-15-A	188	LL	FP		29-Oct-2013	KTM	53	66		CNEZ419015	MB1PBEEYC9CENK0718	47

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1330	RSA740	KL-15-A	189	TATA	FP		31-Oct-2013	KMGH	53	66	TATA 1512 BSIII	31A84094668	MAT412021DOB01098	55
1331	RSM733	KL-15-A	190	TATA	FP		31-Oct-2013	VLRD	53	66	1512 TC BS 111	31A84094311	MAT412021DOB01179	93
1332	RSE623	KL-15-A	193	LL	FP		1-Nov-2013	KPA	53	66		CPEZ417138	MB1PBHEYC2CEPJ8878	74
1333	RSC750	KL-15-A	194	TATA	FP		5-Nov-2013	KPA	53	66		31A84094663	MAT412021DOB01090	74
1334	RSE624	KL-15-A	199	LL	FP		5-Nov-2013	KPA	53	66	HINO BSIII	CREZ416619	MB1PBHEYC7CEPJ8066	74
1335	RSM734	KL-15-A	205	TATA	FP		5-Nov-2013	KHD	53	66		31A84093902	MAT412021DOB00995	106
1336	RSM735	KL-15-A	206	TATA	FP		8-Nov-2013	KHD	53	66		31A84094313	MAT412021DOB01032	106
1337	RSA741	KL-15-A	204	TATA	FP		5-Nov-2013	KPA	53	66		31A84093953	MAT412021DOB00947	74
1338	RSM742	KL-15-A	216	TATA	FP		12-Nov-2013	KHD	53	66	1512 TC	31A84093641	MAT412021DOB00943	106
1339	RSA759	KL-15-A	217	TATA	FP		12-Nov-2013	KHD	53	66	1512 TC BSIII	31A94093894	MAT412021DOB00981	106
1340	RSA760	KL-15-A	220	TATA	FP		15-Nov-2013	KHD	53	66		31A84091666	MAT412021DOB00831	106
1341	RSA761	KL-15-A	221	TATA	FP		15-Nov-2013	PLKD	53	66	BS 111	31A84093901	MAT412021DOB00938	69
1342	RSM743	KL-15-A	222	TATA	FP		15-Nov-2013	KTDA	53	66	BS 111	31A84093947	MAT412021D0B00990	25
1343	RSM744	KL-15-A	224	TATA	FP		19-Nov-2013	KMGH	53	66	LP 1512TC/59 BSIII	31A84094661	MATA12021DOB01088	55
1344	RSM745	KL-15-A	229	TATA	FP		22-Nov-2013	PLD	53	66		31A84094660	MAT412021DOB01096	32
1345	RSM729	KL-15-A	172	TATA	FP		10-Oct-2013	TVL	53	66		31A84090939	MAT412021DOB00825	43
1346	RSM746	KL-15-A	232	TATA	FP		26-Nov-2013	ARK	53	66		21L84085996	MAT412021DOA00419	06
1347	RSC534	KL-15-A	236	TATA	FP		29-Nov-2013	CLDY	53	66		31A84093639	MAT412021DOB00982	58
1348	RSM747	KL-15-A	237	TATA	FP		29-Nov-2013	TPLM	53	66		31A84093952	MATA12021DOB01180	94
1349	RSM662	KL-15-A	107	TATA	FP		5-Aug-2013	ARND	53	66		31A84093447	MATA12021DOB00993	19
1350	RSM730	KL-15-A	176	TATA	FP		17-Oct-2013	TVL	53	66		31A84094308	MATA12021DOB01181	43
1351	RSM752	KL-15-A	244	TATA	FP		5-Dec-2013	TSR	53	66		31A84094621	MAT412021DOB01093	63
1352	RSC535	KL-15-A	245	TATA	FP		6-Dec-2013	CTNR	53	66		31A84091664	MAT412021DOB00828	97
1353	RSK756	KL-15-A	248	TATA	FP		9-Dec-2013	CGNR	53	66		31A84093651	MAT412021DOB00942	40
1354	RSC748	KL-15-A	249	TATA	FP		10-Dec-2013	ARND	53	66		31A84094657	MAT412021DOB01097	19
1355	RSC751	KL-15-A	250	TATA	FP		11-Dec-2013	CTNR	53	66		31A84094649	MAT412021DOB01094	97
1356	RSM754	KL-15-A	252	TATA	FP		10-Dec-2013	ADR	53	66	CUMMINS 6BT 5.9 BSIII	31A84094665	MAT412021DOB01095	38
1357	RSC749	KL-15-A	254	TATA	FP		13-Dec-2013	VKM	53	66		21A84037063	MAT412021DOB01036	51
1358	RSA755	KL-15-A	256	TATA	FP		16-Dec-2013	KKD	53	66		31A84093949	MAT412021DOB00946	72
1359	RSA753	KL-15-A	258	TATA	FP		19-Dec-2013	ATL	53	66		31A84091662	MAT412021DOB00830	33
1360	RSK757	KL-15-A	259	TATA	FP		21-Dec-2013	ADR	53	66	CUMMINS 6BT 5.9 BSIII	31A84094630	MAT412021DOB01089	38
1361	RSK758	KL-15-A	260	TATA	FP		31-Dec-2013	PTPM	53	66		31A84094654	MAT412021DOB01092	15
1362	RT 249	KL-15	5427	LL	MINI		3-May-2004	KDLR	53	46	HINO WO4D	WVH 251395	WVR 129131	90
1363	RR 45	KL-15	6223	TATA	MINI		12-Aug-2006	ALV	53	46	709	CTZ 828662	CTZ 808294	61
1364	RRC452	KL-15	6614	TATA	ORD	VND	5-Feb-2008	CTY	48	60		JSZ 143287	LSZ 018219	28
1365	RRK510	KL-15	6787	LL	ORD	VND	24-Mar-2008	VTRA	48	60	HINO EURO BSII	NPH 508817	NPE 640881	17
1366	RAA149	KL-15	7312	LL	ORD		29-Dec-2008	EMLY	48	60	ALPSV 4/89 VIKING	BNE 103717Z	BNE 665493	95
1367	RAC163	KL-15	7315	LL	ORD		29-Dec-2008	SBY	48	60	HINO BSII TUEBO INTER COOLER	CNH 559444	CNE 663371	75
1368	RAA152	KL-15	7348	LL	ORD		8-Jan-2009	NTA	48	60	HINO BSII	CNE 103251Z	CNE 664138	22
1369	RAA195	KL-15	7353	LL	ORD		9-Jan-2009	KNI	48	60	HINO BSII	ZNE 104149Z	ZNE 666657	107
1370	RAC207	KL-15	7376	LL	ORD		16-Jan-2009	KMR	48	60	HINO BSII TURBO INTER COOLER	ZNE 104003Z	ZNE 666198	30
1371	RAC 20	KL-15	7236	LL	ORD		21-Nov-2008	MDY	48	60	HINO W06ETI BSII	JNH 541738	JNE 654629	76
1372	RAC142	KL-15	7289	LL	ORD	SWB	19-Dec-2008	MLTM	48	60	HINO W06ETI BSII	ZNE 104111Z	ZNE 666535	54
1373	RAE277	KL-15	7457	LL	ORD		2-Mar-2009	PBVR	48	60	HINO W06ETI BSII	YNE 104592Z	XNE 667898	59
1374	RAM218	KL-15	7427	TATA	ORD		4-Feb-2009	VDCY	48	60		80K62718410	LRZ 019237	82

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1375	RAC334	KL-15	7496	LL	ORD	MLB	28-Feb-2009	VDCY	48	60	XNE 1046502	XNE 104650Z	XNE 667965	82
1376	RAC266	KL-15	7439	LL	ORD		10-Feb-2009	KMGH	48	60	HINO BSII TURBO INTER COOLER	ZNE 104418Z	YNE 667355	55
1377	RAE309	KL-15	7477	LL	ORD		27-Mar-2009	KTDA	48	60	HINO W06ETI BSII	ZNE 104040Z	ZNE 666217	25
1378	RAM285	KL-15	7531	TATA	ORD		20-Mar-2009	VDCY	48	60		80K62718425	LRZ 019370	82
1379	RAM286	KL-15	7532	TATA	ORD		20-Mar-2009	VDCY	48	60		80K62715310	LRZ 019306	82
1380	RAM287	KL-15	7533	TATA	ORD		20-Mar-2009	VDCY	48	60		80K62714635	LRZ 019314	82
1381	RAC394	KL-15	7594	LL	ORD		1-Apr-2009	CHRY	48	60	HINO BSII TURBO INTER COOLER	NXH 571534	NXE 669073	44
1382	RAC450	KL-15	7613	LL	ORD	SWB	13-Apr-2009	MLTM	48	60	HINO W06ETI BSII	LXH 572110	LXE 669782	54
1383	RAC449	KL-15	7614	LL	ORD	SWB	13-Apr-2009	MLTM	48	60	HINO W06ETI BSII	LXH 572142	LXE 669787	54
1384	RAC484	KL-15	7645	LL	ORD	SWB	24-Apr-2009	PNR	48	60	HINO BSII	LXH 572204	LXE 669924	78
1385	RAA472	KL-15	7631	TATA	ORD		18-Apr-2009	VZM	48	60	LP 1512 TC/59 BSII	80M62725659	AQZ 000166	24
1386	RAA473	KL-15	7652	TATA	ORD		23-Apr-2009	VZM	48	60	LP 1512 TC/59 BSII	62337437	AQZ 000167	24
1387	RAA475	KL-15	7664	TATA	ORD		27-Apr-2009	VZM	48	60	LP 1512 TC/59 BSII	21L84086822	AQZ 000175	24
1388	RAM461	KL-15	7751	TATA	ORD		27-May-2009	CLDY	48	60		80M62726258	AQZ 000174	58
1389	RAC647	KL-15	7828	TATA	ORD	SWB	25-Jun-2009	CLDY	48	60		90B62735025	CQZ 002989	58
1390	RNC198	KL-15	8371	TATA	ORD		7-Jun-2010	CLDY	48	60	LP 1512 TC/59 BSIII	01C62855090	MAT412088A0C07322	58
1391	RNC312	KL-15	8534	LL	ORD	SWB	3-Aug-2010	PKD	48	60		VAE122502Z	MB1PCEHC3AEVC7430	65
1392	RNM320	KL-15	8538	TATA	ORD	MLB	5-Aug-2010	PNR	48	60	LP 1512 TC/59 BSIII	01C62862840	MAT412088A0D08744	78
1393	RNM321	KL-15	8539	TATA	ORD	MLB	5-Aug-2010	PNR	48	60	LP 1512 TC/59 BSIII	01C62862845	MAT412088A0D08743	78
1394	RNA338	KL-15	8582	TATA	ORD		20-Aug-2010	PNR	48	60	LP 1512 TC/59 BSIII	01C62855087	MAT412088A0C07323	78
1395	RNA378	KL-15	8583	TATA	ORD		20-Aug-2010	PNR	48	60	LP 1512 TC/59 BSIII	01C62863307	MAT412088A0E09612	78
1396	RNC342	KL-15	8584	LL	ORD	SWB	20-Aug-2010	VDCY	48	60		VAE120970Z	MB1PBCHC3AEVC5113	82
1397	RNC430	KL-15	8669	TATA	ORD	SWB	28-Sep-2010	PTA	48	60	LP 1512 TC/59 BSII	01C62862628	MAT412088A0D09398	37
1398	RNC431	KL-15	8677	TATA	ORD	SWB	30-Sep-2010	PNR	48	60	LP 1512 TC/59 BSIII	01C62862669	MAT412088A0D09397	78
1399	RNC509	KL-15	8764	LL	ORD	SWB	1-Nov-2010	MLTM	48	60	HINO W06ETI BSII	MAE131384Z	MB1PCEHCXAEMD6509	54
1400	RNM519	KL-15	8838	TATA	ORD		22-Nov-2010	KYLM	48	60	LP 1512 TC/59 BSIII	01G62908015	MAT412088A0H13946	41
1401	RNK559	KL-15	8929	LL	ORD		22-Dec-2010	MLTM	48	60	HINO EURO BSII	MAE130884Z	MB1PBEHC5AEMD6002	54
1402	RNK560	KL-15	8930	LL	ORD		22-Dec-2010	MLTM	48	60	HINO EURO BSII	NAE129368Z	MB1PBEHC2AEND4730	54
1403	RNC710	KL-15	8989	TATA	ORD	SWB	24-Jan-2011	PNR	48	60	LP 1512 TC 48 BSII	01J62930135	MAT412266A0J16480	78
1404	RNC735	KL-15	8995	TATA	ORD	SWB	25-Jan-2011	PNR	48	60	LP 1512 TC/59 BSIII	01J62930296	MAT461302A0J16475	78
1405	RNK694	KL-15	9054	LL	ORD		1-Mar-2011	PTA	48	60	HINO EURO III	MAE130893Z	MB1PBEHC7AEMD5983	37
1406	RNE732	KL-15	9097	LL	ORD	SWB	22-Mar-2011	VDCY	48	60		NAE129265Z	MB1PBEHCXAEND4407	82
1407	RNE730	KL-15	9101	LL	ORD	SWB	25-Mar-2011	PKD	48	60		MAE130979Z	MB1PBEHCZAEMD6066	65
1408	RNC869	KL-15	9314	LL	ORD	SWB	23-Dec-2011	PTA	48	60	HINO 6ETI3K BSIII	NBE158798Z	MB1PCEYC8BENG3907	37
1409	RNC955	KL-15	9405	TATA	ORD	SWB	3-Mar-2012	ALV	48	60	LP 1512 TC/59 BSIII	11M63213239	MAT412031BOP23850	61
1410	RNC956	KL-15	9404	LL	ORD	SWB	1-Mar-2012	NBR	48	60	HINO 6ETI3K BSIII	BMEZ401182	MB1PCEYC4BEMG6168	86
1411	RRC 73	KL-15	6243	TATA	ORD		24-Aug-2007	PSL	48	60	1510 TCIC	697 TC55 FSZ 130657	436062 FSZ 010450	21
1412	RRC439	KL-15	6590	TATA	ORD	VND	30-Jan-2008	CTLA	48	60	697 NA 1510 BSII	BRZ 112245	LSZ 018225	46
1413	RRC442	KL-15	6596	TATA	ORD		31-Jan-2008	KNPY	48	60	CUMMINS	KSZ 144984	LSZ 018296	87
1414	RRC448	KL-15	6602	TATA	ORD	MLB	1-Feb-2008	NBR	48	60	697 NA	KSZ 144746	LSZ 018110	86
1415	RRC449	KL-15	6603	TATA	ORD	VND	1-Feb-2008	CTLA	48	60	1512 CUMMINS	GSZ 135638	LSZ 018223	46
1416	RRC443	KL-15	6607	TATA	ORD	VND	4-Feb-2008	KYLM	48	60	CUMMINS	LSZ 148702	LSZ 018323	41
1417	RRC468	KL-15	6625	TATA	ORD	VND	11-Feb-2008	CTLA	48	60	697 NA 1510 BSII	LSZ 152459	MSZ 020931	46
1418	RRA588	KL-15	6780	TATA	ORD	VND	24-Mar-2008	NPR	48	60	697 NA	MSZ 158417	ARZ 000621	62
1419	RRA763	KL-15	6952	TATA	ORD	VND	12-May-2008	KYLM	48	60	697 NA	ARZ 105433	BRZ 003585	41

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1420	RRA766	KL-15	6976	TATA	ORD		20-May-2008	VZM	48	60	697 NA	ARZ 101013	CRZ 004669	24
1421	RRA764	KL-15	6958	TATA	ORD	VND	13-May-2008	KNPY	48	60	697 TCIC	BRZ 108703	BRZ 003589	87
1422	RRA892	KL-15	7152	TATA	ORD	VND	27-Aug-2008	ALP	48	60	697 NA	CRZ 118652	DRZ 007898	45
1423	RRC287	KL-15	6455	TATA	ORD		22-Dec-2007	KLM	48	60	697 TCIC	697 TC55 JSZ 140381	436062 JSZ 015312	34
1424	RRC261	KL-15	6445	TATA	ORD	VND	19-Dec-2007	KLM	48	60	697 TCIC	697 TC55 GSZ 135659	436062 HSZ 013454	34
1425	RRC450	KL-15	6604	TATA	ORD		1-Feb-2008	CTNR	48	60	697 TCIC	KSZ 148106	LSZ 018192	97
1426	RRA433	KL-15	6664	TATA	ORD	MLB	18-Feb-2008	KLM	48	60	697 TCIC	KSZ 146664	KSZ 016685	34
1427	RRC527	KL-15	6681	TATA	ORD	VND	23-Feb-2008	KLM	48	60	697 TCIC	LSZ 152732	MSZ 021044	34
1428	RRC528	KL-15	6682	TATA	ORD	VND	23-Feb-2008	KLM	48	60	697 TCIC	MSZ 153752	MSZ 020840	34
1429	RRC517	KL-15	6678	TATA	ORD	VND	23-Feb-2008	CTY	48	60	697 TCIC	697 TC55 MS2 155944	MSZ 020848	28
1430	RRA481	KL-15	6725	TATA	ORD	VND	6-Mar-2008	CTLA	48	60	697 TCIC	KSZ 148220	LSZ 018605	46
1431	RRA480	KL-15	6721	TATA	ORD	VND	4-Mar-2008	KLM	48	60	697 TCIC	KSZ 148104	LSZ 018604	34
1432	RRA430	KL-15	6627	TATA	ORD	VND	11-Feb-2008	KLM	48	60	697 TCIC	JSZ 142874	KSZ 016655	34
1433	RRA587	KL-15	6764	TATA	ORD	VND	17-Mar-2008	KLM	48	60	697 TCIC	MSZ 155950	ARZ 000620	34
1434	RRC515	KL-15	6662	TATA	ORD	VND	18-Feb-2008	KLM	48	60	697 TCIC	KSZ 144969	MSZ 021112	34
1435	RRC519	KL-15	6667	TATA	ORD	VND	20-Feb-2008	KLM	48	60	697 TCIC	MSZ 153955	MSZ 020839	34
1436	RRC990	KL-15	7144	TATA	ORD	SWB	22-Aug-2008	KLM	48	60	697 TCIC	ERZ 128709	ERZ 121870	34
1437	RRM 66	KL-15	6241	TATA	ORD		24-Aug-2007	HPD	48	60	697 TCIC	00462162033	436062 FSZ 010375	42
1438	RRC 71	KL-15	6239	TATA	ORD	MLB	24-Aug-2007	TSY	48	60	697 TCIC	697 TC55 FSZ 130511	436062 FSZ 010448	73
1439	RRC414	KL-15	6570	TATA	ORD		24-Jan-2008	ATL	48	60	697 TCIC BSII	JSZ 143045	LSZ 016681	33
1440	RRC411	KL-15	6565	TATA	ORD		23-Jan-2008	KDLR	48	60	697 TCIC	JSZ 139874	JSZ 015314	90
1441	RRC391	KL-15	6563	TATA	ORD		22-Jan-2008	HPD	48	60	697 TCIC	CRZ 118645	LSZ 018321	42
1442	RRC444	KL-15	6608	TATA	ORD	VND	4-Feb-2008	HPD	48	60	697 TCIC	KSZ 144982	LSZ 018325	42
1443	RRM490	KL-15	6676	TATA	ORD	VND	23-Feb-2008	CTNR	48	60	697 TCIC	LSZ 148710	LSZ 018386	97
1444	RRM487	KL-15	6637	TATA	ORD		12-Feb-2008	ATL	48	60	697 TCIC	LSZ 148909	LSZ 018387	33
1445	RRA429	KL-15	6626	TATA	ORD	VND	11-Feb-2008	KPM	48	60	697 TCIC BSII	JSZ 143043	KSZ 016654	91
1446	RRC564	KL-15	6726	TATA	ORD	VND	7-Mar-2008	ATL	48	60	697 TCIC BSII	MSZ 158402	ARZ 000615	33
1447	RRC579	KL-15	6735	TATA	ORD	VND	10-Mar-2008	CTY	48	60	697 TCIC	JSZ 140975	ARZ 000859	28
1448	RRC640	KL-15	6804	TATA	ORD	VND	27-Mar-2008	ATL	48	60	697 TCIC	ARZ 105456	BRZ 002878	33
1449	RRM541	KL-15	6755	TATA	ORD	VND	14-Mar-2008	ATL	48	60	697 TCIC	MSZ 158450	ARZ 000625	33
1450	RRA589	KL-15	6779	TATA	ORD	VND	24-Mar-2008	ATL	48	60	697 TCIC BSII	MSZ 158409	ARZ 000622	33
1451	RRC669	KL-15	6830	TATA	ORD	MLB	1-Apr-2008	NBR	48	60	697 TCIC	CRZ 118659	BRZ 002831	86
1452	RRM674	KL-15	6883	TATA	ORD	VND	17-Apr-2008	ATL	48	60	697 TCIC	ARZ 105631	BRZ 002968	33
1453	RRC805	KL-15	6973	TATA	ORD	VND	17-May-2008	ATL	48	60	697 TCIC	BRZ 1122227	CRZ 005826	33
1454	RRC801	KL-15	6959	TATA	ORD		13-May-2008	KYLM	48	60	697 TCIC	BRZ 112223Z	CRZ 005828	41
1455	RRM776	KL-15	6981	TATA	ORD		21-May-2008	KLM	48	60	697 TCIC	BRZ 108707	CRZ 004671	34
1456	RRM824	KL-15	7014	TATA	ORD	VND	2-Jun-2008	MALA	48	60	697 TCIC	BRZ 112001	CRZ 005832	85
1457	RRC382	KL-15	6545	TATA	ORD	MLB	17-Jan-2008	TSY	48	60	697 TCIC	JSZ 143045	KSZ 016681	73
1458	RRM243	KL-15	6372	TATA	ORD	MLB	28-Nov-2007	MPM	48	60	697 TCIC	697 TC55 GSZ 135687	436042 HSZ 013355	71
1459	RRM199	KL-15	6384	TATA	ORD		1-Dec-2007	PKD	48	60	697 TCIC	697 TC55 HSZ 135968	436042 HSZ 013387	65
1460	RRC234	KL-15	6388	TATA	ORD	MLB	3-Dec-2007	KLM	48	60	697 TCIC	697 TC55 GSZ 135547	436042 HSZ 012713	34
1461	RRA434	KL-15	6665	TATA	ORD	VND	20-Feb-2008	CDLM	48	60	697 TCIC	FSZ 13095	KSZ 016688	80
1462	RRM537	KL-15	6704	TATA	ORD		29-Feb-2008	CTLA	48	60	1512 CUMMINS	50A62384705	MSZ 020926	46
1463	RRA591	KL-15	6801	TATA	ORD		27-Mar-2008	CTLA	48	60	697 TCIC 1510 BSII	ARZ 106452	ARZ 000674	46
1464	RRC817	KL-15	6979	TATA	ORD	VND	21-May-2008	PVR	48	60	697 TCIC	CRZ115036	436062 CRZ 006600	23

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1465	RRC819	KL-15	6980	TATA	ORD	VND	21-May-2008	CTY	48	60	697 TCIC	FSZ 130832	CRZ 006588	28
1466	RAA 51	KL-15	7242	TATA	ORD	VND	26-Nov-2008	ATL	48	60	697 TCIC	DRZ 120909	DRZ 008341	33
1467	RAA 50	KL-15	7241	TATA	ORD	VND	26-Nov-2008	ATL	48	60	697 TCIC	DRZ 120902	DRZ 008339	33
1468	RAA255	KL-15	7431	TATA	ORD	MLB	7-Feb-2009	ATL	48	60	697 TCIC		LRZ 019228	33
1469	RRC225	KL-15	6365	TATA	ORD	VND	24-Nov-2007	PVR	48	60	697 TCIC	697TC55 GSZ 134924	436042 HSZ 012589	23
1470	RRA765	KL-15	6971	TATA	ORD	VND	17-May-2008	PVR	48	60	697 TCIC	CRZ112912	436062 CRZ 005847	23
1471	RRA876	KL-15	7046	TATA	ORD	MLB	18-Jun-2008	ALP	48	60	697 TCIC	CRZ 115042	CRZ 006429	45
1472	RRA877	KL-15	7048	TATA	ORD	MLB	19-Jun-2008	MDY	48	60	697 TCIC	BRZ 111526	CRZ 006586	76
1473	RRA897	KL-15	7076	TATA	ORD	MLB	2-Jul-2008	VDCY	48	60	697 TCIC	CRZ 112917	DRZ 007694	82
1474	RRA889	KL-15	7095	TATA	ORD	MLB	30-Jul-2008	CTY	48	60	697 TCIC	CRZ 118660	DRZ 007965	28
1475	RRA901	KL-15	7093	TATA	ORD	MLB	30-Jul-2008	VDCY	48	60	697 TCIC	CRZ 115035	DRZ 007962	82
1476	RRC997	KL-15	7149	TATA	ORD	VND	26-Aug-2008	EDT	48	60	1510 BSII	BRZ 108663	CRZ 004668	98
1477	RRC994	KL-15	7154	TATA	ORD	VND	27-Aug-2008	EDT	48	60	697 TCIC 1510 BSII	CRZ 118643	DRZ 007693	98
1478	RRA986	KL-15	7163	TATA	CFP	VND	1-Sep-2008	PPD	53	60	697 TCIC	RZ115038	DRZ 007718	26
1479	RRA988	KL-15	7179	TATA	ORD	MLB	15-Sep-2008	ALV	48	60	697 TCIC	CRZ 118646	DRZ 007895	61
1480	RRA989	KL-15	7184	TATA	ORD	MLB	19-Sep-2008	MALA	48	60	697 TCIC	CRZ 118659	DRZ 008040	85
1481	RAA 44	KL-15	7193	TATA	ORD	MLB	3-Oct-2008	ALP	48	60	697 TCIC	CRZ 118740	DRZ 008043	45
1482	RAA 43	KL-15	7194	TATA	ORD	MLB	3-Oct-2008	ALP	48	60	697 TCIC	CRZ 118751	DRZ 008041	45
1483	RAA 45	KL-15	7203	TATA	ORD		10-Oct-2008	PNI	48	60	697 TC BS I	00462161708	DRZ 008109	67
1484	RRA878	KL-15	7056	TATA	ORD	VND	23-Jun-2008	CTNR	48	60	697 TCIC	CRZ 118649	DRZ 007894	97
1485	RRA879	KL-15	7065	TATA	ORD	VND	28-Jun-2008	EDT	48	60	697 TCIC 1510 BSII	CRZ 118645	DRZ 007968	98
1486	RRA890	KL-15	7098	TATA	ORD	MLB	28-Jul-2008	TVL	48	60	697 TCIC	30J 6200289185	DRZ 008039	43
1487	RRA891	KL-15	7105	TATA	ORD	MLB	4-Aug-2008	KYLM	48	60	697 TCIC	FSZ 131009	DRZ 007717	41
1488	RRC996	KL-15	7155	TATA	ORD	VND	29-Aug-2008	PLR	48	60	697 TCIC	CRZ 112914	DRZ 007692	36
1489	RAA 48	KL-15	7215	TATA	ORD	VND	23-Oct-2008	CTLA	48	60	697 TCIC	DRZ 120194	DRZ 008107	46
1490	RAA 49	KL-15	7219	TATA	ORD	MLB	4-Nov-2008	KNR	48	60	697 TCIC	DRZ 119532	DRZ 008110	77
1491	RAA 47	KL-15	7211	TATA	ORD		17-Oct-2008	PNR	48	60	697 TCIC	KSZ 148221	LSZ 018293	78
1492	RRC991	KL-15	7159	TATA	ORD	SWB	30-Aug-2008	MALA	48	60	697 TCIC	ERZ 128710	ERZ 121913	85
1493	RRC993	KL-15	7178	TATA	ORD	SWB	10-Sep-2008	MALA	48	60	697 TCIC	ERZ 129004	ERZ 121929	85
1494	RRA899	KL-15	7080	TATA	ORD	VND	7-Jul-2008	PVR	48	60	697 TCIC	CRZ118647	436062 DRZ 007897	23
1495	RAA 46	KL-15	7204	TATA	ORD		10-Oct-2008	PNR	48	60	697 TCIC	DRZ 120907	DRZ 008344	78
1496	RT 710	KL-15	5888	TATA	ORD		25-Apr-2005	VJMD	48	60	1512	O0B62137557	41207LAUZ103783	16
1497	RT 776	KL-15	5954	TATA	ORD		18-Jun-2005	VJMD	48	60	1512	O0C62158057	412071AUZ103738	16
1498	RAA386	KL-15	7555	TATA	ORD	VND	20-Mar-2009	GVR	48	60	6BT CUMMINS BSII	80M 62725129	412081 MRZ020043	66
1499	RAA424	KL-15	7558	TATA	ORD	VND	23-Mar-2009	GVR	48	60	6BT CUMMINS BSII	80L 62721483	412081 CRZ019403	66
1500	RAM343	KL-15	7568	TATA	ORD		25-Mar-2009	GVR	48	60	6BT CUMMINS BSII	80M 62725133	412081 MRZ020038	66
1501	RAM344	KL-15	7569	TATA	ORD		25-Mar-2009	GVR	48	60	6BT CUMMINS BSII	80M 62725109	412081 MRZ020006	66
1502	RAA427	KL-15	7586	TATA	ORD	VND	30-Mar-2009	GVR	48	60	6BT CUMMINS BSII	80M 62725067	412081 MRZ020067	66
1503	RAA385	KL-15	7552	TATA	ORD		18-Mar-2009	GVR	48	60	6BT CUMMINS BSII	80M 62725130	412081 MRZ020040	66
1504	RAM346	KL-15	7585	TATA	ORD	VND	17-Apr-2009	GVR	48	60	6BT CUMMINS BSII	80M 62725128	412081 MRZ020044	66
1505	RAM347	KL-15	7605	TATA	ORD	VND	17-Apr-2009	GVR	48	60	6BT CUMMINS BSII	80M 62725134	412081 MRZ020039	66
1506	RAA429	KL-15	7617	TATA	ORD		8-Apr-2009	GVR	48	60	6BT CUMMINS BSII	80M 62725073	412081 MRZ020069	66
1507	RAM281	KL-15	7549	TATA	ORD	MLB	18-Mar-2009	IJK	48	60	6BT CUMMINS BSII 1512/TC BS II	62163469	LRZ 019241	89
1508	RAM288	KL-15	7550	TATA	ORD	MLB	18-Mar-2009	IJK	48	60	6BT CUMMINS BSII	80K62714649	LRZ 019313	89
1509	RAM289	KL-15	7551	TATA	ORD	MLB	18-Mar-2009	GVR	48	60	6BT CUMMINS BSII	80K 62718415	412081 LRZ019310	66

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1510	RAC633	KL-15	7824	TATA	ORD	SWB	24-Jun-2009	PMNA	48	60	6BT CUMMINS BSII	90C62735266	412263CQ2002930	68
1511	RAM972	KL-15	8176	TATA	ORD		13-Jan-2010	NPR	48	60	6BT CUMMINS BSII	90F62759923	MAT41208190F09055	62
1512	RNM 93	KL-15	8342	TATA	ORD		26-May-2010	IJK	48	60	LP 1512 TC/59 BSII	01B62841376	MAT412081A0B03693	89
1513	RNM134	KL-15	8343	TATA	ORD		26-May-2010	IJK	48	60	LP 1512 TC/59 BSII	01C62857064	MAT412088A0B06836	89
1514	RNC221	KL-15	8425	TATA	ORD	VND	1-Jul-2010	CTLA	48	60	LP 1512 TC/59 BSIII	01C62854419	MB1PBEHEA0C06162	46
1515	RNM228	KL-15	8521	TATA	ORD		29-Jul-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62856402	MAT412088A0C07407	62
1516	RNM474	KL-15	8743	TATA	ORD		20-Oct-2010	CTLA	48	60	LP 1512 TC/59 BSIII	01G62907453	MAT412088A0G13675	46
1517	RNM476	KL-15	8757	TATA	ORD		1-Nov-2010	ALP	48	60	LP 1512 TC/59 BSII	01G62904583	MAT412088A0G13490	45
1518	RNM475	KL-15	8796	TATA	ORD	VND	10-Nov-2010	ALP	48	60	LP 1512 TC/59 BSIII	01G62907501	MAT412088A0G13683	45
1519	RNM478	KL-15	8797	TATA	ORD	VND	10-Nov-2010	KNPY	48	60	LP 1512 TC/59 BSII	01G62907167	MAT412088A0G13582	87
1520	RNC584	KL-15	8861	TATA	ORD		26-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62923508	MAT412088A0J15622	56
1521	RNC605	KL-15	8866	TATA	ORD		27-Nov-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01J62924100	MAT412088A0J15676	90
1522	RNC588	KL-15	8868	TATA	ORD		29-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01H62922809	MAT412088A0J15639	56
1523	RNC604	KL-15	8869	TATA	ORD		29-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62923897	MAT412088A0J15636	56
1524	RNC609	KL-15	8880	TATA	ORD		1-Dec-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01J62923526	MAT412088A0J15621	90
1525	RNC610	KL-15	8881	TATA	ORD		1-Dec-2010	EKM	48	60	LP 1512 TC/59 BSII	01H62922480	MAT412088A0J15477	56
1526	RNC611	KL-15	8882	TATA	ORD		1-Dec-2010	EKM	48	60	LP 1512 TC/59 BSII	01H62922480	MAT412088A0J15469	56
1527	RNC612	KL-15	8888	TATA	ORD		3-Dec-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01J62923885	MAT412088A0J15625	90
1528	RNC613	KL-15	8893	TATA	ORD		6-Dec-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01J62923434	MAT412088A0J15635	90
1529	RNC743	KL-15	9039	TATA	ORD	SWB	17-Feb-2011	GVR	48	60	LP 1512 TC/59 BSII	01J62929463	MAT412266A0J16464	66
1530	RNM747	KL-15	9086	TATA	ORD		21-Mar-2011	KNPY	48	60	LP 1512 TC/59 BSII	01J62923524	MAT412088A0J15573	87
1531	RNC170	KL-15	8344	TATA	ORD		27-May-2010	IJK	48	60	LP 1512 TC/59 BSII	01C62857049	MAT412081A0B06831	89
1532	RR 23	KL-15	6201	TATA	ORD		29-May-2006	TSY	48	60	6BT CUMMINS BSII			73
1533	RT 133	KL-15	5311	TATA	ORD		20-Mar-2004	ATL	48	60	6BT CUMMINS		JWZ 125797	33
1534	RT 220	KL-15	5398	TATA	ORD		3-May-2004	ATL	48	60	6BT CUMMINS	40A62308240	AVZ 100668	33
1535	RT 277	KL-15	5455	TATA	ORD		1-Jun-2004	ATL	48	60	6BT CUMMINS	40D62327396	DVZ 113128	33
1536	RT 350	KL-15	5528	TATA	ORD		22-Jul-2004	ATL	48	60	6BT CUMMINS	40E62333220	EVZ 117080	33
1537	RT 370	KL-15	5548	TATA	ORD		12-Aug-2004	ATL	48	60	6BT CUMMINS	40F62331229	FVZ 120286	33
1538	RT 374	KL-15	5552	TATA	ORD		13-Aug-2004	ATL	48	60	6BT CUMMINS	40F62338432	FVZ 121526	33
1539	RT 384	KL-15	5562	TATA	ORD		20-Aug-2004	ATL	48	60	6BT CUMMINS		FVZ 121485	33
1540	RT 397	KL-15	5575	TATA	ORD		10-Sep-2004	HPD	48	60	6BT CUMMINS	40G62342411	412071GVZ122982	42
1541	RT 407	KL-15	5585	TATA	ORD		22-Sep-2004	ATL	48	60	6BT CUMMINS	40G62343109	GVZ 123499	33
1542	RT 414	KL-15	5592	TATA	ORD		24-Sep-2004	ATL	48	60	6BT CUMMINS	OOC62141344	GVZ 123673	33
1543	RT 415	KL-15	5593	TATA	ORD		24-Sep-2004	ATL	48	60	6BT CUMMINS	40G62343343	GVZ 123672	33
1544	RT 487	KL-15	5665	TATA	ORD		6-Nov-2004	ATL	48	60	6BT CUMMINS	40462349568	HVZ 127644	33
1545	RT 520	KL-15	5698	TATA	ORD		10-Nov-2004	ATL	48	60	6BT CUMMINS	40H62349436	HVZ 127612	33
1546	RT 522	KL-15	5700	TATA	ORD		16-Nov-2004	CLDY	48	60	6BT CUMMINS		412.71HVZ127613	58
1547	RT 570	KL-15	5748	TATA	ORD		17-Dec-2004	ATL	48	60	6BT CUMMINS	62340120	JVZ 131116	33
1548	RT 571	KL-15	5749	TATA	ORD		18-Dec-2004	ATL	48	60	6BT CUMMINS	50C62393437	JVZ 131258	33
1549	RT 576	KL-15	5754	TATA	ORD		23-Dec-2004	ATL	48	60	6BT CUMMINS		GVZ 124312	33
1550	RT 603	KL-15	5780	TATA	ORD		13-Jan-2005	ATL	48	60	6BT CUMMINS	40J62355040	JVZ 131313	33
1551	RT 700	KL-15	5878	TATA	ORD		1-Apr-2005	ATL	48	60	6BT CUMMINS		AUZ 103629	33
1552	RT 701	KL-15	5879	TATA	ORD		1-Apr-2005	ATL	48	60	6BT CUMMINS	50A62381744	AUZ 103631	33
1553	RT 702	KL-15	5880	TATA	ORD		1-Apr-2005	PKD	48	60	6BT CUMMINS		412071AYZ103581	65
1554	RT 785	KL-15	5963	TATA	ORD		23-Jun-2005	ATL	48	60	6BT CUMMINS	50A62384496	AUZ 103739	33

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1555	RT 840	KL-15	6018	TATA	ORD	VND	26-Jul-2005	ATL	48	60	6BT CUMMINS	50C62392919	CUZ 109671	33
1556	RT 901	KL-15	6079	TATA	ORD	VND	3-Sep-2005	NDD	48	60	6BT CUMMINS		CUZ 109591	31
1557	RT 909	KL-15	6087	TATA	ORD	VND	12-Sep-2005	KYLM	48	60	6BT CUMMINS	30J62290793	CUZ 110027	41
1558	RAC645	KL-15	7825	TATA	ORD	SWB	24-Jun-2009	KNR	48	60	6BT CUMMINS	90C62735277	412263CQZ002938	77
1559	RNM 88	KL-15	8292	TATA	ORD		5-May-2010	MDY	48	60	LP 1512 TC/59 BSII	01A62831756	MAT412081A0B03013	76
1560	RNM397	KL-15	8628	TATA	ORD	VND	13-Sep-2010	EDT	48	60	LP 1512 TC/59 BSII	01G62906934	MAT412088A0G13533	98
1561	RNM324	KL-15	8570	TATA	ORD	VND	17-Aug-2010	VJMD	48	60	LP 1512 TC/59 BSII	01D62871934	MAT412088A0E09621	16
1562	RNM377	KL-15	8622	TATA	ORD		9-Sep-2010	MALA	48	60	LP 1512 TC/59 BSII	01B62847889	MAT412088A0B03365	85
1563	RNM 8	KL-15	8305	TATA	ORD	VND	10-May-2010	KTDA	48	60	LP 1512 TC/59 BSIII	62383957	MAT41208190G11188	25
1564	RNC387	KL-15	8637	TATA	ORD	VND	15-Sep-2010	KTDA	48	60	LP 1512 TC/59 BSIII	90F62759540	MAT412088A0D09116	25
1565	RNM703	KL-15	9096	TATA	ORD		22-Mar-2011	CTLA	48	60	LP 1512 TC/59 BSII	01H62923199	MAT412088A0J15496	46
1566	RNC345	KL-15	8596	TATA	ORD		1-Sep-2010	MALA	48	60	LP 1512 TC/59 BSII	01C62856902	MAT412088A0C07193	85
1567	RAM352	KL-15	7648	TATA	ORD	VND	23-Apr-2009	CTNR	48	60	1512 TC BSII	80M 62725116	MRZ 020065	97
1568	RAM537	KL-15	7765	TATA	ORD		1-Jun-2009	KYLM	48	60	1512 TC BSII		412081BQZ001063	41
1569	RAM460	KL-15	7750	TATA	ORD		27-May-2009	KYLM	48	60	1512 TC BSII		412081AQZ000173	41
1570	RAM459	KL-15	7749	TATA	ORD		27-May-2009	CTNR	48	60	1512 TC BSII	62726328	AQZ 000293	97
1571	RNA166	KL-15	8332	TATA	ORD		22-May-2010	KPM	48	60	LP 1512 TC/59 BSIII	01B62840583	MAT412081A0B03324	91
1572	RNC171	KL-15	8345	TATA	ORD		27-May-2010	CTLA	48	60	LP 1512 TC/59 BSII	01C62857070	MAT412081A0B06905	46
1573	RNC172	KL-15	8346	TATA	ORD		27-May-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01C62857069	MAT412088A0C06835	90
1574	RNC173	KL-15	8347	TATA	ORD		27-May-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01C62853471	MAT412088A0C06165	90
1575	RNC175	KL-15	8348	TATA	ORD	VND	29-May-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01C62855225	MAT412088A0C06568	90
1576	RNM135	KL-15	8349	TATA	ORD	VND	31-May-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01C62855945	MAT412088A0C06573	90
1577	RNC174	KL-15	8350	TATA	ORD	VND	31-May-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01C62856893	MAT412088A0C07191	90
1578	RNC178	KL-15	8351	TATA	ORD	VND	31-May-2010	KDLR	48	60	LP 1512 TC/59 BSIII	01C62856833	MAT412081A0C07197	90
1579	RNC176	KL-15	8352	TATA	ORD		1-Jun-2010	KLM	48	60	LP 1512 TC/59 BSIII	01C62854417	MAT412081A0B06163	34
1580	RNC195	KL-15	8353	TATA	ORD		1-Jun-2010	KLM	48	60	LP 1512 TC/59 BSIII	01C62855478	MAT412081A0C07393	34
1581	RNA168	KL-15	8357	TATA	ORD		2-Jun-2010	KPM	48	60	LP 1512 TC/59 BSIII	01B62840565	MAT412081A0B03379	91
1582	RNC177	KL-15	8362	TATA	ORD	VND	3-Jun-2010	HPD	48	60	LP 1512 TC/59 BSII	01C62856903	MAT412081A0B07198	42
1583	RNC199	KL-15	8372	TATA	ORD		7-Jun-2010	HPD	48	60	LP 1512 TC/59 BSII	01C62856922	MAT412081A0C07203	42
1584	RNC215	KL-15	8382	TATA	ORD	VND	10-Jun-2010	HPD	48	60	LP 1512 TC/59 BSII	01C62862919	MB1PBEHEA0D08706	42
1585	RNM231	KL-15	8435	TATA	ORD	TK	6-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62855961	MAT412088A0C06572	56
1586	RNM232	KL-15	8436	TATA	ORD	TK	6-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62855219	MAT412088A0C06567	56
1587	RNM233	KL-15	8437	TATA	ORD	TK	6-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62855134	MAT412088A0C07132	56
1588	RNC267	KL-15	8439	TATA	ORD		6-Jul-2010	PVM	48	60	LP 1512 TC/59 BSII	01C62856923	MAT412088A0C07320	83
1589	RNC268	KL-15	8440	TATA	ORD	TK	6-Jul-2010	PVM	48	60	LP 1512 TC/59 BSII	01C62855133	MAT412088A0C07131	83
1590	RNA256	KL-15	8449	TATA	ORD	TK	7-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62856898	MAT412088A0C07205	56
1591	RNA257	KL-15	8450	TATA	ORD	TK	7-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62856963	MAT412088A0C07319	56
1592	RNM278	KL-15	8454	TATA	ORD	TK	8-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62862842	MAT412088A0D08550	56
1593	RNM279	KL-15	8455	TATA	ORD	TK	8-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62863039	MAT412088A0D08626	61
1594	RNM229	KL-15	8496	TATA	ORD		17-Jul-2010	EMLY	48	60	LP 1512 TC/59 BSIII	01C62856911	MAT412088A0C06841	95
1595	RNC394	KL-15	8652	TATA	ORD	SWB	20-Sep-2010	VKBN	48	60	CUMMINS 6BT 5.9	01C62862664	MAT412088A0D09399	29
1596	RNC395	KL-15	8659	TATA	ORD	SWB	23-Sep-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62863515	MAT412088A0D09400	56
1597	RNC466	KL-15	8754	TATA	ORD	SWB	28-Oct-2010	ALP	48	60	LP 1512 TC/59 BSII	01D62866067	MAT412266A0F09407	45
1598	RNC505	KL-15	8782	TATA	ORD	SWB	3-Nov-2010	CTLA	48	60	LP 1512 TC/59 BSII	01F62887774	MAT412266A0F11252	46
1599	RNC535	KL-15	8803	TATA	ORD	SWB	10-Nov-2010	NTA	48	60	LP 1512 TC/59 BSIII	01F62887761	MAT412088A0F11254	22

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1600	RNC669	KL-15	8942	TATA	ORD	SWB	29-Dec-2010	KLM	48	60	LP 1512 TC/59 BSIII	01J62925312	MAT412266A0J15790	34
1601	RNC670	KL-15	8945	TATA	ORD	VND	31-Dec-2010	ALP	48	60	LP 1512 TC/59 BSII	01J62930271	MAT412266A0J16479	45
1602	RNC750	KL-15	9043	TATA	ORD	SWB	21-Feb-2011	KLM	48	60	LP 1512 TC/59 BSIII	01J62930290	MAT412266A0J16476	34
1603	RT 844	KL-15	6022	TATA	ORD	VND	28-Jul-2005	CGNR	48	60	1512 TC CUMMINS	SOC62393011	412071C4Z109828	40
1604	RNA258	KL-15	8456	TATA	ORD	TK	8-Jul-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62862820	MAT412088A0C08546	62
1605	RAC661	KL-15	7837	TATA	ORD	SWB	27-Jun-2009	CTY	48	60	1512 TC LP 48 BSII TURBO INTER COOLER	90C62735234	CQZ 002941	28
1606	RAC662	KL-15	7848	TATA	ORD	SWB	2-Jul-2009	CTY	48	60	1512 TC LP 48 BSII TURBO INTER COOLER	62907386	CQZ 002990	28
1607	RAC663	KL-15	7849	TATA	ORD	SWB	2-Jul-2009	CHRY	48	60	1512 TC LP 48 BSII TURBO INTER COOLER	90C62735204	CQZ 002935	44
1608	RAM941	KL-15	8166	TATA	ORD		7-Jan-2010	CGNR	48	60	1512 TC TATA LP 1512	90F6275953Z	MAT41208190F09054	40
1609	RAM942	KL-15	8167	TATA	ORD		7-Jan-2010	CGNR	48	60	1512 TC TATA LP 1512	90F52759927	MAT41208190F09057	40
1610	RAM973	KL-15	8177	TATA	ORD		13-Jan-2010	EKM	48	60	1512 TC TATA LP 1512	90F62759525	MAT41208190F09051	56
1611	RAM974	KL-15	8193	TATA	ORD		28-Jan-2010	CHRY	48	60	1512 TC TATA LP 1512	90G62768365	MAT41208190G11183	44
1612	RNM136	KL-15	8360	TATA	ORD	VND	3-Jun-2010	ARND	48	60	LP 1512 TC/59 BSII	01C62854415	MAT412088A0B06161	19
1613	RR 15	KL-15	6193	TATA	ORD		18-May-2006	ATL	48	60	1512 TCIC BSII	60B62455648	CTZ 712763	33
1614	RAM282	KL-15	7478	TATA	ORD	VND	24-Feb-2009	EDT	48	60	1512 TCIC 412081-2RZ-019242	90A 62728242 TC	LRZ 019242	98
1615	RAA428	KL-15	7604	TATA	ORD	VND	1-Apr-2009	EDT	48	60	1512 TCIC	62871974	MRZ 020068	98
1616	RAA470	KL-15	7610	TATA	ORD	VND	6-Apr-2009	EDT	48	60	1512 TCIC	80M62726373 TC	AQZ 000164 412081	98
1617	RAM455	KL-15	7649	TATA	ORD	VND	23-Apr-2009	KNPY	48	60	LP 1512 TC/59 BSII	80K62717752	AQZ 000168	87
1618	RAM456	KL-15	7650	TATA	ORD	VND	23-Apr-2009	KNPY	48	60	LP 1512 TCIC/59 BSII	80M62726265	AQZ 000172	87
1619	RAM457	KL-15	7651	TATA	ORD	VND	23-Apr-2009	KNPY	48	60	1512 TC/59 BSII	90A62726433	AQZ 000298	87
1620	RNM 74	KL-15	8284	TATA	ORD		3-May-2010	VLND	48	60	LP 1512 TC/59 BSII	01A62831755	MAT412081A0B03010	20
1621	RNC142	KL-15	8307	TATA	ORD		10-May-2010	KNPY	48	60	LP 1512 TC/59 BSII	01B62841424	MAT412081A0B03631	87
1622	RNA427	KL-15	8657	TATA	ORD		22-Sep-2010	TSY	48	60	LP 1512 TC/59 BSIII	01G62907451	MAT412088A0G13674	73
1623	RNA428	KL-15	8658	TATA	ORD		23-Sep-2010	VKBN	48	60	LP 1512 TC/59 BSIII	01G62907448	MAT412088R0G13679	29
1624	RAM219	KL-15	7437	TATA	ORD	MLB	10-Feb-2009	ATL	48	60	1512 TCIC BSII		LRZ 019227	33
1625	RAM283	KL-15	7490	TATA	ORD	VND	26-Feb-2009	CDLM	48	60	1512 TCIC BSII	80K 62717504	LRZ 019234	80
1626	RAM284	KL-15	7491	TATA	ORD	VND	26-Feb-2009	CDLM	48	60	1512 TCIC BSII	80K 62714008	KRZ 018570	80
1627	RAA304	KL-15	7498	TATA	ORD	VND	28-Feb-2009	CDLM	48	60	1512 TCIC BSII	K62718847	LRZ 019305	80
1628	RAA471	KL-15	7621	TATA	ORD		15-Apr-2009	ALP	48	60	1512 TCIC BSII	412081	KQZ 000165	45
1629	RAC612	KL-15	7791	TATA	ORD	SWB	19-Jun-2009	CTY	48	60	1512 TCIC BSII	90C62735531	CQZ 002931	28
1630	RAC613	KL-15	7792	TATA	ORD	SWB	19-Jun-2009	KYLM	48	60	1512 TCIC BSII		412263 CQZ 002925	41
1631	RAC608	KL-15	7800	TATA	ORD	SWB	20-Jun-2009	CDLM	48	60	1512 TCIC BSII	90C62735267	CQZ 002927	80
1632	RAC644	KL-15	7827	TATA	ORD	SWB	25-Jun-2009	CDLM	48	60	1512 TCIC BSII	90C62735237	CQZ 002929	80
1633	RNM 91	KL-15	8299	TATA	ORD		6-May-2010	ATL	48	60	LP 1512 TC/59 BSII	01B62841374	MAT412081A0B03694	33
1634	RNM 92	KL-15	8301	TATA	ORD		7-May-2010	ATL	48	60	LP 1512 TC/59 BSII	01A62831747	MAT412081A0B03011	33
1635	RNA186	KL-15	8367	TATA	ORD		4-Jun-2010	CDLM	48	60	LP 1512 TC/59 BSIII	01A62830541	MAT412081A0B03390	80
1636	RNM517	KL-15	8836	TATA	ORD		22-Nov-2010	CDLM	48	60	LP 1512 TC/59 BSIII	01G62907366	MAT412088A0G13687	80
1637	RNC436	KL-15	8660	TATA	ORD	SWB	23-Sep-2010	EKM	48	60	LP 1512 TC/59 BSII	01E62884505	MAT412264A0F11043	56
1638	RNC545	KL-15	8822	TATA	ORD		18-Nov-2010	PVM	48	60	LP 1512 TC/59 BSII	01H62923186	MAT412088A0J15618	83
1639	RNC546	KL-15	8823	TATA	ORD		18-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62923506	MAT412088A0J15637	56
1640	RNC548	KL-15	8824	LL	ORD	TK	18-Nov-2010	EKM	48	60	1512 TS BSII	WAE120020Z	MB1PBEHC9AEWC3839	56
1641	RAC631	KL-15	7814	TATA	ORD	SWB	22-Jun-2009	PNR	48	60	1512/LP48 BSII TCIC		CQZ 002937	78
1642	RT 961	KL-15	6139	TATA	ORD		25-Mar-2006	ATL	48	60	1616 TC LPO	50A62382249	CUZ 002122	33
1643	RT 977	KL-15	6155	TATA	ORD		4-Apr-2006	KPM	48	60	1616 TCIC	40J62359597	CUZ 002187	91
1644	RNA254	KL-15	8411	TATA	ORD		28-Jun-2010	KNR	48	60	LP 1512 TC/59 BSIII	01C62855142	MAT412088A0C06902	77

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1645	RNC217	KL-15	8418	TATA	ORD		29-Jun-2010	KNR	48	60	LP 1512 TC/59 BSII	01C62854607	MB1PBEHEA0C07321	77
1646	RNC222	KL-15	8419	TATA	ORD		29-Jun-2010	KNR	48	60	LP 1512 TC/59 BSII	01C62857057	MB1PBEHEA0C06833	77
1647	RNM193	KL-15	8491	TATA	ORD	VND	16-Jul-2010	KNR	48	60	LP 1512 TC/59 BSII	01C62856831	MAT412088A0C07397	77
1648	RNC348	KL-15	8602	TATA	ORD		2-Sep-2010	VZM	48	60	LP 1512 TC/59 BSIII	01C62855141	MAT412088A0D09118	24
1649	RNC716	KL-15	8960	TATA	ORD	SWB	6-Jan-2011	ARND	48	60	LP 1512 TC/59 BSII	M62726212	MAT412266A0J16473	19
1650	RNM282	KL-15	8523	TATA	ORD		29-Jul-2010	KNR	48	60	LP 1512 TC/59 BSII	01C62862837	MAT412088A0D08747	77
1651	RNM283	KL-15	8533	TATA	ORD		3-Aug-2010	KNR	48	60	LP 1512 TC/59 BSII	01B62847455	MAT412088A0D08548	77
1652	RNC351	KL-15	8610	TATA	ORD	SWB	3-Sep-2010	KNR	48	60	LP 1512 TC/59 BSII	01C62862625	MAT412266A0D09403	77
1653	RNC390	KL-15	8638	TATA	ORD	SWB	15-Sep-2010	KNR	48	60	LP 1512 TC/59 BSII	01C62862624	MAT412088A0D09402	77
1654	RNC391	KL-15	8639	TATA	ORD	SWB	15-Sep-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62862680	MAT412088A0D09406	62
1655	RNC432	KL-15	8670	TATA	ORD	SWB	28-Sep-2010	PBVR	48	60	LP 1512 TC/59 BSII	01C62862639	MAT412088A0D09396	59
1656	RNC711	KL-15	8965	TATA	ORD	SWB	11-Jan-2011	MDY	48	60	LP 1512 TC/59 BSII	01J62930270	MAT412266A0J16472	76
1657	RNC713	KL-15	8997	TATA	ORD	SWB	27-Jan-2011	KNR	48	60	LP 1512 TC/59 BSII	01J62929474	MAT412266A0J16461	77
1658	RNC908	KL-15	9345	LL	ORD	SWB	13-Jan-2012	ARK	48	60	HINO 6ETI3K BSIII	BMEZ400543	MB1PCEYC3BENG5478	06
1659	RNC673	KL-15	9013	LL	ORD	SWB	5-Feb-2011	PLKD	48	60	6HETI BSII	MAE131346Z	MB1PCEHC5AEMD6465	69
1660	RNC672	KL-15	9014	LL	ORD	SWB	7-Feb-2011	PLKD	48	60	6HETI BSII	MAE131018Z	MB1PCEHC5AEMD6093	69
1661	RNC507	KL-15	8756	LL	ORD	SWB	28-Oct-2010	KGD	48	60	6HETI HINO	NAE129503Z	MAT4122662AEND4577	84
1662	RNC630	KL-15	8901	LL	ORD	VND	7-Dec-2010	PLKD	48	60	6HETI HINO BSII	MAE132351Z	MB1PBEHC5AEMD7490	69
1663	RAC564	KL-15	7726	LL	ORD		16-May-2009	TLY	48	60	ALPSN 4/100 W06ETI BSII	KXH 574126	KXE 672066	18
1664	RNE729	KL-15	9088	LL	ORD	SWB	21-Mar-2011	TDP	48	60	ALPSV 4/100 EURO BSII	MAE131344Z	MB1PBEHC7AEMD6466	53
1665	RAC527	KL-15	7701	LL	ORD	SWB	8-May-2009	VLND	48	60	ALPSV 4/100 HINO BSII	LXH 572248	LXE 669946	20
1666	RAC143	KL-15	7298	LL	ORD	SWB	23-Dec-2008	KKD	48	60	ALPSV 4/100 HINO W06ETI BSII	ZNE 1041047	ZNE 666530	72
1667	RAC478	KL-15	7625	LL	ORD	SWB	20-Apr-2009	MALA	48	60	ALPSV 4/100 HINO W06ETI BSII	LXH 572141	LXE 669780	85
1668	RAC 29	KL-15	7188	LL	ORD	SWB	22-Sep-2008	RNI	48	60	ALPSV 4/100 VIKING BSII	FNE 101605Z	FNE 656747	101
1669	RAC 24	KL-15	7175	LL	ORD	SWB	8-Sep-2008	PNR	48	60	ALPSV 4/100 VIKING BSII W06ETI HINO EURO	FNH 545619	FNE 657033	78
1670	RAC111	KL-15	7262	LL	ORD	SWB	5-Dec-2008	KMY	48	60	HINO EURO II	ZNE 104034Z	ZNE 666224	05
1671	RAC114	KL-15	7273	LL	ORD	SWB	12-Dec-2008	KNPY	48	60	ALPSV 4/100 VIKING HINO W06ETI BSII	ZNE 104019Z	ZNE 666204	87
1672	RAC544	KL-15	7706	LL	ORD	SWB	8-May-2009	PNR	48	60	ALPSV 4/100 W06ETI BSII HINO EURO	LXH 573688	LXE 670714	78
1673	RAC 36	KL-15	7195	LL	ORD	MLB	3-Oct-2008	ARND	48	60	ALPSV 4/100 W06ETI BSII	HX 1034	JNE 654652	19
1674	RAC 35	KL-15	7212	LL	ORD		18-Oct-2008	KTP	48	60	ALPSV 4/100 W06ETI BSII	FNH 548623	JNE 654719	14
1675	RAC 38	KL-15	7226	LL	ORD	SWB	12-Nov-2008	ANK	48	60	ALPSV 4/100 W06ETI BSII	FNH 548382	FNE 656783	57
1676	RAC 37	KL-15	7234	LL	ORD	SWB	21-Nov-2008	PKD	48	60	ALPSV 4/100 W06ETI BSII	FNH 548686	FNE 657224	65
1677	RAC353	KL-15	7507	LL	ORD	VND	2-Mar-2009	ARND	48	60	ALPSV 4/100 W06ETI BSII	LXH 573104	XNE 667896	19
1678	RAC354	KL-15	7508	LL	ORD	VND	2-Mar-2009	KTR	48	60	ALPSV 4/100 W06ETI BSII	XNE 104897Z	NXE 668408	35
1679	RAC335	KL-15	7509	LL	ORD	MLB	2-Mar-2009	KTP	48	60	ALPSV 4/100 W06ETI BSII	NXH 571569	XNE 667939	14
1680	RAC357	KL-15	7510	LL	ORD	MLB	2-Mar-2009	KGD	48	60	ALPSV 4/100 W06ETI BSII	XNE 104887Z	NXE 668396	84
1681	RAC362	KL-15	7511	LL	ORD	MLB	2-Mar-2009	KTR	48	60	ALPSV 4/100 W06ETI BSII	ZNE 104007Z	ZNE 666170	35
1682	RAC369	KL-15	7513	LL	ORD		4-Mar-2009	KGD	48	60	ALPSV 4/100 W06ETI BSII	TPH 501990	NXE 668466	84
1683	RAC371	KL-15	7515	LL	ORD		5-Mar-2009	KGD	48	60	ALPSV 4/100 W06ETI BSII	XNE 104809Z	NXE 668405	84
1684	RAC370	KL-15	7516	LL	ORD		6-Mar-2009	PNR	48	60	ALPSV 4/100 W06ETI BSII	BNH 568368	NXE 668471	78
1685	RAC372	KL-15	7522	LL	ORD		7-Mar-2009	KHD	48	60	ALPSV 4/100 W06ETI BSII	XNE 104888Z	NXE 668393	106
1686	RAC376	KL-15	7524	LL	ORD		7-Mar-2009	KHD	48	60	ALPSV 4/100 W06ETI BSII	XNE 104899Z	NXE 668464	106
1687	RAC375	KL-15	7526	LL	ORD	MLB	9-Mar-2009	KGD	48	60	ALPSV 4/100 W06ETI BSII	XNE 104956Z	NXE 668475	84
1688	RAC378	KL-15	7527	LL	ORD	MLB	9-Mar-2009	KHD	48	60	ALPSV 4/100 W06ETI BSII	XNE 104910Z	NXE 668406	106
1689	RAC377	KL-15	7528	LL	ORD	MLB	11-Mar-2009	TLY	48	60	ALPSV 4/100 W06ETI BSII	XNE 104891Z	NXE 668402	18

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1690	RAC380	KL-15	7529	LL	ORD	MLB	11-Mar-2009	PPD	48	60	ALPSV 4/100 W06ETI BSII	XNE 104906Z	NXE 668394	26
1691	RAC292	KL-15	7443	LL	ORD	MLB	12-Feb-2009	KHD	48	60	ALPSV 4/100 W06ETI BSII	ZNE 104341Z	ZNE 667233	106
1692	RAM129	KL-15	7438	LL	ORD	MLB	10-Feb-2009	SBY	48	60	ALPSV 4/100 W06ETI BSII	BNE 103608Z	BNE 665277	75
1693	RAC382	KL-15	7543	LL	ORD		16-Mar-2009	NTA	48	60	ALPSV 4/100 W06ETI BSII	XNE 104892Z	NXE 668304	22
1694	RAC543	KL-15	7705	LL	ORD	SWB	8-May-2009	PNR	48	60	ALPSV 4/100 W06ETI BSII	KXH 574430	LXE 671551	78
1695	RAE466	KL-15	7618	LL	ORD		15-Apr-2009	NTA	48	60	ALPSV 4/100 W06ETI BSII	NXE 105295Z	NXE 669246	22
1696	RAE467	KL-15	7619	LL	ORD		15-Apr-2009	ARND	48	60	ALPSV 4/100 W06ETI BSII	10VHC 3025	LXE 669643	19
1697	RAE468	KL-15	7637	LL	ORD		20-Apr-2009	KTDA	48	60	ALPSV 4/100 W06ETI BSII	LXE 105518Z	LXE 669644	25
1698	RAE434	KL-15	7609	LL	ORD		4-Apr-2009	PNR	48	60	ALPSV 4/100 W06ETI BSII	NXE105272Z	NXE 669213	78
1699	RAC601	KL-15	7772	LL	ORD		1-Jun-2009	TLY	48	60	ALPSV 4/100 W06ETI BSII	KXH 574634	KXE 672098	18
1700	RAC602	KL-15	7773	LL	ORD		1-Jun-2009	TLY	48	60	ALPSV 4/100 W06ETI BSII	LXH 573275	LXE 670268	18
1701	RAE947	KL-15	8136	LL	ORD	MLB	19-Dec-2009	PNR	48	60	ALPSV 4/100 W06ETI BSII	YXE 112980Z	MB1PBEHC69EYB2850	78
1702	RNC 12	KL-15	8199	LL	ORD		3-Feb-2010	PKDA	48	60	ALPSV 4/100 W06ETI BSII	YXE 113124Z	EYB 3104	81
1703	RNM 6	KL-15	8205	LL	ORD		17-Feb-2010	TLY	48	60	ALPSV 4/100 W06ETI BSII	WXE114147Z	MB1PBEMCX39EWB4582	18
1704	RNE 27	KL-15	8206	LL	ORD		19-Feb-2010	KGD	48	60	ALPSV 4/100 W06ETI BSII	ZXE110992Z	MB1PBEH09EZA9509	84
1705	RNC 13	KL-15	8207	LL	ORD		19-Feb-2010	KGD	48	60	ALPSV 4/100 W06ETI BSII	WXE 114704Z	EWB 5538	84
1706	RNC 16	KL-15	8208	LL	ORD		19-Feb-2010	KHD	48	60	ALPSV 4/100 W06ETI BSII	WXE 114727Z	EWB 5536	106
1707	RNC 17	KL-15	8209	LL	ORD		19-Feb-2010	KGD	48	60	ALPSV 4/100 W06ETI BSII	WXE 114699Z	EWB 5438	84
1708	RNC 18	KL-15	8210	LL	ORD		19-Feb-2010	PKDA	48	60	ALPSV 4/100 W06ETI BSII	WXE 114853Z	EWB 5674	81
1709	RNK306	KL-15	8631	LL	ORD		15-Sep-2010	KGD	48	60	ALPSV 4/100 W06ETI BSII	WAE120611Z	MB1PBEHC7AEVC4615	84
1710	RNK366	KL-15	8632	LL	ORD		15-Sep-2010	KGD	48	60	ALPSV 4/100 W06ETI BSII	WAH614448	MB1PBEHC8AEWC3931	84
1711	RT 364	KL-15	5542	LL	ORD		2-Aug-2004	CTY	48	60	ALPSV 4/19 HINO W06E BSI	SWH 267467	PWA 043172	28
1712	RT 577	KL-15	5755	LL	ORD		24-Dec-2004	CTY	48	60	ALPSV 4/19 HINO W06E BSI	SWH 265394	KWA 045110	28
1713	RT 584	KL-15	5762	LL	ORD		1-Jan-2005	CTY	48	60	ALPSV 4/19 HINO W06E BSI	MWH 276991	KWA 045126	28
1714	RT 712	KL-15	5890	LL	ORD	VND	2-May-2005	ARK	48	60	ALPSV 4/19 HINO W06E BSII	JBH 1142583	DWA 046523	06
1715	RT 715	KL-15	5893	LL	ORD	VND	2-May-2005	ARK	48	60	ALPSV 4/19 HINO W06E BSII	XVH 247801	WDA 047254	06
1716	RT 78	KL-15	5256	LL	ORD		5-Mar-2004	CTY	48	60	ALPSV 4/19 HINO W06EI	HB 11108	WVH 251743	28
1717	RT 23	KL-15	5201	LL	ORD		6-Feb-2004	CTY	48	60	ALPSV 4/19 HINO W06ETI	YBH 153020	WVE 518569	28
1718	RRE575	KL-15	6740	LL	ORD		10-Mar-2008	CHRY	48	60	ALPSV 4/89	NPH 506947	NPE 640909	44
1719	RAK 39	KL-15	7209	LL	ORD		15-Oct-2008	KMR	48	60	ALPSV 4/89	JNH 541721	JNE 654623	30
1720	RAK 41	KL-15	7220	LL	ORD		4-Nov-2008	PSL	48	60	ALPSV 4/89	KNH 534610	JNE 654633	21
1721	RAM215	KL-15	7567	LL	ORD		25-Mar-2009	GVR	48	60	ALPSV 4/89 BSII	ZNE 103991Z	ZNE 666244	66
1722	RNC227	KL-15	8407	LL	ORD	SWB	23-Jun-2010	PPD	48	60	ALPSV 4/89 BSII	VAE 122551Z	MB1PCEHEXAEVC7358	26
1723	RNC603	KL-15	8843	LL	ORD		22-Nov-2010	EKM	48	60	ALPSV 4/89 BSII	MAE132284Z	MB1PBEHC8AEMD7418	56
1724	RNC308	KL-15	8524	LL	ORD	SWB	29-Jul-2010	PKD	48	60	ALPSV 4/89 EINO EURO BSII TI	VAE122558Z	MB1PCEHC1AEVC7359	65
1725	RRC707	KL-15	6854	LL	ORD		10-Apr-2008	KTR	48	60	HINO BSII	LNH 100234Z	LNE 648587	35
1726	RAC 54	KL-15	7210	LL	ORD		15-Oct-2008	PSL	48	60	ALPSV 4/89 HINO BSII	JNH 540638	JNE 654569	21
1727	RNA 24	KL-15	8197	LL	ORD	VND	1-Feb-2010	TDP	48	60	ALPSV 4/89 HINO BSII VIKING	WXE 114603Z	MB1PBEH99EWB5512	53
1728	RAC325	KL-15	7482	LL	ORD	VND	24-Feb-2009	NBR	48	60	ALPSV 4/89 HINO EURO BSII	ZNE 104460Z	XNE 667919	86
1729	RAC583	KL-15	7728	LL	ORD		16-May-2009	PNR	48	60	ALPSV 4/89 HINO EURO BSII	LXE 105501Z	LXE 670037	78
1730	RNC 20	KL-15	8212	LL	ORD	MLB	19-Feb-2010	PNR	48	60	ALPSV 4/89 HINO EURO BSII	WXE 114856Z	EWB 5655	78
1731	RNC 21	KL-15	8213	LL	ORD	MLB	19-Feb-2010	PNR	48	60	ALPSV 4/89 HINO EURO BSII	WXE 114852Z	EWB 5656	78
1732	RAK 40	KL-15	7214	LL	ORD		23-Oct-2008	MDY	48	60	ALPSV 4/89 HINO EURO II	JNH 541998	JNE 654594	76
1733	RAC701	KL-15	7893	LL	ORD		14-Aug-2009	TDP	48	60	ALPSV 4/89 HINO EURO II INTER COOLER(TURBO)	KXH 574913		53

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1734	RRC416	KL-15	6585	LL	ORD	VND	29-Jan-2008	VLRD	48	60	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	TPH 498768	TPE 637328	93
1735	RRC800	KL-15	6968	LL	ORD		16-May-2008	ADR	48	60	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	MNE 100069Z	LNE 648568	38
1736	RRC799	KL-15	6957	LL	ORD		13-May-2008	EMLY	48	60	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	LNH 526713	LNE 648564	95
1737	RAC702	KL-15	7895	LL	ORD		17-Aug-2009	KGD	48	60	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	KXH 574293	KXE 672068	84
1738	RAC718	KL-15	7896	LL	ORD		17-Aug-2009	KGD	48	60	ALPSV 4/89 HINO EURO II TURBO INTER COOLER	NXH 571575	NXE 669323	84
1739	RAC410	KL-15	7574	LL	ORD	MLB	26-Mar-2009	MPM	48	60	ALPSV 4/89 HINO EUROII TI	LXH 572322	DE 652007	71
1740	RAC436	KL-15	7575	LL	ORD	MLB	26-Mar-2009	MPM	48	60	ALPSV 4/89 HINO EUROII TI	LXH 572738	LXE 669872	71
1741	RAC435	KL-15	7582	LL	ORD	MLB	28-Mar-2009	MPM	48	60	ALPSV 4/89 HINO EUROII TI	LXH 572757	LXE 669881	71
1742	RAC437	KL-15	7583	LL	ORD	MLB	28-Mar-2009	MPM	48	60	ALPSV 4/89 HINO EUROII TI	LXH 572221	DE 670024	71
1743	RNC 10	KL-15	8187	LL	ORD		21-Jan-2010	TDP	48	60	ALPSV 4/89 HINO EUROII TIC	YXE 113143Z	EYB 3137	53
1744	RNC 11	KL-15	8188	LL	ORD		23-Jan-2010	TDP	48	60	ALPSV 4/89 HINO EUROII TIC	WXE 113984Z	EWB 4436	53
1745	RRC723	KL-15	6896	LL	ORD	VND	21-Apr-2008	CDLM	48	60	ALPSV 4/89 HINO W06 BSII	LNH 100246Z	LNE 648565	80
1746	RRC722	KL-15	6878	LL	ORD		16-Apr-2008	KMGH	48	60	ALPSV 4/89 HINO W06 BSII	LNH 524053	LNE 647785	55
1747	RRC499	KL-15	6655	LL	ORD	VND	16-Feb-2008	PLR	48	60	ALPSV 4/89 HINO W06E BSII	NPH 505699	NPE 640750	36
1748	RRC861	KL-15	7023	LL	ORD		7-Jun-2008	PTPM	48	60	ALPSV 4/89 HINO W06E BSII	XPH 475030	JNE 653339	15
1749	RRC860	KL-15	7026	LL	ORD	VND	10-Jun-2008	PSL	48	60	ALPSV 4/89 HINO W06E BSII	KNH 534996	JNE 652998	21
1750	RRC862	KL-15	7027	LL	ORD		10-Jun-2008	MKD	48	60	ALPSV 4/89 HINO W06E BSII	KNH 535251	JNE 653205	08
1751	RRC857	KL-15	7007	LL	ORD	VND	2-Jun-2008	ARND	48	60	ALPSV 4/89 HINO W06E BSII	KNH 535451	WNE 653414	19
1752	RRC859	KL-15	7020	LL	ORD		4-Jun-2008	PNKM	48	60	ALPSV 4/89 HINO W06E BSII TURBO INTER COOLER	KNH 535452	JNE 653415	49
1753	RRC938	KL-15	7143	LL	ORD		21-Aug-2008	KMGH	48	60	ALPSV 4/89 HINO W06ETI BS II	JNH 543981	JNE 655512	55
1754	RRC780	KL-15	6946	LL	ORD		8-May-2008	KHD	48	60	ALPSV 4/89 HINO W06ETI BSII	LNH 526738	LNE 648567	106
1755	RRC871	KL-15	7030	LL	ORD		11-Jun-2008	SBY	48	60	ALPSV 4/89 HINO W06ETI BSII	KNH535399	JNE653338	75
1756	RRC873	KL-15	7037	LL	ORD		16-Jun-2008	PTPM	48	60	ALPSV 4/89 HINO W06ETI BSII	KNH 532645	KNE 652864	15
1757	RRC874	KL-15	7036	LL	ORD		16-Jun-2008	MNR	48	60	ALPSV 4/89 HINO W06ETI BSII	ZNE 104038Z	JNE 653379	60
1758	RRC872	KL-15	7032	LL	ORD		12-Jun-2008	ETPA	48	60	ALPSV 4/89 HINO W06ETI BSII	KNH 534760	KNE 652987	48
1759	RRC937	KL-15	7097	LL	ORD		25-Jul-2008	KTR	48	60	ALPSV 4/89 HINO W06ETI BSII	JNH 543980	JNE 655510	35
1760	RRC940	KL-15	7148	LL	ORD	VND	26-Aug-2008	KTR	48	60	ALPSV 4/89 HINO W06ETI BSII	JNH 543983	JNE 655511	35
1761	RRC939	KL-15	7174	LL	ORD	VND	8-Sep-2008	PNKM	48	60	ALPSV 4/89 HINO W06ETI BSII	JNH 544078	JNE 655626	49
1762	RAC264	KL-15	7432	LL	ORD		7-Feb-2009	KNI	48	60	ALPSV 4/89 HINO W06ETI BSII	ZNE 104425Z	YNE 667353	107
1763	RAE278	KL-15	7446	LL	ORD		16-Feb-2009	TDP	48	60	ALPSV 4/89 HINO W06ETI BSII	ZNE 104333Z	YNE 667560	53
1764	RAE401	KL-15	7579	LL	ORD		20-Apr-2009	MPM	48	60	ALPSV 4/89 HINO W06ETI BSII		NXE 669055	71
1765	RRC744	KL-15	6911	LL	ORD	VND	24-Apr-2008	KHD	48	60	ALPSV 4/89 HINO W06FTI BSII TURBO INTER COOLER	LNE 1002312	LNE 648566	106
1766	RRC743	KL-15	6907	LL	ORD		23-Apr-2008	TSY	48	60	ALPSV 4/89 HINO W06FTI BSII	LNH 524112	LNE 647881	73
1767	RRK276	KL-15	6448	LL	ORD	MLB	19-Dec-2007	TSY	48	60	ALPSV 4/89 VIKING	WPH 480995	WPE 628376	73
1768	RRK277	KL-15	6474	LL	ORD	VND	28-Dec-2007	PTA	48	60	ALPSV 4/89 VIKING	XPH 474914	WPE 628491	37
1769	RRK319	KL-15	6487	LL	ORD	MLB	31-Dec-2007	VDA	48	60	ALPSV 4/89 VIKING	WPH 482574	WPE 628655	92
1770	RRK333	KL-15	6520	LL	ORD	MLB	10-Jan-2008	KHD	48	60	ALPSV 4/89 VIKING	UPH 487155	VPE 633304	106
1771	RRK334	KL-15	6532	LL	ORD	MLB	14-Jan-2008	VDA	48	60	ALPSV 4/89 VIKING	UPH 489426	VPE 633303	92

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1772	RRK335	KL-15	6540	LL	ORD	MLB	16-Jan-2008	TLY	48	60	ALPSV 4/89 VIKING	UPH 489294	VPE 633308	18
1773	RRK388	KL-15	6573	LL	ORD	MLB	25-Jan-2008	NBR	48	60	ALPSV 4/89 VIKING	UPH 496383	UPE 634369	86
1774	RRK389	KL-15	6583	LL	ORD	MLB	28-Jan-2008	NBR	48	60	LXH 573312 LL BSII	UPH 496340	UPE 634368	86
1775	RRK387	KL-15	6562	LL	ORD	MLB	22-Jan-2008	SBY	48	60	ALPSV 4/89 VIKING	UPH492867	UPE634264	75
1776	RRK453	KL-15	6597	LL	ORD	MLB	31-Jan-2008	NBR	48	60	ALPSV 4/89 VIKING	NPH 506579	NPE 639543	86
1777	RRK552	KL-15	6709	LL	ORD	VND	1-Mar-2008	MPM	48	60	ALPSV 4/89 VIKING	TPH 499157	TPE 637605	71
1778	RRK558	KL-15	6710	LL	ORD		1-Mar-2008	PSL	48	60	ALPSV 4/89 VIKING BS11	PNH 512166	PNE 642315	21
1779	RRK523	KL-15	6658	LL	ORD	VND	18-Feb-2008	NPR	48	60	ALPSV 4/89 VIKING	TPH 498862	TPE 637115	62
1780	RRK570	KL-15	6729	LL	ORD		7-Mar-2008	ETPA	48	60	ALPSV 4/89 VIKING	NPH 508715	NPE 640740	48
1781	RRK574	KL-15	6765	LL	ORD	MLB	17-Mar-2008	TPLM	48	60	ALPSV 4/89 VIKING	NPH 507652	NPE 639576	94
1782	RRK571	KL-15	6731	LL	ORD		10-Mar-2008	EDT	48	60	ALPSV 4/89 VIKING LL BSII	YNE 104602Z	UPE 635630	98
1783	RRK629	KL-15	6826	LL	ORD	VND	1-Apr-2008	CDLM	48	60	ALPSV 4/89 VIKING	00266222	NPH 00266222	80
1784	RRK569	KL-15	6835	LL	ORD		2-Apr-2008	TVL	48	60	ALPSV 4/89 VIKING	PNH 512294	PNE 642428	43
1785	RRK457	KL-15	6887	LL	ORD	MLB	18-Apr-2008	GVR	48	60	ALPSV 4/89 VIKING	MNH 522347	MNE 646544	66
1786	RRK634	KL-15	6871	LL	ORD	MLB	15-Apr-2008	MPM	48	60	ALPSV 4/89 VIKING	PNH 513729	PNE 643830	71
1787	RRK757	KL-15	6934	LL	ORD	MLB	3-May-2008	SBY	48	60	ALPSV 4/89 VIKING	NPH505693	NPE640854	75
1788	RRK758	KL-15	6941	LL	ORD	VND	6-May-2008	CDLM	48	60	ALPSV 4/89 VIKING	LLH 524052	LNE 647784	80
1789	RRK759	KL-15	6945	LL	ORD	VND	8-May-2008	ANK	48	60	ALPSV 4/89 VIKING	LNH 524110	LNE 647873	57
1790	RRK630	KL-15	6852	LL	ORD	MLB	9-Apr-2008	TLY	48	60	ALPSV 4/89 VIKING HINO BSIII	NPH 505698	NPE 640860	18
1791	RRK761	KL-15	6960	LL	ORD		14-May-2008	PLKD	48	60	ALPSV 4/89 VIKING	LNH 527487	LNE 647843	69
1792	RRK806	KL-15	6969	LL	ORD		17-May-2008	NBR	48	60	ALPSV 4/89 VIKING	ZVH 240695	LNE 647830	86
1793	RRK835	KL-15	7029	LL	ORD	MLB	10-Jun-2008	MKD	48	60	ALPSV 4/89 VIKING	KNH 533478	KNE 651445	08
1794	RRK760	KL-15	6951	LL	ORD		12-May-2008	TSY	48	60	ALPSV 4/89 VIKING	LNH 524104	LNE 647842	73
1795	RRK903	KL-15	7071	LL	ORD	MLB	1-Jul-2008	KPA	48	60	ALPSV 4/89 VIKING	JNH 540066	JNE 653954	74
1796	RRK904	KL-15	7072	LL	ORD	MLB	1-Jul-2008	MKD	48	60	ALPSV 4/89 VIKING	JNH 540094	JNE 653953	08
1797	RRK832	KL-15	7103	LL	ORD		31-Jul-2008	KMR	48	60	ALPSV 4/89 VIKING	KNH 533699	KNE 651598	30
1798	RRK948	KL-15	7141	LL	ORD		18-Aug-2008	NBR	48	60	ALPSV 4/89 VIKING	JNH 543085	JNE 655548	86
1799	RRK984	KL-15	7162	LL	ORD	MLB	1-Sep-2008	CTY	48	60	ALPSV 4/89 VIKING	JNH 542060	JNE 654591	28
1800	RAK 18	KL-15	7187	LL	ORD	MLB	22-Sep-2008	MKD	48	60	HINO EURO II	ONH 541614	ONE 654622	08
1801	RAK 21	KL-15	7192	LL	ORD	VND	30-Sep-2008	VJMD	48	60	ALPSV 4/89 VIKING	JNH 541722	JNE 654630	16
1802	RRK983	KL-15	7181	LL	ORD		15-Sep-2008	NBR	48	60	ALPSV 4/89 VIKING	JNH 544064	JNE 655625	86
1803	RRK981	KL-15	7180	LL	ORD		15-Sep-2008	EKM	48	60	LL HINO BSII	JNH 540221	JNE 654250	56
1804	RAA198	KL-15	7385	LL	ORD		21-Jan-2009	NBR	48	60	ALPSV 4/89 VIKING	ZNH 567000	ZNE 666765	86
1805	RNK234	KL-15	8444	LL	ORD	TK	7-Jul-2010	EKM	48	60	ALPSV 4/89 VIKING	VAE121428Z	MB1PBEHC3AEVC5745	56
1806	RNK236	KL-15	8445	LL	ORD	TK	7-Jul-2010	EKM	48	60	ALPSV 4/89 VIKING	VAE121703Z	MB1PBEHC8AEVC6406	56
1807	RNK237	KL-15	8446	LL	ORD	TK	7-Jul-2010	EKM	48	60	ALPSV 4/89 VIKING	VAE121833Z	MB1PBEHC0AEVC6366	56
1808	RNK238	KL-15	8447	LL	ORD	TK	7-Jul-2010	EKM	48	60	ALPSV 4/89 VIKING	VAE121542Z	MB1PBEHC4AEVC5883	56
1809	RNK239	KL-15	8448	LL	ORD	TK	7-Jul-2010	NPR	48	60	ALPSV 4/89 VIKING	VAE121846Z	MB1PBEHC3AEVC6359	62
1810	RNE270	KL-15	8461	LL	ORD	TK	8-Jul-2010	EKM	48	60	ALPSV 4/89 VIKING	VAE121697Z	MB1PBEHC4AEVC6130	56
1811	RNE271	KL-15	8462	LL	ORD	TK	8-Jul-2010	EKM	48	60	ALPSV 4/89 VIKING	VAE121648Z	MB1PBEHC4AEVC6081	56
1812	RNE272	KL-15	8468	LL	ORD	TK	8-Jul-2010	ALV	48	60	ALPSV 4/89 VIKING	VAE121545Z	MB1PBEHC3AEVC5888	61
1813	RNE273	KL-15	8480	LL	ORD	TK	12-Jul-2010	ALV	48	60	ALPSV 4/89 VIKING	WAE119843Z	MB1PBEHC0AEVC3602	61
1814	RNE274	KL-15	8481	LL	ORD	TK	12-Jul-2010	ALV	48	60	ALPSV 4/89 VIKING	VAE121645Z	MB1PBEHC4AEVC6080	61
1815	RNE417	KL-15	8679	LL	ORD	TK	1-Oct-2010	ALV	48	60	ALPSV 4/89 VIKING	NAE130300Z	MB1PBEHC5AEND5424	61
1816	RRK632	KL-15	6844	LL	ORD	VND	5-Apr-2008	EDT	48	60	ALPSV 4/89 VIKING LL BS II	PNH 511621	PNE 643800	98

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1817	RRK753	KL-15	6926	LL	ORD		30-Apr-2008	NTA	48	60	ALPSV 4/89 VIKING BSII	LNE 100235Z	LNE 648512	22
1818	RRK809	KL-15	6989	LL	ORD	VND	23-May-2008	MLPY	48	60	ALPSV 4/89 VIKING BSII	LNH 526701	LNE 648563	96
1819	RRK808	KL-15	6985	LL	ORD	VND	22-May-2008	MLPY	48	60	ALPSV 4/89 VIKING BSII	LNH 524872	LNE 648672	96
1820	RRK839	KL-15	6997	LL	ORD	VND	27-May-2008	MLPY	48	60	ALPSV 4/89 VIKING BSII	KNH 532145	KNE 651774	96
1821	RRK834	KL-15	7021	LL	ORD	VND	7-Jun-2008	MLPY	48	60	ALPSV 4/89 VIKING BSII	KNE 100647Z	KNE 651775	96
1822	RRK907	KL-15	7106	LL	ORD	VND	5-Aug-2008	NTA	48	60	ALPSV 4/89 VIKING BSII	JNH 541709	JNE 653987	22
1823	RRK332	KL-15	6513	LL	ORD	MLB	8-Jan-2008	SBY	48	60	ALPSV 4/89 VIKING BSII W06ETI	UPH	VPE 633302	75
1824	RNE767	KL-15	9102	LL	ORD	SWB	25-Mar-2011	CLDY	48	60	ALPSV 4/100 VIKING E II EURO BS II	NAE129505Z	MB1PBEHC6AEND4579	58
1825	RRK906	KL-15	7088	LL	ORD		19-Jul-2008	KMY	48	60	ALPSV 4/89 VIKING HENO II	JNH 541670	JNE 653941	05
1826	RRK836	KL-15	7033	LL	ORD		13-Jun-2008	PNKM	48	60	ALPSV 4/89 VIKING HINO BSII	KNE 100643Z	KNE 651675	49
1827	RRC754	KL-15	6940	LL	ORD	MLB	6-May-2008	SBY	48	60	ALPSV 4/89 VIKING HINO EURO 12 W06ETI	LNH 100243Z	LNE 648611	75
1828	RRK455	KL-15	6880	LL	ORD	MLB	16-Apr-2008	KTP	48	60	ALPSV 4/89 VIKING HINO EURO BSII	PNH 515866	PNE 644249	14
1829	RRK789	KL-15	7084	LL	ORD		10-Jul-2008	VLRD	48	60	ALPSV 4/89 VIKING HINO EURO BSII	PNH 514140	PNE 642385	93
1830	RAK 42	KL-15	7221	LL	ORD		4-Nov-2008	TSR	48	60	ALPSV 4/89 VIKING HINO EURO BSII	JNH 538895	JNE 654653	63
1831	RAE946	KL-15	8133	LL	ORD		16-Dec-2009	PNR	48	60	ALPSV 4/89 VIKING HINO EURO BSII		MB1PBECHO9EZE0210	78
1832	RRK512	KL-15	6656	LL	ORD	VND	16-Feb-2008	ARND	48	60	ALPSV 4/89 VIKING HINO EURO II	CNH 560723	TPE 637635	19
1833	RRK534	KL-15	6674	LL	ORD	MLB	23-Feb-2008	PNR	48	60	ALPSV 4/89 VIKING HINO EURO II	NPH 507659	NPE 639577	78
1834	RRK274	KL-15	6439	LL	ORD	VND	14-Dec-2007	CGNR	48	60	ALPSV 4/89 VIKING HINO EURO II TURBO IC	WPH 480995	WPE 628376	40
1835	RRK454	KL-15	6870	LL	ORD	MLB	15-Apr-2008	MPM	48	60	ALPSV 4/89 VIKING HINO EUROII	MNH 522230	MNE 646543	71
1836	RRC751	KL-15	6913	LL	ORD		25-Apr-2008	KNR	48	60	ALPSV 4/89 VIKING HINO EUROII TI	BPH 456503	LNE 647853	77
1837	RRK807	KL-15	6974	LL	ORD	MLB	19-May-2008	SBY	48	60	ALPSV 4/89 VIKING HINO W06ETI	LNH 524105	LNE 647840	75
1838	RAK 17	KL-15	7185	LL	ORD		19-Sep-2008	KMGM	48	60	ALPSV 4/89 VIKING HINO W06ETI BSII	JNH 542233	JNE 654698	55
1839	RRK456	KL-15	6897	LL	ORD		21-Apr-2008	KNR	48	60	ALPSV 4/89 W06ETI BSII	PNH 513730	PNE 643829	77
1840	RRC840	KL-15	6994	LL	ORD		27-May-2008	PNR	48	60	ALPSV 4/89 W06ETI BSII	KNH 534764	KNE 652866	78
1841	RRC841	KL-15	6995	LL	ORD	VND	27-May-2008	VJMD	48	60	ALPSV 4/89 W06ETI BSII	KNH 534855	KNE 652874	16
1842	RRC843	KL-15	7000	LL	ORD		28-May-2008	TSY	48	60	ALPSV 4/89 W06ETI BSII	KNH 538141	KNE 652988	73
1843	RRC844	KL-15	7004	LL	ORD		2-Jun-2008	TSY	48	60	ALPSV 4/89 W06ETI BSII	KNH 534853	JNE 652992	73
1844	RRC847	KL-15	7006	LL	ORD	VND	2-Jun-2008	MLTM	48	60	ALPSV 4/89 W06ETI BSII	KNH 538142	JNE 652993	54
1845	RRC957	KL-15	7117	LL	ORD		11-Aug-2008	VZM	48	60	ALPSV 4/89 W06ETI BSII	8PE017179	MNE 644686	24
1846	RRC958	KL-15	7118	LL	ORD		11-Aug-2008	KTM	48	60	ALPSV 4/89 W06ETI BSII	MNH 519486	MNE 644687	47
1847	RRC960	KL-15	7120	LL	ORD		11-Aug-2008	KLM	48	60	ALPSV 4/89 W06ETI BSII	PNH 516779	MNE 644703	34
1848	RAE 68	KL-15	7284	LL	ORD		17-Dec-2008	TSY	48	60	ALPSV 4/89 W06ETI BSII HINO	BNE 102721Z	CNE 663479	73
1849	RRC952	KL-15	7110	LL	ORD		11-Aug-2008	SBY	48	60	ALPSV 4/89 W06FTI BSII	MNH 519948	MNE 645167	75
1850	RRC953	KL-15	7112	LL	ORD		11-Aug-2008	PNR	48	60	ALPSV 4/89 W06FTI BSII	MNH 519847	MNE 645037	78
1851	RRC954	KL-15	7113	LL	ORD		11-Aug-2008	KTM	48	60	ALPSV 4/89 W06FTI BSII	MNH 518156	MNE 645193	47
1852	RRC955	KL-15	7114	LL	ORD		11-Aug-2008	PNR	48	60	ALPSV 4/89 W06FTI BSII	MNH 518355	MNE 645038	78
1853	RRC959	KL-15	7119	LL	ORD		11-Aug-2008	VDA	48	60	ALPSV 4/89 W06FTI BSII	PNH 516770	MNE 644701	92
1854	RRC962	KL-15	7123	LL	ORD		11-Aug-2008	KKLM	48	60	ALPSV 4/89 W06ETI BSII	MNH 519572	MNE 644763	108
1855	RRC970	KL-15	7124	LL	ORD		11-Aug-2008	PBVR	48	60	ALPSV 4/89 W06ETI BSII	MNH 519579	MNE 644805	59
1856	RRC973	KL-15	7125	LL	ORD		11-Aug-2008	PNKM	48	60	ALPSV 4/89 W06FTI BSII	MNH 519640	MNE 644838	49
1857	RRC965	KL-15	7126	LL	ORD		11-Aug-2008	ARND	48	60	ALPSV 4/89 W06FTI BSII	VPH 00488298	MNE 645010	19
1858	RRC971	KL-15	7127	LL	ORD		11-Aug-2008	KTM	48	60	ALPSV 4/89 W06FTI BSII	MNH 519637	MNE 644836	47
1859	RRC967	KL-15	7128	LL	ORD		12-Aug-2008	KHD	48	60	ALPSV 4/89 W06FTI BSII	MNH 518463	MNE 645192	106
1860	RRC979	KL-15	7138	LL	ORD		13-Aug-2008	TVL	48	60	ALPSV 4/89 W06FTI BSII	MNH 519629	MNE 644804	43
1861	RRC966	KL-15	7132	LL	ORD		13-Aug-2008	KNI	48	60	ALPSV 4/89 W06FTI BSII	PNH 516772	MNE 644702	107

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1862	RRC978	KL-15	7151	LL	ORD		26-Aug-2008	KNI	48	60	ALPSV 4/89 W06FTI BSII	MNH 518418	MNE 645110	107
1863	RRC964	KL-15	7129	LL	ORD		11-Aug-2008	KHD	48	60	ALPSV 4/89 W06FTI BSII	MNH 519575	MNE 644762	106
1864	RRC976	KL-15	7145	LL	ORD		22-Aug-2008	ARND	48	60	ALPSV 4/89 W06FTI BSII	JXH 576628	MNE 645165	19
1865	RRC974	KL-15	7135	LL	ORD		13-Aug-2008	PLKD	48	60	ALPSV 4/89 W06FTI BSII	MNH 519493	MNE 644688	69
1866	RRC972	KL-15	7136	LL	ORD		13-Aug-2008	PLKD	48	60	ALPSV 4/89 W06FTI BSII	MNH 519951	MNE 645179	69
1867	RRC547	KL-15	6700	LL	ORD	MLB	28-Feb-2008	NBR	48	60	ALPSV 4/89 W06PTI BSII HINO		NPE 640749	86
1868	RT 111	KL-15	5289	LL	ORD		15-Mar-2004	CTY	48	60	ALPSV HINO W06ETI	VBH 158906	VWF 521914	28
1869	RAC138	KL-15	7288	LL	ORD	SWB	18-Dec-2008	ANK	48	60	ALPSV4/100 W06ETI BSII	ZNE 104024Z	ZNE 666214	57
1870	RAC139	KL-15	7287	LL	ORD	SWB	18-Dec-2008	ANK	48	60	ALPSV4/100 W06ETI BSII	ZNE 104027Z	ZNE 666211	57
1871	RNC469	KL-15	8717	LL	ORD	SWB	11-Oct-2010	ANK	48	60	ALPSV4/100 W06ETI BSII	NAE129337Z	MB1PCEHCXAEND4410	57
1872	RAA151	KL-15	7333	LL	ORD		2-Jan-2009	PPD	48	60	BSII	HN 12804	CNE 664129	26
1873	RAC524	KL-15	7678	LL	ORD	SWB	2-May-2009	NTA	48	60	BSII	LXH 573672	LXE 670721	22
1874	RNC665	KL-15	8959	TATA	ORD	SWB	6-Jan-2011	TVL	48	60	LP 1512 TC/59 BSIII	01J62929482	MAT412266A0J16460	43
1875	RFM283	KL-15	6441	TATA	ORD	VND	17-Dec-2007	KLM	48	60	697 TCIC	697 TC55 JSZ 140977	436062 JSZ 015229	34
1876	RNC508	KL-15	8783	LL	ORD	SWB	3-Nov-2010	TVL	48	60	BSII 176	NAE129507Z	MB1PCEHC4AEND4578	43
1877	RNC754	KL-15	9058	LL	ORD	SWB	3-Mar-2011	TVL	48	60	BSII 176"	MAE131027Z	MB1PCEHC7AEMD6094	43
1878	RNC467	KL-15	8733	TATA	ORD	SWB	15-Oct-2010	MVPA	48	60	LP 1512 TC/59 BSII	O1E62884488	MAT412266A0F11046	52
1879	RNC 14	KL-15	8189	LL	ORD	VND	23-Jan-2010	KTDA	48	60	BSII ALPSV 4189	YXE 113661Z	EWB 5534	25
1880	RNC318	KL-15	8540	TATA	ORD		5-Aug-2010	PVM	48	60	LP 1512 TC/59 BSIII	90J62793792	MAT412088A0C06755	83
1881	RNC359	KL-15	8568	LL	ORD	MLB	16-Feb-2010	TLY	48	60	BSIII	PAH636769	MB1PBEJC8AEPD2870	18
1882	RRE502	KL-15	6690	LL	ORD	VND	27-Feb-2008	MLPY	48	60	CINO W06ETI BSII	NPH 504595	NPE 639537	96
1883	RT 32	KL-15	5210	TATA	ORD		6-Feb-2004	PBVR	48	60	CUMMINS	62285940	JW 2125799	59
1884	RT 69	KL-15	5247	TATA	ORD		5-Mar-2004	PKD	48	60	CUMMINS			65
1885	RT 92	KL-15	5270	TATA	ORD		11-Mar-2004	CTLA	48	60	CUMMINS	30J62290205	JWZ 125733	46
1886	RT 93	KL-15	5271	TATA	ORD		11-Mar-2004	NPR	48	60	CUMMINS	62289574	JWZ 125678	62
1887	RT 94	KL-15	5272	TATA	ORD		11-Mar-2004	KNPY	48	60	CUMMINS	30J62290370	JWZ 125841	87
1888	RT 174	KL-15	5352	TATA	ORD		1-Apr-2004	VKBN	48	60	CUMMINS 1512 TC	40A62308715	AVZ 100783	29
1889	RT 210	KL-15	5388	TATA	ORD		16-Apr-2004	KTDA	48	60	CUMMINS	40A62308565	AVZ 100839	25
1890	RT 264	KL-15	5442	TATA	ORD		13-May-2004	ALV	48	60	CUMMINS	30K62291692	KWZ 126666	61
1891	RT 68	KL-15	5246	TATA	ORD		5-Mar-2004	ALV	48	60	CUMMINS	30J62289573	JWZ 125679	61
1892	RT 276	KL-15	5454	TATA	ORD		1-Jun-2004	CTNR	48	60	CUMMINS	40062327372	DVZ 113127	97
1893	RT 304	KL-15	5482	TATA	ORD		25-Jun-2004	KNPY	48	60	CUMMINS	40E62333219	EVZ 117081	87
1894	RT 311	KL-15	5489	TATA	ORD		1-Jul-2004	KPM	48	60	CUMMINS	40D62327373	DVZ 113141	91
1895	RT 344	KL-15	5522	TATA	ORD		13-Jul-2004	KYLM	48	60	CUMMINS		412071EVZ117429	41
1896	RT 345	KL-15	5523	TATA	ORD		13-Jul-2004	ALP	48	60	CUMMINS	40E62333128	412071EVZ117083	45
1897	RT 367	KL-15	5545	TATA	ORD		2-Aug-2004	PVR	48	60	6BT CUMMINS	62141132	412071 FVZ 120264	23
1898	RT 376	KL-15	5554	TATA	ORD		16-Aug-2004	CLDY	48	60	CUMMINS	00D62145376	EVZ 117085	58
1899	RT 381	KL-15	5559	TATA	ORD		20-Aug-2004	MALA	48	60	CUMMINS	40F62339660	412071FVZ121397	85
1900	RT 387	KL-15	5565	TATA	ORD		20-Aug-2004	KYLM	48	60	CUMMINS		412071GVZ123323	41
1901	RT 389	KL-15	5567	TATA	ORD		20-Aug-2004	NPR	48	60	CUMMINS		GVZ 123325	62
1902	RT 413	KL-15	5591	TATA	ORD		24-Sep-2004	KYLM	48	60	CUMMINS	OOB 62137827	412071GVZ123671	41
1903	RT 417	KL-15	5595	TATA	ORD		1-Oct-2004	CTLA	48	60	CUMMINS	40E62340117	FVZ 121527	46
1904	RT 419	KL-15	5597	TATA	ORD		1-Oct-2004	KNPY	48	60	CUMMINS	40D 62329871	GVZ 123669	87
1905	RT 477	KL-15	5655	TATA	ORD		3-Nov-2004	ALV	48	60	CUMMINS	40H62349799	HVZ 127871	61
1906	RT 488	KL-15	5666	TATA	ORD		6-Nov-2004	PVR	48	60	6BT CUMMINS	40462349504	412071 HVZ 127645	23

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1907	RT 521	KL-15	5699	TATA	ORD		10-Nov-2004	CHRY	48	60	CUMMINS	50B62389642	412071HVZ127281	44
1908	RT 539	KL-15	5717	TATA	ORD		19-Nov-2004	PBVR	48	60	CUMMINS	62349569	HVZ 127870	59
1909	RT 545	KL-15	5723	TATA	ORD		29-Nov-2004	CTNR	48	60	CUMMINS	40H 62349096	HVZ 127020	97
1910	RT 551	KL-15	5729	TATA	ORD		2-Dec-2004	KNPY	48	60	CUMMINS	40H 62349564	HVZ 128048	87
1911	RT 553	KL-15	5731	TATA	ORD		4-Dec-2004	KPM	48	60	CUMMINS	40H62350951	HVZ 128156	91
1912	RT 560	KL-15	5738	TATA	ORD		10-Dec-2004	CTLA	48	60	CUMMINS	40H62349102	HVZ 127032	46
1913	RT 565	KL-15	5743	TATA	ORD		17-Dec-2004	CHRY	48	60	CUMMINS	40G62344368	412071GVZ124235	44
1914	RT 569	KL-15	5747	TATA	ORD		17-Dec-2004	KYLM	48	60	CUMMINS		412071JVZ131117	41
1915	RT 586	KL-15	5764	TATA	ORD		1-Jan-2005	CTLA	48	60	CUMMINS	OOD 62145675	JVZ 131259	46
1916	RT 691	KL-15	5869	TATA	ORD		15-Mar-2005	ALP	48	60	CUMMINS	50A62383943	412071AUZ103555	45
1917	RT 692	KL-15	5870	TATA	ORD		1-Apr-2005	KYLM	48	60	CUMMINS		412071AUZ103551	41
1918	RT 693	KL-15	5871	TATA	ORD		1-Apr-2005	KYLM	48	60	CUMMINS		412071AUZ103579	41
1919	RT 698	KL-15	5876	TATA	ORD		1-Apr-2005	EKM	48	60	CUMMINS	50A62384021	AUZ 103552	56
1920	RT 699	KL-15	5877	TATA	ORD		1-Apr-2005	KPM	48	60	CUMMINS	50A62384725	AUZ 103870	91
1921	RT 703	KL-15	5881	TATA	ORD		4-Apr-2005	KNPY	48	60	CUMMINS	50A 62384022	AUZ 103556	87
1922	RT 704	KL-15	5882	TATA	ORD		4-Apr-2005	KNPY	48	60	CUMMINS	OOG 62155745	AUZ 103292	87
1923	RT 705	KL-15	5883	TATA	ORD		7-Apr-2005	ALV	48	60	CUMMINS	50A62381652	AUZ 103293	61
1924	RT 706	KL-15	5884	TATA	ORD		7-Apr-2005	PVR	48	60	CUMMINS	50A 62385474	AUZ 104303	23
1925	RT 709	KL-15	5887	TATA	ORD		18-Apr-2005	ALP	48	60	CUMMINS	50A62383063	412071AUZ103335	45
1926	RT 711	KL-15	5889	TATA	ORD		2-May-2005	CHRY	48	60	CUMMINS	DOG 62158092	412071AUZ103785	44
1927	RT 737	KL-15	5915	TATA	ORD		9-May-2005	PVM	48	60	CUMMINS	50A 62384383	412071 AUZ 104260	83
1928	RT 739	KL-15	5917	TATA	ORD		12-May-2005	KYLM	48	60	CUMMINS		412071 AUZ 103294	41
1929	RT 750	KL-15	5928	TATA	ORD		23-May-2005	PVR	48	60	6BT CUMMINS	50C62392926	412071 BUZ 160920	23
1930	RT 760	KL-15	5938	TATA	ORD		2-Jun-2005	PPD	48	60	CUMMINS 1512 TC	50A62384067	412071 BUZ 106919	26
1931	RT 763	KL-15	5941	TATA	ORD		6-Jun-2005	ALP	48	60	CUMMINS	50A62384498	412071AUZ103869	45
1932	RT 764	KL-15	5942	TATA	ORD		6-Jun-2005	ALP	48	60	CUMMINS	50A62384220	412071AUZ104263	45
1933	RT 784	KL-15	5962	TATA	ORD		23-Jun-2005	CTNR	48	60	CUMMINS	50A 62384701	AUZ 103877	97
1934	RT 787	KL-15	5965	TATA	ORD		23-Jun-2005	KPM	48	60	CUMMINS	50B62388680	BUZ 107007	91
1935	RT 788	KL-15	5966	TATA	ORD		24-Jun-2005	CTLA	48	60	CUMMINS	50B62389650	BVZ 107381	46
1936	RT 772	KL-15	5950	TATA	ORD	VND	14-Jun-2005	CTNR	48	60	CUMMINS	50B 62389648	BUZ 107324	97
1937	RT 773	KL-15	5951	TATA	ORD	VND	16-Jun-2005	ALP	48	60	CUMMINS	50B62388446	412071BUZ107251	45
1938	RT 774	KL-15	5952	TATA	ORD	VND	16-Jun-2005	ALP	48	60	CUMMINS	50B62389642	412071BUZ107325	45
1939	RT 796	KL-15	5974	TATA	ORD	MLB	1-Jul-2005	IJK	48	60	CUMMINS	50B62389639	412071BUZ107384	89
1940	RT 811	KL-15	5989	TATA	ORD		12-Jul-2005	KPM	48	60	CUMMINS	50A62384066	AUZ 104103	91
1941	RT 815	KL-15	5993	TATA	ORD		12-Jul-2005	TVL	48	60	CUMMINS	OOH 62160724	BUZ 104628	43
1942	RT 817	KL-15	5995	TATA	ORD	VND	15-Jul-2005	KYLM	48	60	CUMMINS		412071 BUZ 107008	41
1943	RT 818	KL-15	5996	TATA	ORD	VND	15-Jul-2005	ALV	48	60	CUMMINS	50C62392665	CUZ 109592	61
1944	RT 821	KL-15	5999	TATA	ORD	VND	18-Jul-2005	KPM	48	60	CUMMINS	50A62384870	BUZ 104698	91
1945	RT 823	KL-15	6001	TATA	ORD	VND	18-Jul-2005	PBVR	48	60	CUMMINS	62389645	BVZ 107323	59
1946	RT 829	KL-15	6007	TATA	ORD	VND	20-Jul-2005	PVR	48	60	6BT CUMMINS	50A62384218	412071 CUZ 109867	23
1947	RT 831	KL-15	6009	TATA	ORD		20-Jul-2005	ALP	48	60	CUMMINS	50B62389649	412071BUZ107325	45
1948	RT 848	KL-15	6026	TATA	ORD	VND	28-Jul-2005	VDCY	48	60	CUMMINS	SOC 62393650	CVZ 110103	82
1949	RT 852	KL-15	6030	TATA	ORD		5-Aug-2005	PPD	48	60	CUMMINS	50C62392820	412071 CUZ 109669	26
1950	RT 855	KL-15	6033	TATA	ORD		9-Aug-2005	PVM	48	60	CUMMINS	50A 62385621	412071 BUZ 104818	83
1951	RT 858	KL-15	6036	TATA	ORD		12-Aug-2005	PPD	48	60	CUMMINS	62137775	CUZ 110770	26

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1952	RT 859	KL-15	6037	TATA	ORD		12-Aug-2005	PPD	48	60	CUMMINS	Q08726689	CUZ 110772	26
1953	RT 865	KL-15	6043	TATA	ORD		19-Aug-2005	PPD	48	60	CUMMINS	62170930	AUZ 103973	26
1954	RT 867	KL-15	6045	TATA	ORD	VND	24-Aug-2005	PVR	48	60	6BT CUMMINS	50C62392819	412071 CUZ 109668	23
1955	RT 869	KL-15	6047	TATA	ORD		22-Aug-2005	PPD	48	60	CUMMINS	50C62393216	CUZ 109830	26
1956	RT 870	KL-15	6048	TATA	ORD		22-Aug-2005	PPD	48	60	CUMMINS	62388664	CUZ 110104	26
1957	RT 871	KL-15	6049	TATA	ORD		22-Aug-2005	PPD	48	60	CUMMINS	62384701	CUZ 109869	26
1958	RT 890	KL-15	6068	TATA	ORD	VND	1-Sep-2005	GVR	48	60	CUMMINS	50C62392821	412071CUZ109593	66
1959	RT 902	KL-15	6080	TATA	ORD		6-Sep-2005	PPD	48	60	CUMMINS	62355065	CUZ 109591	26
1960	RT 907	KL-15	6085	TATA	ORD		12-Sep-2005	PPD	48	60	CUMMINS	62308715	AUZ 103735	26
1961	RT 908	KL-15	6086	TATA	ORD	VND	12-Sep-2005	CTLA	48	60	CUMMINS	5A62 385298	BVZ 104620	46
1962	RT 988	KL-15	6166	TATA	ORD	VND	17-Apr-2006	ALV	48	60	CUMMINS	50K62432458	KUZ 136591	61
1963	RT 989	KL-15	6167	TATA	ORD	VND	17-Apr-2006	VDCY	48	60	CUMMINS	50K62428212	KVZ 135897	82
1964	RT 990	KL-15	6168	TATA	ORD	VND	17-Apr-2006	VDCY	48	60	CUMMINS	50K62432459	KVZ 136525	82
1965	RR 7	KL-15	6185	TATA	ORD		8-May-2006	ALP	48	60	CUMMINS	50K62431591	412081KVZ136128	45
1966	RNC667	KL-15	8934	TATA	ORD	SWB	27-Dec-2010	KKD	48	60	LP 1512 TC/59 BSIII	01H62918629	MAT412266A0J15792	72
1967	RT 765	KL-15	5943	TATA	ORD		7-Jun-2005	KDLR	48	60	CUMMINS 1512	50A62385473	AUZ 104306	90
1968	RT 830	KL-15	6008	TATA	ORD		21-Jul-2005	MVK	48	60	CUMMINS 1512	50B62 389478	BUZ 107382	88
1969	RAM221	KL-15	7459	TATA	ORD	MLB	18-Feb-2009	TSY	48	60	CUMMINS 1512 BSII	80K62718418	LRZ 019235	73
1970	RAA254	KL-15	7423	TATA	ORD		3-Feb-2009	PLKD	48	60	CUMMINS 1512 BSII	K62716441	LRZ 019233	69
1971	RAM345	KL-15	7632	TATA	ORD		20-Apr-2009	KLM	48	60	CUMMINS 1512 BSII	80M 62725198	MRZ 020045	34
1972	RAM348	KL-15	7633	TATA	ORD		20-Apr-2009	KLM	48	60	CUMMINS 1512 BSII	62725118	MRZ 020064	34
1973	RAM349	KL-15	7634	TATA	ORD		20-Apr-2009	KLM	48	60	CUMMINS 1512 BSII	62725131	MRZ 020041	34
1974	RAM350	KL-15	7635	TATA	ORD		20-Apr-2009	CTNR	48	60	CUMMINS 1512 BSII	62725071	MRZ 020042	97
1975	RAM351	KL-15	7636	TATA	ORD		20-Apr-2009	KLM	48	60	CUMMINS 1512 BSII	62725123	MRZ 020063	34
1976	RR 208	KL-15	6406	TATA	ORD	VND	6-Dec-2007	VKBN	48	60	CUMMINS 1612 BSII TCIC	70 C 62552420	410 292 HSZ 012255	29
1977	RR 216	KL-15	6414	TATA	ORD	VND	6-Dec-2007	CTNR	48	60	CUMMINS 1512 BSII TCIC	70 C 62552482	410 292 GSZ 011084	97
1978	RNC154	KL-15	8319	TATA	ORD	VND	15-May-2010	KTM	48	60	LP 1512 TC/59 BSII	01C62855952	MAT412088A0C06870	47
1979	RNA185	KL-15	8358	TATA	ORD	VND	2-Jun-2010	KTM	48	60	LP 1512 TC/59 BSII	01B62840562	MAT412081A0B03382	47
1980	RNC197	KL-15	8359	TATA	ORD	VND	2-Jun-2010	KTM	48	60	LP 1512 TC/59 BSII	01C62855100	MAT412081A0C07408	47
1981	RNA426	KL-15	8651	TATA	ORD	VND	20-Sep-2010	KTM	48	60	LP 1512 TC/59 BSII	01G62906803	MAT412088A0G13534	47
1982	RT 708	KL-15	5886	TATA	ORD		11-Apr-2005	CDLM	48	60	CUMMINS 1512 C	40H 623536	JVZ 131671	80
1983	RT 33	KL-15	5211	TATA	ORD		6-Feb-2004	VZM	48	60	CUMMINS 1512 TC	62308238	JWZ 125838	24
1984	RT 258	KL-15	5436	TATA	ORD		7-May-2004	VKM	48	60	CUMMINS 1512 TC	OOE 62149535	AVZ 100478	51
1985	RT 271	KL-15	5449	TATA	ORD		17-May-2004	VKM	48	60	CUMMINS 1512 TC	30M 62307327	AVZ 100479	51
1986	RT 305	KL-15	5483	TATA	ORD		25-Jun-2004	VZM	48	60	CUMMINS 1512 TC	50C62 392919	EVZ 117165	24
1987	RT 307	KL-15	5485	TATA	ORD		28-Jun-2004	VLND	48	60	CUMMINS 1512 TC		412071DVZ113298	20
1988	RT 337	KL-15	5515	TATA	ORD		13-Jul-2004	CDLM	48	60	CUMMINS 1512 TC	62333622	EVZ 117408	80
1989	RT 349	KL-15	5527	TATA	ORD		22-Jul-2004	VZM	48	60	CUMMINS 1512 TC	62161703	EVZ 117084	24
1990	RT 372	KL-15	5550	TATA	ORD		12-Aug-2004	KTR	48	60	CUMMINS 1512 TC	62337092	FVZ 120261	35
1991	RT 396	KL-15	5574	TATA	ORD		7-Sep-2004	VZM	48	60	CUMMINS 1512 TC	62384872	EVZ 117164	24
1992	RT 434	KL-15	5612	TATA	ORD		11-Oct-2004	KLM	48	60	CUMMINS 1512 TC	62348843	HVZ 126983	34
1993	RT 446	KL-15	5624	TATA	ORD		25-Oct-2004	KTM	48	60	CUMMINS 1512 TC	4OH 62349566	HVZ 127278	47
1994	RT 447	KL-15	5625	TATA	ORD		15-Oct-2004	VLND	48	60	CUMMINS 1512 TC		412071HVZ127215	20
1995	RT 450	KL-15	5628	TATA	ORD		26-Oct-2004	KLM	48	60	CUMMINS 1512 TC	62349942	HVZ 127873	34
1996	RT 476	KL-15	5654	TATA	ORD		3-Nov-2004	KLM	48	60	CUMMINS 1512 TC	62348990	HVZ 126995	34

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
1997	RT 481	KL-15	5659	TATA	ORD	VND	8-Nov-2004	VKM	48	60	CUMMINS 1512 TC	4DF 62340116	HVZ 128151	51
1998	RT 524	KL-15	5702	TATA	ORD		16-Nov-2004	VKM	48	60	CUMMINS 1512 TC	OOH 62162599	HVZ 128024	51
1999	RT 549	KL-15	5727	TATA	ORD		1-Dec-2004	KLM	48	60	CUMMINS 1512 TC	62349267	HVZ 127615	34
2000	RT 564	KL-15	5742	TATA	ORD		17-Dec-2004	KLM	48	60	CUMMINS 1512 TC	62384501	JVZ 131251	34
2001	RT 695	KL-15	5873	TATA	ORD		1-Apr-2005	KTM	48	60	CUMMINS 1512 TC	50A62384497	AUZ 103583	47
2002	RT 696	KL-15	5874	TATA	ORD		1-Apr-2005	VZM	48	60	CUMMINS 1512 TC	00062 140745	AUZ 103295	24
2003	RT 697	KL-15	5875	TATA	ORD		1-Apr-2005	KTM	48	60	CUMMINS 1512 TC	OOD 62145003	AUZ 103578	47
2004	RT 738	KL-15	5916	TATA	ORD		12-May-2005	VZM	48	60	CUMMINS 1512 TC	OOE 62344790	AUZ 103872	24
2005	RT 743	KL-15	5921	TATA	ORD		19-May-2005	VZM	48	60	CUMMINS 1512 TC	62170937	AUZ 103871	24
2006	RT 755	KL-15	5933	TATA	ORD		26-May-2005	VKM	48	60	CUMMINS 1512 TC	50A 62385295	AUZ 104305	51
2007	RT 769	KL-15	5947	TATA	ORD		13-Jun-2005	CTNR	48	60	CUMMINS 1512 TC	62384873	AUZ 104104	97
2008	RT 770	KL-15	5948	TATA	ORD	VND	14-Jun-2005	KTM	48	60	CUMMINS 1512 TC	50B62388698	BUZ 106921	47
2009	RT 771	KL-15	5949	TATA	ORD	VND	14-Jun-2005	KLM	48	60	CUMMINS 1512 TC	62384729	BUZ 107326	34
2010	RT 797	KL-15	5975	TATA	ORD		1-Jul-2005	KTR	48	60	CUMMINS 1512 TC	OOH 62162374	BUZ 104630	35
2011	RT 822	KL-15	6000	TATA	ORD	VND	18-Jul-2005	VZM	48	60	CUMMINS 1512 TC	62388680	AUZ 104261	24
2012	RT 884	KL-15	6062	TATA	ORD	VND	29-Aug-2005	KLM	48	60	CUMMINS 1512 TC	62165100	AUZ 103879	34
2013	RR 22	KL-15	6200	TATA	ORD		25-May-2006	KTR	48	60	CUMMINS 1512 TC	60C62461582	412080CTZ712878	35
2014	RNM191	KL-15	8482	TATA	ORD		22-Jul-2010	KMR	48	60	LP 1512 TC/59 BSII	01C62856958	MAT412088A0C07399	30
2015	RAA300	KL-15	7464	TATA	ORD	VND	19-Feb-2009	VJMD	48	60	CUMMINS 1512 TCIC	K62716217	LRZ 019303	16
2016	RAA301	KL-15	7471	TATA	ORD	VND	21-Feb-2009	VJMD	48	60	CUMMINS 1512 TCIC	K62718414	LRZ 019238	16
2017	RAM222	KL-15	7473	TATA	ORD	VND	21-Feb-2009	TSY	48	60	CUMMINS 1512 TCIC	80K62718421	LRZ 019239	73
2018	RAM280	KL-15	7474	TATA	ORD	VND	21-Feb-2009	VJMD	48	60	CUMMINS 1512 TCIC	80K62718412	LRZ 019240	16
2019	RAA477	KL-15	7690	TATA	ORD	VND	5-May-2009	CTNR	48	60	CUMMINS 1512 TCIC	80M62726212	AQZ 000294	97
2020	RNC123	KL-15	8308	TATA	ORD		11-May-2010	KMR	48	60	LP 1512 TC/59 BSII	01B62841427	MAT412081A0B03634	30
2021	RNA167	KL-15	8336	TATA	ORD	VND	24-May-2010	TSR	48	60	LP 1512 TC/59 BSIII	01B62840571	MAT412081A0B03330	63
2022	RNM137	KL-15	8361	TATA	ORD	VND	3-Jun-2010	VJMD	48	60	LP 1512 TC/59 BSII	01C62855146	MAT412088A0B07404	16
2023	RNC196	KL-15	8363	TATA	ORD	VND	3-Jun-2010	KTR	48	60	LP1512TC/59 BSII	01C62855526	MAT412088A0C07394	35
2024	RNA188	KL-15	8405	TATA	ORD		21-Jun-2010	VJMD	48	60	LP 1512 TC/59 BSII	01C62856900	MAT412088A0C07126	16
2025	RNA255	KL-15	8420	TATA	ORD	MLB	30-Jun-2010	TPLM	48	60	LP 1512 TC/59 BSIII	01C62856929	MAT412088A0C07196	94
2026	RNC242	KL-15	8486	TATA	ORD	VND	15-Jul-2010	KMR	48	60	LP 1512 TC/59 BSII	01C62855527	MAT412088A0C06912	30
2027	RNM192	KL-15	8490	TATA	ORD	VND	26-Jul-2010	KMR	48	60	LP 1512 TC/59 BSII	01C62855098	MAT412088A0C07402	30
2028	RNA340	KL-15	8571	TATA	ORD	VND	17-Aug-2010	VZM	48	60	LP 1512 TC/59 BSII	01C62862937	MAT412088A0C08705	24
2029	RNC346	KL-15	8591	TATA	ORD	VND	27-Aug-2010	VZM	48	60	LP 1512 TC/59 BSII	01C62857059	MAT412088A0D09119	24
2030	RNC347	KL-15	8597	TATA	ORD		31-Aug-2010	KMR	48	60	LP 1512 TC/59 BSII	C62863288	MAT412088A0E09611	30
2031	RNA380	KL-15	8603	TATA	ORD		2-Sep-2010	VJMD	48	60	LP 1512 TC/59 BSII	01C62863289	MAT412089A0E09614	16
2032	RNA381	KL-15	8604	TATA	ORD		2-Sep-2010	VJMD	48	60	LP 1512 TC/59 BSII	01D62871935	MAT412089A0E09615	16
2033	RNA425	KL-15	8640	TATA	ORD	VND	15-Sep-2010	VJMD	48	60	LP 1512 TC/59 BSII	01G62906933	MAT412088A0G13531	16
2034	RNC392	KL-15	8649	TATA	ORD	SWB	17-Sep-2010	KTR	48	60	LP 1512 TC/59 BSII	01C62862647	MAT412266A0D09405	35
2035	RNC434	KL-15	8671	TATA	ORD	SWB	28-Sep-2010	KTR	48	60	LP 1512 TC/59 BSII	01C62862665	MAT412266A0D09395	35
2036	RNC433	KL-15	8678	TATA	ORD	SWB	30-Sep-2010	KTR	48	60	LP1512TC/59 BSII	01C62855446	MAT412266A0D08627	35
2037	RNC503	KL-15	8750	TATA	ORD	SWB	25-Oct-2010	KTR	48	60	LP 1512 TC/59 BSII	01E62885894	MAT412266A0F11041	35
2038	RAA358	KL-15	7505	TATA	ORD	MLB	2-Mar-2009	TSR	48	60	CUMMINS 1512 TCIC BSII		LRZ 019308	63
2039	RAA359	KL-15	7514	TATA	ORD	MLB	5-Mar-2009	TSR	48	60	CUMMINS 1512 TCIC BSII		LRZ 019309	63
2040	RAA360	KL-15	7521	TATA	ORD		7-Mar-2009	TSR	48	60	CUMMINS 1512 TCIC BSII		LRZ 019311	63
2041	RAA361	KL-15	7530	TATA	ORD	MLB	11-Mar-2009	TSR	48	60	CUMMINS 1512 TCIC BSII		LRZ 019312	63

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2042	RAA384	KL-15	7547	TATA	ORD		16-Mar-2009	TSR	48	60	CUMMINS 1512 TCIC BSII		MRZ 020005	63
2043	RAM462	KL-15	7752	TATA	ORD		27-May-2009	TSR	48	60	CUMMINS 1512 TCIC BSII		412081BC2001108	63
2044	RNA164	KL-15	8326	TATA	ORD	VND	19-May-2010	PKD	48	60	LP 1512 TC/59 BSIII	01B62840810	MAT412081A0B03383	65
2045	RNA165	KL-15	8327	TATA	ORD	VND	19-May-2010	PKD	48	60	LP 1512 TC/59 BSIII	01B62840821	MAT412081A0B03323	65
2046	RNA187	KL-15	8387	TATA	ORD	VND	14-Jun-2010	MVPA	48	60	LP 1512 TC/59 BSIII	01C62856915	MAT412088A0C07123	52
2047	RNM194	KL-15	8495	TATA	ORD	MLB	17-Jul-2010	TSR	48	60	LP 1512 TC/59 BSIII	01C62856909	MAT412088A0C07200	63
2048	RAA383	KL-15	7536	TATA	ORD		13-Mar-2009	MKD	48	60	CUMMINS 1512 TCIC BSII	80M62725065	412081MRZ020004	08
2049	RT 8	KL-15	5186	TATA	ORD		3-Feb-2004	VKM	48	60	CUMMINS 1512TC	50C62393449	JWZ 126118	51
2050	RT 827	KL-15	6005	TATA	ORD		21-Jul-2005	CTLA	48	60	CUMMINS 1616 TC LPO	62379391	BVZ 001182	46
2051	RNC468	KL-15	8755	TATA	ORD	SWB	28-Oct-2010	VDA	48	60	LP 1512 TC/59 BSIII	01F62887797	MAT412266A0F11255	92
2052	RNC284	KL-15	8451	TATA	ORD	TK	7-Jul-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62856914	MAT412088A0C07190	62
2053	RNC219	KL-15	8421	TATA	ORD	MLB	30-Jun-2010	TPLM	48	60	LP 1512 TC/59 BSIII	01C62856928	MB1PBEHEA0C07202	94
2054	RNC393	KL-15	8646	TATA	ORD	SWB	16-Sep-2010	VKBN	48	60	LP 1512 TC/59 BSIII	01C62862614	MAT412088A0D09404	29
2055	RNC437	KL-15	8683	TATA	ORD	SWB	4-Oct-2010	CGNR	48	60	LP 1512 TC/59 BSII	01E62884705	MAT412264A0F11039	40
2056	RNC540	KL-15	8813	TATA	ORD	TK	15-Nov-2010	ALV	48	60	LP 1512 TC/59 BSII	01H62915348	MAT412088A0H14681	61
2057	RNC627	KL-15	8896	TATA	ORD	VND	6-Dec-2010	MALA	48	60	LP 1512 TC/59 BSII	01J62926476	MATU12088A0J15977	85
2058	RNC629	KL-15	8903	TATA	ORD		10-Dec-2010	CTY	48	60	LP 1512 TC/59 BSII	01J62929349	MATU12088A0J16581	28
2059	RNC640	KL-15	8904	TATA	ORD		10-Dec-2010	CTR	48	60	LP 1512 TC/59 BSII	01J62924099	MATU12088A0J15685	70
2060	RNC642	KL-15	8905	TATA	ORD		10-Dec-2010	CTR	48	60	LP 1512 TC/59 BSII	01J62926466	MAT412088A0J15979	70
2061	RNC709	KL-15	8954	TATA	ORD	SWB	5-Jan-2011	TDY	48	60	LP 1512 TC/59 BSIII	LLP133968	MAT412266A0J16477	79
2062	RNC708	KL-15	8964	TATA	ORD	SWB	10-Jan-2011	VKBN	48	60	LP 1512 TC/59 BSII	01J62930288	MAT412266A0J16481	29
2063	RNC737	KL-15	9005	TATA	ORD	SWB	1-Feb-2011	CTR	48	60	LP 1512 TC/59 BSII	01J62930283	MAT412266A0J16482	70
2064	RNC285	KL-15	8452	TATA	ORD	TK	7-Jul-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62862920	MAT412088A0D08701	62
2065	RNC286	KL-15	8457	TATA	ORD		8-Jul-2010	PVM	48	60	LP 1512 TC/59 BSII	01C62856970	MAT412088A0C07125	83
2066	RNC287	KL-15	8458	TATA	ORD	TK	8-Jul-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62856404	MAT412088A0C06908	62
2067	RNC289	KL-15	8459	TATA	ORD	TK	8-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62857063	MAT412088A0C06832	56
2068	RNC290	KL-15	8460	TATA	ORD	TK	8-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62857077	MAT412088A0C06839	56
2069	RNC628	KL-15	8900	TATA	ORD	VND	7-Dec-2010	MALA	48	60	LP 1512 TC/59 BSII	01J62924071	MAT412088A0J15680	85
2070	RNC259	KL-15	8408	TATA	ORD	TK	25-Jun-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62856962	MAT412088A0C07124	56
2071	RNC260	KL-15	8409	TATA	ORD	TK	25-Jun-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62855129	MAT412088A0C07130	56
2072	RNC261	KL-15	8412	TATA	ORD		28-Jun-2010	PVM	48	60	LP 1512 TC/59 BSII	01C62855106	MAT412088A0C07129	83
2073	RNC262	KL-15	8413	TATA	ORD	TK	28-Jun-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62855958	MAT412088A0C07400	62
2074	RNC263	KL-15	8422	TATA	ORD	TK	30-Jun-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62855088	MAT412088A0C07405	56
2075	RNC264	KL-15	8423	TATA	ORD	TK	30-Jun-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62856827	MAT412088A0C06834	62
2076	RNC266	KL-15	8426	TATA	ORD	TK	1-Jul-2010	EKM	48	60	LP 1512 TC/59 BSII	01C62856918	MAT412088A0C06914	56
2077	RNC265	KL-15	8429	TATA	ORD	TK	2-Jul-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62855099	MAT412088A0C06913	62
2078	RNC269	KL-15	8430	TATA	ORD	TK	2-Jul-2010	NPR	48	60	LP 1512 TC/59 BSII	01C62855949	MAT412088A0C06574	62
2079	RAC646	KL-15	7836	TATA	ORD	SWB	27-Jun-2009	ALP	48	60	CUMMINS BSII	90B6273511	A12263CQZ002939	45
2080	RAM623	KL-15	7847	TATA	ORD	VND	2-Jul-2009	ALP	48	60	CUMMINS BSII	90C62737584	412081CQZ003381	45
2081	RAM682	KL-15	7863	TATA	ORD		9-Jul-2009	PBVR	48	60	CUMMINS BSII	62726573	AQZ 000297	59
2082	RAA711	KL-15	7882	TATA	ORD		28-Jul-2009	PBVR	48	60	CUMMINS BSII	90B62734389	CQZ 002640	59
2083	RNC140	KL-15	8304	TATA	ORD		7-May-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01B62841995	MAT412081A0B03635	59
2084	RNC143	KL-15	8312	TATA	ORD	VND	12-May-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01A62831925	MAT412081A0B03015	59
2085	RNC145	KL-15	8313	TATA	ORD	VND	12-May-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01B62840618	MAT412081A0B03326	59
2086	RNC141	KL-15	8314	TATA	ORD		13-May-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01B62841423	MAT412081A0B03633	59

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2087	RNC146	KL-15	8315	TATA	ORD		13-May-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01B62841226	MAT412081A0B03380	59
2088	RNC144	KL-15	8317	TATA	ORD	VND	14-May-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01A62831750	MAT412081A0B03012	59
2089	RNC148	KL-15	8318	TATA	ORD	VND	14-May-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01B62843849	MAT412081A0B03636	59
2090	RNM396	KL-15	8627	TATA	ORD	VND	13-Sep-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01C62855524	MAT412088A0C06904	59
2091	RNM398	KL-15	8635	TATA	ORD	VND	15-Sep-2010	PBVR	48	60	LP 1512 TC/59 BSIII	01G62906922	MAT412088A0G13532	59
2092	RNM401	KL-15	8675	TATA	ORD		30-Sep-2010	PDM	48	60	LP 1512 TC/59 BSIII	01G62907452	MAT412088A0G13676	39
2093	RT 849	KL-15	6027	TATA	ORD	VND	28-Jul-2005	PSL	48	60	CUMMINS TATA 1512 TC	50C62393008	412071CUZ109868	21
2094	RT 868	KL-15	6046	TATA	ORD	VND	24-Aug-2005	PSL	48	60	CUMMINS TATA 1512 TC	50C62393648	412071CUZ110026	21
2095	RR 6	KL-15	6184	TATA	ORD		6-May-2006	ADR	48	60	CUMMINS TATA 1512 TC	50K62432329	412081KUZ136447	38
2096	RT 877	KL-15	6055	TATA	ORD	VND	25-Aug-2005	PSL	48	60	CUMMINS TATS 1512 TC	50C62393009	412071CUZ109670	21
2097	RNC626	KL-15	8895	TATA	ORD	VND	6-Dec-2010	MALA	48	60	LP 1512 TC/59 BSII	01J62926472	MAT412088A0J15976	85
2098	RNE333	KL-15	8561	LL	ORD	VND	13-Aug-2010	VJMD	48	60	EURO BSII	WAE120148Z	MB1PBEHC5AEWC3997	16
2099	RNK696	KL-15	9065	LL	ORD		8-Mar-2011	KMY	48	60	HE BSII	MAE130896Z	MB1PBEHC7AEMD6003	05
2100	TP 752	KL-15	4930	LL	ORD		12-Sep-2003	TVL	48	60	HINO	WDH 295990	DVE 504734	43
2101	RAC479	KL-15	7626	LL	ORD	SWB	20-Apr-2009	MLTM	48	60	HINO 106ETI BSII	LXH 572108	LXE 669775	54
2102	RT 993	KL-15	6171	LL	ORD	VND	20-Apr-2006	KTR	48	60	HINO 6DTI BSII	SDH 315590	SDE 555884	35
2103	RR 54	KL-15	6232	LL	ORD		23-Jan-2007	PTPM	48	60	HINO 6DTI BSII	TDH 313318	SDE 555849	15
2104	RRK460	KL-15	6629	LL	ORD	VND	11-Feb-2008	VKM	48	60	HINO 6E BSII TURBO INTER COOLER	TPH 502295	TPE 637652	51
2105	RRK511	KL-15	6788	LL	ORD	MLB	25-Mar-2008	SBY	48	60	HINO 6ETCIC VIKING	NPH 508811	NPE 640880	75
2106	RAM124	KL-15	7346	LL	ORD		8-Jan-2009	KGD	48	60	HINO 6ETI	CNH 560809	BNE 664146	84
2107	RT 927	KL-15	6105	LL	ORD		17-Oct-2005	KTR	48	60	HINO BSI	UDH 308964	TDE 553964	35
2108	RT 928	KL-15	6106	LL	ORD		17-Oct-2005	KTR	48	60	HINO BSI	UDH 308904	TDE 553968	35
2109	RT 956	KL-15	6134	LL	ORD	SWB	12-Jan-2006	KTR	48	60	HINO EURO	UDH 303065	UDE 551555	35
2110	RT 808	KL-15	5986	LL	ORD		12-Jul-2005	PSL	48	60	HINO EURO	DWH 291499	WDA 047449	21
2111	RT 958	KL-15	6136	LL	ORD	VND	16-Feb-2006	NDD	48	60	HINO BSII		E549656	31
2112	RT 960	KL-15	6138	LL	ORD	VND	16-Feb-2006	NDD	48	60	HINO BSII	VDH 301231	UDE 550638	31
2113	RT 965	KL-15	6143	LL	ORD	VND	1-Apr-2006	PSL	48	60	HINO BSII	UDH 308965	TDE 554021	21
2114	RT 967	KL-15	6145	LL	ORD	VND	1-Apr-2006	PSL	48	60	HINO BSII	TDH 313101	TDE 554119	21
2115	RT 968	KL-15	6146	LL	ORD	VND	1-Apr-2006	PSL	48	60	HINO BSII	DWH 292792	UDE 551339	21
2116	RT 972	KL-15	6150	LL	ORD	VND	1-Apr-2006	PSL	48	60	HINO BSII	TDH 312494	TDE 553816	21
2117	RT 998	KL-15	6176	LL	ORD		9-May-2006	KTR	48	60	HINO BSII	SBH 314705	SDE 554997	35
2118	RT 999	KL-15	6177	LL	ORD		9-May-2006	KTR	48	60	HINO BSII	TDH 313701	SDE 555161	35
2119	RR 3	KL-15	6181	LL	ORD	VND	2-May-2006	KTR	48	60	HINO BSII	SDH 314873	SDE 554998	35
2120	RRE170	KL-15	6382	LL	ORD	VND	30-Nov-2007	KNI	48	60	HINO BSII	WPH 480732	WPE 628346	107
2121	RRC394	KL-15	6568	LL	ORD	VND	23-Jan-2008	TVL	48	60	HINO BSII	UPH 497261	UPE 635282	43
2122	RRC516	KL-15	6666	LL	ORD	VND	20-Feb-2008	KTR	48	60	HINO BSII	NPH 504724	NPE 639575	35
2123	RRC521	KL-15	6679	LL	ORD	VND	23-Feb-2008	KTR	48	60	HINO BSII	NPH 504720	NPE 639578	35
2124	RRE507	KL-15	6719	LL	ORD	VND	3-Mar-2008	NDD	48	60	HINO BSII	NPH 505694	NPE 640828	31
2125	RRK461	KL-15	6630	LL	ORD	MLB	11-Feb-2008	KPA	48	60	HINO BSII	NPH 507653	NPE 639538	74
2126	RRE506	KL-15	6703	LL	ORD		29-Feb-2008	RNI	48	60	HINO BSII	NPH 508819	NPE 640827	101
2127	RRK533	KL-15	6670	LL	ORD	MLB	21-Feb-2008	SBY	48	60	HINO BSII	NPH 504593	NPE 639569	75
2128	RRK631	KL-15	6846	LL	ORD	VND	7-Apr-2008	CGNR	48	60	HINO BSII	TPH 504065	NPE 639598	40
2129	RRK633	KL-15	6857	LL	ORD	MLB	11-Apr-2008	CDLM	48	60	HINO BSII	PNH 511625	PNE 643798	80
2130	RRE850	KL-15	7008	LL	ORD	VND	2-Jun-2008	ATL	48	60	HINO BSII	KNH 533476	KNE 651441	33
2131	RRC977	KL-15	7133	LL	ORD		13-Aug-2008	SBY	48	60	HINO BSII	PAH 635665EZ	MNE 645126	75

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2132	RRC975	KL-15	7134	LL	ORD	MLB	13-Aug-2008	KPA	48	60	HINO BSII EURO	MNH 519640	MNE 644917	74
2133	RAA105	KL-15	7253	LL	ORD		29-Nov-2008	ADR	48	60	HINO BSII	JNH 543733	JNE 656175	38
2134	RAC164	KL-15	7316	LL	ORD		29-Dec-2008	PALA	48	60	HINO BSII	BNE 103543Z	BNE 665158	50
2135	RAA196	KL-15	7369	LL	ORD	VND	15-Jan-2009	ARND	48	60	HINO BSII	ZNH 567939	ZNE 666662	19
2136	RAC392	KL-15	7592	LL	ORD	VND	1-Apr-2009	KTR	48	60	HINO BSII	NXE 105209Z	NXE 669036	35
2137	RAC454	KL-15	7624	LL	ORD	SWB	20-Apr-2009	PTA	48	60	HINO BSII	LXH 572109	LXE 669770	37
2138	RAC496	KL-15	7647	LL	ORD	SWB	24-Apr-2009	RNI	48	60	HINO BSII	LXH 572847	LXE 669896	101
2139	RAC495	KL-15	7653	LL	ORD	SWB	23-Apr-2009	PTA	48	60	HINO BSII	LXH 572843	LXE 669905	37
2140	RAC497	KL-15	7654	LL	ORD	SWB	23-Apr-2009	PTA	48	60	HINO BSII	LXH 572746	LXE 669962	37
2141	RAC390	KL-15	7570	LL	ORD		25-Mar-2009	CHRY	48	60	HINO BSII	NXH 571623	NXE 669092	44
2142	RAC501	KL-15	7641	LL	ORD		20-Apr-2009	KTP	48	60	HINO BSII	LXH 573171	LXE 670134	14
2143	RAC699	KL-15	7892	LL	ORD	VND	14-Aug-2009	PALA	48	60	HINO BSII	KXH 574883	KXE 672097	50
2144	RAK961	KL-15	8139	LL	ORD		23-Dec-2009	PTA	48	60	HINO BSII	ZXE 111946Z	MBIPBEHC29EZB1164	37
2145	RAE966	KL-15	8140	LL	ORD		23-Dec-2009	ADR	48	60	HINO BSII	ZXE 111371Z	MB1PBEHCX9E2B0232	38
2146	RAE968	KL-15	8141	LL	ORD		23-Dec-2009	ADR	48	60	HINO BSII	YXE 113123Z	MP1PBEHC29EYB3106	38
2147	RAK925	KL-15	8127	LL	ORD		14-Dec-2009	RNI	48	60	HINO BSII	BXE 110175Z	MB1PBEHC69EBA8165	101
2148	RAK924	KL-15	8124	LL	ORD	VND	9-Dec-2009	KDLR	48	60	HINO BSII	ZXE 110989Z		90
2149	RAK990	KL-15	8204	LL	ORD		15-Feb-2010	TSR	48	60	HINO BSII		MB1PBEHC19E2A9566	63
2150	RNK 85	KL-15	8295	LL	ORD		5-May-2010	CGNR	48	60	HINO BSII	VAE121263Z	MB1PBEHC3AEVC5535	40
2151	RNK111	KL-15	8341	LL	ORD		26-May-2010	VJMD	48	60	HINO BSII	VAE120830Z	MB1PBEHC8AEVC4851	16
2152	RNE149	KL-15	8354	LL	ORD		2-Jun-2010	PTA	48	60	HINO BSII	VAE121443Z	MB1PBEHC3AEVC5762	37
2153	RNE150	KL-15	8355	LL	ORD		2-Jun-2010	PTA	48	60	HINO BSII	VAE120707Z	MB1PBEHC4AEVC4765	37
2154	RNK179	KL-15	8379	LL	ORD		9-Jun-2010	TPLM	48	60	HINO BSII	VAE120702Z	MB1PBEHC8AEVC4768	94
2155	RNC225	KL-15	8390	LL	ORD	SWB	15-Jun-2010	KTR	48	60	HINO BSII	VAE 122480Z	MB1PCEHC3AEVC7279	35
2156	RNC249	KL-15	8487	LL	ORD	SWB	15-Jul-2010	PALA	48	60	HINO BSII	VAE122568Z	MB1PCEHC6AEVC7356	50
2157	RNC311	KL-15	8536	LL	ORD	SWB	4-Aug-2010	NTA	48	60	HINO BSII	VAE122609Z	MB1PCEHC7AEVC7429	22
2158	RNC314	KL-15	8576	LL	ORD	SWB	18-Aug-2010	ATL	48	60	HINO BSII	VAE1222585Z	MB1PCEHCXAEVC7361	33
2159	RNK365	KL-15	8613	LL	ORD		6-Sep-2010	TDY	48	60	HINO BSII	WAE120140Z	MB1PBEHC2AEWC3990	79
2160	RNC471	KL-15	8739	LL	ORD	SWB	20-Oct-2010	KMR	48	60	HINO BSII	NAE129339Z	MB1PCEHC8AEND4406	30
2161	RNC473	KL-15	8749	LL	ORD	SWB	25-Oct-2010	KTR	48	60	HINO BSII	NAE129338Z	MB1PCEHC3AEND4409	35
2162	RNC510	KL-15	8765	LL	ORD	SWB	1-Nov-2010	PALA	48	60	HINO BSII	NAE129502Z	MAT4122669AEMD4575	50
2163	RNK550	KL-15	8883	LL	ORD		2-Dec-2010	CTR	48	60	HINO BSII	MAE132281Z	MB1PBEHCXAEND7419	70
2164	RNK556	KL-15	8915	LL	ORD		15-Dec-2010	CTR	48	60	HINO BSII	MAE132171Z	MB1PBEHC8AEMD7306	70
2165	RNK557	KL-15	8916	LL	ORD		15-Dec-2010	CTR	48	60	HINO BSII	MAE132286Z	MB1PBEHC0AEMD7428	70
2166	RNK691	KL-15	8992	LL	ORD		25-Jan-2011	ETPA	48	60	HINO BSII	NAE130541Z	MB1PBEHC1AEND5674	48
2167	RNK693	KL-15	9015	LL	ORD		8-Feb-2011	ETPA	48	60	HINO BSII	MAE131214Z	MB1PBEHC0AEMD6361	48
2168	RNK695	KL-15	9064	LL	ORD		8-Mar-2011	ETPA	48	60	HINO BSII	NAE129662Z	MB1PBEHC8AEND4750	48
2169	RNC930	KL-15	9375	LL	ORD	SWB	7-Feb-2012	KMR	48	60	HINO 6ETI3K BSIII	BMEZ400539	MB1PCEYCXBEMG5476	30
2170	RRK 57	KL-15	6249	LL	ORD		4-Sep-2007	VLRD	48	60	HINO BSII 6ETI	YPH 471604	XPE 624818	93
2171	RAC296	KL-15	7456	LL	ORD		16-Feb-2009	VLRD	48	60	HINO BSII 6ETI	ZNE 1042077Z	YNE 667352	93
2172	RAC298	KL-15	7465	LL	ORD		16-Feb-2009	VLRD	48	60	HINO BSII 6ETI	ZNE 104355Z	YNE 667277	93
2173	RAC316	KL-15	7466	LL	ORD		19-Feb-2009	VLRD	48	60	HINO BSII 6ETI	ZNE 104397Z	YNE 667372	93
2174	RAC317	KL-15	7467	LL	ORD		19-Feb-2009	VLRD	48	60	HINO BSII 6ETI	ZNE 104356Z	YNE 667472	93
2175	RAC320	KL-15	7475	LL	ORD	VND	21-Feb-2009	VLRD	48	60	HINO BSII 6ETI	YNE 104591Z	XNE 667921	93
2176	RAC323	KL-15	7476	LL	ORD	VND	21-Feb-2009	VLRD	48	60	HINO BSII 6ETI	ZNE 104281Z	YNE 667279	93

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2177	RAC321	KL-15	7480	LL	ORD	VND	24-Feb-2009	VLRD	48	60	HINO BSII 6ETI	ZNE 104462Z	YNE 667274	93
2178	RAC324	KL-15	7481	LL	ORD	VND	24-Feb-2009	VLRD	48	60	HINO BSII 6ETI	YNE 104624Z	XNE 667932	93
2179	RAC293	KL-15	7451	LL	ORD		16-Feb-2009	CDLM	48	60	HINO BSII TCIC	NNE 104348Z	YNE 667375	80
2180	RAC294	KL-15	7452	LL	ORD		16-Feb-2009	CDLM	48	60	HINO BSII TCIC	FUH 228652	YNE 667387	80
2181	RAC999	KL-15	8181	LL	ORD		15-Jan-2010	CDLM	48	60	HINO BSII TCIC	YXE 113138Z	MB1PHBEHCX9EYB3161	80
2182	RAE995	KL-15	8192	LL	ORD		28-Jan-2010	CDLM	48	60	HINO BSII TCIC	ZXE 111378Z	MB1PBEHC29EZB0239	80
2183	RNK182	KL-15	8394	LL	ORD	VND	16-Jun-2010	CDLM	48	60	HINO BSII TCIC	WAE119791Z	MB1PBEHCXAWC3591	80
2184	RAK986	KL-15	8190	LL	ORD		25-Jan-2010	TDP	48	60	HINO BSII VIKING	ZXE 111382Z	MB1PBEHC89EZB0231	53
2185	RAK992	KL-15	8219	LL	ORD		1-Mar-2010	MPM	48	60	HINO BSII VIKING			71
2186	RNK113	KL-15	8378	LL	ORD		9-Jun-2010	KKD	48	60	HINO BSII VIKING	VAE120698Z	MB1PBEHC5AEVC4743	72
2187	RAA148	KL-15	7304	LL	ORD		27-Dec-2008	KTDA	48	60	HINO BSII VIKING ALPSV 4189	NAE 129658Z	BNE 665302	25
2188	RNC871	KL-15	9316	LL	ORD	SWB	26-Dec-2011	PALA	48	60	HINO 6ETI3K BSIII	BMEZ400538	MB1PCEYCBENG5474	50
2189	TP 654	KL-15	4830	LL	ORD		4-Jan-2003	NTA	48	60	HINO EURO	DMH 201586	CME 486477	22
2190	TP 658	KL-15	4835	LL	ORD		25-Jan-2003	KNR	48	60	HINO EURO	XBH 155457	CME 486867	77
2191	TP 690	KL-15	4868	LL	ORD		12-May-2003	KTDA	48	60	HINO EURO	VLH 176252	LVE 498718	25
2192	TP 699	KL-15	4877	LL	ORD		18-Jun-2003	KNPY	48	60	HINO EURO	ZSH 099547	LVE 498998	87
2193	TP 727	KL-15	4905	LL	ORD		21-Aug-2003	PLD	48	60	HINO EURO	FVH 228685	FVE 504360	32
2194	TP 761	KL-15	4940	LL	ORD		20-Sep-2003	MPM	48	60	HINO EURO			71
2195	TP 859	KL-15	5037	LL	ORD		14-Nov-2003	CGNR	48	60	HINO EURO	TDH311977	BVE 510603	40
2196	TP 870	KL-15	5048	LL	ORD		20-Nov-2003	VZM	48	60	HINO EURO	DWH 293520	ZVA 038843	24
2197	TP 894	KL-15	5072	LL	ORD		2-Dec-2003	VZM	48	60	HINO EURO	HNI2227	ZVA 038801	24
2198	TP 896	KL-15	5074	LL	ORD		2-Dec-2003	VLRD	48	60	HINO EURO	HN 131415	YVA 039182	93
2199	TP 929	KL-15	5107	LL	ORD		22-Dec-2003	PMNA	48	60	HINO EURO	MWH 00276613	BVE 510533	68
2200	TP 942	KL-15	5120	LL	ORD		1-Jan-2004	EKM	48	60	HINO EURO	ZVH 241073	ZVA 038904	56
2201	TP 968	KL-15	5146	LL	ORD		8-Jan-2004	MVPA	48	60	HINO EURO	ZVH 240699	ZVA 038949	52
2202	TP 992	KL-15	5170	LL	ORD		23-Jan-2004	PLD	48	60	HINO EURO	XVH 248646	WVE 517701	32
2203	TP 999	KL-15	5177	LL	ORD		24-Jan-2004	NTA	48	60	HINO EURO	MUH 16279	WVE 518436	22
2204	RT 1	KL-15	5179	LL	ORD		3-Feb-2004	NDD	48	60	HINO EURO	WDH 298425	WVE 518397	31
2205	RT 4	KL-15	5182	LL	ORD		3-Feb-2004	TLY	48	60	HINO EURO	MWH 277943	WEV 518822	18
2206	RT 10	KL-15	5188	LL	ORD		5-Feb-2004	NTA	48	60	HINO EURO	DWA 294370	WVE 518380	22
2207	RT 25	KL-15	5203	LL	ORD		6-Feb-2004	KNR	48	60	HINO EURO	ZSH 097970	WVE 518379	77
2208	RT 38	KL-15	5216	LL	ORD		10-Feb-2004	KHD	48	60	HINO EURO	00249743	WVE 518592	106
2209	RT 39	KL-15	5217	LL	ORD		10-Feb-2004	PPD	48	60	HINO EURO	SDH 076190	WVE 518629	26
2210	RT 40	KL-15	5218	LL	ORD		12-Feb-2004	VLRD	48	60	HINO EURO	LBH 163125	WVE 518540	93
2211	RT 42	KL-15	5220	LL	ORD	VND	12-Feb-2004	KTDA	48	60	HINO EURO	DWH 289860	WVE 518386	25
2212	RT 45	KL-15	5223	LL	ORD		16-Feb-2004	PSL	48	60	HINO EURO	WVH 249698	WVE 518571	21
2213	RT 47	KL-15	5225	LL	ORD		17-Feb-2004	EDT	48	60	HINO EURO		XVE 517626	98
2214	RT 48	KL-15	5226	LL	ORD		17-Feb-2004	PPD	48	60	HINO EURO	FWH 287249	WVE 518821	26
2215	RT 50	KL-15	5228	LL	ORD		19-Feb-2004	PVR	48	60	HINO EURO	WVH250362	WVE 518541	23
2216	RT 53	KL-15	5231	LL	ORD		19-Feb-2004	NTA	48	60	HINO EURO	WVH 250497	WVE 518631	22
2217	RT 55	KL-15	5233	LL	ORD		24-Feb-2004	NDD	48	60	HINO EURO	FVH 227369	WVE 518691	31
2218	RT 57	KL-15	5235	LL	ORD		19-Feb-2004	KTDA	48	60	HINO EURO	ZNE 104003	WVE 518934	25
2219	RT 60	KL-15	5238	LL	ORD		21-Feb-2004	KMR	48	60	HINO EURO	YBE 153521	WVE 519247	30
2220	RT 63	KL-15	5241	LL	ORD		5-Mar-2004	CDLM	48	60	HINO EURO	KH 123848	WVE 518720	80
2221	RT 64	KL-15	5242	LL	ORD		5-Mar-2004	PPD	48	60	HINO EURO	HA 12885	WVE 518765	26

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2222	RT 77	KL-15	5255	LL	ORD		5-Mar-2004	NTA	48	60	HINO EURO	CVH 234819	WVE 518724	22
2223	RT 79	KL-15	5257	LL	ORD		5-Mar-2004	MVPA	48	60	HINO EURO LL BS 111	WPH 482654	WVE 519272	52
2224	RT 83	KL-15	5261	LL	ORD		5-Mar-2004	TPLM	48	60	HINO EURO			94
2225	RT 84	KL-15	5262	LL	ORD		5-Mar-2004	KKD	48	60	HINO EURO	00258539	WVE 518712	72
2226	RT 87	KL-15	5265	LL	ORD		9-Mar-2004	PNI	48	60	HINO EURO	10HB491	WVE 519324	67
2227	RT 98	KL-15	5276	LL	ORD		11-Mar-2004	KTDA	48	60	HINO EURO	JMH 196198	WVE 519540	25
2228	RT 99	KL-15	5277	LL	ORD		11-Mar-2004	KPA	48	60	HINO EURO			74
2229	RT 103	KL-15	5281	LL	ORD		15-Mar-2004	KNR	48	60	HINO EURO	YBH 152577	WVE 519626	77
2230	RT 106	KL-15	5284	LL	ORD		15-Mar-2004	TDP	48	60	HINO EURO	FBH 144988	WVE 519566	53
2231	RT 110	KL-15	5288	LL	ORD		15-Mar-2004	PNR	48	60	HINO EURO		WVE 519519	78
2232	RT 113	KL-15	5291	LL	ORD		15-Mar-2004	NDD	48	60	HINO EURO	WVH 251099	WVE 519082	31
2233	RT 114	KL-15	5292	LL	ORD		16-Mar-2004	KPA	48	60	HINO EURO			74
2234	RT 116	KL-15	5294	LL	ORD		16-Mar-2004	KPZA	48	60	HINO EURO			07
2235	RT 132	KL-15	5310	LL	ORD		18-Mar-2004	TVL	48	60	HINO EURO	WBH 156658	WVE 519539	43
2236	RT 178	KL-15	5356	LL	ORD		1-Apr-2004	KMR	48	60	HINO EURO	ZVH00240505	UWE 522209	30
2237	RT 179	KL-15	5357	LL	ORD		1-Apr-2004	MLPY	48	60	HINO EURO	WVH 255784	WVE 522292	96
2238	RT 184	KL-15	5362	LL	ORD		1-Apr-2004	TVL	48	60	HINO EURO	VWH 255711	UWE 522196	43
2239	RT 185	KL-15	5363	LL	ORD		1-Apr-2004	KKD	48	60	HINO EURO	165833	WVE 522017	72
2240	RT 192	KL-15	5370	LL	ORD		1-Apr-2004	KTR	48	60	HINO EURO	YBH 153072	UWE 522706	35
2241	RT 193	KL-15	5371	LL	ORD		1-Apr-2004	MVPA	48	60	HINO EURO	BVH 00237777	BVA 038498	52
2242	RT 195	KL-15	5373	LL	ORD		5-Apr-2004	TLY	48	60	HINO EURO	XVH 245832	XVA 039575	18
2243	RT 202	KL-15	5380	LL	ORD		5-Apr-2004	MVPA	48	60	HINO EURO	BVH 238320	BVA 038449	52
2244	RT 204	KL-15	5382	LL	ORD		12-Apr-2004	PNR	48	60	HINO EURO	JBH 143097	UWE 522729	78
2245	RT 206	KL-15	5384	LL	ORD		12-Apr-2004	VTRA	48	60	HINO EURO	UWH 256470	UWE 522728	17
2246	RT 207	KL-15	5385	LL	ORD		12-Apr-2004	NTA	48	60	HINO EURO	VWH 255989	VWF 521917	22
2247	RT 213	KL-15	5391	LL	ORD		20-Apr-2004	PALA	48	60	HINO EURO	VWH 256086	VWE 522085	50
2248	RT 219	KL-15	5397	LL	ORD		26-Apr-2004	KNR	48	60	HINO EURO W06EI	VWH 255788	UWE 522293	77
2249	RT 225	KL-15	5403	LL	ORD		19-Mar-2004	ALV	48	60	HINO EURO	VWH 256082	VWE 522077	61
2250	RT 226	KL-15	5404	LL	ORD		3-May-2004	KNR	48	60	HINO EURO	DMH 202008	TWA 041647	77
2251	RT 254	KL-15	5432	LL	ORD		6-May-2004	KTR	48	60	HINO EURO	UWH 255715	UWE 522195	35
2252	RT 255	KL-15	5433	LL	ORD		6-May-2004	PSL	48	60	HINO EURO	UWH 259060	UWA 041556	21
2253	RT 257	KL-15	5435	LL	ORD		6-May-2004	MLPY	48	60	HINO EURO	MSH 112971	UWA 041553	96
2254	RT 259	KL-15	5437	LL	ORD		7-May-2004	KTDA	48	60	HINO EURO	DWH 291765	UWA 041554	25
2255	RT 260	KL-15	5438	LL	ORD		7-May-2004	KHD	48	60	HINO EURO	UWH 258040	UWH 258040	106
2256	RT 262	KL-15	5440	LL	ORD		7-May-2004	KMGH	48	60	HINO EURO	WVH 251829	TWA 041748	55
2257	RT 263	KL-15	5441	LL	ORD		13-May-2004	KTDA	48	60	HINO EURO	FWH 00286713	TWA 041650	25
2258	RT 265	KL-15	5443	LL	ORD		13-May-2004	NTA	48	60	HINO EURO	BVA 238482	VWE 522086	22
2259	RT 279	KL-15	5457	LL	ORD		1-Jun-2004	KTR	48	60	HINO EURO	UWH 259714	TWA 041745	35
2260	RT 282	KL-15	5460	LL	ORD		7-Jun-2004	MVPA	48	60	HINO EURO	SDH 316845	SWA 042392	52
2261	RT 283	KL-15	5461	LL	ORD		11-Jun-2004	MVK	48	60	HINO EURO	SWH 265665	SWA 042411	88
2262	RT 284	KL-15	5462	LL	ORD		11-Jun-2004	VTRA	48	60	HINO EURO	SWH 264437	SWA 042487	17
2263	RT 286	KL-15	5464	LL	ORD		11-Jun-2004	PPD	48	60	HINO EURO	UDH 306422	SWA 042489	26
2264	RT 288	KL-15	5466	LL	ORD		14-Jun-2004	PMNA	48	60	HINO EURO	BXH 051599	SWA 042357	68
2265	RT 289	KL-15	5467	LL	ORD		14-Jun-2004	MVPA	48	60	HINO EURO	UWH 00259797	TWA 041744	52
2266	RT 291	KL-15	5469	LL	ORD		15-Jun-2004	KTR	48	60	HINO EURO	XLH 171909	SWA 042361	35

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2267	RT 292	KL-15	5470	LL	ORD		15-Jun-2004	NTA	48	60	HINO EURO	NWH 274738	SWA 042353	22
2268	RT 294	KL-15	5472	LL	ORD		15-Jun-2004	MKD	48	60	HINO EURO	VPH 494346	SWA 042491	08
2269	RT 295	KL-15	5473	LL	ORD		17-Jun-2004	KTR	48	60	HINO EURO	JNH 543972	SWA 042325	35
2270	RT 301	KL-15	5479	LL	ORD		24-Jun-2004	PNR	48	60	HINO EURO	SWH 264430	SWA 042486	78
2271	RT 303	KL-15	5481	LL	ORD		25-Jun-2004	NDD	48	60	HINO EURO	UDH 495447	XWA 042490	31
2272	RT 308	KL-15	5486	LL	ORD		28-Jun-2004	ADR	48	60	HINO EURO	SWH 266222	SWA 042630	38
2273	RT 309	KL-15	5487	LL	ORD		28-Jun-2004	KPZA	48	60	HINO EURO			07
2274	RT 310	KL-15	5488	LL	ORD		28-Jun-2004	VLRD	48	60	HINO EURO	SWH 265718	SWA 042415	93
2275	RT 317	KL-15	5495	LL	ORD		1-Jul-2004	KTDA	48	60	HINO EURO	SWH 00264437	SWA 042628	25
2276	RT 318	KL-15	5496	LL	ORD		1-Jul-2004	NTA	48	60	HINO EURO	10VHX2224	SWA 042416	22
2277	RT 321	KL-15	5499	LL	ORD		1-Jul-2004	PLR	48	60	HINO EURO	SWH 266171	SWA 042931	36
2278	RT 322	KL-15	5500	LL	ORD		3-Jul-2004	PTPM	48	60	HINO EURO	DBH 147310	SWA 042572	15
2279	RT 328	KL-15	5506	LL	ORD		13-Jul-2004	ALV	48	60	HINO EURO	SWH 265107	SWA 042573	61
2280	RT 329	KL-15	5507	LL	ORD		13-Jul-2004	KTR	48	60	HINO EURO	DBH 148004	SWA 042492	35
2281	RT 330	KL-15	5508	LL	ORD		13-Jul-2004	MLPY	48	60	HINO EURO	FBH 14539	SWA 042497	96
2282	RT 332	KL-15	5510	LL	ORD		13-Jul-2004	CDLM	48	60	HINO EURO	FMH 199489	SWA 042586	80
2283	RT 333	KL-15	5511	LL	ORD		13-Jul-2004	ADR	48	60	HINO EURO	XBH 154612	SWA 042596	38
2284	RT 334	KL-15	5512	LL	ORD		13-Jul-2004	TDP	48	60	HINO EURO	DVH 230164	SWA 042592	53
2285	RT 335	KL-15	5513	LL	ORD		13-Jul-2004	MPM	48	60	HINO EURO	SWH 266108	SWA 042420	71
2286	RT 343	KL-15	5521	LL	ORD		13-Jul-2004	KTDA	48	60	HINO EURO	WFH 395833	SWA 042423	25
2287	RT 356	KL-15	5534	LL	ORD		23-Jul-2004	NDD	48	60	HINO EURO	00238431	PWA 043161	31
2288	RT 357	KL-15	5535	LL	ORD		23-Jul-2004	KPZA	48	60	HINO EURO			07
2289	RT 361	KL-15	5539	LL	ORD		2-Aug-2004	KTDA	48	60	HINO EURO	FWH 287310	PWA 042897	25
2290	RT 362	KL-15	5540	LL	ORD		2-Aug-2004	VDCY	48	60	HINO EURO	ZVH 239760	PWA 042819	82
2291	RT 363	KL-15	5541	LL	ORD		2-Aug-2004	CDLM	48	60	HINO EURO	OVHN 32962	PWA 043173	80
2292	RT 368	KL-15	5546	LL	ORD		2-Aug-2004	KMR	48	60	HINO EURO	CVH 00233170	PWA 043170	30
2293	RT 369	KL-15	5547	LL	ORD		7-Aug-2004	PVM	48	60	HINO EURO	PWH 268419	PWA 043165	83
2294	RT 378	KL-15	5556	LL	ORD		17-Aug-2004	PNR	48	60	HINO EURO		PWA 043171	78
2295	RT 379	KL-15	5557	LL	ORD		17-Aug-2004	PMNA	48	60	HINO EURO	WBH 156663	PWA 043175	68
2296	RT 399	KL-15	5577	LL	ORD		14-Sep-2004	PALA	48	60	HINO EURO	NWH 272728	MWA 043649	50
2297	RT 402	KL-15	5580	LL	ORD		14-Sep-2004	PKDA	48	60	HINO EURO	BVH 238895	MWA 043980	81
2298	RT 422	KL-15	5600	LL	ORD		7-Oct-2004	NTA	48	60	HINO EURO	SWH 267400	PWA 042820	22
2299	RT 423	KL-15	5601	LL	ORD		7-Oct-2004	NBR	48	60	HINO EURO	SWH 00265180	PWA 042828	86
2300	RT 424	KL-15	5602	LL	ORD		7-Oct-2004	NTA	48	60	HINO EURO	SWH 266653	PWA 042894	22
2301	RT 425	KL-15	5603	LL	ORD		7-Oct-2004	PMNA	48	60	HINO EURO	WVH 00251875	PWA 042817	68
2302	RT 428	KL-15	5606	LL	ORD		11-Oct-2004	KTDA	48	60	HINO EURO	MWH 279748	LWA 044317	25
2303	RT 436	KL-15	5614	LL	ORD		11-Oct-2004	CDLM	48	60	HINO EURO	OVHN 34024	MWA 043849	80
2304	RT 454	KL-15	5632	LL	ORD		1-Nov-2004	NDD	48	60	HINO EURO	XVH 00247809	KWA 045000	31
2305	RT 456	KL-15	5634	LL	ORD		1-Nov-2004	PTA	48	60	HINO EURO	00279106	KWA 045065	37
2306	RT 505	KL-15	5682	LL	ORD		9-Nov-2004	CDLM	48	60	HINO EURO	MWH 277512	KWA 045063	80
2307	RT 506	KL-15	5683	LL	ORD		9-Nov-2004	KTR	48	60	HINO EURO	VBH 159439	KWA 045053	35
2308	RT 507	KL-15	5684	LL	ORD		9-Nov-2004	VTRA	48	60	HINO EURO	MWH 280137	KWA 045055	17
2309	RT 534	KL-15	5712	LL	ORD		19-Nov-2004	VLRD	48	60	HINO EURO	VHP 51011	KWA 045061	93
2310	RT 536	KL-15	5714	LL	ORD		19-Nov-2004	TLY	48	60	HINO EURO	BKH 138094	KWA 045003	18
2311	RT 537	KL-15	5715	LL	ORD		19-Nov-2004	KMR	48	60	HINO EURO	WDH 295722	KWA 045066	30

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2312	RT 556	KL-15	5734	LL	ORD		10-Dec-2004	PALA	48	60	HINO EURO	NWH 275965	KWA 045108	50
2313	RT 557	KL-15	5735	LL	ORD		9-Dec-2004	KNR	48	60	HINO EURO	JHV 16822	KWA 045113	77
2314	RT 558	KL-15	5736	LL	ORD		10-Dec-2004	KNR	48	60	HINO EURO	CVH 234049	KWA 045120	77
2315	RT 567	KL-15	5745	LL	ORD		17-Dec-2004	TLY	48	60	HINO EURO	NWH 00278621	KWA 045114	18
2316	RT 572	KL-15	5750	LL	ORD		23-Dec-2004	KNPY	48	60	HINO EURO	NWH 276442	KWA 045112	87
2317	RT 583	KL-15	5761	LL	ORD		1-Jan-2005	KMR	48	60	HINO EURO	XVH 247128	KWA 045066	30
2318	RT 591	KL-15	5769	LL	ORD		3-Jan-2005	ARND	48	60	HINO EURO	JVH 225054	KWA 045107	19
2319	RT 592	KL-15	5770	LL	ORD		3-Jan-2005	NTA	48	60	HINO EURO	WVH 251874	LWA 044487	22
2320	RT 594	KL-15	5772	LL	ORD		6-Jan-2005	NTA	48	60	HINO EURO	FWH 284634	FWA 045932	22
2321	RT 605	KL-15	5782	LL	ORD		24-Jan-2005	KNR	48	60	HINO EURO	JWH 292075	JWA 045860	77
2322	RT 607	KL-15	5784	LL	ORD		24-Jan-2005	KPZA	48	60	HINO EURO			07
2323	RT 610	KL-15	5787	LL	ORD		25-Jan-2005	KNR	48	60	HINO EURO	FWH 284673	JHA 045891	77
2324	RT 613	KL-15	5790	LL	ORD		1-Feb-2005	NDD	48	60	HINO EURO		FWA 045962	31
2325	RT 614	KL-15	5791	LL	ORD		1-Feb-2005	KNR	48	60	HINO EURO	FWH 284870	JWA 045890	77
2326	RT 615	KL-15	5792	LL	ORD		1-Feb-2005	PNI	48	60	HINO EURO	FVH 227087	JWA 045862	67
2327	RT 616	KL-15	5793	LL	ORD		1-Feb-2005	PNR	48	60	HINO EURO		JWA 045899	78
2328	RT 618	KL-15	5795	LL	ORD		4-Feb-2005	KNR	48	60	HINO EURO	FWH 286656	DWA 046439	77
2329	RT 619	KL-15	5796	LL	ORD		5-Feb-2005	PALA	48	60	HINO EURO	FWH 288346	DWA 046443	50
2330	RT 620	KL-15	5797	LL	ORD		5-Feb-2005	PALA	48	60	HINO EURO	BLH 165890	DWA 046430	50
2331	RT 621	KL-15	5798	LL	ORD		5-Feb-2005	VTRA	48	60	HINO EURO	FWH 287313	DWA 046437	17
2332	RT 622	KL-15	5799	LL	ORD		10-Feb-2005	PVM	48	60	HINO EURO	LBH 162535	DWA 046440	83
2333	RT 623	KL-15	5800	LL	ORD		10-Feb-2005	PNR	48	60	HINO EURO		FWA 046249	78
2334	RT 624	KL-15	5801	LL	ORD		10-Feb-2005	NTA	48	60	HINO EURO	FWH 288320	DWA 046441	22
2335	RT 625	KL-15	5802	LL	ORD		10-Feb-2005	PALA	48	60	HINO EURO	FWH 287354	DWA 046434	50
2336	RT 626	KL-15	5803	LL	ORD		10-Feb-2005	VKM	48	60	HINO EURO	UPH 494344	FWA 045971	51
2337	RT 628	KL-15	5805	LL	ORD		15-Feb-2005	VLRD	48	60	HINO EURO	FWH 287259	DWA 046429	93
2338	RT 629	KL-15	5806	LL	ORD		15-Feb-2005	KMR	48	60	HINO EURO	DWH 292074	DWA 046432	30
2339	RT 631	KL-15	5808	LL	ORD		15-Feb-2005	TSY	48	60	HINO EURO	XBH 153926	FWA 046193	73
2340	RT 632	KL-15	5809	LL	ORD		15-Feb-2005	PALA	48	60	HINO EURO	FWH 288495	DWA 046446	50
2341	RT 636	KL-15	5813	LL	ORD		18-Feb-2005	KTR	48	60	HINO EURO	FWH 286712	FWA 046195	35
2342	RT 637	KL-15	5814	LL	ORD		21-Feb-2005	PNKM	48	60	HINO EURO	XVW 248594	DWA 046431	49
2343	RT 638	KL-15	5815	LL	ORD		21-Feb-2005	KKLM	48	60	HINO EURO	FWH 286765	FWA 046306	108
2344	RT 639	KL-15	5816	LL	ORD		21-Feb-2005	CTLA	48	60	HINO EURO	FWH 287314	JVZ 131259	46
2345	RT 718	KL-15	5896	LL	ORD		2-May-2005	PPD	48	60	HINO EURO	FWH 286757	DWA 046359	26
2346	RT 719	KL-15	5897	LL	ORD		2-May-2005	PPD	48	60	HINO EURO	NKH 123227	WDA 047444	26
2347	RT 720	KL-15	5898	LL	ORD		2-May-2005	PPD	48	60	HINO EURO	WPH 480991	WDA 047442	26
2348	RT 721	KL-15	5899	LL	ORD		2-May-2005	PPD	48	60	HINO EURO	HN 1450	DWA 046361	26
2349	RT 722	KL-15	5900	LL	ORD		2-May-2005	PPD	48	60	HINO EURO	LBH 163199	WDA 017249	26
2350	RT 727	KL-15	5905	LL	ORD		2-May-2005	VLND	48	60	HINO EURO	FBH 145046	WOA 047356	20
2351	RT 740	KL-15	5918	LL	ORD		16-May-2005	PLR	48	60	HINO EURO	00250383	WDA 047538	36
2352	RT 741	KL-15	5919	LL	ORD		16-May-2005	ADR	48	60	HINO EURO	DWH 289414	WDA 047747	38
2353	RT 744	KL-15	5922	LL	ORD		19-May-2005	PPD	48	60	HINO EURO	DWH 292198	WDA 047446	26
2354	RT 745	KL-15	5923	LL	ORD		19-May-2005	PPD	48	60	HINO EURO	CVH 00234986	WDA 047364	26
2355	RT 746	KL-15	5924	LL	ORD		19-May-2005	VLND	48	60	HINO EURO	WDH 298425	WDA 047754	20
2356	RT 751	KL-15	5929	LL	ORD		24-May-2005	VLND	48	60	HINO EURO	00293520	WDA 047242	20

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2357	RT 766	KL-15	5944	LL	ORD	VND	7-Jun-2005	PVR	48	60	HINO EURO	DWH292295	WDA 047443	23
2358	RT 767	KL-15	5945	LL	ORD	VND	7-Jun-2005	KMR	48	60	HINO EURO	00292117	WDA 047245	30
2359	RT 777	KL-15	5955	LL	ORD	VND	21-Jun-2005	CHRY	48	60	HINO EURO	DWH293519	WDA047251	44
2360	RT 778	KL-15	5956	LL	ORD	VND	21-Jun-2005	KNR	48	60	HINO EURO	ZBH 162689	WDA 047253	77
2361	RT 780	KL-15	5958	LL	ORD	VND	21-Jun-2005	PTA	48	60	HINO EURO	2LH 167413	WDA 047587	37
2362	RT 781	KL-15	5959	LL	ORD	VND	21-Jun-2005	ADR	48	60	HINO EURO	DWH 292202	WDA 047247	38
2363	RT 782	KL-15	5960	LL	ORD	VND	21-Jun-2005	PLD	48	60	HINO EURO	WDH 295721	WDA 047423	32
2364	RT 783	KL-15	5961	LL	ORD	VND	21-Jun-2005	VTRA	48	60	HINO EURO	WDH 295622	WDA047425	17
2365	RT 790	KL-15	5968	LL	ORD	VND	25-Jun-2005	VLRD	48	60	HINO EURO	WDH 296563	WDA 047757	93
2366	RT 801	KL-15	5979	LL	ORD	VND	4-Jul-2005	PALA	48	60	HINO EURO	WDH 296204	WDA 047566	50
2367	RT 802	KL-15	5980	LL	ORD		4-Jul-2005	VLRD	48	60	HINO EURO	CVH 233159	WDA 047750	93
2368	RT 805	KL-15	5983	LL	ORD	VND	11-Jul-2005	PALA	48	60	HINO EURO	WDH 296193	WDA 047567	93
2369	RT 806	KL-15	5984	LL	ORD		11-Jul-2005	VLRD	48	60	HINO EURO	ZLH 167903	WDA 047579	93
2370	RT 807	KL-15	5985	LL	ORD		12-Jul-2005	PTPM	48	60	HINO EURO	WQH 00295962	WDA 047453	15
2371	RT 809	KL-15	5987	LL	ORD		12-Jul-2005	KMY	48	60	HINO EURO		WDA 047753	05
2372	RT 810	KL-15	5988	LL	ORD		12-Jul-2005	KMGH	48	60	HINO EURO	UDH 306829 170352	WDA 047749	55
2373	RT 812	KL-15	5990	LL	ORD	VND	12-Jul-2005	MDY	48	60	HINO EURO	OO295716	WDA 047422	76
2374	RT 813	KL-15	5991	LL	ORD	VND	12-Jul-2005	KPZA	48	60	HINO EURO			07
2375	RT 814	KL-15	5992	LL	ORD	VND	12-Jul-2005	KPA	48	60	HINO EURO			74
2376	RT 824	KL-15	6002	LL	ORD		19-Jul-2005	PTA	48	60	HINO EURO	KXE 1067172	WDA 047353	37
2377	RT 825	KL-15	6003	LL	ORD	VND	19-Jul-2005	TDP	48	60	HINO EURO	WPH 295959	WDA 047454	53
2378	RT 832	KL-15	6010	LL	ORD		20-Jul-2005	NTA	48	60	HINO EURO	UDH 308183	UDE 551694	22
2379	RT 833	KL-15	6011	LL	ORD		20-Jul-2005	NTA	48	60	HINO EURO	UDH 308184	UDE 551683	22
2380	RT 834	KL-15	6012	LL	ORD	VND	26-Jul-2005	MPM	48	60	HINO EURO			71
2381	RT 835	KL-15	6013	LL	ORD		26-Jul-2005	TDP	48	60	HINO EURO	UDH 307538	UDE 551704	53
2382	RT 836	KL-15	6014	LL	ORD		26-Jul-2005	TDP	48	60	HINO EURO	UDH 307531	UDE 551693	53
2383	RT 837	KL-15	6015	LL	ORD		26-Jul-2005	KTDA	48	60	HINO EURO	WAE 1200242	UDE 551695	25
2384	RT 838	KL-15	6016	LL	ORD	VND	26-Jul-2005	KTDA	48	60	HINO EURO	VWH 258437	WDA 047351	25
2385	RT 839	KL-15	6017	LL	ORD	VND	26-Jul-2005	KTDA	48	60	HINO EURO	HN 131415	WDA 047450	25
2386	RT 841	KL-15	6019	LL	ORD	VND	27-Jul-2005	VLRD	48	60	HINO EURO	CVH 235103	WDA 047452	93
2387	RT 886	KL-15	6064	LL	ORD		27-Aug-2005	KTR	48	60	HINO EURO	UDH 308171	UDE 551839	35
2388	RT 888	KL-15	6066	LL	ORD		27-Aug-2005	KTDA	48	60	HINO EURO	VHN 36462	UDE 551268	25
2389	RT 889	KL-15	6067	LL	ORD		27-Aug-2005	VTRA	48	60	HINO EURO	UDH 306792	UDE 551206	17
2390	RT 894	KL-15	6072	LL	ORD		1-Sep-2005	PPD	48	60	HINO EURO	YVH 243876	UDE 551840	26
2391	RT 895	KL-15	6073	LL	ORD		1-Sep-2005	KTDA	48	60	HINO	BNE 103724	UDE 551282	25
2392	RT 898	KL-15	6076	LL	ORD		2-Sep-2005	CTLA	48	60	HINO EURO	UWH 258545	UDE 551222	46
2393	RT 899	KL-15	6077	LL	ORD		2-Sep-2005	RNI	48	60	HINO EURO	WDH 295990	WDA 047359	101
2394	RT 900	KL-15	6078	LL	ORD		3-Sep-2005	PNKM	48	60	HINO EURO	CMH 203103	UDE 551221	49
2395	RT 920	KL-15	6098	LL	ORD		19-Sep-2005	PPD	48	60	HINO EURO	UDH 308243	UDE 551818	26
2396	RT 925	KL-15	6103	LL	ORD	VND	17-Oct-2005	ARK	48	60	HINO EURO	10 VHC 3017	TDE 553837	06
2397	RT 939	KL-15	6117	LL	ORD		19-Nov-2005	KTDA	48	60	HINO EURO BS III	VVH 249399	TDE 553952	25
2398	RT 940	KL-15	6118	LL	ORD		19-Nov-2005	PPD	48	60	HINO EURO	ZVH 00240753	UDE 550880	26
2399	RT 945	KL-15	6123	LL	ORD	SWB	3-Dec-2005	ARK	48	60	HINO EURO	SWH 00266232	WDE 551558	06
2400	RT 949	KL-15	6127	LL	ORD	SWB	6-Dec-2005	VTRA	48	60	HINO EURO	UDH 306422	UDE 551557	17
2401	RT 950	KL-15	6128	LL	ORD	SWB	12-Dec-2005	NDD	48	60	HINO EURO	1036132 LL HINO	UDE 551380	31

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2402	RT 951	KL-15	6129	LL	ORD	SWB	22-Dec-2005	PTA	48	60	HINO EURO	UDH 306417	UDE 551556	37
2403	RT 952	KL-15	6130	LL	ORD	SWB	24-Dec-2005	KTR	48	60	HINO EURO	UDH 306429	UDE 551478	35
2404	RT 953	KL-15	6131	LL	ORD	SWB	2-Jan-2006	PNKM	48	60	HINO EURO	UDH 306416	UBE 551562	49
2405	RT 954	KL-15	6132	LL	ORD	SWB	5-Jan-2006	NTA	48	60	HINO EURO	WFH 396100	UDE 552068	22
2406	RT 955	KL-15	6133	LL	ORD	SWB	12-Jan-2006	KPZA	48	60	HINO EURO			07
2407	RT 963	KL-15	6141	LL	ORD	VND	1-Apr-2006	PMNA	48	60	HINO EURO	UDH 307278	UDE 551341	68
2408	RT 964	KL-15	6142	LL	ORD	VND	1-Apr-2006	TVL	48	60	HINO EURO	TDH 312550	TDE 553965	43
2409	RT 970	KL-15	6148	LL	ORD	VND	1-Apr-2006	CHRY	48	60	HINO EURO	TDH313124	TDE553824	44
2410	RT 975	KL-15	6153	LL	ORD	VND	3-Apr-2006	VKBN	48	60	HINO W0 6E BSII	TDH 312288	TDE 553872	29
2411	RT 976	KL-15	6154	LL	ORD	VND	4-Apr-2006	CHRY	48	60	HINO EURO	UDH306644	UDE551069	44
2412	RT 980	KL-15	6158	LL	ORD	VND	6-Apr-2006	KKD	48	60	HINO EURO	TDH 312217	SDE 554786	72
2413	RT 981	KL-15	6159	LL	ORD	VND	10-Apr-2006	KHD	48	60	HINO EURO	TDH 314550	SDE 554696	106
2414	RT 995	KL-15	6173	LL	ORD	VND	20-Apr-2006	PLKD	48	60	HINO EURO	TDH 313086	TDE 553867	69
2415	RT 996	KL-15	6174	LL	ORD	VND	21-Apr-2006	VDA	48	60	HINO EURO			92
2416	RT 997	KL-15	6175	LL	ORD	VND	21-Apr-2006	MVPA	48	60	HINO EURO	00265107	TDE 552687	52
2417	RR 1	KL-15	6179	LL	ORD		9-May-2006	KTM	48	60	HINO EURO	TDH 314470	SDE 555162	47
2418	RR 4	KL-15	6182	LL	ORD		2-May-2006	CGNR	48	60	HINO EURO	SDH315099	SDE555160	40
2419	RR 18	KL-15	6196	LL	ORD	VND	19-May-2006	KPA	48	60	HINO EURO			74
2420	RR 19	KL-15	6197	LL	ORD	VND	19-May-2006	ADR	48	60	HINO BSII	UDH 310145	TDE 552699	38
2421	RR 27	KL-15	6205	LL	ORD	VND	22-Jun-2006	KPA	48	60	HINO EURO			74
2422	RR 51	KL-15	6229	LL	ORD		29-Aug-2006	NTA	48	60	HINO EURO BSII	SDH 314743	SDE 555048	22
2423	RRC968	KL-15	7122	LL	ORD		11-Aug-2008	KMR	48	60	HINO EURO 11 TURBO INTER COOLER	MNH 518359	MNE 645036	30
2424	RRK908	KL-15	7130	LL	ORD		8-Sep-2008	PSL	48	60	HINO EURO 11 TURBO INTER COOLER BS11	JNH 541907	JNE 654242	21
2425	RR 20	KL-15	6198	LL	ORD	VND	22-May-2006	TSY	48	60	HINO EURO 6E BSII	TDH 312406	TDE 553866	73
2426	TP 712	KL-15	4890	LL	ORD		1-Aug-2003	KKD	48	60	HINO EURO ALPSV 4/19	WBH 157735	FVE 503157	72
2427	RT 37	KL-15	5215	LL	ORD		12-Feb-2004	CTY	48	60	HINO EURO ALPSV 4/19 HINO W06EI	YVH 00243404	WVE 518450	28
2428	RT 56	KL-15	5234	LL	ORD		19-Feb-2004	PNR	48	60	HINO EURO ALPSV 4/19 K106EI		XVE 517631	78
2429	RR 5	KL-15	6183	LL	ORD		2-May-2006	TDP	48	60	HINO EURO ALPSV 4/51	SDH 315020	SDE 555120	53
2430	RR 8	KL-15	6186	LL	ORD	VND	8-May-2006	NTA	48	60	HINO EURO BS II	UDH 307712	TDE 552648	22
2431	RR 9	KL-15	6187	LL	ORD	VND	8-May-2006	NTA	48	60	HINO EURO BS II	TDH 314226	SDE 554787	22
2432	RR 10	KL-15	6188	LL	ORD	VND	8-May-2006	NTA	48	60	HINO EURO BS II	UDH 310374	TDE 552712	22
2433	RR 11	KL-15	6189	LL	ORD	VND	8-May-2006	NTA	48	60	HINO EURO BS II	UDH 310328	TDE 552697	22
2434	RT 484	KL-15	5662	LL	ORD		6-Nov-2004	PDM	48	60	HINO EURO BSI	277478	KWA 045111	39
2435	RT 959	KL-15	6137	LL	ORD		16-Feb-2006	ADR	48	60	HINO BSII	UDH 292202	UDH 093609	38
2436	RT 966	KL-15	6144	LL	ORD	VND	1-Apr-2006	KTDA	48	60	HINO EURO BSII	FWH 00288788	TDE 554120	25
2437	RT 973	KL-15	6151	LL	ORD	VND	1-Apr-2006	VLRD	48	60	HINO BSII	245793	VBE 548724	93
2438	RT 982	KL-15	6160	LL	ORD	VND	10-Apr-2006	KTDA	48	60	HINO EURO BSII	WVH 00251647	SDE 554652	25
2439	RT 983	KL-15	6161	LL	ORD	VND	10-Apr-2006	KTDA	48	60	HINO EURO BSII	SWH 266653	SDE 554849	25
2440	RT 994	KL-15	6172	LL	ORD	VND	20-Apr-2006	PLD	48	60	HINO EURO BSII	SDH 315428	SDE 555848	32
2441	RR 2	KL-15	6180	LL	ORD		2-May-2006	MPM	48	60	HINO EURO BSII			71
2442	RR 21	KL-15	6199	LL	ORD	VND	25-May-2006	TVL	48	60	HINO EURO BSII	KDH 342273	TDE 553823	43
2443	RR 24	KL-15	6202	LL	ORD	VND	29-May-2006	TVL	48	60	HINO EURO BSII	TDH 313307	TDE 554035	43
2444	RR 25	KL-15	6203	LL	ORD	VND	2-Jun-2006	TVL	48	60	HINO EURO BSII	XBH 154579	SDE 554651	43
2445	RR 48	KL-15	6226	LL	ORD		17-Aug-2006	TVL	48	60	HINO EURO BSII	VHX 02331	SDE 555024	43
2446	RR 49	KL-15	6227	LL	ORD		17-Aug-2006	TVL	48	60	HINO EURO BSII	ZLH 167763	SDE 555850	43

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2447	RR 52	KL-15	6230	LL	ORD		29-Aug-2006	KTDA	48	60	HINO EURO BSII	TDH314651	SDE 555047	25
2448	RR 53	KL-15	6231	LL	ORD		31-Aug-2006	NTA	48	60	HINO EURO BSII	SDH 314719	SDE 555049	22
2449	RRC378	KL-15	6537	LL	ORD	MLB	15-Jan-2008	TLY	48	60	HINO EURO BSII	TPH 498866	TPE 637116	18
2450	RRC362	KL-15	6524	LL	ORD	MLB	11-Jan-2008	TLY	48	60	HINO EURO BSII	TPH 502294	TPE 637604	18
2451	RRC361	KL-15	6531	LL	ORD	MLB	14-Jan-2008	TLY	48	60	HINO EURO BSII	UPH 497747	TPE 637329	18
2452	RRC379	KL-15	6543	LL	ORD	MLB	16-Jan-2008	MDY	48	60	HINO EURO BSII	UPH 497753	TPE 637117	76
2453	RRK336	KL-15	6551	LL	ORD	MLB	21-Jan-2008	TLY	48	60	HINO EURO BSII	UPH 495360	VPE 635255	18
2454	RRK386	KL-15	6560	LL	ORD	MLB	21-Jan-2008	TLY	48	60	HINO EURO BSII	UPH 495362	UPE 635256	18
2455	RRE400	KL-15	6591	LL	ORD	MLB	31-Jan-2008	KPA	48	60	HINO EURO BSII	UPH 492931	UPE 634367	74
2456	RRC436	KL-15	6599	LL	ORD	VND	1-Feb-2008	MLPY	48	60	HINO EURO BSII	UPH 497222	UPE 635425	96
2457	RRE597	KL-15	6759	LL	ORD	MLB	14-Mar-2008	TSY	48	60	HINO EURO BSII	NPH 505649	NPE 640741	73
2458	RRE409	KL-15	6651	LL	ORD	VND	16-Feb-2008	KMGH	48	60	HINO EURO BSII	UPH 493956	UPE 635631	55
2459	RRK522	KL-15	6660	LL	ORD	VND	18-Feb-2008	CTY	48	60	HINO EURO BSII	IOUHD1362	UPE 635629	28
2460	RRK492	KL-15	6641	LL	ORD	VND	13-Feb-2008	CTY	48	60	HINO EURO BSII	NPH 504721	NPE 639568	28
2461	RRK838	KL-15	7059	LL	ORD		23-Jun-2008	ADR	48	60	HINO EURO BSII	KNH 333801	KNE 651673	38
2462	RRE918	KL-15	7078	LL	ORD		4-Jul-2008	MNR	48	60	HINO EURO BSII	JNE 654697	JNE 654227	60
2463	RRC956	KL-15	7115	LL	ORD		11-Aug-2008	KLM	48	60	HINO EURO BSII	MNH 518368	MNE 645056	34
2464	RRC961	KL-15	7116	LL	ORD		11-Aug-2008	VZM	48	60	HINO EURO BSII	MNH 519571	MNE 644761	24
2465	RRE920	KL-15	7081	LL	ORD		7-Jul-2008	PKDA	48	60	HINO EURO BSII	JNH 538744	JNE 654637	81
2466	RRE921	KL-15	7082	LL	ORD		9-Jul-2008	CDLM	48	60	HINO EURO BSII	VXH 7773	JNE 653988	80
2467	RAC 8	KL-15	7169	LL	ORD	SWB	3-Sep-2008	ARK	48	60	HINO EURO BSII	FWH 545562	FNE 656794	06
2468	RAE130	KL-15	7291	LL	ORD		20-Dec-2008	EDT	48	60	HINO EURO BSII	BNE 103640Z	BNE 665338	98
2469	RAA121	KL-15	7301	LL	ORD		24-Dec-2008	PLR	48	60	HINO EURO BSII	CNE 103232Z	CNE 664112	36
2470	RAA147	KL-15	7302	LL	ORD		24-Dec-2008	EDT	48	60	HINO EURO BSII	JNH 539395 VHG2817	JNE 655736	98
2471	RAK159	KL-15	7340	LL	ORD		6-Jan-2009	CGNR	48	60	HINO EURO BSII	BNE 103630Z	BNE 665333	40
2472	RAK103	KL-15	7309	LL	ORD		29-Dec-2008	ATL	48	60	HINO EURO BSII	CNH 560767	BNE 665250	33
2473	RAE269	KL-15	7409	LL	ORD		30-Jan-2009	PDM	48	60	HINO EURO BSII	ZNE 104336	YNE 667396	39
2474	RAE270	KL-15	7415	LL	ORD		2-Feb-2009	PLD	48	60	HINO W06ETI BSII	ZNE 104284	YNE 667361	32
2475	RAA199	KL-15	7405	LL	ORD		29-Jan-2009	CGNR	48	60	HINO EURO BSII	ZNE 104156Z	ZNE 666771	40
2476	RAC262	KL-15	7429	LL	ORD	VND	5-Feb-2009	KTR	48	60	HINO EURO BSII	ZNE 104038Z	ZNE 666219	35
2477	RAC295	KL-15	7453	LL	ORD		16-Feb-2009	MNR	48	60	HINO EURO BSII	WXE 114469Z	YNE 667374	60
2478	RAC337	KL-15	7506	LL	ORD	VND	2-Mar-2009	TPLM	48	60	HINO EURO BSII	ZNE 104269Z	XNE 667899	94
2479	RAC374	KL-15	7523	LL	ORD		7-Mar-2009	KHD	48	60	HINO EURO BSII	ZNE 104366Z	XNE 667920	106
2480	RAE331	KL-15	7517	LL	ORD		7-Mar-2009	TSY	48	60	HINO EURO BSII	XNE 104649Z	XNE 667963	73
2481	RAE367	KL-15	7540	LL	ORD		16-Mar-2009	VLRD	48	60	HINO EURO BSII		NXE 669087	93
2482	RAC387	KL-15	7544	LL	ORD		16-Mar-2009	VLRD	48	60	HINO EURO BSII	XNE 104398Z	NXE 668392	93
2483	RAC388	KL-15	7545	LL	ORD		16-Mar-2009	PSL	48	60	HINO EURO BSII	NXE 105206Z	NXE 669041	21
2484	RAC402	KL-15	7553	LL	ORD		18-Mar-2009	NTA	48	60	HINO EURO BSII	NXE 105284Z	NXE 669222	22
2485	RAC403	KL-15	7557	LL	ORD		21-Mar-2009	KTDA	48	60	HINO EURO BSII	NXH 171399	NXE 669221	25
2486	RAC381	KL-15	7542	LL	ORD		16-Mar-2009	TLY	48	60	HINO EURO BSII	XNE 104932Z	NXE 668470	18
2487	RAC453	KL-15	7616	LL	ORD	SWB	13-Apr-2009	KMGH	48	60	HINO EURO BSII	LXH 572100	LXE 669948	55
2488	RAC529	KL-15	7669	LL	ORD		28-Apr-2009	ADR	48	60	HINO EURO BSII	LXH 573069	LXE 670156	38
2489	RAC565	KL-15	7727	LL	ORD		16-May-2009	PPD	48	60	HINO EURO BSII	KXH 574904	KXE 672072	26
2490	RAC649	KL-15	7797	LL	ORD	VND	20-Jun-2009	ADR	48	60	HINO BSII	LXH 572806	LXE 670115	38
2491	RAC607	KL-15	7811	LL	ORD	VND	22-Jun-2009	ADR	48	60	HINO BSII	KXH 574764	KXE 671915	38

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2492	RAC669	KL-15	7851	LL	ORD	VND	2-Jul-2009	MNR	48	60	HINO EURO BSII	LXH 572996	LXE 670236	60
2493	RAC652	KL-15	7815	LL	ORD	VND	23-Jun-2009	ADR	48	60	HINO BSII	LXE 105774Z	LXE 670499	38
2494	RAC664	KL-15	7816	LL	ORD	VND	23-Jun-2009	ADR	48	60	HINO BSII	KXH 574026	KXE 672039	38
2495	RAK893	KL-15	8085	LL	ORD		19-Nov-2009	PDM	48	60	HINO EURO BSII	CXE 108849Z	MB1PBEHC39ECA5212	39
2496	RAC976	KL-15	8156	LL	ORD		2-Jan-2010	KDLR	48	60	HINO EURO BSII			90
2497	RAC977	KL-15	8157	LL	ORD		2-Jan-2010	KDLR	48	60	HINO EURO BSII	ZXE 11643Z	MB1PBEHC99EZB0674	90
2498	RAC985	KL-15	8170	LL	ORD		11-Jan-2010	MNR	48	60	HINO EURO BSII	YXE 112982Z	MB1PBEHC29EYB2859	60
2499	RAK964	KL-15	8171	LL	ORD		12-Jan-2010	MNR	48	60	HINO EURO BSII	ZXE 111567Z	MB1PBEHC59EZB0543	60
2500	RNC 1	KL-15	8180	LL	ORD	VND	14-Jan-2010	ADR	48	60	HINO BSII	YXE 112887Z	EYB 2999	38
2501	RAE996	KL-15	8200	LL	ORD		4-Feb-2010	VKBN	48	60	HINO EURO BSII		MB1PBEHC89EWB5436	29
2502	RNE 26	KL-15	8202	LL	ORD		9-Feb-2010	KHD	48	60	HINO EURO BSII	CXE108948Z	MB1PBEHC79ECA5486	106
2503	RAK989	KL-15	8203	LL	ORD		9-Feb-2010	VKBN	48	60	HINO EURO BSII		MB1PBEHC09E2B0238	29
2504	RNC 19	KL-15	8211	LL	ORD	MLB	19-Feb-2010	TLY	48	60	HINO EURO BSII	WXE 114478Z	EWB 5654	18
2505	RNM 5	KL-15	8226	LL	ORD		15-Mar-2010	PVM	48	60	HINO EURO BSII	WXE114475Z	MB1PBEHCX9EWB5535	83
2506	RNK 81	KL-15	8274	LL	ORD		26-Apr-2010	PVM	48	60	HINO EURO BSII	WAE119664Z	MB1PBEHC6AEWC3359	83
2507	RNK112	KL-15	8356	LL	ORD		2-Jun-2010	ADR	48	60	HINO BSII	WAE119123Z	MB1PBEHC5AEWC3112	38
2508	RNK180	KL-15	8380	LL	ORD		9-Jun-2010	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	WXE114469Z	MB1PBEHC1AE9B5646	14
2509	RNE153	KL-15	8381	LL	ORD	VND	10-Jun-2010	KTP	48	60	HINO EURO BSII TURBO COOLER	ZXE111541Z	MB1PBEHC5AEVC5603	14
2510	RNK305	KL-15	8513	LL	ORD	VND	27-Jul-2010	ADR	48	60	HINO BSII	VAE121870Z	MB1PBEHC7AEVC6364	38
2511	RNC341	KL-15	8577	LL	ORD	SWB	18-Aug-2010	NDD	48	60	HINO EURO BSII	VAE122469Z	MAT412088XAEVC7280	31
2512	RNC472	KL-15	8734	LL	ORD	SWB	15-Oct-2010	VTRA	48	60	HINO EURO BSII	NAE129221Z	MB1PCEHC1AEND4408	17
2513	RNC643	KL-15	8912	LL	ORD		13-Dec-2010	TLY	48	60	HINO EURO BSII	WAE120644Z	MB1PBEHC7AEVC4632	18
2514	RNK563	KL-15	8936	LL	ORD		28-Dec-2010	MNR	48	60	HINO EURO BSII	NAE129986Z	MB1PBEHC4AEND5085	60
2515	RNK561	KL-15	8952	LL	ORD		5-Jan-2011	PDM	48	60	HINO EURO BSII	MAE13235Z	MB1PBEHC1AEMD7499	39
2516	RNK562	KL-15	8953	LL	ORD		5-Jan-2011	MDY	48	60	HINO EURO BSII	NAE129659Z	MB1PBEHC7AEND4738	76
2517	RNK564	KL-15	8980	LL	ORD		19-Jan-2011	ATL	48	60	HINO EURO BSII	NAE129751Z	MB1PBEHC9AEND4899	33
2518	RNE731	KL-15	9089	LL	ORD	SWB	21-Mar-2011	MNR	48	60	HINO EURO BSII	MAE130980Z	MB1PBEHC4AEMD6067	60
2519	RAC336	KL-15	7486	LL	ORD	VND	26-Feb-2009	KMGM	48	60	HINO EURO BSII ALPSV 4/89	ZNE 104310Z	YNE 667410	55
2520	RAC651	KL-15	7799	LL	ORD		20-Jun-2009	KMGM	48	60	HINO EURO BSII ALPSV 4/89	LXE 105715Z	LXE 670497	55
2521	RAC606	KL-15	7810	LL	ORD		22-Jun-2009	KMGM	48	60	HINO EURO BSII ALPSV 4/89	KXE 106050Z	KXE 671904	55
2522	RAC665	KL-15	7832	LL	ORD		26-Jun-2009	KMGM	48	60	HINO EURO BSII ALPSV 4/89	KXH 574356	KXE 671512	55
2523	RAC668	KL-15	7850	LL	ORD	VND	2-Jul-2009	EKM	48	60	HINO EURO BSII ALPSV 4/89	KXE 672004	KXH 574475	56
2524	RAC666	KL-15	7817	LL	ORD	SWB	23-Jun-2009	KMGM	48	60	HINO EURO BSII ALPSV 4/89	KXE 106230Z	KXE 671480	55
2525	RNK689	KL-15	8981	LL	ORD		19-Jan-2011	KMGM	48	60	HINO EURO BSII ALPSV 4/89	NAE129656Z	MB1PBEHC3AEND4736	55
2526	RNK690	KL-15	8982	LL	ORD		19-Jan-2011	KMGM	48	60	HINO EURO BSII ALPSV 4/89	NAE129654Z	MB1PBEHC5AEND4737	55
2527	RAE994	KL-15	8179	LL	ORD		14-Jan-2010	EKM	48	60	HINO EURO BSII ALPSV 4/89 VIKING	YXE 112941Z	MBIPBEHC59EYBZ984	56
2528	RAC297	KL-15	7460	LL	ORD	VND	18-Feb-2009	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	ZNE 104396Z	YNE 667395	14
2529	RAC299	KL-15	7461	LL	ORD	VND	18-Feb-2009	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	ZNE 104313Z	YNE 667349	14
2530	RAK965	KL-15	8184	LL	ORD		19-Jan-2010	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	LXH 573178	MB1PBEHC79EZB0513	14
2531	RAK988	KL-15	8185	LL	ORD		19-Jan-2010	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	ZNE 104389Z	MB1PBEHC99EZB0237	14
2532	RAC592	KL-15	7771	LL	ORD	VND	1-Jun-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER	KXH 574133	KXE 672005	07
2533	RT 969	KL-15	6147	LL	ORD	VND	1-Apr-2006	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER			07
2534	RT 991	KL-15	6169	LL	ORD		20-Apr-2006	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER			07
2535	RAC206	KL-15	7373	LL	ORD		15-Jan-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER		BNE 665515	07
2536	RAC441	KL-15	7598	LL	ORD	SWB	1-Apr-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER	LXH 572150	LXE 669768	07

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2537	RAC586	KL-15	7735	LL	ORD		20-May-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER	LXH 573272	LXE 670242	07
2538	RAC589	KL-15	7736	LL	ORD		20-May-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER	LXH 573278	LXE 670233	07
2539	RAC590	KL-15	7757	LL	ORD		28-May-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER	LXH 573496	KXE 671176	07
2540	RAC588	KL-15	7762	LL	ORD	VND	30-May-2009	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER	LXH 572357	LXE 670152	07
2541	RAK962	KL-15	8163	LL	ORD		6-Jan-2010	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER			07
2542	RT 97	KL-15	5275	LL	ORD		11-Mar-2004	KLM	48	60	HINO EURO I	251874	WVE 519485	34
2543	RT 905	KL-15	6083	LL	ORD		9-Sep-2005	NTA	48	60	HINO EURO II	VDH 301403	UDF 550636	22
2544	RT 906	KL-15	6084	LL	ORD		12-Sep-2005	NTA	48	60	HINO EURO II	VDH 301321	UDF 550916	22
2545	RT 992	KL-15	6170	LL	ORD		20-Apr-2006	VTRA	48	60	HINO BS II	SDH 315475	SDE 555658	17
2546	RAE 71	KL-15	7314	LL	ORD	VND	29-Dec-2008	VTRA	48	60	HINO EURO II	CNH 560891	CNE 663425	17
2547	RAC177	KL-15	7324	LL	ORD	SWB	1-Jan-2009	KMY	48	60	HINO EURO II	NAE 129751Z	ZNE 666532	05
2548	RAK154	KL-15	7311	LL	ORD		29-Dec-2008	KNI	48	60	HINO EURO II	CNH 559786	BNE 665235	107
2549	RAC318	KL-15	7469	LL	ORD	VND	20-Feb-2009	NPR	48	60	HINO EURO II	ZNE104384Z	YNE 667362	62
2550	RAC319	KL-15	7470	LL	ORD	VND	20-Feb-2009	NPR	48	60	HINO EURO II	ZNE 104365Z	XNE 667901	62
2551	RAC340	KL-15	7497	LL	ORD	VND	28-Feb-2009	KMY	48	60	HINO EURO II	YNE 104617Z	XNE 667938	05
2552	RAC135	KL-15	7565	LL	ORD		1-Apr-2009	KMGH	48	60	HINO EURO II	CNH 560719	BNE 665242	55
2553	RAE397	KL-15	7561	LL	ORD		23-Mar-2009	CTY	48	60	HINO EURO II		NXE 668472	28
2554	RAE398	KL-15	7562	LL	ORD		23-Mar-2009	CTY	48	60	HINO EURO II		NXE 668403	28
2555	RAC408	KL-15	7576	LL	ORD	SWB	26-Mar-2009	KMY	48	60	HINO EURO II	LXH 572065	DE 669705	05
2556	RAC448	KL-15	7601	LL	ORD	SWB	1-Apr-2009	VTRA	48	60	HINO EURO II	LXH 572106	LXE 669774	17
2557	RAC444	KL-15	7606	LL	ORD	SWB	2-Apr-2009	VTRA	48	60	HINO EURO II	LXH 572839	LXE 669916	17
2558	RAC512	KL-15	7675	LL	ORD	SWB	2-May-2009	KMY	48	60	HINO EURO II	LXH 573613	LXE 670704	05
2559	RAC521	KL-15	7676	LL	ORD	SWB	2-May-2009	KMY	48	60	HINO EURO II	VAE121354Z	LXE 670705	05
2560	RAC546	KL-15	7716	LL	ORD	SWB	15-May-2009	KMY	48	60	HINO EURO II	LXH 572572	LXE 669684	05
2561	RAC625	KL-15	7795	LL	ORD		20-Jun-2009	KMY	48	60	HINO EURO II	LXE 105773Z	LXE670498	05
2562	RAC627	KL-15	7813	LL	ORD		22-Jun-2009	KMY	48	60	HINO EURO II		KXE671497	05
2563	RAC653	KL-15	7829	LL	ORD		25-Jun-2009	KMY	48	60	HINO EURO II	KXH 574296	KXE 671902	05
2564	RAC667	KL-15	7840	LL	ORD		29-Jun-2009	KMY	48	60	HINO EURO II	KXE 106226	KXE 671498	05
2565	RAC697	KL-15	7852	LL	ORD	VND	2-Jul-2009	KMY	48	60	HINO EURO II	KXH 574468	KXE 671872	05
2566	RAE944	KL-15	8128	LL	ORD		14-Dec-2009	KMY	48	60	HINO EURO II	ZXE 111365Z	MB1PEHC89EZB0214	05
2567	RAE945	KL-15	8129	LL	ORD		14-Dec-2009	KMY	48	60	HINO EURO II	BXE 110638Z	MB1PBEHC19EZA9485	05
2568	RNC 3	KL-15	8182	LL	ORD		16-Jan-2010	KMY	48	60	HINO EURO II	YXE 112709Z	EYB 3000	05
2569	RNC 2	KL-15	8183	LL	ORD		18-Jan-2010	KMY	48	60	HINO EURO II	YXE 113072Z	EYB 3101	05
2570	RAC956	KL-15	8155	LL	ORD	VND	2-Jan-2010	KDLR	48	60	HINO EURO II	ZXE 111451Z	MB1PBEHC39EZB0332	90
2571	RNC224	KL-15	8389	LL	ORD	SWB	15-Jun-2010	CHRY	48	60	HINO EURO II	VAE 122638Z	MB1PBEHE2AETC7459	44
2572	13000	KL-15	6178	LL	ORD		9-May-2006	PTA	48	60	HINO EURO II ALPSV 4/89	TDH 313675	SDE 554996	37
2573	RAC379	KL-15	7534	LL	ORD	MLB	12-Mar-2009	PNR	48	60	HINO EURO II ALPSV4/89	XNE 104940Z	NXE 668467	78
2574	RAC409	KL-15	7571	LL	ORD	SWB	25-Mar-2009	PLR	48	60	HINO EURO II BSII	LXH 572099	DE 669781	36
2575	RAK846	KL-15	8072	LL	ORD		16-Nov-2009	PDM	48	60	HINO EURO II BSII	OXH 583000	MB1PBEHC29ECA5699	39
2576	RAE967	KL-15	8144	LL	ORD		30-Dec-2009	PNI	48	60	HINO EURO II	NXH 571593	MB1PBEHC49EYB2927	67
2577	RNK 84	KL-15	8294	LL	ORD		5-May-2010	KPA	48	60	HINO EURO II TI	WAE120661Z	MB1PBEHC1AEVC4691	74
2578	RAC338	KL-15	7483	LL	ORD	VND	24-Feb-2009	PLR	48	60	HINO EURO II TIC	YNE 104590Z	XNE 667911	36
2579	RAC322	KL-15	7484	LL	ORD	VND	25-Feb-2009	PLR	48	60	HINO EURO II TIC	ZNE 104243Z	YNE 667397	36
2580	RAC339	KL-15	7485	LL	ORD	VND	25-Feb-2009	PLR	48	60	HINO EURO II TIC	ZNE 104372Z	XNE 667912	36
2581	RNC226	KL-15	8406	LL	ORD	SWB	23-Jun-2010	PLR	48	60	HINO EURO II TIC	VAE 122598Z	MB1PBEHE4AEVC7436	36

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2582	RRC963	KL-15	7121	LL	ORD		11-Aug-2008	KMR	48	60	HINO EURO II TURBO INTER COLLER	MNH 519638	MNE 644806	30
2583	RRE127	KL-15	6316	LL	ORD	VND	31-Oct-2007	KKLM	48	60	HINO EURO II TURBO INTER COOLER	YPH 470437	XPE 624561	108
2584	RRE281	KL-15	6472	LL	ORD	MLB	28-Dec-2007	PMNA	48	60	HINO EURO II TURBO INTER COOLER	WPH 481109	WPE 628537	68
2585	RRC417	KL-15	6580	LL	ORD	MLB	28-Jan-2008	TPLM	48	60	HINO EURO II TURBO INTER COOLER	UPH 495369	UPE 635423	94
2586	RRC413	KL-15	6579	LL	ORD	VND	28-Jan-2008	CGNR	48	60	HINO EURO II TURBO INTER COOLER	UPH 493723	UPE 6354222	40
2587	RRC395	KL-15	6557	LL	ORD	VND	21-Jan-2008	KKLM	48	60	HINO EURO II TURBO INTER COOLER	TPH 498918	TPE 637178	108
2588	RRC424	KL-15	6593	LL	ORD	VND	31-Jan-2008	MVPA	48	60	HINO EURO II TURBO INTER COOLER	UPH 497253	UPE 635281	52
2589	RRK551	KL-15	6688	LL	ORD	VND	27-Feb-2008	PNKM	48	60	HINO EURO II TURBO INTER COOLER	NPH 504744	NPE 639597	49
2590	RRK833	KL-15	7002	LL	ORD	VND	29-May-2008	PTPM	48	60	HINO EURO II TURBO INTER COOLER	JBH 143803	KNE 651627	15
2591	RRC842	KL-15	7003	LL	ORD		29-May-2008	KTM	48	60	HINO EURO II TURBO INTER COOLER	KNH 533488	KNE 651446	47
2592	RAC 23	KL-15	7173	LL	ORD	SWB	6-Sep-2008	MVPA	48	60	HINO EURO II TURBO INTER COOLER	FNE 101594Z	FNE 656784	52
2593	RAC112	KL-15	7278	LL	ORD	SWB	16-Dec-2008	KTM	48	60	HINO EURO II TURBO INTER COOLER	ZNE 104035Z	ZNE 666252	47
2594	RAE307	KL-15	7468	LL	ORD	VND	20-Feb-2009	KKLM	48	60	HINO EURO II TURBO INTER COOLER	ZNE 104379Z	YNE 667557	108
2595	RAK310	KL-15	7455	LL	ORD	VND	17-Feb-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	ZNH 566882	ZNE 666689	47
2596	RAC333	KL-15	7495	LL	ORD	VND	28-Feb-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER		XNE 667897	47
2597	RAC439	KL-15	7578	LL	ORD	SWB	26-Mar-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	LXH 572105	LXE 669798	47
2598	RAC395	KL-15	7595	LL	ORD	VND	1-Apr-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	NXH 571537	NXE 669083	47
2599	RAC526	KL-15	7687	LL	ORD	SWB	4-May-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	LXH 572155	LXE 670716	47
2600	RAC591	KL-15	7789	LL	ORD		19-Jun-2009	CTR	48	60	HINO EURO II TURBO INTER COOLER	LXH573719	KXE 672118	70
2601	RAC903	KL-15	8073	LL	ORD		16-Nov-2009	PNR	48	60	HINO EURO II TURBO INTER COOLER	BXE 1096668Z	MBIPBEHC19EBA7215	78
2602	RAK993	KL-15	8196	LL	ORD	VND	30-Jan-2010	KTM	48	60	HINO EURO II TURBO INTER COOLER	WXE114818Z	MB1PBEHC89EWB5680	47
2603	RNC251	KL-15	8494	LL	ORD	SWB	17-Jul-2010	MVPA	48	60	HINO EURO II TURBO INTER COOLER	VAE120969Z	MB1PCEHC1AEVC5112	52
2604	RNC250	KL-15	8498	LL	ORD	SWB	19-Jul-2010	KLM	48	60	HINO EURO II TURBO INTER COOLER	VAE122470Z	MB1PCEHC1AEVC7278	34
2605	RNC253	KL-15	8505	LL	ORD	SWB	20-Jul-2010	KLM	48	60	HINO EURO II TURBO INTER COOLER	VAE122611Z	MB1PCEHC5AEVC7428	34
2606	RNC252	KL-15	8509	LL	ORD	SWB	23-Jul-2010	MVPA	48	60	HINO EURO II TURBO INTER COOLER	VAE122553Z	MB1PCEHC8AEVC7357	52
2607	RAE305	KL-15	7454	LL	ORD	VND	17-Feb-2009	KTM	48	60	HINO EURO II TURBO INTER COOLR	ZNH 567901	ZNE 666578	47
2608	RAC140	KL-15	7290	LL	ORD	SWB	19-Dec-2008	VKM	48	60	HINO EURO II W06ETI BSII	ZNE 104023Z	ZNE 666210	51
2609	RAC172	KL-15	7307	LL	ORD	SWB	27-Dec-2008	PLR	48	60	HINO EURO TI BSII	ZNE 104108Z	ZNE 666531	36
2610	RAE275	KL-15	7444	LL	ORD		23-Mar-2009	PLR	48	60	HINO EURO TI BSII	ZNE 104194Z	YNE 667401	36
2611	RAC438	KL-15	7584	LL	ORD	SWB	28-Mar-2009	PLR	48	60	HINO EURO TI BSII	LXH 572144	DE 669786	36
2612	RAE400	KL-15	7564	LL	ORD		23-Mar-2009	PLR	48	60	HINO EURO TI BSII	NXE 105211Z	NXE 669033	36
2613	RAC174	KL-15	7305	LL	ORD	SWB	27-Dec-2008	PLD	48	60	HINO EURO TIC BSII	ZNE 104166Z	ZNE 666537	32
2614	RAE136	KL-15	7357	LL	ORD		12-Jan-2009	PLD	48	60	HINO EURO TIC BSII	CNH 565560	BNE 665254	32
2615	RAC411	KL-15	7577	LL	ORD	SWB	26-Mar-2009	PLD	48	60	HINO EURO TIC BSII	LXH 572147	LXE 669769	32
2616	RAC523	KL-15	7677	LL	ORD	SWB	2-May-2009	PLD	48	60	HINO W06HETI BSII	LXH 573343	LXE 670713	32
2617	RAC982	KL-15	8161	LL	ORD		4-Jan-2010	PLD	48	60	HINO EURO TIC BSII	YXE 1130037	MB1PBEHC79EYB2985	32
2618	RNC133	KL-15	8309	LL	ORD		11-May-2010	PLD	48	60	HINO EURO TIC BSII	WAE 119660Z	MB1PBEHC0AEWC3356	32
2619	RNC470	KL-15	8702	LL	ORD	SWB	7-Oct-2010	PLD	48	60	HINO EURO TIC BSII	NAE129264Z	MB1PCEHC6AEND4405	32
2620	RAC263	KL-15	7421	LL	ORD		2-Feb-2009	KNI	48	60	HINO EURO TURBO INTER COOLER	ZNH 569228	YNE 667325	107
2621	RAK242	KL-15	7419	LL	ORD	VND	2-Feb-2009	TDP	48	60	HINO EURO VIKING	BNE 103712Z	BNE 665488	53
2622	RAK 63	KL-15	7387	LL	ORD	VND	21-Jan-2009	KPA	48	60	HINO EURO VIKING	DNH 553096	CNE 663512	74
2623	RAK963	KL-15	8164	LL	ORD		6-Jan-2010	EKM	48	60	HINO EURO VIKING	ZXE 11970Z	MB1PBEHC09EZB1163	56
2624	RAK160	KL-15	7358	LL	ORD		12-Jan-2009	MPM	48	60	HINO EURO VIKING BSII	BNE 103721Z	BNE 665517	71
2625	RT 792	KL-15	5970	LL	ORD	VND	28-Jun-2005	MDY	48	60	HINO EURO W06E			76
2626	RT 828	KL-15	6006	LL	ORD	VND	21-Jul-2005	MDY	48	60	HINO EURO W06E			76

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2627	RT 842	KL-15	6020	LL	ORD	VND	27-Jul-2005	SBY	48	60	HINO EURO W06E	WDH 296202	WDA 047580	75
2628	RT 843	KL-15	6021	LL	ORD	VND	27-Jul-2005	MDY	48	60	HINO EURO W06E			76
2629	RR 26	KL-15	6204	LL	ORD	VND	12-Jun-2006	CGNR	48	60	HINO EURO W06E BSII	TDH313238	TDE553971	40
2630	RT 27	KL-15	5205	LL	ORD		6-Feb-2004	CGNR	48	60	HINO EURO W06EI	WVH250526	WVE51867Z	40
2631	RT 67	KL-15	5245	LL	ORD		5-Mar-2004	CGNR	48	60	HINO EURO W06EI	SXH070549	WVE519039	40
2632	RT 100	KL-15	5278	LL	ORD		15-Mar-2004	SBY	48	60	HINO EURO W06EI	WVH 251609	WVE 519245	75
2633	RT 191	KL-15	5369	LL	ORD		1-Apr-2004	SBY	48	60	HINO EURO W06EI	VWH 255713	VVE 522208	75
2634	RT 314	KL-15	5492	LL	ORD		1-Jul-2004	CGNR	48	60	HINO EURO W06EI	SWH265377	SWA042408	40
2635	RT 380	KL-15	5558	LL	ORD		19-Aug-2004	CGNR	48	60	HINO EURO W06EI	4BH160819	SWA042627	40
2636	RT 598	KL-15	5776	LL	ORD		10-Jan-2005	CGNR	48	60	HINO EURO W06EI	4SH107323	KWA045054	40
2637	RT 608	KL-15	5785	LL	ORD		25-Jan-2005	CGNR	48	60	HINO EURO W06EI	FWH284928	JWA045898	40
2638	RT 896	KL-15	6074	LL	ORD		1-Sep-2005	KLM	48	60	HINO EURO W06EI	306753	UDE 551269	34
2639	RT 897	KL-15	6075	LL	ORD		1-Sep-2005	KLM	48	60	HINO EURO W06EI	306831	UDE 551207	34
2640	RT 9	KL-15	5187	LL	ORD		5-Feb-2004	VZM	48	60	HINO EURO W06ETI	CNE 103245Z	WVE 518326	24
2641	RT 74	KL-15	5252	LL	ORD		5-Mar-2004	TSY	48	60	HINO EURO W06ETI	UBH 160169	WVE 519015	73
2642	RRC158	KL-15	6317	LL	ORD	VND	31-Oct-2007	VTRA	48	60	HINO EURO W06ETI BSII	WPH 480928	WPE 628528	17
2643	RRC194	KL-15	6404	LL	ORD	SWB	5-Dec-2007	VTRA	48	60	HINO EURO W06ETI BSII	VPH 491528	VPE 633150	17
2644	RRE928	KL-15	7139	LL	ORD		28-Aug-2008	SBY	48	60	HINO EURO W06ETI BSII	JNH 542160	JNE 654592	75
2645	RAE 67	KL-15	7283	LL	ORD		17-Dec-2008	KTP	48	60	HINO EURO W06ETI BSII TURBO INTER COOLER	CNE 103243Z	CNE 664133	14
2646	RAC404	KL-15	7556	LL	ORD		20-Mar-2009	SBY	48	60	HINO EURO W06ETI BSII	NXH 171770	NXE 669239	75
2647	RAC405	KL-15	7559	LL	ORD		23-Mar-2009	SBY	48	60	HINO EURO W06ETI BSII	NXE 106292Z	NXE 669240	75
2648	RAC406	KL-15	7560	LL	ORD		23-Mar-2009	SBY	48	60	HINO EURO W06ETI BSII	NXE 105208Z	NXE 669048	75
2649	RAC528	KL-15	7702	LL	ORD	SWB	8-May-2009	SBY	48	60	HINO EURO W06ETI BSII	LXH 572780	LXE 670462	75
2650	RAC585	KL-15	7731	LL	ORD		18-May-2009	SBY	48	60	HINO EURO W06ETI BSII	KXH 574520	KXE 671906	75
2651	RAC587	KL-15	7732	LL	ORD		18-May-2009	SBY	48	60	HINO EURO W06ETI BSII	LXH 573056	LXE 670271	75
2652	RAC 26	KL-15	7206	LL	ORD		13-Oct-2008	PKD	48	60	HINO EURO W06ETI TCIC BSII	ZPH 465831	YPE 621938	65
2653	RT 921	KL-15	6099	LL	ORD		17-Oct-2005	MVPA	48	60	HINO EURO I	UDH 312407	TDE 553933	52
2654	RAK 19	KL-15	7190	LL	ORD		26-Sep-2008	TDY	48	60	HINO EURO II	JNH 541978	JNE 654251	79
2655	RAC978	KL-15	8158	LL	ORD		2-Jan-2010	NPR	48	60	HINO EURO II	ZXE 111968Z	MB1PBEHC89EYB1170	62
2656	RAC979	KL-15	8159	LL	ORD		2-Jan-2010	NPR	48	60	HINO EURO II	BXE 110246Z	MB1PBEHC69EYB2852	62
2657	RAC980	KL-15	8162	LL	ORD		5-Jan-2010	NPR	48	60	HINO EURO II	YXE 113136Z	MB1PBEHC19EYB3159	62
2658	RAC998	KL-15	8174	LL	ORD		12-Jan-2010	NPR	48	60	HINO EURO II	YXE 113062Z	MB1PBEHC89EYB3062	62
2659	RRC396	KL-15	6558	LL	ORD	VND	21-Jan-2008	MLTM	48	60	HINO EURO II ALPSV 4/89	TPH 502026	TPE 637175	54
2660	RAC604	KL-15	7808	LL	ORD	VND	22-Jun-2009	EKM	48	60	HINO EURO II ALPSV 4/89	KXE 106336Z	KXE 671914	56
2661	RAC605	KL-15	7809	LL	ORD	VND	22-Jun-2009	EKM	48	60	HINO EURO II ALPSV 4/89	KXH 574630	KXE 672067	56
2662	RAC983	KL-15	8165	LL	ORD		6-Jan-2010	CGNR	48	60	HINO EURO II ALPSV 4/89	7XE 112986Z	MB1PBEHC89EYB2851	40
2663	RAC984	KL-15	8168	LL	ORD		7-Jan-2010	CGNR	48	60	HINO EURO II ALPSV 4/89	7XE 113121Z	MB1PBEHC79EYB3103	40
2664	RAC997	KL-15	8169	LL	ORD		8-Jan-2010	EKM	48	60	HINO EURO II ALPSV 4/89	YXE 113005Z	MB1PBEHC39EYB2983	56
2665	15000	KL-15	8178	LL	ORD		14-Jan-2010	EKM	48	60	HINO EURO II ALPSV 4/89	YXE 112885Z	MB1PBEHC59EYB3102	56
2666	RRC192	KL-15	6354	LL	ORD	SWB	20-Nov-2007	ARK	48	60	HINO EURO II TURBO INTER COOLER	YVH 243233	VPE 632978	06
2667	RAC670	KL-15	7860	LL	ORD	VND	8-Jul-2009	MVPA	48	60	HINO EURO II TURBO INTER COOLER	LXH 572451	KXE 671169	52
2668	RNC313	KL-15	8555	LL	ORD	SWB	11-Aug-2010	TDY	48	60	HINO EURO II TURBO INTER COOLER	VPH 488813	MB1PCEHC8AEVC7360	79
2669	RAC145	KL-15	7323	LL	ORD	SWB	1-Jan-2009	VKM	48	60	HINO EURO II W06ETI BSII	ZNE 104028Z	ZNE 666223	51
2670	RNK307	KL-15	8514	LL	ORD	VND	27-Jul-2010	VKM	48	60	HINO EURO II W06ETI BSII	WAE120609Z	MB1PBEHC0AEVC4634	51
2671	RNC384	KL-15	8599	LL	ORD		1-Sep-2010	KMY	48	60	HINO III ELECTRONIC	PN1636156	MB1PBEJC2AEFPD2919	05

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2672	RNC385	KL-15	8600	LL	ORD		1-Sep-2010	ANK	48	60	HINO III ELECTRONIC	PAH636757	MB1PBEJC1AEPD2578	57
2673	RNC 15	KL-15	8195	LL	ORD		28-Jan-2010	CDLM	48	60	HINO TCIC BSII	WXE 113983Z	EWB 4438	80
2674	RT 984	KL-15	6162	LL	ORD	VND	10-Apr-2006	CGNR	48	60	HINO W06E BSI	TDH314544	SDE534765	40
2675	RT 985	KL-15	6163	LL	ORD	VND	10-Apr-2006	KNR	48	60	HINO W06E BSI	TDH 313929	SDE 554653	77
2676	RT 987	KL-15	6165	LL	ORD	VND	17-Apr-2006	CGNR	48	60	HINO W06E BSI	PDH312546	TDE554091	40
2677	RR 50	KL-15	6228	LL	ORD		26-Aug-2006	KNR	48	60	HINO W06E BSI	SDH 315725	SDE 554995	77
2678	RT 986	KL-15	6164	LL	ORD	VND	10-Apr-2006	KNR	48	60	HINO W06E BSII	TDH 312721	TDE 554090	77
2679	RRE398	KL-15	6575	LL	ORD	VND	25-Jan-2008	TSY	48	60	HINO W06E BSII	VPH 488132	VPE 631935	73
2680	RRE399	KL-15	6578	LL	ORD	MLB	28-Jan-2008	TDY	48	60	HINO W06E BSII	LXH 572783	VPE 631937	79
2681	RRE397	KL-15	6574	LL	ORD		25-Jan-2008	SBY	48	60	HINO W06E T1 BSII	UPH 496391	UPE 634245	75
2682	RAE132	KL-15	7295	LL	ORD		22-Dec-2008	KTR	48	60	HINO W06E T1 BSII	BNE 103610Z	BNE 665339	35
2683	RT 590	KL-15	5768	LL	ORD		3-Jan-2005	TSR	48	60	HINO W06ETI BSII		KWA 045104	63
2684	RRK 55	KL-15	6233	LL	ORD	VND	16-Aug-2007	VTRA	48	60	HINO W06ETI BSII	ZPH 465831	YPE 621938	17
2685	RRK 56	KL-15	6244	LL	ORD		24-Aug-2007	PSL	48	60	HINO W06ETI BSII	ZPH 460801	YPE 621996	21
2686	RRE 67	KL-15	6237	LL	ORD	VND	18-Aug-2007	KMR	48	60	HINO W06ETI BSII	YPH 469634	YPE 622459	30
2687	RRE 68	KL-15	6248	LL	ORD	VND	4-Sep-2007	TVL	48	60	HINO W06ETI BSII	BNE 103719Z	YPE 622501	43
2688	RRE 97	KL-15	6257	LL	ORD	MLB	24-Sep-2007	KNR	48	60	HINO W06ETI BSII	YPH 470895	YPE 624162	77
2689	RRE 98	KL-15	6264	LL	ORD	MLB	27-Sep-2007	KNR	48	60	HINO W06ETI BSII	YPH 470296	YPE 262429	77
2690	RRE 99	KL-15	6275	LL	ORD	MLB	3-Oct-2007	KNR	48	60	HINO W06ETI BSII	YPH 470348	XPE 624689	77
2691	RRK 61	KL-15	6289	LL	ORD		15-Oct-2007	PSL	48	60	HINO W06ETI BSII	YPH 470449	YPE 624637	21
2692	RRE108	KL-15	6282	LL	ORD		10-Oct-2007	TDY	48	60	HINO W06ETI BSII	YPH 471960	YPE 624578	79
2693	RRE109	KL-15	6288	LL	ORD	VND	15-Oct-2007	ARND	48	60	HINO W06ETI BSII	YPH 471304	YPE 624614	19
2694	RRE110	KL-15	6297	LL	ORD		22-Oct-2007	TVL	48	60	HINO W06ETI BSII	YPH 470327	YPE 624699	43
2695	RRC143	KL-15	6302	LL	ORD		25-Oct-2007	MKD	48	60	HINO W06ETI BSII	XPH 473421	WPE 628535	08
2696	RRK137	KL-15	6304	LL	ORD	VND	26-Oct-2007	NDD	48	60	HINO W06ETI BSII	YPH 472136	XPE 624823	31
2697	RRK138	KL-15	6315	LL	ORD		31-Oct-2007	NTA	48	60	HINO W06ETI BSII	YPH 470075	YPE 623744	22
2698	RRK139	KL-15	6320	LL	ORD	VND	2-Nov-2007	KMGH	48	60	HINO W06ETI BSII	YPH 472758	XPE 624839	55
2699	RRC147	KL-15	6311	LL	ORD		29-Oct-2007	PLD	48	60	HINO EURO II WITH INTERCOOLER	WPH 479928	WPE 628607	32
2700	RRC148	KL-15	6318	LL	ORD	MLB	2-Nov-2007	VDA	48	60	HINO W06ETI BSII	XPH 473172	WPE 628608	92
2701	RRC149	KL-15	6324	LL	ORD	VND	5-Nov-2007	CGNR	48	60	HINO W06ETI BSII	WPH 479931	WPE 628616	40
2702	RRC142	KL-15	6305	LL	ORD	MLB	26-Oct-2007	KPA	48	60	HINO W06ETI BSII	WPH 482420	WPE 628527	74
2703	RRC157	KL-15	6329	LL	ORD	VND	7-Nov-2007	VJMD	48	60	HINO W06ETI BSII	WPH 482423	WPE 628521	16
2704	RRC159	KL-15	6330	LL	ORD	VND	7-Nov-2007	KMR	48	60	HINO W06ETI BSII	WPH 482427	WPE 628536	30
2705	RRK 62	KL-15	6303	LL	ORD	MLB	26-Oct-2007	PLKD	48	60	HINO W06ETI BSII	YPH 470439	YPE 624553	69
2706	RRC178	KL-15	6350	LL	ORD	SWB	17-Nov-2007	KMGH	48	60	HINO W06ETI BSII	YXE 113143Z	VPE 632998	55
2707	RRC191	KL-15	6343	LL	ORD	SWB	17-Nov-2007	SBY	48	60	HINO W06ETI BSII	VPH 490923	WPE 632523	75
2708	RRC195	KL-15	6357	LL	ORD	SWB	20-Nov-2007	PLR	48	60	HINO W06ETI BSII	VPH 491522	VPE 633149	36
2709	RRE167	KL-15	6355	LL	ORD	MLB	20-Nov-2007	MDY	48	60	HINO W06ETI BSII	XPH 479504	WPE 628333	76
2710	RRE168	KL-15	6359	LL	ORD	MLB	21-Nov-2007	MDY	48	60	HINO W06ETI BSII	XPH 473252	WPE 628334	76
2711	RRK184	KL-15	6353	LL	ORD		20-Nov-2007	PTPM	48	60	HINO W06ETI BSII	WPH 480741	WPE 628399	15
2712	RRK185	KL-15	6358	LL	ORD		21-Nov-2007	KHD	48	60	HINO W06ETI BSII	WPH 480948	WPE 628349	106
2713	RRC150	KL-15	6325	LL	ORD	VND	5-Nov-2007	TDP	48	60	HINO W06ETI BSII	XPH 474917	WPE 628641	53
2714	RRC155	KL-15	6328	LL	ORD	VND	6-Nov-2007	VLRD	48	60	HINO W06ETI BSII	VPH 470054	WPE 628490	93
2715	RRK186	KL-15	6363	LL	ORD	VND	24-Nov-2007	PLR	48	60	HINO W06ETI BSII	XPH 478701	WPE 628348	36
2716	RRK187	KL-15	6371	LL	ORD	VND	27-Nov-2007	PTPM	48	60	HINO W06ETI BSII	WPH 479759	WPE 628447	15

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2717	RRC146	KL-15	6306	LL	ORD	VND	27-Oct-2007	EMLY	48	60	HINO W06ETI BSII	WPH 479933	WPE 628606	95
2718	RRC200	KL-15	6368	LL	ORD	SWB	26-Nov-2007	PNKM	48	60	HINO W06ETI BSII	YXE 113148Z	VPE 633167	49
2719	RRE166	KL-15	6345	LL	ORD	MLB	17-Nov-2007	PNR	48	60	HINO W06ETI BSII	YPH 473437	XPE 626783	78
2720	RRC153	KL-15	6332	LL	ORD		9-Nov-2007	GVR	48	60	HINO W06ETI BSII	XPH 475030	WPE 628471	66
2721	RRC174	KL-15	6346	LL	ORD	SWB	17-Nov-2007	TDY	48	60	HINO W06ETI BSII	VWH 00255788	VPE 632524	79
2722	RRC175	KL-15	6347	LL	ORD	SWB	17-Nov-2007	TSY	48	60	HINO W06ETI BSII	VPH 490652	VPE 632977	73
2723	RRC176	KL-15	6348	LL	ORD	SWB	17-Nov-2007	ARK	48	60	HINO W06ETI BSII	VPH 491367	VPE 632979	06
2724	RRC177	KL-15	6349	LL	ORD	SWB	17-Nov-2007	PLR	48	60	HINO W06ETI BSII	VPH 489215	VPE 632997	36
2725	RRC193	KL-15	6351	LL	ORD	SWB	17-Nov-2007	TDP	48	60	HINO W06ETI BSII	VPH 489273	VPE 633135	53
2726	RRC156	KL-15	6319	LL	ORD	VND	2-Nov-2007	KTDA	48	60	HINO W06ETI BSII	10VHC 1989	WPE 628492	25
2727	RRC154	KL-15	6333	LL	ORD		9-Nov-2007	KMR	48	60	HINO W06ETI BSII	ZNE 1041492	WPE 628472	30
2728	RRK140	KL-15	6331	LL	ORD		9-Nov-2007	TVL	48	60	HINO W06ETI BSII	XPH 475085	WPE 628374	43
2729	RRK188	KL-15	6385	LL	ORD	MLB	1-Dec-2007	MDY	48	60	HINO W06ETI BSII	WPH 480594	WPE 628422	76
2730	RRE169	KL-15	6362	LL	ORD	VND	24-Nov-2007	VLRD	48	60	HINO W06ETI BSII	XPH 473108	WPE 628335	93
2731	RRC249	KL-15	6390	LL	ORD	SWB	3-Dec-2007	PLKD	48	60	HINO W06ETI BSII	VPH 490569	VPE 632432	69
2732	RRK189	KL-15	6405	LL	ORD	VND	5-Dec-2007	TDP	48	60	HINO W06ETI BSII	XPH 473253	WPE 628423	53
2733	RRE228	KL-15	6391	LL	ORD	MLB	3-Dec-2007	PNR	48	60	HINO W06ETI BSII	WPH 479742	WPE 628375	78
2734	RRE229	KL-15	6419	LL	ORD	MLB	7-Dec-2007	PLKD	48	60	HINO W06ETI BSII	WPH 480571	WPE 628345	69
2735	RRE230	KL-15	6429	LL	ORD	VND	10-Dec-2007	CGNR	48	60	HINO W06ETI BSII	WPH 480950	WPE 628347	40
2736	RRK190	KL-15	6420	LL	ORD	VND	7-Dec-2007	PTPM	48	60	HINO W06ETI BSII	XPH 473313	WPE 628426	15
2737	RRC151	KL-15	6337	LL	ORD	VND	12-Nov-2007	TVL	48	60	HINO W06ETI BSII	MNE 100069Z	WPE 628654	43
2738	RRC161	KL-15	6338	LL	ORD		12-Nov-2007	TVL	48	60	HINO W06ETI BSII	WPH 481237	WPE 628684	43
2739	RRE231	KL-15	6425	LL	ORD	MLB	10-Dec-2007	TSY	48	60	HINO W06ETI BSII	XPH 475240	WPE 628397	73
2740	RRC254	KL-15	6430	LL	ORD	MLB	10-Dec-2007	TLY	48	60	HINO W06ETI BSII	VPH 488054	VPE 631944	18
2741	RRC267	KL-15	6436	LL	ORD	MLB	13-Dec-2007	KHD	48	60	HINO W06ETI BSII	VPH 488308	VPE 632068	106
2742	RRC270	KL-15	6446	LL	ORD	VND	19-Dec-2007	PKDA	48	60	HINO W06ETI BSII	VPH 488165	VPE 631941	81
2743	RRE279	KL-15	6442	LL	ORD	MLB	17-Dec-2007	KNR	48	60	HINO W06ETI BSII	WPH 480998	WPE 628421	77
2744	RRC271	KL-15	6457	LL	ORD	VND	22-Dec-2007	KNI	48	60	HINO W06ETI BSII	VPH 488161	VPE 631942	107
2745	RRE232	KL-15	6438	LL	ORD	VND	14-Dec-2007	PLD	48	60	HINO W06ETI BSII	WPH 480943	WPF 628398	32
2746	RRC269	KL-15	6463	LL	ORD		27-Dec-2007	VLND	48	60	HINO W06ETI BSII	VPH 488191	VPE 631938	20
2747	RRC160	KL-15	6334	LL	ORD	MLB	9-Nov-2007	MDY	48	60	HINO W06ETI BSII	WPH 480989	WPE 628549	76
2748	RRE324	KL-15	6481	LL	ORD	VND	29-Dec-2007	CDLM	48	60	HINO W06ETI BSII	VPH 488170	VPE 631945	80
2749	RRE280	KL-15	6471	LL	ORD	MLB	28-Dec-2007	VDA	48	60	HINO W06ETI BSII	WPH 481051	WPE 628473	92
2750	RRE282	KL-15	6473	LL	ORD	MLB	28-Dec-2007	VDA	48	60	HINO W06ETI BSII	WPH 479912	WPE 628615	92
2751	RRE278	KL-15	6440	LL	ORD	MLB	17-Dec-2007	MDY	48	60	HINO W06ETI BSII	XPH 474092	WPE 628424	76
2752	RRC342	KL-15	6498	TATA	ORD	MLB	3-Jan-2008	KGD	48	60	HINO W06ETI BSII	JSZ 139228	JSZ 015316	84
2753	RRC341	KL-15	6506	TATA	ORD	MLB	7-Jan-2008	PNR	48	60	HINO W06ETI BSII	JSZ 139223	JSZ 015227	78
2754	RRC339	KL-15	6511	TATA	ORD	MLB	8-Jan-2008	KGD	48	60	HINO W06ETI BSII	JSZ 140961	JSZ 015222	84
2755	RRE329	KL-15	6514	LL	ORD	MLB	9-Jan-2008	SBY	48	60	HINO W06ETI BSII	VPH 486767	VPE 632078	75
2756	RRE328	KL-15	6508	LL	ORD	MLB	7-Jan-2008	SBY	48	60	HINO W06ETI BSII	VPH 488163	VPE 631943	75
2757	RRE327	KL-15	6504	LL	ORD	MLB	4-Jan-2008	SBY	48	60	HINO W06ETI BSII	VPH 490264	VPE 631940	75
2758	RRE325	KL-15	6493	LL	ORD	MLB	1-Jan-2008	KPA	48	60	HINO W06ETI BSII	YPH 488193	VPE 632067	74
2759	RRK323	KL-15	6509	LL	ORD	MLB	7-Jan-2008	KPA	48	60	HINO W06ETI BSII	UPH 492868	UPE 634265	74
2760	RRK322	KL-15	6501	LL	ORD	MLB	4-Jan-2008	KHD	48	60	HINO W06ETI BSII	UPH 495019	UPE 634243	106
2761	RRK321	KL-15	6492	LL	ORD	MLB	1-Jan-2008	KNR	48	60	HINO W06ETI BSII	UPH 488318	VPE 632077	77

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2762	RRE330	KL-15	6521	LL	ORD	MLB	10-Jan-2008	KHD	48	60	HINO W06ETI BSII	KNH 533551	VPE 632071	106
2763	RRC359	KL-15	6517	LL	ORD	MLB	10-Jan-2008	KHD	48	60	HINO W06ETI BSII	TPH 501916	TPE 637322	106
2764	RRE326	KL-15	6497	LL	ORD	VND	3-Jan-2008	KTM	48	60	HINO W06ETI BSII	VPH 490575	VPE 632093	47
2765	RRK273	KL-15	6432	LL	ORD	VND	11-Dec-2007	PKDA	48	60	HINO W06ETI BSII	WPH 480991	WPE 628414	81
2766	RRE331	KL-15	6525	LL	ORD	MLB	11-Jan-2008	TLY	48	60	HINO W06ETI BSII	VPH 491273	VPE 633309	18
2767	RRE369	KL-15	6541	LL	ORD	MLB	16-Jan-2008	KKD	48	60	HINO W06ETI BSII	UPH 495018	UPE 634244	72
2768	RRE368	KL-15	6533	LL	ORD	MLB	14-Jan-2008	VDA	48	60	HINO W06ETI BSII	UPH 492612	UPE 634266	92
2769	RRE370	KL-15	6561	LL	ORD	MLB	21-Jan-2008	KHD	48	60	HINO W06ETI BSII	UPH 492924	UPE 634289	106
2770	RRE401	KL-15	6606	LL	ORD	MLB	2-Feb-2008	MDY	48	60	HINO W06ETI BSII	TPH 501924	TPE 637337	76
2771	RRE372	KL-15	6553	LL	ORD	MLB	21-Jan-2008	KKD	48	60	HINO W06ETI BSII	UPH 492971	UPE 634291	72
2772	RRE371	KL-15	6552	LL	ORD	MLB	21-Jan-2008	KKD	48	60	HINO W06ETI BSII	UPH 492974	UPE 634290	72
2773	RRE405	KL-15	6634	LL	ORD	VND	11-Feb-2008	CHRY	48	60	HINO W06ETI BSII	UPH 497432	UPE 635667	44
2774	RRE402	KL-15	6610	LL	ORD	MLB	4-Feb-2008	NBR	48	60	HINO W06ETI BSII	UPH 497226	UPE 635426	86
2775	RRE501	KL-15	6673	LL	ORD	VND	21-Feb-2008	MLPY	48	60	HINO W06ETI BSII	UPH 494101	NPE 639539	96
2776	RRE505	KL-15	6687	LL	ORD	VND	25-Feb-2008	PTPM	48	60	HINO W06ETI BSII	NPH 505645	NPE 640755	15
2777	RRE504	KL-15	6707	LL	ORD	VND	29-Feb-2008	ADR	48	60	HINO W06ETI BSII	TPH 498834	TPE 637077	38
2778	RRE508	KL-15	6724	LL	ORD	MLB	6-Mar-2008	CTR	48	60	HINO W06ETI BSII	UPH 497258	UPE 635280	70
2779	RRE576	KL-15	6739	LL	ORD	MLB	10-Mar-2008	CTR	48	60	HINO W06ETI BSII	NPH 505692	NPE 640836	70
2780	RRE503	KL-15	6691	LL	ORD	MLB	27-Feb-2008	RWK	48	60	HINO W06ETI BSII	UPH 497267	UPE 635479	13
2781	RRE408	KL-15	6657	LL	ORD		16-Feb-2008	KTP	48	60	HINO W06ETI BSII TURBO COOLER	TPH 498921	TPE 637200	14
2782	RRE599	KL-15	6761	LL	ORD	MLB	15-Mar-2008	EKM	48	60	HINO W06ETI BSII	NPH 504716	NPE 639580	56
2783	RRE404	KL-15	6624	LL	ORD	MLB	7-Feb-2008	CTR	48	60	HINO W06ETI BSII	TPH 502326	TPE 637633	70
2784	RRE406	KL-15	6635	LL	ORD	MLB	11-Feb-2008	CTR	48	60	HINO W06ETI BSII	TPH 498567	TPE 636736	70
2785	RRE407	KL-15	6642	LL	ORD	MLB	13-Feb-2008	CHRY	48	60	HINO W06ETI BSII	TPH 500784	TPE 637174	44
2786	RRE600	KL-15	6763	LL	ORD	VND	17-Mar-2008	TLY	48	60	HINO W06ETI BSII	DXH 581124	NPE 640782	18
2787	RRE598	KL-15	6749	LL	ORD	MLB	12-Mar-2008	KNR	48	60	HINO W06ETI BSII	NPH 504655	NPE 639574	77
2788	RRE604	KL-15	6790	LL	ORD	MLB	25-Mar-2008	TPLM	48	60	HINO W06ETI BSII	PNH 514282	PNE 642654	94
2789	RRE605	KL-15	6796	LL	ORD	MLB	26-Mar-2008	TPLM	48	60	HINO W06ETI BSII	PNH 313985	PNE 642317	94
2790	RRK572	KL-15	6743	LL	ORD		12-Mar-2008	PNKM	48	60	HINO W06ETI BSII	PNH 514137	PNE 642384	49
2791	RRE651	KL-15	6814	LL	ORD		29-Mar-2008	KMY	48	60	HINO W06ETI BSII	MNH 522447	MNE 646683	05
2792	RRE500	KL-15	6669	LL	ORD	MLB	20-Feb-2008	TLY	48	60	HINO W06ETI BSII	UPH 497306	UPE 635480	18
2793	RRE654	KL-15	6824	LL	ORD		1-Apr-2008	PALA	48	60	HINO W06ETI BSII	MNE 100071	LNE 647821	50
2794	RRE603	KL-15	6789	LL	ORD	MLB	25-Mar-2008	KHD	48	60	HINO W06ETI BSII	PNH 512169	PNE 642335	106
2795	RRE657	KL-15	6840	LL	ORD		4-Apr-2008	MNR	48	60	HINO W06ETI BSII	PNH 512165	PNE 642316	60
2796	RRE653	KL-15	6823	LL	ORD		1-Apr-2008	PTA	48	60	HINO W06ETI BSII	CNE 102816	LNE 647786	37
2797	RRE655	KL-15	6825	LL	ORD		1-Apr-2008	PDM	48	60	HINO W06ETI BSII	MNE 100071	LNE 647821	39
2798	RRE656	KL-15	6843	LL	ORD		5-Apr-2008	CGNR	48	60	HINO W06ETI BSII	LNH 524050	LNE 647831	40
2799	RRE602	KL-15	6786	LL	ORD	MLB	24-Mar-2008	PVM	48	60	HINO W06ETI BSII	PNH 512168	PNE 642336	83
2800	RRE509	KL-15	6720	LL	ORD		3-Mar-2008	MLPY	48	60	HINO W06ETI BSII	UPH 495404	UPE 635668	96
2801	RRE658	KL-15	6845	LL	ORD		7-Apr-2008	PTA	48	60	HINO W06ETI BSII	JXE 106952Z	NPE 640742	37
2802	RRE652	KL-15	6800	LL	ORD	MLB	27-Mar-2008	MDY	48	60	HINO W06ETI BSII	MNE 100172	LNE 647820	76
2803	RRE686	KL-15	6933	LL	ORD	MLB	3-May-2008	TDP	48	60	HINO W06ETI BSII	NPH 508706	NPE 640876	53
2804	RRE687	KL-15	6932	LL	ORD		3-May-2008	TPLM	48	60	HINO W06ETI BSII	PNH 512292	PNE 642427	94
2805	RRE688	KL-15	6939	LL	ORD		6-May-2008	KHD	48	60	HINO W06ETI BSII	ZVH 0024491	PNE 642653	106
2806	RRE798	KL-15	6993	LL	ORD	VND	26-May-2008	MLPY	48	60	HINO W06ETI BSII	KNH 533327	KNE 651440	96

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2807	RRE797	KL-15	6990	LL	ORD	VND	23-May-2008	MLPY	48	60	HINO W06ETI BSII	YMH 214126	KNE 651463	96
2808	RRE682	KL-15	6892	LL	ORD		19-Apr-2008	KMGH	48	60	HINO W06ETI BSII	NXE 1053452	NPE 640861	55
2809	RRE788	KL-15	6947	LL	ORD		8-May-2008	PPD	48	60	HINO W06ETI BSII	LNH 524866	LNE 648670	26
2810	RRE660	KL-15	6873	LL	ORD	MLB	15-Apr-2008	KTM	48	60	HINO EURO II	PNH 512296	PNE 642435	47
2811	RRE680	KL-15	6858	LL	ORD	MLB	11-Apr-2008	TSY	48	60	HINO W06ETI BSII	PNH 514129	PNE 642375	73
2812	RRE685	KL-15	6919	LL	ORD	MLB	28-Apr-2008	TSY	48	60	HINO W06ETI BSII	PNH 511044	PNE 642522	73
2813	RRE683	KL-15	6899	LL	ORD	MLB	22-Apr-2008	SBY	48	60	HINO W06ETI BSII	NPH 505803	NPE 640919	75
2814	RRC724	KL-15	6885	LL	ORD		17-Apr-2008	KNR	48	60	HINO W06ETI BSII	LNE 100239	LNE 648513	77
2815	RRE659	KL-15	6853	LL	ORD		9-Apr-2008	TSY	48	60	HINO W06ETI BSII	NPH 508702	NPE 640754	73
2816	RRE684	KL-15	6912	LL	ORD		24-Apr-2008	KNR	48	60	HINO W06ETI BSII	PNH 514134	PNE 642374	77
2817	RRK524	KL-15	6906	LL	ORD	MLB	23-Apr-2008	KHD	48	60	HINO W06ETI BSII	PNH 511628	PNE 643910	106
2818	RRE792	KL-15	6967	LL	ORD	VND	16-May-2008	PLR	48	60	HINO W06ETI BSII	PNH 511053	PNE 642523	36
2819	RRE794	KL-15	6970	LL	ORD	VND	17-May-2008	SBY	48	60	HINO W06ETI BSII	KNH 533551	KNE 651462	75
2820	RRE795	KL-15	6977	LL	ORD		20-May-2008	KHD	48	60	HINO W06ETI BSII	KNH 533931	KNE 651773	106
2821	RRE791	KL-15	6965	LL	ORD	VND	15-May-2008	TDY	48	60	HINO W06ETI BSII	PNH 511052	PNE 642524	79
2822	RRE793	KL-15	6986	LL	ORD	VND	22-May-2008	MLPY	48	60	HINO W06ETI BSII	KNH 533604	KNE 651489	96
2823	RRE689	KL-15	6950	LL	ORD		12-May-2008	PNR	48	60	HINO W06ETI BSII	PNH 514130	PNE 642386	78
2824	RRE790	KL-15	6956	LL	ORD		13-May-2008	PKDA	48	60	HINO W06ETI BSII	LNH 524869	LNE 648671	81
2825	RRE796	KL-15	6999	LL	ORD	VND	28-May-2008	PKDA	48	60	HINO W06ETI BSII	KNH 533714	KNE 651597	81
2826	RRE852	KL-15	7025	LL	ORD		9-Jun-2008	MDY	48	60	HINO W06ETI BSII	KNE 100607Z	KNE 651442	76
2827	RRE880	KL-15	7045	LL	ORD	VND	18-Jun-2008	KPA	48	60	HINO W06ETI TC BSII	KNH 538140	JNE 652994	74
2828	RRE894	KL-15	7060	LL	ORD		24-Jun-2008	SBY	48	60	HINO W06ETI BSII	JNH 541441	JNE 653857	75
2829	RRE896	KL-15	7070	LL	ORD		1-Jul-2008	NBR	48	60	HINO W06ETI BSII	JNH 539975	JNE 653856	86
2830	RRE893	KL-15	7069	LL	ORD		1-Jul-2008	PLD	48	60	HINO W06ETI BSII	JNH 541488	JNE 653690	32
2831	RRE895	KL-15	7073	LL	ORD	MLB	1-Jul-2008	MKD	48	60	HINO W06ETI BSII	JNH 541359	JNE 653602	08
2832	RRC941	KL-15	7101	LL	ORD		29-Jul-2008	TDY	48	60	HINO EURO	JNH 539339	NXE 1052192	79
2833	RRE944	KL-15	7140	LL	ORD		28-Aug-2008	KHD	48	60	HINO W06ETI BSII	JNH	JNE 653955	106
2834	RRE942	KL-15	7107	LL	ORD	VND	7-Aug-2008	PSL	48	60	HINO W06ETI BSII	JNH 540556	JNE 654624	21
2835	RRE945	KL-15	7157	LL	ORD	MLB	30-Aug-2008	KPA	48	60	HINO W06ETI BSII	JNH 541985	JNE 654570	74
2836	RRE946	KL-15	7158	LL	ORD		30-Aug-2008	VJMD	48	60	HINO W06ETI BSII	SWH 00264428	JNE 655734	16
2837	RRE947	KL-15	7167	LL	ORD	VND	3-Sep-2008	PSL	48	60	HINO W06ETI BSII	JNH 542061	JNE 654593	21
2838	RAC 9	KL-15	7170	LL	ORD	SWB	3-Sep-2008	KNR	48	60	HINO W06ETI BSII	FNH 545895	FNE 657225	77
2839	RAC 10	KL-15	7176	LL	ORD	SWB	9-Sep-2008	MLTM	48	60	HINO W06ETI BSII	FNH 548744	FNE 657226	54
2840	RAC 7	KL-15	7177	LL	ORD	SWB	10-Sep-2008	EMLY	48	60	HINO W06ETI BSII	FNH 548388	FNE 656793	95
2841	RAC 30	KL-15	7182	LL	ORD	SWB	16-Sep-2008	MDY	48	60	HINO W06ETI BSII	FNH 545707	FNE 657019	76
2842	RAC 11	KL-15	7186	LL	ORD	SWB	22-Sep-2008	TVL	48	60	HINO W06ETI BSII	FNH 545708	FNE 657031	43
2843	RAK 56	KL-15	7205	LL	ORD		13-Oct-2008	ADR	48	60	HINO W06ETI BSII	ZPH 465831	YPE 621938	38
2844	RAK 27	KL-15	7207	LL	ORD	SWB	13-Oct-2008	PTPM	48	60	HINO W06ETI BSII	ZPH 465831	YPE 621938	15
2845	RAC 28	KL-15	7202	LL	ORD		7-Oct-2008	PBVR	48	60	HINO W06ETI BSII	FNE 101589	YPE 621938	59
2846	RAC 25	KL-15	7198	LL	ORD	SWB	4-Oct-2008	MDY	48	60	HINO W06ETI BSII	FNH 548383	FNE 656759	76
2847	RRE999	KL-15	7200	LL	ORD	MLB	6-Oct-2008	PKDA	48	60	HINO W06ETI BSII	JNH 540307	JNE 654631	81
2848	RAK 22	KL-15	7201	LL	ORD		6-Oct-2008	PVM	48	60	HINO W06ETI BSII	KXE 106728Z	JNE 654595	83
2849	RAE 58	KL-15	7222	LL	ORD		4-Nov-2008	MLPY	48	60	HINO W06ETI BSII	JNH 543167	JNE 655770	96
2850	RAE 57	KL-15	7223	LL	ORD		5-Nov-2008	MVK	48	60	HINO W06ETI BSII	JNH 544070	JNE 655735	88
2851	RAK 62	KL-15	7229	LL	ORD		15-Nov-2008	EKM	48	60	HINO W06ETI BSII	CNH 565700	BNE 665240	56

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2852	RAK 65	KL-15	7233	LL	ORD		21-Nov-2008	KMGM	48	60	HINO W06ETI BSII	CNH 560608	BNE 665169	55
2853	RAM 72	KL-15	7248	LL	ORD	VND	5-Dec-2008	KMR	48	60	HINO W06ETI BSII	JNH 544190	JNE 655804	30
2854	RAM 73	KL-15	7249	LL	ORD	VND	28-Nov-2008	GVR	48	60	HINO W06ETI BSII	JNH 543292	JNE 655861	66
2855	RAE 60	KL-15	7261	LL	ORD		5-Dec-2008	KTP	48	60	HINO W06ETI BSII	DNE 102495Z	CNE 663498	14
2856	RAE 69	KL-15	7256	LL	ORD		11-Dec-2008	PSL	48	60	HINO W06ETI BSII	BNE 103601Z	BNE 665275	21
2857	RAE 83	KL-15	7263	LL	ORD		6-Dec-2008	VJMD	48	60	HINO W06ETI BSII	CNH 560516	BNE 665186	16
2858	RAC116	KL-15	7276	LL	ORD	SWB	15-Dec-2008	NDD	48	60	HINO W06ETI BSII	ZNE 104025Z	ZNE 666205	31
2859	RAC113	KL-15	7275	LL	ORD	SWB	15-Dec-2008	KNR	48	60	HINO W06ETI BSII	ZNE 104022Z	ZNE 666207	77
2860	RAC137	KL-15	7277	LL	ORD	SWB	15-Dec-2008	KNR	48	60	HINO W06ETI BSII	ZNE 104026Z	ZNE 666213	77
2861	RAE 86	KL-15	7285	LL	ORD	VND	17-Dec-2008	KTR	48	60	HINO W06ETI BSII	CNH 557563	CNE 663384	35
2862	RAK 79	KL-15	7281	LL	ORD		17-Dec-2008	TPLM	48	60	HINO W06ETI BSII	NXE 105180	CNE 663513	94
2863	RAC171	KL-15	7299	LL	ORD	SWB	23-Dec-2008	TDY	48	60	HINO W06ETI BSII	NPH 482420	ZNE 666225	79
2864	RAC175	KL-15	7294	LL	ORD	SWB	22-Dec-2008	NDD	48	60	HINO W06ETI BSII	ZNE 104166Z	ZNE 666694	31
2865	RAC146	KL-15	7306	LL	ORD	SWB	27-Dec-2008	CTR	48	60	HINO W06ETI BSII	ZNE 104 103Z	ZNE 666524	70
2866	RAC144	KL-15	7300	LL	ORD	SWB	24-Dec-2008	TDY	48	60	HINO W06ETI BSII	KNH 534946	ZNE 666206	79
2867	RAE133	KL-15	7332	LL	ORD		2-Jan-2009	MDY	48	60	HINO W06ETI BSII	CNH 560727	BNE 665253	76
2868	RAA150	KL-15	7322	LL	ORD		1-Jan-2009	MDY	48	60	HINO W06ETI BSII		CNE 663499	76
2869	RAE 84	KL-15	7329	LL	ORD		1-Jan-2009	NBR	48	60	HINO W06ETI BSII	MNH 519850	CNE 664137	86
2870	RAC165	KL-15	7321	LL	ORD	MLB	1-Jan-2009	PMNA	48	60	HINO W06ETI BSII	DNE 102730Z	CNE 663470	68
2871	RAE178	KL-15	7347	LL	ORD		8-Jan-2009	MDY	48	60	HINO W06ETI BSII	DNH 554488	CNE 663449	76
2872	RAE134	KL-15	7352	LL	ORD		9-Jan-2009	NBR	48	60	HINO W06ETI BSII	MWH 278203	CNE 663376	86
2873	RAC223	KL-15	7359	LL	ORD	SWB	12-Jan-2009	CTR	48	60	HINO W06ETI BSII	JNH543292	ZNE 666230	70
2874	RAC224	KL-15	7360	LL	ORD	SWB	12-Jan-2009	PLKD	48	60	HINO W06ETI BSII	ZNE104100Z	ZNE 666536	69
2875	RAE183	KL-15	7377	LL	ORD		19-Jan-2009	PTPM	48	60	HINO W06ETI BSII	DNH 552604	ZNE 666192	15
2876	RAM214	KL-15	7381	LL	ORD	MLB	21-Jan-2009	PMNA	48	60	HINO W06ETI BSII	ZNE 104042Z	ZNE 666220	68
2877	RAE248	KL-15	7386	LL	ORD		22-Jan-2009	MVK	48	60	HINO W06ETI BSII	CNH 564002	ZNE 666592	88
2878	RAM216	KL-15	7392	LL	ORD	MLB	23-Jan-2009	PMNA	48	60	HINO W06ETI BSII	ZNE 104009Z	ZNE 666193	68
2879	RAC238	KL-15	7398	LL	ORD		27-Jan-2009	MLPY	48	60	HINO W06ETI BSII	ZNE 104196Z	YNE 667398	96
2880	RAK162	KL-15	7403	LL	ORD		29-Jan-2009	SBY	48	60	HINO W06ETI BSII	CNH 563999	BNE 666575	75
2881	RAC234	KL-15	7402	LL	ORD	MLB	28-Jan-2009	PMNA	48	60	HINO W06ETI BSII	ZNE 104000Z	ZNE 666160	68
2882	RAC235	KL-15	7411	LL	ORD	MLB	30-Jan-2009	PMNA	48	60	HINO W06ETI BSII	ZNE 104357Z	YNE 667388	68
2883	RAC237	KL-15	7412	LL	ORD	MLB	30-Jan-2009	MDY	48	60	HINO W06ETI BSII		YNE 667412	76
2884	RAC236	KL-15	7413	LL	ORD	MLB	31-Jan-2009	PLKD	48	60	HINO W06ETI BSII	ZNE104324Z	YNE 667280	69
2885	RAC261	KL-15	7414	LL	ORD	MLB	31-Jan-2009	PLKD	48	60	HINO W06ETI BSII	ZNE104498Z	YNE 667373	69
2886	RAC265	KL-15	7436	LL	ORD		9-Feb-2009	MDY	48	60	HINO W06ETI BSII	ZNE104413Z	YNE 667354	76
2887	RAC341	KL-15	7487	LL	ORD	VND	26-Feb-2009	KMR	48	60	HINO W06ETI BSII	XNE 104646Z	XNE 667966	30
2888	RAE276	KL-15	7445	LL	ORD		16-Feb-2009	TSY	48	60	HINO W06ETI BSII	ZNE 104560Z	YNE 667562	73
2889	RAK245	KL-15	7447	LL	ORD		16-Feb-2009	PMNA	48	60	HINO W06ETI BSII	ZNH 569236	YNE 667323	68
2890	RAC342	KL-15	7492	LL	ORD	VND	27-Feb-2009	KMR	48	60	HINO W06ETI BSII	ZNE 104464Z	YNE 667561	30
2891	RAC355	KL-15	7493	LL	ORD	VND	27-Feb-2009	KMR	48	60	HINO W06ETI BSII	CNH 559788	NXE 668401	30
2892	RAK 64	KL-15	7393	LL	ORD	VND	23-Jan-2009	KPA	48	60	HINO W06ETI BSII	FNH 547059	BNE 665184	74
2893	RAE363	KL-15	7519	LL	ORD		7-Mar-2009	TSY	48	60	HINO W06ETI BSII	ZNE104120	ZNE 666658	73
2894	RAE364	KL-15	7520	LL	ORD		7-Mar-2009	PMNA	48	60	HINO W06ETI BSII	ZNE104326	ZNE 667232	68
2895	RAC407	KL-15	7566	LL	ORD		1-Apr-2009	MNR	48	60	HINO W06ETI BSII	XNE 104909EZZ	BNE 665243	60
2896	RAM213	KL-15	7426	LL	ORD		25-Mar-2009	MDY	48	60	HINO W06ETI BSII		ZNE 666245	76

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2897	RAM217	KL-15	7422	LL	ORD		25-Mar-2009	MDY	48	60	HINO W06ETI BSII		ZNE 666243	76
2898	RAE365	KL-15	7535	LL	ORD		13-Mar-2009	KNR	48	60	HINO W06ETI BSII	ZNE 104049Z	ZNE 666221	77
2899	RAE399	KL-15	7563	LL	ORD	VND	23-Mar-2009	PTPM	48	60	HINO W06ETI BSII	NXE 105210	NXE 669049	15
2900	RAC440	KL-15	7597	LL	ORD	SWB	1-Apr-2009	MVPA	48	60	HINO W06ETI BSII	LXH 572139	LXE 669776	52
2901	RAC442	KL-15	7599	LL	ORD	SWB	1-Apr-2009	PKDA	48	60	HINO W06ETI BSII	LXH 572745	LXE 669860	81
2902	RAC451	KL-15	7607	LL	ORD	SWB	2-Apr-2009	NDD	48	60	HINO W06ETI BSII	LXH 572101	LXE 669784	31
2903	RAE366	KL-15	7539	LL	ORD		16-Mar-2009	KPA	48	60	HINO W06ETI BSII			74
2904	RAE368	KL-15	7541	LL	ORD		16-Mar-2009	KPA	48	60	HINO W06ETI BSII			74
2905	RAC373	KL-15	7538	LL	ORD		13-Mar-2009	KNR	48	60	HINO W06ETI BSII	XNE 104917Z	NXE 668397	77
2906	RAE326	KL-15	7499	LL	ORD		13-Apr-2009	KPA	48	60	HINO W06ETI BSII	ZNE 104278Z	XNE 667914	74
2907	RAE327	KL-15	7500	LL	ORD		13-Apr-2009	KPA	48	60	HINO W06ETI BSII	ZNE 104279Z	YNE 667281	74
2908	RAE432	KL-15	7580	LL	ORD		20-Apr-2009	PLKD	48	60	HINO W06ETI BSII	NXH571593	NXE 669086	69
2909	RAE430	KL-15	7587	LL	ORD		20-Apr-2009	PLKD	48	60	HINO W06ETI BSII	NXH571601	NXE 669093	69
2910	RAE431	KL-15	7588	LL	ORD		31-Mar-2009	PLKD	48	60	HINO W06ETI BSII	NXH571767	NXE 669226	69
2911	RAC452	KL-15	7615	LL	ORD	SWB	13-Apr-2009	VJMD	48	60	HINO W06ETI BSII	LXH 572952	LXE 669926	16
2912	RAC480	KL-15	7627	LL	ORD	SWB	21-Apr-2009	TSY	48	60	HINO W06ETI BSII	LXH 572800	LXE 669982	73
2913	RAC498	KL-15	7655	LL	ORD	SWB	23-Apr-2009	TSY	48	60	HINO W06ETI BSII	LXH 572548	LXE 669723	73
2914	RAC500	KL-15	7656	LL	ORD	SWB	23-Apr-2009	TDY	48	60	HINO W06ETI BSII	JXE 107060Z	LXE 669938	79
2915	RAC499	KL-15	7660	LL	ORD	SWB	25-Apr-2009	KTP	48	60	HINO W06ETI BSII TURBO INTER COOLER	LXH 572957	LXE 669915	14
2916	RAC505	KL-15	7661	LL	ORD	SWB	25-Apr-2009	MDY	48	60	HINO W06ETI BSII	LXH 572740	LXE 670397	76
2917	RAC507	KL-15	7662	LL	ORD	SWB	25-Apr-2009	MDY	48	60	HINO W06ETI BSII	LXH 572166	LXE 669947	76
2918	RAE433	KL-15	7608	LL	ORD		4-Apr-2009	PMNA	48	60	HINO W06ETI BSII	NXE 105232Z	NXE 669256	68
2919	RAC445	KL-15	7602	LL	ORD		1-Apr-2009	PKD	48	60	HINO W06ETI BSII	YNE 104581Z	XNE 667895	65
2920	RAC446	KL-15	7603	LL	ORD		1-Apr-2009	PKD	48	60	HINO W06ETI BSII	XNE 104895Z	NXE 668400	65
2921	RAC447	KL-15	7612	LL	ORD		7-Apr-2009	PMNA	48	60	HINO W06ETI BSII	CNH 560759	BNE 665245	68
2922	RAE465	KL-15	7611	LL	ORD		7-Apr-2009	PMNA	48	60	HINO W06ETI BSII	NXE 105223Z	NXE 669040	68
2923	RAC506	KL-15	7665	LL	ORD	SWB	27-Apr-2009	MDY	48	60	HINO W06ETI BSII	LXH 572242	LXE 669937	76
2924	RAC508	KL-15	7666	LL	ORD	SWB	27-Apr-2009	MDY	48	60	HINO W06ETI BSII	LXH 572302	LXE 669917	76
2925	RAC509	KL-15	7667	LL	ORD	SWB	27-Apr-2009	KNR	48	60	HINO W06ETI BSII	LXH 572842	LXE 669917	77
2926	RAC510	KL-15	7668	LL	ORD	SWB	27-Apr-2009	KNR	48	60	HINO W06ETI BSII	LXH 572130	LXE 669967	77
2927	RAC511	KL-15	7670	LL	ORD	SWB	29-Apr-2009	TPLM	48	60	HINO W06ETI BSII	LXH 572842	LXE 669925	94
2928	RAC513	KL-15	7671	LL	ORD	SWB	29-Apr-2009	KNR	48	60	HINO W06ETI BSII	LXH 573803	LXE 670706	77
2929	RAC514	KL-15	7672	LL	ORD	SWB	29-Apr-2009	TDY	48	60	HINO W06ETI BSII	LXH 573374	LXE 670715	79
2930	RAC522	KL-15	7685	LL	ORD	SWB	4-May-2009	PTPM	48	60	HINO W06ETI BSII	LXH 573658	LXE 670711	15
2931	RAC525	KL-15	7686	LL	ORD	SWB	4-May-2009	PTPM	48	60	HINO W06ETI BSII	LXH 573675	LXE 670717	15
2932	RAC541	KL-15	7703	LL	ORD	SWB	8-May-2009	MDY	48	60	HINO W06ETI BSII	LXH 572137	LXE 670464	76
2933	RAC542	KL-15	7704	LL	ORD	SWB	8-May-2009	MDY	48	60	HINO W06ETI BSII	LXH 573697	LXE 670718	76
2934	RAC584	KL-15	7729	LL	ORD		16-May-2009	PNKM	48	60	HINO W06ETI BSII	KXH 574199	KXE 671906	49
2935	RAK576	KL-15	7768	LL	ORD		1-Jun-2009	KTR	48	60	HINO W06ETI BSII	LXH572702	LXE6656970	35
2936	RAC626	KL-15	7796	LL	ORD		20-Jun-2009	PLKD	48	60	HINO W06ETI BSII	LXE105831Z	LXE670559	69
2937	RAC650	KL-15	7798	LL	ORD	VND	20-Jun-2009	PTPM	48	60	HINO W06ETI BSII	LXE 1057622	LXE 670493	15
2938	RAC624	KL-15	7812	LL	ORD	VND	22-Jun-2009	PTPM	48	60	HINO W06ETI BSII	LXH 572241	LXE 670602	15
2939	RAC698	KL-15	7856	LL	ORD		6-Jul-2009	EMLY	48	60	HINO W06ETI BSII	KXH 574517	KXE 671877	95
2940	RAC700	KL-15	7861	LL	ORD		8-Jul-2009	KNR	48	60	HINO W06ETI BSII	KXE 106056Z	KXE 671074	77
2941	RAC603	KL-15	7790	LL	ORD		19-Jun-2009	KNR	48	60	HINO W06ETI BSII	LXH 572550	LXE 670019	77

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2942	RAE593	KL-15	7740	LL	ORD		16-Jul-2009	KHD	48	60	HINO W06ETI BSII			106
2943	RAC696	KL-15	7866	LL	ORD		13-Jul-2009	KPA	48	60	HINO W06ETI BSII			74
2944	RAK730	KL-15	7904	LL	ORD		22-Aug-2009	KPA	48	60	HINO W06ETI BSII			74
2945	RAK728	KL-15	7899	LL	ORD	MLB	19-Aug-2009	MDY	48	60	HINO W06ETI BSII			76
2946	RAE817	KL-15	8032	LL	ORD		5-Nov-2009	PKDA	48	60	HINO W06ETI BSII	KXH574422	MB1PBEHC89HCA1901	81
2947	RAK845	KL-15	8066	LL	ORD		24-Nov-2009	KMR	48	60	HINO W06ETI BSII	CXH 583008	MB1PBEHC69ECA5703	30
2948	RAE885	KL-15	8107	LL	ORD	VND	2-Dec-2009	MVK	48	60	HINO W06ETI BSII	JXE 106911Z	MB1PBEHC79EJA0816	88
2949	RAK922	KL-15	8108	LL	ORD	VND	2-Dec-2009	MVK	48	60	HINO W06ETI BSII	JXE 107104Z	MB1PBEHC59EJA1222	88
2950	RAE943	KL-15	8123	LL	ORD	VND	17-Dec-2009	KMR	48	60	HINO W06ETI BSII	ZXE 111550Z	MB1PBEHC69EZB0535	30
2951	RAK926	KL-15	8135	LL	ORD	MLB	19-Dec-2009	KNR	48	60	HINO W06ETI BSII	BXE 109973Z	MB1PBEHCX9EBA7813	77
2952	RAC981	KL-15	8160	LL	ORD	VND	4-Jan-2010	NDD	48	60	HINO W06ETI BSII	YXE113134Z	MB1PBEHCX9EYB3158	31
2953	RAE969	KL-15	8172	LL	ORD		12-Jan-2010	MNR	48	60	HINO W06ETI BSII	ZVH 00241073	MB1PBEHC69EZB1149	60
2954	RAE970	KL-15	8173	LL	ORD		12-Jan-2010	MNR	48	60	HINO W06ETI BSII	YXE 113148Z	MB1PBEHC19EYB3162	60
2955	RAE886	KL-15	8121	LL	ORD	VND	9-Dec-2009	MVK	48	60	HINO W06ETI BSII	ZXE 111939Z	29 EZB 1150	88
2956	RAE887	KL-15	8122	LL	ORD	VND	9-Dec-2009	MVK	48	60	HINO W06ETI BSII	ZXE 111948Z	MB1PBEHC49EXB1148	88
2957	RNC 22	KL-15	8214	LL	ORD	MLB	19-Feb-2010	KPA	48	60	HINO W06ETI BSII	WXE 114801Z	MB1PBEHC49ECA5025	74
2958	RAC141	KL-15	7292	LL	ORD	SWB	20-Dec-2008	NDD	48	60	HINO W06ETI BSII	ZNE104031Z	ZNE666208	31
2959	RNK 79	KL-15	8263	LL	ORD	MLB	21-Apr-2010	TSY	48	60	HINO W06ETI BSII	WAE119658Z	MB1PBEHC4AEWC3358	73
2960	RNK 80	KL-15	8264	LL	ORD	MLB	21-Apr-2010	TSY	48	60	HINO W06ETI BSII	WAE119344Z	MB1PBEHC5AEWC2963	73
2961	RNK 82	KL-15	8275	LL	ORD		26-Apr-2010	MDY	48	60	HINO W06ETI BSII	VAE121332Z	MB1PBEHC8AEVC5630	76
2962	RNC132	KL-15	8303	LL	ORD		7-May-2010	PBVR	48	60	HINO W06ETI BSII	WAE 119343Z	MB1PBEHC1AEWC2961	59
2963	RNK 86	KL-15	8310	LL	ORD	VND	18-May-2010	KMR	48	60	HINO W06ETI BSII	VAE120709Z	MB1PBEHC1AEVC4772	30
2964	RNK 87	KL-15	8320	LL	ORD	MLB	19-May-2010	MDY	48	60	HINO W06ETI BSII	VAE121701Z	MB1PBEHC8AEVC4770	76
2965	RNK107	KL-15	8321	LL	ORD	MLB	19-May-2010	MDY	48	60	HINO W06ETI BSII	VAE121344Z	MB1PBEHC3AEVC5602	76
2966	RNK108	KL-15	8322	LL	ORD	MLB	19-May-2010	MDY	48	60	HINO W06ETI BSII	VAE121246Z	MB1PBEHC5AEVC5536	76
2967	RNK109	KL-15	8339	LL	ORD		26-May-2010	MDY	48	60	HINO W06ETI BSII	VAE121246Z	MB1PBEHC3AEVC5759	76
2968	RNK110	KL-15	8340	LL	ORD		26-May-2010	MDY	48	60	HINO W06ETI BSII	WAE119338Z	MB1PBEHC5AEWC2977	76
2969	RNE152	KL-15	8375	LL	ORD		7-Jun-2010	MDY	48	60	HINO W06ETI BSII	VAE120755Z	MB1PBEHC3AEVC4806	76
2970	RNK181	KL-15	8393	LL	ORD	MLB	16-Jun-2010	KPA	48	60	HINO W06ETI BSII	VAE121340Z	MB1PBEHC7AEVC5604	74
2971	RNC223	KL-15	8399	LL	ORD	SWB	18-Jun-2010	KPA	48	60	HINO W06ETI BSII	VAE 122576Z	MB1PBEHE1AEBC7363	74
2972	RNK184	KL-15	8402	LL	ORD		21-Jun-2010	PNKM	48	60	HINO W06ETI BSII	WAE119342Z	MB1PBEHC3AEWC2962	49
2973	RNK183	KL-15	8403	LL	ORD		21-Jun-2010	PNKM	48	60	HINO W06ETI BSII	WAH614446Z	MB1PBEHCXAEWC4028	49
2974	RNE210	KL-15	8432	LL	ORD		3-Jul-2010	KPA	48	60	HINO W06ETI BSII	WAE120618Z	MB1PBEHE5AEVC4614	74
2975	RNK327	KL-15	8550	LL	ORD	MLB	10-Aug-2010	KNR	48	60	HINO W06ETI BSII	VAE121851Z	MB1PBEHC4AEVC6323	77
2976	RNC343	KL-15	8588	LL	ORD	SWB	26-Aug-2010	KNR	48	60	HINO W06ETI BSII	VAE120967Z	MB1PBCHC3AEVC5114	77
2977	RNC506	KL-15	8741	LL	ORD	SWB	20-Oct-2010	PTPM	48	60	HINO W06ETI BSII	NAE129506Z	MAT4122660AEND4576	15
2978	RNC644	KL-15	8906	LL	ORD		10-Dec-2010	KNR	48	60	HINO W06ETI BSII	VAE121421Z	MB1PBEHC1AEVC5761	77
2979	RNC753	KL-15	9057	LL	ORD	SWB	3-Mar-2011	PTPM	48	60	HINO W06ETI BSII	MAE130980Z	MAT4122666AEMD6068	15
2980	RAC115	KL-15	7286	LL	ORD	SWB	17-Dec-2008	MALA	48	60	HINO W06ETI BSII 176 ALPSV 4/100	ZNE 104033Z	ZNE 666231	85
2981	14000	KL-15	7165	LL	ORD	SWB	2-Sep-2008	KTDA	48	60	HINO W06ETI BSII ALPSV 4/100	FNH 545565	FNE 656799	25
2982	RAC443	KL-15	7600	LL	ORD	SWB	1-Apr-2009	KTDA	48	60	HINO W06ETI BSII ALPSV 4/100	LXH 572250	LXE 669936	25
2983	RRC152	KL-15	6327	LL	ORD	VND	5-Nov-2007	KTDA	48	60	HINO W06ETI BSII ALPSV 4/89	XPH 473341	WPE 628425	25
2984	RRE929	KL-15	7108	LL	ORD		18-Aug-2008	PMNA	48	60	HINO W06ETI BSII ALPSV 4/89	JXH 576221	JNE 654233	68
2985	RAE 70	KL-15	7320	LL	ORD		30-Dec-2008	KTDA	48	60	HINO W06ETI BSII ALPSV 4/89	BNH 568363	BNE 665185	25
2986	RAE131	KL-15	7303	LL	ORD		26-Dec-2008	KTDA	48	60	HINO W06ETI BSII ALPSV 4/89	JNH 541907	BNE 665505	25

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
2987	RRC252	KL-15	6428	LL	ORD	VND	10-Dec-2007	PLD	48	60	HINO EURO II TURBO INTERCOOLER	VPH 488197	VPE 631959	32
2988	RRE126	KL-15	6308	LL	ORD		27-Oct-2007	MVPA	48	60	HINO W06ETI BSII TURBO INTER COOLER	YPH 470986	XPE 624802	52
2989	RRK141	KL-15	6340	LL	ORD		14-Nov-2007	PKDA	48	60	HINO W06ETI BSII TURBO INTER COOLER	WPH 479753	WPE 628357	81
2990	RRE128	KL-15	6326	LL	ORD		5-Nov-2007	MVPA	48	60	HINO W06ETI BSII TURBO INTER COOLER	YPH 471300	YPE 624613	52
2991	RRC253	KL-15	6426	LL	ORD		10-Dec-2007	KMGM	48	60	HINO W06ETI BSII TURBO INTER COOLER	VPH 488003	VPE 631933	55
2992	RRE403	KL-15	6621	LL	ORD	VND	6-Feb-2008	KHD	48	60	HINO W06ETI BSII TURBO INTER COOLER	UPH 495446	UPE 635671	106
2993	RRK 58	KL-15	6256	LL	ORD	MLB	19-Sep-2007	PNR	48	60	HINO W06ETI BSII VIKING	YPH 470370	XPE 624746	78
2994	RRK 59	KL-15	6263	LL	ORD	MLB	27-Sep-2007	PNR	48	60	HINO W06ETI BSII VIKING	YPH 471298	YPE 624621	78
2995	RRK 60	KL-15	6274	LL	ORD	MLB	3-Oct-2007	PNR	48	60	HINO W06ETI BSII VIKING	YPH 470441	YPE 624698	78
2996	RNC870	KL-15	9315	LL	ORD	SWB	24-Dec-2011	EMLY	48	60	HINO 6ETI3K BSIII	NBE158509Z	MB1PCEYC0BENG3822	95
2997	RRE917	KL-15	7074	LL	ORD	MLB	1-Jul-2008	CTR	48	60	HINO W06ETII BSII	KNH 535461	JNE 653416	70
2998	RRE919	KL-15	7079	LL	ORD		4-Jul-2008	ETPA	48	60	HINO W06ETII BSII	JNH 540214	JNE 654227	48
2999	RRE924	KL-15	7091	LL	ORD		22-Jul-2008	TVL	48	60	HINO W06ETII BSII	JNH 542225	JNE 654571	43
3000	RRE925	KL-15	7092	LL	ORD		22-Jul-2008	TVL	48	60	HINO W06ETII BSII	ZXE 111968Z	JNE 653935	43
3001	RRE926	KL-15	7099	LL	ORD		28-Jul-2008	TDY	48	60	HINO W06ETII BSII	JNH 540297	JNE 654586	79
3002	RRE922	KL-15	7083	LL	ORD		8-Jul-2008	KMR	48	60	HINO W06ETII BSII	JNH 541904	JNE 654194	30
3003	RAC483	KL-15	7630	LL	ORD	SWB	21-Apr-2009	EDT	48	60	HINO W06ETT BSII	XPH 478701	LXE 669861	98
3004	RRC514	KL-15	6659	LL	ORD	VND	18-Feb-2008	KNR	48	60	HINO W06PTI BSII	NPH 505697	NPE 640812	77
3005	RRE849	KL-15	7001	LL	ORD		30-May-2008	KTR	48	60	HINO W06WTI BSII	KNE 100610Z	KNE 651444	35
3006	RRE853	KL-15	7022	LL	ORD		7-Jun-2008	VZM	48	60	HINO W06WTI BSII	CNH 560892	KNE 651596	24
3007	RRE851	KL-15	7009	LL	ORD	VND	2-Jun-2008	PKDA	48	60	HINO W06WTI BSII	KNH 533539	KNE 651461	81
3008	RRE854	KL-15	7028	LL	ORD		10-Jun-2008	MKD	48	60	HINO W06WTI BSII	KNH 533698	KNE 651595	08
3009	RRE856	KL-15	7034	LL	ORD	VND	13-Jun-2008	VLND	48	60	HINO W06WTI BSII	KNE 100641Z	KNE 651674	20
3010	RAC173	KL-15	7293	LL	ORD	SWB	22-Dec-2008	NDD	48	60	HINO W06ETI BSII	ZNE 104107Z	ZNE 666523	31
3011	RAE 82	KL-15	7313	LL	ORD		29-Dec-2008	NDD	48	60	HINO W06ETI BSII	CNE 103250Z	BNE 664145	31
3012	RAK157	KL-15	7325	LL	ORD	VND	1-Jan-2009	NDD	48	60	HINO W06ETI BSII	BNE 103638Z	BNE 665331	31
3013	RAC695	KL-15	7855	LL	ORD		4-Jul-2009	EMLY	48	60	HINO W06ETI BSII	KXH 574252	KXE 671875	95
3014	RRK777	KL-15	7052	LL	ORD		20-Jun-2008	KHD	48	60	HINO W06ETI BSII	PNH 512476	PNE 642655	106
3015	RAC356	KL-15	7494	LL	ORD	VND	27-Feb-2009	KMR	48	60	HONO W06ETI BSII	ZNE 104004Z	ZNE 666180	30
3016	RRC622	KL-15	6776	TATA	ORD	VND	19-Mar-2008	KLM	48	60	697 TCIC	BRZ 105994	BRZ 002847	34
3017	RRC426	KL-15	6592	LL	ORD	VND	31-Jan-2008	NTA	48	60	LL BSII	UPH 493903	UPE 635242	22
3018	RNK408	KL-15	8653	LL	ORD		22-Sep-2010	TSY	48	60	LL BSII	WAE120151Z	MB1PBEHC4AEWC4025	73
3019	RNK558	KL-15	8917	LL	ORD		15-Dec-2010	VDA	48	60	LL BSII	NAE130079Z	MB1PBEHC0AEND5178	92
3020	RAC259	KL-15	7420	LL	ORD		2-Feb-2009	SBY	48	60	LL BSII W06ETI HINO EURO	CNE 103236Z	CNE 664128	75
3021	RAE 55	KL-15	7208	LL	ORD		14-Oct-2008	TDP	48	60	LL HINO ALPSV 4/89 BSII	JNH 543170	JNE 655768	53
3022	RRC272	KL-15	6447	LL	ORD	VND	19-Dec-2007	PSL	48	60	LL HINO BSII	VPH 488194	VPE 631939	21
3023	RRC418	KL-15	6576	LL	ORD	VND	25-Jan-2008	PSL	48	60	LL HINO BSII	TPH 501927	TPE 637324	21
3024	RRK573	KL-15	6757	LL	ORD		14-Mar-2008	ETPA	48	60	LL HINO BSII	TPH 501248	NPE 639579	48
3025	RRE681	KL-15	6886	LL	ORD		17-Apr-2008	ETPA	48	60	LL HINO BSII	ZNE 104138Z	NPE 640748	48
3026	RRC905	KL-15	7238	LL	ORD		22-Nov-2008	ETPA	48	60	LL HINO BSII	JNH 541684	JNE 653940	48
3027	RRC982	KL-15	7239	LL	ORD		24-Nov-2008	ETPA	48	60	LL HINO BSII	JNH 539345	JNE 655549	48
3028	RAA104	KL-15	7252	LL	ORD		29-Nov-2008	ETPA	48	60	LL HINO BSII	JNH 543583	JNE 652065	48
3029	RAA106	KL-15	7254	LL	ORD		29-Nov-2008	CHRY	48	60	LL HINO BSII	NPH 508705	BNE 664842	44
3030	RAA197	KL-15	7382	LL	ORD	VND	20-Jan-2009	ARND	48	60	LL HINO BSII	ZNE 104181Z	ZNE 666762	19
3031	RAC482	KL-15	7629	LL	ORD	SWB	21-Apr-2009	ETPA	48	60	LL HINO BSII	LXH 572112	LXE 669968	48

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3032	RNC 9	KL-15	8186	LL	ORD	VND	21-Jan-2010	PSL	48	60	LL HINO BSII	NXE 113915Z	EWB 4437	21
3033	RNE151	KL-15	8364	LL	ORD		4-Jun-2010	PSL	48	60	LL HINO BSII	WAE119417Z	MB1PBEHC7AEWC3113	21
3034	RNK326	KL-15	8537	LL	ORD	VND	4-Aug-2010	GVR	48	60	LL HINO BSII	VAE121475Z	MB1PBEHC8AEVC5871	66
3035	RAC485	KL-15	7646	LL	ORD	SWB	21-Apr-2009	VZM	48	60	LL HINO BSII W06ETI	LXH 572559	LXE 669706	24
3036	RAK923	KL-15	8106	LL	ORD	VND	7-Dec-2009	HPD	48	60	LL HINO EURO BSII	BXE110094Z	MB1PBEHC99EBA8046	42
3037	RNC309	KL-15	8510	LL	ORD	SWB	24-Jul-2010	KLM	48	60	LL HINO EURO II TURBO INTER COOLER	VAE122579Z	MB1PCEHC5AEVC7364	34
3038	RNC549	KL-15	8833	LL	ORD	TK	19-Nov-2010	ANK	48	60	LL HINO EURO II TURBO INTER COOLER	MAE132172Z	MB1PBEHCXAEMD7307	57
3039	RAC212	KL-15	7380	LL	ORD	VND	19-Jan-2009	KTR	48	60	LL HINO EURO II TURBOINTER COOLER	ZNE 104121Z	ZNE 666567	35
3040	RAC229	KL-15	7397	LL	ORD		24-Jan-2009	VZM	48	60	LL HINO EURO II TURBOINTER COOLER	ZNE 104124Z	ZNE 666565	24
3041	RNC310	KL-15	8535	LL	ORD	SWB	3-Aug-2010	PPD	48	60	LL HINO EUROII TURBO INTER COOLER	VAE122645Z	MB1PCEHC0AETC7458	26
3042	RNA 25	KL-15	8201	LL	ORD		5-Feb-2010	PPD	48	60	LL HINO TCIC BSII	WXE 114487Z	MB1PBEH89EWB5517	26
3043	RRC144	KL-15	6312	LL	ORD		30-Oct-2007	ETPA	48	60	LL HINO W06ETI BSII	WRG 2080	WPE 628548	48
3044	RRC145	KL-15	6313	LL	ORD	VND	30-Oct-2007	ETPA	48	60	LL HINO W06ETI BSII	WPH 480946	WPE 628550	48
3045	RRC268	KL-15	6434	LL	ORD	VND	12-Dec-2007	ETPA	48	60	LL HINO W06ETI BSII	VPH 488174	VPE 631934	48
3046	RAE 61	KL-15	7243	LL	ORD		26-Nov-2008	KPZA	48	60	HINO EURO BSII TURBO INTERCOOLER	JNE 101418Z	JNE 655769	07
3047	RAE 59	KL-15	7244	LL	ORD		27-Nov-2008	ETPA	48	60	LL HINO W06ETI BSII	JNH 541478	JNE 653858	48
3048	RAK 66	KL-15	7266	LL	ORD		9-Dec-2008	ETPA	48	60	LL HINO W06ETI BSII	CNE 103247Z	CNE 664130	48
3049	RAK 81	KL-15	7282	LL	ORD		17-Dec-2008	ETPA	48	60	LL HINO W06ETI BSII	BNE 103616Z	BNE 665303	48
3050	RAK987	KL-15	8191	LL	ORD		28-Jan-2010	CHRY	48	60	LL HINO/E BSII	ZXE111356Z	MB1PBEHC99EZB0173	44
3051	RNC671	KL-15	8987	LL	ORD	SWB	22-Jan-2011	TDY	48	60	LL HINO/E BSII	JNH 539975	MB1PCEHC8AEMD6508	79
3052	RAC481	KL-15	7628	LL	ORD	SWB	21-Apr-2009	CHRY	48	60	LL HINO/E BSII ALPSV 4/100	LXH 572067	LXE 669966	44
3053	RAC545	KL-15	7715	LL	ORD	SWB	15-May-2009	CHRY	48	60	LL HINO/E BSII ALPSV 4/100	LXH 572403	LXE 670398	44
3054	RRC415	KL-15	6571	TATA	ORD		24-Jan-2008	KPM	48	60	697 TCIC	KSZ 146662	KSZ 016687	91
3055	RRC464	KL-15	6631	TATA	ORD	VND	11-Feb-2008	PNI	48	60	697 TCIC	DRZ 1620468	MSZ 020917	67
3056	RRM133	KL-15	6314	TATA	ORD	VND	31-Oct-2007	PVR	48	60	697 TCIC	697 TC55 FSZ 130830	436062 FSZ 010520	23
3057	RRC493	KL-15	6649	TATA	ORD	VND	16-Feb-2008	NPR	48	60	697 TCIC	697TC55LS2152418	436062MSZ021047	62
3058	RRC472	KL-15	6636	TATA	ORD	VND	12-Feb-2008	KYLM	48	60	697 TCIC	MSZ 155941	MSZ 021115	41
3059	RRC637	KL-15	6784	TATA	ORD	VND	24-Mar-2008	KPM	48	60	697 TCIC	ARZ 105619	BRZ 002967	91
3060	RRC644	KL-15	6805	TATA	ORD	VND	27-Mar-2008	ATL	48	60	697 TCIC	MSZ 158400	BRZ 002970	33
3061	RRC636	KL-15	6807	TATA	ORD	VND	27-Mar-2008	PALA	48	60	697 TCIC	ARZ 105445	BRZ 002870	50
3062	RRC701	KL-15	6860	TATA	ORD	VND	15-Apr-2008	NPR	48	60	697 TCIC	BRZ 108666	BRZ 003583	62
3063	RRC781	KL-15	6954	TATA	ORD	VND	12-May-2008	VKBN	48	60	697 TCIC	CRZ 115032	CRZ 006599	29
3064	RRM821	KL-15	7011	TATA	ORD		2-Jun-2008	CTY	48	60	697 TCIC	KSZ 148228	CRZ 006295	28
3065	RRC562	KL-15	6723	TATA	ORD	VND	6-Mar-2008	KLM	48	60	697 TCIC	ARZ 100295	ARZ 000796	34
3066	RRC584	KL-15	6746	TATA	ORD	VND	12-Mar-2008	KLM	48	60	697 TCIC	ARZ 101661	ARZ 001423	34
3067	RRC980	KL-15	7150	TATA	ORD	SWB	26-Aug-2008	VTRA	48	60	697 1510 BSII	ERZ 128723	436042 ERZ121887	17
3068	RRC608	KL-15	6748	TATA	ORD	VND	12-Mar-2008	MVK	48	60	697 TCIC	ARZ 101926	436062 ARZ001424	88
3069	RRC498	KL-15	6654	TATA	ORD	MLB	16-Feb-2008	CLDY	48	60	697 TCIC	KSZ 148222	MSZ 020843	58
3070	RRC610	KL-15	6772	TATA	ORD	MLB	18-Mar-2008	TPLM	48	60	697 TCIC	ARZ 101460	ARZ 000902	94
3071	RRC611	KL-15	6766	TATA	ORD	MLB	17-Mar-2008	TPLM	48	60	697 TCIC	ARZ 105633	BRZ 002830	94
3072	RRC613	KL-15	6768	TATA	ORD	MLB	18-Mar-2008	TPLM	48	60	697 TCIC	ARZ 105431	BRZ 002839	94
3073	RRC615	KL-15	6770	TATA	ORD	MLB	18-Mar-2008	KNR	48	60	697 TCIC	ARZ 106000	BRZ 002836	77
3074	RRC617	KL-15	6791	TATA	ORD	VND	25-Mar-2008	VKBN	48	60	697 TCIC	ARZ 105454	BRZ 002877	29
3075	RRC606	KL-15	6758	TATA	ORD	VND	14-Mar-2008	CTLA	48	60	697 TCIC 1510 BSII	ARZ 105620	ARZ 002829	46
3076	RRA898	KL-15	7077	TATA	ORD	VND	4-Jul-2008	TDP	48	60	697 TCIC	MSZ 155837	DRZ 007848	53

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3077	RRC295	KL-15	6467	TATA	ORD	MLB	27-Dec-2007	KHD	48	60	697 TCIC	697 TC55 JSZ 135647	436062 JSZ 013357	106
3078	RRC286	KL-15	6468	TATA	ORD	MLB	27-Dec-2007	KNR	48	60	697 TCIC	697 TC55 HSZ 136257	436062 HSZ 013453	77
3079	RRC290	KL-15	6458	TATA	ORD	MLB	22-Dec-2007	MDY	48	60	697 TCIC	697 TC55 JSZ 139878	436062 JSZ 014691	76
3080	RRC301	KL-15	6485	TATA	ORD	MLB	31-Dec-2007	KNR	48	60	697 TCIC	697 TC55 JSZ 139627	436062 JSZ 015219	77
3081	RRC340	KL-15	6486	TATA	ORD	MLB	31-Dec-2007	KNR	48	60	697 TCIC	JSZ 139267	JSZ 015225	77
3082	RRC298	KL-15	6489	TATA	ORD	MLB	1-Jan-2008	KHD	48	60	697 TCIC	697 TC55 JSZ 140638	436062 JSZ 015230	106
3083	RRA344	KL-15	6539	TATA	ORD	MLB	16-Jan-2008	KNR	48	60	697 TCIC	JSZ 140646	JSZ 015319	77
3084	RRC337	KL-15	6495	TATA	ORD	MLB	2-Jan-2008	KHD	48	60	697 TCIC	GSZ 135531	HSZ 012471	106
3085	RRC475	KL-15	6643	TATA	ORD	MLB	13-Feb-2008	CLDY	48	60	697 TCIC	MSZ 155840	MSZ 021119	58
3086	RRC802	KL-15	6961	TATA	ORD	VND	14-May-2008	PTA	48	60	697 TCIC	ARZ 101463	CRZ 005842	37
3087	RRC803	KL-15	6975	TATA	ORD	VND	19-May-2008	PKDA	48	60	697 TCIC	BRZ 1122242	CRZ 005848	81
3088	RRC846	KL-15	7017	TATA	ORD	VND	2-Jun-2008	CTNR	48	60	697 TCIC	CRZ 115030	CRZ 006596	97
3089	RRC884	KL-15	7042	TATA	ORD	VND	17-Jun-2008	KDLR	48	60	697 TCIC	CRZ 111527	CRZ 006591	90
3090	RRC885	KL-15	7043	TATA	ORD	VND	17-Jun-2008	KDLR	48	60	697 TCIC	CRZ 115037	CRZ 006594	90
3091	RRC886	KL-15	7047	TATA	ORD	MLB	18-Jun-2008	TLY	48	60	697 TCIC	CRZ 115043	CRZ 006301	18
3092	RRC887	KL-15	7049	TATA	ORD	MLB	19-Jun-2008	TLY	48	60	697 TCIC	BRZ 108170	CRZ 005855	18
3093	RRC888	KL-15	7057	TATA	ORD	MLB	23-Jun-2008	TLY	48	60	697 TCIC	BRZ 112921	CRZ 005841	18
3094	RRC 74	KL-15	6245	TATA	ORD		24-Aug-2007	KTR	48	60	697 TCIC	697 TC55 MSZ 154098	436062 FSZ 010452	35
3095	RRC236	KL-15	6380	TATA	ORD		29-Nov-2007	ANK	48	60	697 TCIC	697 TC55 GSZ 135630	436042 HSZ 013351	57
3096	RRC343	KL-15	6496	TATA	ORD	MLB	2-Jan-2008	KHD	48	60	697 TCIC	JSZ 140465	JSZ 015328	106
3097	RRC357	KL-15	6515	LL	ORD	MLB	9-Jan-2008	SBY	48	60	697 TCIC	TPH 501990	TPE 637136	75
3098	RRC352	KL-15	6518	TATA	ORD	MLB	10-Jan-2008	KHD	48	60	697 TCIC	JSZ 139881	JSZ 015313	106
3099	RRM363	KL-15	6534	TATA	ORD		14-Jan-2008	GVR	48	60	1510 TCIC	697TC 55JSZ 140385	436062JSZ015333	66
3100	RRC374	KL-15	6528	TATA	ORD		14-Jan-2008	KTR	48	60	1510 TCIC	JSZ 140455	436062JSZ 015329	35
3101	RRC354	KL-15	6522	TATA	ORD	MLB	11-Jan-2008	TPLM	48	60	697 TCIC	JSZ 140466	JSZ 015318	94
3102	RRC356	KL-15	6529	TATA	ORD	MLB	14-Jan-2008	VDA	48	60	697 TCIC	JSZ 140456	JSZ 015326	92
3103	RRC381	KL-15	6546	TATA	ORD		17-Jan-2008	KNPY	48	60	697 TCIC	KSZ 148209	LSZ 018221	87
3104	RRA348	KL-15	6587	TATA	ORD	VND	29-Jan-2008	VJMD	48	60	697 TCIC	JSZ 140641	JSZ 015322	16
3105	RRM366	KL-15	6554	TATA	ORD	MLB	21-Jan-2008	NBR	48	60	697 TCIC	JSZ 143057	KSZ 016317	86
3106	RRC438	KL-15	6589	TATA	ORD		30-Jan-2008	NPR	48	60	697 TCIC	LSZ 148707	LSZ 018322	62
3107	RRC437	KL-15	6582	TATA	ORD		28-Jan-2008	NPR	48	60	697 TCIC	JSZ 142590	KSZ 016682	62
3108	RRC412	KL-15	6566	TATA	ORD		23-Jan-2008	VKM	48	60	697 TCIC	GSZ 135638	LSZ 018221	51
3109	RRM367	KL-15	6569	TATA	ORD	MLB	23-Jan-2008	NBR	48	60	697 TCIC	BRZ 108706	KSZ 016647	86
3110	RRM419	KL-15	6588	TATA	ORD	MLB	29-Jan-2008	VKM	48	60	697 TCIC	JSZ 143044	KSZ 016649	51
3111	RRA350	KL-15	6555	TATA	ORD	VND	21-Jan-2008	KNPY	48	60	CUMMINS	FSZ 131009	FSZ 010527	87
3112	RRC390	KL-15	6559	TATA	ORD	VND	21-Jan-2008	KTR	48	60	697TC555 BRZ106001	436062LSZ 018320	436062LSZ 018320	35
3113	RRM420	KL-15	6598	TATA	ORD	MLB	1-Feb-2008	NBR	48	60	697 TCIC	BRZ 106842	KSZ 016651	86
3114	RRC446	KL-15	6601	TATA	ORD	VND	1-Feb-2008	ALV	48	60	697 TCIC	KSZ 144754	LSZ 018113	61
3115	RRC451	KL-15	6605	TATA	ORD	VND	2-Feb-2008	CLDY	48	60	697 TCIC	CRZ 115040	LSZ 018326	58
3116	RRM365	KL-15	6547	TATA	ORD	MLB	18-Jan-2008	VDA	48	60	697 TCIC	JSZ 143287	KSZ 016318	92
3117	RRA428	KL-15	6615	TATA	ORD		6-Feb-2008	ANK	48	60	697 TCIC	JSZ 142588	KSZ 016648	57
3118	RRC445	KL-15	6613	TATA	ORD	VND	5-Feb-2008	KKLM	48	60	697 TCIC	MSZ 153957	MSZ 020927	108
3119	RRC474	KL-15	6648	TATA	ORD	VND	16-Feb-2008	PSL	48	60	1510 TCIC	MSZ 154100	MSZ 020929	21
3120	RRC520	KL-15	6668	TATA	ORD	VND	20-Feb-2008	VJMD	48	60	697 TCIC	697 TC55 LSZ 152737	436062MSZ021046	16
3121	RRC463	KL-15	6617	TATA	ORD	VND	6-Feb-2008	MVK	48	60	697 TCIC	MSZ 155837	436062 MSZ021111	88

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3122	RRM421	KL-15	6612	TATA	ORD	MLB	5-Feb-2008	NBR	48	60	697 TCIC	JSZ 140646	KSZ 016683	86
3123	RRM422	KL-15	6619	TATA	ORD	MLB	6-Feb-2008	NBR	48	60	697 TCIC	KSZ 148117	LSZ 018294	86
3124	RRC470	KL-15	6639	TATA	ORD	MLB	12-Feb-2008	CLDY	48	60	697 TCIC	62140986	MSZ 020918	58
3125	RRC497	KL-15	6653	TATA	ORD	MLB	16-Feb-2008	KTR	48	60	697 TCIC	MSZ 153954	MSZ 020849	35
3126	RRA476	KL-15	6683	TATA	ORD	MLB	23-Feb-2008	KYLM	48	60	697 TCIC	LSZ 148708	LSZ 018385	41
3127	RRC518	KL-15	6672	TATA	ORD	VND	21-Feb-2008	EKM	48	60	697 TCIC	CRZ 115032	MSZ 021043	56
3128	RRC525	KL-15	6680	TATA	ORD	VND	23-Feb-2008	KTR	48	60	697 TCIC	MSZ 153948	MSZ 021045	35
3129	RRC529	KL-15	6671	TATA	ORD	VND	21-Feb-2008	KTR	48	60	697 TCIC	MSZ 155944	MSZ 021117	35
3130	RRC471	KL-15	6645	TATA	ORD	VND	13-Feb-2008	KPM	48	60	697 TCIC	MSZ 155933	MSZ 021121	91
3131	RRA431	KL-15	6644	TATA	ORD		13-Feb-2008	KMR	48	60	697 TCIC	JSZ 142591	KSZ 016656	30
3132	RRA477	KL-15	6684	TATA	ORD		25-Feb-2008	KMR	48	60	697 TCIC	LSZ 148904	LSZ 018388	30
3133	RRC526	KL-15	6693	TATA	ORD	VND	28-Feb-2008	PSL	48	60	697 TCIC	MSZ 155962	MSZ 021109	21
3134	RRC531	KL-15	6694	TATA	ORD	VND	28-Feb-2008	KTR	48	60	697 TCIC	BRZ 108705	MSZ 021116	35
3135	RRA478	KL-15	6692	TATA	ORD	VND	28-Feb-2008	KLM	48	60	697 TCIC	LSZ 148713	LSZ 018389	34
3136	RRC466	KL-15	6623	TATA	ORD	VND	7-Feb-2008	KTR	48	60	697 TCIC	MSZ 153947	MSZ 020928	35
3137	RRA349	KL-15	6600	TATA	ORD	VND	1-Feb-2008	ALP	48	60	697 TCIC	JSZ 138987	JSZ 015323	45
3138	RRC530	KL-15	6686	TATA	ORD	MLB	25-Feb-2008	PNI	48	60	697 TC BS I	30J 62290338	MSZ 021122	67
3139	RRC544	KL-15	6697	TATA	ORD	MLB	28-Feb-2008	PNI	48	60	697 TCIC	MSZ 155960	MSZ 021357	67
3140	RRC556	KL-15	6705	TATA	ORD	VND	29-Feb-2008	CTLA	48	60	697 TCIC 1510 BSII	MSZ 158441	ARZ 000616	46
3141	RRC532	KL-15	6695	TATA	ORD	VND	28-Feb-2008	KTR	48	60	697 TCIC	MSZ 154116	MSZ 020847	35
3142	RRC583	KL-15	6745	TATA	ORD	VND	12-Mar-2008	ADR	48	60	697 TCIC	ARZ 101425	ARZ 000632	38
3143	RRC543	KL-15	6696	TATA	ORD	MLB	28-Feb-2008	MALA	48	60	697 TCIC	LSZ 152596	MSZ 021113	85
3144	RRA484	KL-15	6750	TATA	ORD	VND	13-Mar-2008	KPM	48	60	697 TCIC	TR 118749	LSZ 018717	91
3145	RRA482	KL-15	6738	TATA	ORD	VND	10-Mar-2008	CTLA	48	60	697 TCIC	SOA62385669	LSZ 018607	46
3146	RRC559	KL-15	6716	TATA	ORD	VND	1-Mar-2008	CTLA	48	60	697 TCIC	ERQ 731655	ARZ 000673	46
3147	RRC557	KL-15	6715	TATA	ORD	VND	1-Mar-2008	PSL	48	60	697 TCIC	MSZ 155945	MSZ 021120	21
3148	RRA479	KL-15	6711	TATA	ORD	VND	1-Mar-2008	MVK	48	60	697 TCIC	KSZ 148113	436062 LSZ 018392	88
3149	RRA347	KL-15	6756	TATA	ORD	MLB	14-Mar-2008	KYLM	48	60	CUMMINS	JSZ 140640	JSZ 015321	41
3150	RRA485	KL-15	6760	TATA	ORD		15-Mar-2008	NTA	48	60	697 TCIC 155	FSZ 130763	KSZ 016652	22
3151	RRC566	KL-15	6728	TATA	ORD	VND	7-Mar-2008	KYLM	48	60	697 TCIC	ARZ 100750	ARZ 000854	41
3152	RRC568	KL-15	6733	TATA	ORD	VND	10-Mar-2008	ALP	48	60	697 TCIC	ARZ 100756	ARZ 000877	45
3153	RRC577	KL-15	6732	TATA	ORD	VND	10-Mar-2008	CLDY	48	60	697 TCIC	FSZ 130937	ARZ 000901	58
3154	RRC578	KL-15	6734	TATA	ORD	VND	10-Mar-2008	CTLA	48	60	697 TCIC 1510 BSII	ARZ 101461	ARZ 000906	46
3155	RRC580	KL-15	6736	TATA	ORD	VND	10-Mar-2008	ANK	48	60	697 TCIC	ARZ 100230	ARZ 000861	57
3156	RRC545	KL-15	6698	TATA	ORD	MLB	28-Feb-2008	NBR	48	60	697 TCIC	JSZ 140639	MSZ 015237	86
3157	RRC546	KL-15	6699	TATA	ORD	MLB	28-Feb-2008	NBR	48	60	OOH62161147 1512 C	KSZ 148226	MSZ 021356	86
3158	RRC548	KL-15	6701	TATA	ORD	MLB	28-Feb-2008	NBR	48	60	697 TCIC	MSZ 154099	MSZ 020930	86
3159	RRC553	KL-15	6702	TATA	ORD	MLB	28-Feb-2008	NBR	48	60	697 TCIC	MSZ 158448	ARZ 000631	86
3160	RRC550	KL-15	6706	TATA	ORD	VND	29-Feb-2008	PNKM	48	60	697 TCIC	MSZ 155839	MSZ 021110	49
3161	RRC554	KL-15	6713	TATA	ORD	VND	1-Mar-2008	CTLA	48	60	697 TCIC	ARZ 105614	ARZ 000617	46
3162	RRC560	KL-15	6717	TATA	ORD	VND	1-Mar-2008	PNKM	48	60	697 TCIC	MSZ 158421	ARZ 000798	49
3163	RRC561	KL-15	6722	TATA	ORD	VND	6-Mar-2008	ADR	48	60	697 TCIC	ARZ 101014	ARZ 000857	38
3164	RRC565	KL-15	6727	TATA	ORD	VND	7-Mar-2008	PTA	48	60	697 TCIC	60C 62140473	ARZ 000633	37
3165	RRC494	KL-15	6647	TATA	ORD	MLB	14-Feb-2008	IJK	48	60	697 TCIC 1510 TC BS II	MSZ 154115	MSZ 020842	89
3166	RRC496	KL-15	6652	TATA	ORD	VND	16-Feb-2008	IJK	48	60	697 TCIC 1510 TC BS II	MSZ 153754	MSZ 020916	89

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3167	RRC643	KL-15	6798	TATA	ORD	VND	26-Mar-2008	ALV	48	60	697 TCIC	ARZ 105457	BRZ 002874	61
3168	RRC607	KL-15	6752	TATA	ORD	VND	13-Mar-2008	CTLA	48	60	697 TCIC	ARZ 101927	ARZ 001425	46
3169	RRC642	KL-15	6794	TATA	ORD	VND	25-Mar-2008	PDM	48	60	697 TCIC	ARZ 105060	BRZ 002976	39
3170	RRC639	KL-15	6778	TATA	ORD	VND	24-Mar-2008	KYLM	48	60	697 TCIC		BRZ 002851	41
3171	RRC581	KL-15	6741	TATA	ORD	VND	11-Mar-2008	ALV	48	60	697 TCIC	ARZ 101664	ARZ 000904	61
3172	RRC621	KL-15	6771	TATA	ORD	VND	18-Mar-2008	ALP	48	60	697 TCIC	BRZ 106304	BRZ 002841	45
3173	RRC616	KL-15	6774	TATA	ORD	VND	19-Mar-2008	CTNR	48	60	697 TCIC	ARZ 105635	BRZ 002963	97
3174	RRC662	KL-15	6816	TATA	ORD	VND	29-Mar-2008	KYLM	48	60	CUMMINS	BRZ 106310	BRZ 003092	41
3175	RRA590	KL-15	6781	TATA	ORD		24-Mar-2008	PBVR	48	60	697 TCIC	MSZ 158401	ARZ 000624	59
3176	RRM626	KL-15	6795	TATA	ORD	VND	25-Mar-2008	KTR	48	60	697 TCIC	MSZ 157732	ARZ 000795	35
3177	RRA483	KL-15	6742	TATA	ORD	VND	12-Mar-2008	VKBN	48	60	697 TCIC	LSZ 148712	LSZ 018608	29
3178	RRC612	KL-15	6767	TATA	ORD	VND	17-Mar-2008	NPR	48	60	697 TCIC	ARZ 105616	BRZ 002835	62
3179	RRC582	KL-15	6744	TATA	ORD	VND	12-Mar-2008	CTLA	48	60	697 TCIC 1510 BSII	MSZ 155934	ARZ 001422	46
3180	RRC609	KL-15	6753	TATA	ORD	VND	13-Mar-2008	ANK	48	60	697 TCIC	BRZ 112245	ARZ 002828	57
3181	RRC641	KL-15	6793	TATA	ORD		25-Mar-2008	PNR	48	60	697 TCIC	BRZ 106844	BRZ 002879	78
3182	RRC648	KL-15	6809	TATA	ORD	VND	28-Mar-2008	CTNR	48	60	697 TCIC	ARZ 105064	BRZ 002974	97
3183	RRC620	KL-15	6775	TATA	ORD	VND	19-Mar-2008	KNPY	48	60	697 TCIC	BRZ 106307	BRZ 002844	87
3184	RRA592	KL-15	6812	TATA	ORD		29-Mar-2008	ANK	48	60	697 TCIC	MSZ 158430	ARZ 000797	57
3185	RRA593	KL-15	6828	TATA	ORD	VND	1-Apr-2008	NPR	48	60	697 TCIC	ARZ 100504	ARZ 000853	62
3186	RRC665	KL-15	6822	TATA	ORD	VND	1-Apr-2008	NPR	48	60	697 TCIC	ARZ 105618	BRZ 002875	62
3187	RRM710	KL-15	6889	TATA	ORD	VND	18-Apr-2008	KPM	48	60	697 TCIC	RZ 108181	BRZ 003325	91
3188	RRA704	KL-15	6877	TATA	ORD	VND	16-Apr-2008	MPM	48	60	697 TCIC	ARZ 105450	BRZ 002840	71
3189	RRA595	KL-15	6842	TATA	ORD	VND	5-Apr-2008	KTR	48	60	697 TCIC	697TC555ARZ100999	436062 ARZ 000860	35
3190	RRA596	KL-15	6851	TATA	ORD	VND	9-Apr-2008	VZM	48	60	697 TCIC	MSZ 1540944	ARZ 000876	24
3191	RRC619	KL-15	6803	TATA	ORD	VND	27-Mar-2008	PVR	48	60	697 TCIC	BRZ 106842	BRZ 002848	23
3192	RRC645	KL-15	6806	TATA	ORD	VND	27-Mar-2008	KYLM	48	60	697 TCIC	ARZ 105432	BRZ 002966	41
3193	RRC661	KL-15	6815	TATA	ORD	VND	29-Mar-2008	CTLA	48	60	697 TCIC 1510 BSII	MSZ 154119	BRZ 002971	46
3194	RRC663	KL-15	6818	TATA	ORD	VND	31-Mar-2008	VKM	48	60	697 TCIC	62140702	BRZ 002872	51
3195	RRC664	KL-15	6817	TATA	ORD	VND	29-Mar-2008	CTNR	48	60	697 TCIC	LSZ 152743	BRZ 003089	97
3196	RRC666	KL-15	6819	TATA	ORD	VND	31-Mar-2008	ADR	48	60	697 TCIC	ARZ 105058	BRZ 002975	38
3197	RRC667	KL-15	6820	TATA	ORD	VND	31-Mar-2008	ALV	48	60	697 TCIC	BRZ 106544	BRZ 003091	61
3198	RRC690	KL-15	6839	TATA	ORD	VND	4-Apr-2008	CTNR	48	60	62350951	BRZ 106305	BRZ 003103	97
3199	RRC693	KL-15	6848	TATA	ORD	VND	8-Apr-2008	TPLM	48	60	697 TCIC	ARZ 105451	BRZ 002871	94
3200	RRC694	KL-15	6841	TATA	ORD	VND	5-Apr-2008	ALP	48	60	697 TCIC	BRZ 107823	BRZ 003322	45
3201	RRA702	KL-15	6855	TATA	ORD	VND	10-Apr-2008	KNPY	48	60	697 TCIC	ARZ 101011	ARZ 000855	87
3202	RRA703	KL-15	6856	TATA	ORD	VND	11-Apr-2008	NTA	48	60	697 TCIC 55	MSZ 157726	ARZ 000907	22
3203	RRM709	KL-15	6884	TATA	ORD	MLB	17-Apr-2008	CTLA	48	60	697 TCIC 1510 BSII	JSZ 142874	BRZ 003098	46
3204	RRC716	KL-15	6862	TATA	ORD		15-Apr-2008	ALP	48	60	697 TCIC	BRZ 106288	BRZ 003587	45
3205	RRC717	KL-15	6863	TATA	ORD	VND	15-Apr-2008	KTDA	48	60	697 TCIC BS II	CRZ 115026	BRZ 003473	25
3206	RRC719	KL-15	6865	TATA	ORD	VND	15-Apr-2008	CTNR	48	60	697 TCIC	FSZ 130940	BRZ 003584	97
3207	RRC730	KL-15	6890	TATA	ORD	VND	18-Apr-2008	VKM	48	60	697 TCIC	BRZ 106847	BRZ 003582	51
3208	RRC728	KL-15	6888	TATA	ORD	MLB	18-Apr-2008	PNR	48	60	697 TCIC	BRZ 108203	BRZ 003476	78
3209	RRC695	KL-15	6867	TATA	ORD	VND	15-Apr-2008	KYLM	48	60	697 TCIC TURBO INTER COOLER	BRZ 106302	BRZ 003093	41
3210	RRC698	KL-15	6868	TATA	ORD	VND	15-Apr-2008	CHRY	48	60	697 TCIC TURBO INTER COOLER	00062145005	BRZ 003104	44
3211	RRC699	KL-15	6869	TATA	ORD	VND	15-Apr-2008	KYLM	48	60	697 TCIC TURBO INTER COOLER	BRZ 106555	BRZ 003479	41

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3212	RRC700	KL-15	6859	TATA	ORD	VND	15-Apr-2008	VZM	48	60	697 TCIC	00062141071	BRZ 003581	24
3213	RRC715	KL-15	6861	TATA	ORD	VND	15-Apr-2008	NPR	48	60	697 TCIC	ARZ 105068	BRZ 003480	62
3214	RRC718	KL-15	6864	TATA	ORD	VND	15-Apr-2008	ALP	48	60	697 TCIC	GSZ 135376	BRZ 003590	45
3215	RRC720	KL-15	6874	TATA	ORD	VND	16-Apr-2008	TDP	48	60	697 TCIC	BRZ 106544	BRZ 002838	53
3216	RRC726	KL-15	6875	TATA	ORD	VND	16-Apr-2008	CTLA	48	60	697 TCIC 1510 BSII	ESZ 126812	BRZ 003475	46
3217	RRC742	KL-15	6900	TATA	ORD	MLB	22-Apr-2008	PNI	48	60	697 TCIC	697TC55 CRZ115277	CRZ 118660	67
3218	RRC738	KL-15	6895	TATA	ORD	MLB	21-Apr-2008	MPM	48	60	697 TCIC	BRZ 106313	BRZ 003102	71
3219	RRC747	KL-15	6904	TATA	ORD	VND	23-Apr-2008	ANK	48	60	697 TCIC	BRZ 112233	CRZ 005839	57
3220	RRC725	KL-15	6866	TATA	ORD	VND	15-Apr-2008	PVM	48	60	697 TCIC	BRZ 106838	BRZ 003106	83
3221	RRC741	KL-15	6903	TATA	ORD	VND	23-Apr-2008	CTLA	48	60	697 TCIC 1510 BSII	BRZ 111927	CRZ 005831	46
3222	RRC727	KL-15	6876	TATA	ORD		16-Apr-2008	KPM	48	60	697 TCIC	BRZ 110070	BRZ 003478	91
3223	RRC786	KL-15	6942	TATA	ORD	VND	7-May-2008	ADR	48	60	697 TCIC	CRZ 112913	CRZ 005846	38
3224	RRC782	KL-15	6938	TATA	ORD	VND	6-May-2008	KPM	48	60	697 TCIC	BRZ 111515	CRZ 006585	91
3225	RRC749	KL-15	6914	TATA	ORD	VND	26-Apr-2008	NTA	48	60	697 TCIC	BRZ 112204	CRZ 005845	22
3226	RRC746	KL-15	6922	TATA	ORD	VND	29-Apr-2008	PSL	48	60	1510 TCIC	BRZ 111925	BRZ 005833	21
3227	RRC740	KL-15	6920	TATA	ORD	VND	28-Apr-2008	PSL	48	60	1510 TCIC	BRZ 112232	CRZ 005827	21
3228	RRC739	KL-15	6910	TATA	ORD	VND	24-Apr-2008	PSL	48	60	1510 TCIC	BRZ 108705	CRZ 004672	21
3229	RRA732	KL-15	6917	TATA	ORD	VND	26-Apr-2008	PVR	48	60	697 TCIC	BRZ106312	436062 BRZ 003094	23
3230	RRC729	KL-15	6894	TATA	ORD	VND	21-Apr-2008	KYLM	48	60	697 TCIC	BRZ 106004	BRZ 003088	41
3231	RRA706	KL-15	6898	TATA	ORD	MLB	22-Apr-2008	TSY	48	60	697 TCIC	BRZ 106003	BRZ 002846	73
3232	RRC829	KL-15	6992	TATA	ORD	VND	24-May-2008	PBVR	48	60	697 1510 LP 59 BSII TURBO INTER COOLER	BRZ 107083	CRZ 006590	59
3233	RRC804	KL-15	6972	TATA	ORD		17-May-2008	KNPY	48	60	CUMMINS	BRZ 1122243	CRZ 005829	87
3234	RRC748	KL-15	6925	TATA	ORD	VND	30-Apr-2008	ALP	48	60	697 TCIC	BRZ 112225	CRZ 005838	45
3235	RRC784	KL-15	6948	TATA	ORD	VND	9-May-2008	VZM	48	60	697 TCIC	MSZ 153755	CRZ 006583	24
3236	RRA734	KL-15	6927	TATA	ORD	VND	3-May-2008	ANK	48	60	697 TCIC	BRZ 107835	BRZ 003323	57
3237	RRA735	KL-15	6935	TATA	ORD	VND	6-May-2008	ANK	48	60	697 TCIC	BRZ 018178	BRZ 003474	57
3238	RRC767	KL-15	6928	TATA	ORD	VND	3-May-2008	ANK	48	60	697 TCIC	BRZ 112230	CRZ 005849	57
3239	RRC745	KL-15	6923	TATA	ORD	VND	29-Apr-2008	ALV	48	60	697 TCIC	ARZ 105455	BRZ 003586	61
3240	RRC785	KL-15	6949	TATA	ORD	VND	9-May-2008	VKBN	48	60	697 TCIC	BRZ 112224	CRZ 005853	29
3241	RRC787	KL-15	6953	TATA	ORD		12-May-2008	KMR	48	60	697 TCIC	GSZ 194928	BRZ 003477	30
3242	RRC830	KL-15	6984	TATA	ORD	VND	22-May-2008	CTLA	48	60	697 TCIC BSII	CRZ 112918	CRZ 005840	46
3243	RRM823	KL-15	7013	TATA	ORD	VND	2-Jun-2008	PVR	48	60	697 TCIC	BRZ108199	436062 BRZ 003592	23
3244	RRC831	KL-15	6996	TATA	ORD	VND	27-May-2008	VKM	48	60	697 TCIC	62342672	CRZ 006427	51
3245	RRM826	KL-15	7038	TATA	ORD	VND	16-Jun-2008	PSL	48	60	1510 TCIC	BRZ 108708	CRZ 004670	21
3246	RRM827	KL-15	7040	TATA	ORD	VND	16-Jun-2008	PKD	48	60	697 TCIC	BRZ 112228	CRZ 005836	65
3247	RRC858	KL-15	7016	TATA	ORD	MLB	2-Jun-2008	MPM	48	60	697 TCIC	BRZ 112196	CRZ 005844	71
3248	RRM774	KL-15	6963	TATA	ORD	MLB	15-May-2008	ALP	48	60	697 TCIC	BRZ 108198	BRZ 003324	45
3249	RRC863	KL-15	7024	TATA	ORD	VND	7-Jun-2008	ADR	48	60	697 TCIC	CRZ 115276	CRZ 006598	38
3250	RRM825	KL-15	7015	TATA	ORD	VND	2-Jun-2008	KTDA	48	60	697 TCIC		LRZ 005852	25
3251	RRM822	KL-15	7012	TATA	ORD	VND	2-Jun-2008	CTLA	48	60	697 TCIC 1510 BSII	FSZ 130762	CRZ 006291	46
3252	RRC864	KL-15	7041	TATA	ORD	VND	16-Jun-2008	KDLR	48	60	697 TCIC	CRZ 118634	DRZ 007568	90
3253	RRA987	KL-15	7172	TATA	ORD	VND	5-Sep-2008	PNKM	48	60	697 TCIC	FSZ 130657	DRZ 007720	49
3254	RAC 52	KL-15	7235	TATA	ORD	VND	21-Nov-2008	KYLM	48	60	CUMMINS	DRZ 120898	DRZ 008343	41
3255	RAC 53	KL-15	7237	TATA	ORD	VND	22-Nov-2008	KYLM	48	60	CUMMINS	DRZ 106847	DRZ 003593	41
3256	RRA432	KL-15	6650	TATA	ORD	MLB	16-Feb-2008	KHD	48	60	697 TCIC	JSZ 143042	KSZ 016679	106

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3257	RRA 63	KL-15	6234	TATA	ORD		24-Aug-2007	SBY	48	60	697 TCIC	697 TC55 FSZ 126102	436062 FSZ 010091	75
3258	RRA 64	KL-15	6242	TATA	ORD		22-Aug-2007	ANK	48	60	697 TCIC	697 TC55 FSZ 126812	436062 FSZ 010374	57
3259	RRM 65	KL-15	6235	TATA	ORD		24-Aug-2007	MVK	48	60	697 TCIC	697 TC55 DSZ 124112	436062 FSZ 010372	88
3260	RRC 69	KL-15	6236	TATA	ORD		18-Aug-2007	ANK	48	60	697 TCIC	697 TC55 DSZ 124071	436062 FSZ 010373	57
3261	RRC 70	KL-15	6238	TATA	ORD		24-Aug-2007	KNPY	48	60	697 TCIC	697 TC55 FSZ 130654	436062 FSZ 010447	87
3262	RRC 72	KL-15	6240	TATA	ORD	VND	21-Aug-2007	CTNR	48	60	697 TCIC	BRZ 108664	FSZ 010449	97
3263	RRC 75	KL-15	6246	TATA	ORD		24-Aug-2007	PPD	48	60	697 TCIC TATA CUMMINS	40E 62333617	436062 FSZ 010450	26
3264	RRM 95	KL-15	6250	TATA	ORD	VND	14-Sep-2007	PNR	48	60	697 TCIC	697 TC55 FSZ 130658	436062 FSZ 010462	78
3265	RRA102	KL-15	6252	TATA	ORD	MLB	15-Sep-2007	CTLA	48	60	697 TCIC 1510 BSII	697 TC55 FSZ 130284	436062 FSZ 010456	46
3266	RRC 85	KL-15	6268	TATA	ORD		1-Oct-2007	PPD	48	60	697 TCIC BSII	697 TC55 MSZ 155933	436062 FSZ 010518	26
3267	RRC 90	KL-15	6277	TATA	ORD		4-Oct-2007	PPD	48	60	697 TCIC TATA TC	697 TC55 00C62140582	436062 FSZ 010530	26
3268	RRC 81	KL-15	6278	TATA	ORD		6-Oct-2007	KNPY	48	60	697 TCIC	697 TC55 FSZ 130665	436062 FSZ 010461	87
3269	RRA100	KL-15	6284	TATA	ORD	VND	11-Oct-2007	PPD	48	60	697 TCIC TATA BSII	697 ARZ102168	436062 FSZ 010454	26
3270	RRC115	KL-15	6290	TATA	ORD		15-Oct-2007	PPD	48	60	697 TCIC TATA BSII	697 TC55 FSZ131092	436062 HSZ 012703	26
3271	RRM118	KL-15	6298	TATA	ORD	VND	22-Oct-2007	KNPY	48	60	CUMMINS	697 TC55 FSZ 130662	436062 FSZ 010525	87
3272	RRA130	KL-15	6300	TATA	ORD	VND	23-Oct-2007	VZM	48	60	697 TCIC	KSZ147741	436062 FSZ 010517	24
3273	RRM134	KL-15	6307	TATA	ORD		27-Oct-2007	CDLM	48	60	697 TCIC	697 TC55 FSZ 131092	436062 FSZ 010533	80
3274	RRM119	KL-15	6301	TATA	ORD		24-Oct-2007	VZM	48	60	697 TCIC	KSZ 145249	436062 FSZ 010559	24
3275	RRA131	KL-15	6310	TATA	ORD	VND	29-Oct-2007	VZM	48	60	697 TCIC	62333717	436062 FSZ 010524	24
3276	RRA172	KL-15	6352	TATA	ORD	VND	20-Nov-2007	EKM	48	60	697 TCIC	697 TC55 FSZ 130937	436062 FSZ 010561	56
3277	RRM196	KL-15	6361	TATA	ORD	MLB	23-Nov-2007	CLDY	48	60	697 TCIC	697 TC55 JSZ 142592	436042 HSZ 013331	58
3278	RRC179	KL-15	6373	TATA	ORD	SWB	28-Nov-2007	CLDY	48	60	697 TCIC	697 TC55 JSZ 140049	436042 JSZ 129914	58
3279	RRC180	KL-15	6374	TATA	ORD	SWB	28-Nov-2007	IJK	48	60	697 TCIC 1510TC BSII	697 TC55 JSZ 140060	436042 JSZ 129942	89
3280	RRA132	KL-15	6323	TATA	ORD	VND	5-Nov-2007	CTLA	48	60	697 TCIC 1510 BSII	697 TC55 FSZ 131102	436062 FSZ 010528	46
3281	RRC237	KL-15	6381	TATA	ORD	SWB	29-Nov-2007	KNPY	48	60	697 TCIC	697 TC55 JSZ 140044	436042 JSZ 130014	87
3282	RRA241	KL-15	6386	TATA	ORD	VND	1-Dec-2007	PBVR	48	60	697 TCIC	697 TC55 GSZ 135648	436062 HSZ 013329	59
3283	RRC183	KL-15	6377	TATA	ORD	SWB	29-Nov-2007	EMLY	48	60	697 TCIC	ESZ 130830	436042 JSZ 130040	95
3284	RRC222	KL-15	6378	TATA	ORD	SWB	29-Nov-2007	CLDY	48	60	697 TCIC	697 TC55 DRZ 119499	436042 JSZ 130119	58
3285	RRC250	KL-15	6403	TATA	ORD	SWB	5-Dec-2007	KPA	48	60	697 TCIC	697 TC55 JSZ 139879	436042 JSZ 129943	74
3286	RRM198	KL-15	6383	TATA	ORD		30-Nov-2007	KPM	48	60	697 TCIC	HSZ 135628	HSZ 013352	91
3287	RRC181	KL-15	6375	TATA	ORD	SWB	28-Nov-2007	CDLM	48	60	697 TCIC	697 TC55 CRZ 115271	406042 JSZ 130043	80
3288	RRC182	KL-15	6376	TATA	ORD	SWB	28-Nov-2007	CGNR	48	60	697 TCIC	697 TC55 JSZ 140050	436042 JSZ 130039	40
3289	RRC248	KL-15	6387	TATA	ORD	VND	3-Dec-2007	PSL	48	60	1510 TCIC	697 TC55 GSZ 134941	436062 HSZ 013361	21
3290	RRM244	KL-15	6402	TATA	ORD	VND	5-Dec-2007	NTA	48	60	697 TCIC	HSZ 135965	HSZ 012715	22
3291	RRC264	KL-15	6422	TATA	ORD	MLB	10-Dec-2007	HPD	48	60	697 TCIC	CRZ 118643	436062 JSZ 014842	42
3292	RRA255	KL-15	6423	TATA	ORD	VND	10-Dec-2007	PMNA	48	60	697 TC55 HSZ 136550	697 TC55 GSZ 136550	436062 HSZ 013354	68
3293	RRM246	KL-15	6427	TATA	ORD	MLB	10-Dec-2007	PKD	48	60	697 TCIC	697 TC55 JSZ 139626	436042 JSZ 015221	65
3294	RRM247	KL-15	6435	TATA	ORD	VND	13-Dec-2007	EKM	48	60	697 TCIC	BRZ 112204	436062 JSZ 015224	56
3295	RRC305	KL-15	6459	TATA	ORD	SWB	22-Dec-2007	KNPY	48	60	697 TCIC	697 TC55 JSZ 139958	436042 JSZ 129916	87
3296	RRA256	KL-15	6437	TATA	ORD		14-Dec-2007	PKD	48	60	697 TCIC	697 TC55 GSZ 134916	436062 HSZ 012430	65
3297	RRC289	KL-15	6470	TATA	ORD	MLB	27-Dec-2007	KGD	48	60	697 TCIC	697 TC55 JSZ 140458	436062 JSZ 015334	84
3298	RRA258	KL-15	6461	TATA	ORD	VND	24-Dec-2007	PBVR	48	60	697 TCIC	697 TC55 ESZ 128306	436062 GSZ 010817	59
3299	RRC262	KL-15	6450	TATA	ORD		19-Dec-2007	CTNR	48	60	697 TCIC	CRZ 118752	HSZ 013359	97
3300	RRM284	KL-15	6449	TATA	ORD	VND	19-Dec-2007	CLDY	48	60	697 TCIC	697 TC55 JSZ 139751	436062 JSZ 015231	58
3301	RRC291	KL-15	6466	TATA	ORD		27-Dec-2007	KNPY	48	60	697 TCIC	697 TC55 JSZ 140975	436062 JSZ 015228	87

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3302	RRC260	KL-15	6456	TATA	ORD		22-Dec-2007	KNPY	48	60	697 TCIC	697 TC55 GSZ 135776	436062 HSZ 013452	87
3303	RRM285	KL-15	6454	TATA	ORD		22-Dec-2007	CTNR	48	60	697 TCIC	JSZ 139882	JSZ 015233	97
3304	RRA317	KL-15	6505	TATA	ORD	MLB	7-Jan-2008	VDA	48	60	697 TCIC	697 TC55 GSZ 135781	436062 HSZ 013356	92
3305	RRC300	KL-15	6491	TATA	ORD	MLB	1-Jan-2008	KGD	48	60	697 TCIC	697 TC55 JSZ 139710	436062 JSZ 015236	84
3306	RRC297	KL-15	6516	TATA	ORD	MLB	9-Jan-2008	KPM	48	60	697 TCIC	697 TC55 JSZ 139224	436062 JSZ 015226	91
3307	RRC294	KL-15	6483	TATA	ORD	MLB	31-Dec-2007	KHD	48	60	697 TCIC	697 TC55 JSZ 140463	436062 JSZ 015311	106
3308	RRC306	KL-15	6477	TATA	ORD	SWB	28-Dec-2007	MALA	48	60	697 TCIC	697 TC55 JSZ 139970	436042 JSZ 129917	85
3309	RRC308	KL-15	6482	TATA	ORD	SWB	29-Dec-2007	EMLY	48	60	697 TCIC	62355400	436042 JSZ 129940	95
3310	RRM313	KL-15	6510	TATA	ORD	VND	7-Jan-2008	MVK	48	60	697 TCIC	697 TC55 JSZ 140460	436062 JSZ 015331	88
3311	RRA314	KL-15	6494	TATA	ORD		1-Jan-2008	ALP	48	60	697 TCIC	697 TC55 FSZ 130744	436062 FSZ 010459	45
3312	RRC266	KL-15	6453	TATA	ORD	MLB	19-Dec-2007	KLM	48	60	697 TCIC	697 TC55 JSZ 140303	436062 JSZ 015327	34
3313	RRC265	KL-15	6452	TATA	ORD	VND	19-Dec-2007	CTLA	48	60	697 TCIC 1510 BSII	697 TC55 JSZ 140457	436062 JSZ 015317	46
3314	RRC263	KL-15	6451	TATA	ORD	VND	19-Dec-2007	ALP	48	60	697 TCIC	697 TC55 GSZ 135786	436062 HSZ 013388	45
3315	RRM310	KL-15	6488	TATA	ORD	MLB	31-Dec-2007	CTLA	48	60	697 TCIC	697 TC55 JSZ 139611	436062 JSZ 015220	46
3316	RRM312	KL-15	6478	TATA	ORD	VND	28-Dec-2007	CTLA	48	60	697 TCIC	697 TC55 JSZ 139801	436062 JSZ 015335	46
3317	RRM383	KL-15	6542	TATA	ORD	VND	16-Jan-2008	ALP	48	60	697 TCIC	JSZ 739712	JSZ 015235	45
3318	RRM384	KL-15	6572	TATA	ORD	MLB	24-Jan-2008	NBR	48	60	00G621 54682 1512 C	JSZ 142587	KSZ 016684	86
3319	RRM385	KL-15	6584	TATA	ORD	MLB	28-Jan-2008	NBR	48	60	1512 CUMMINS 00J6216523	00J62165238	KSZ 016689	86
3320	RRC380	KL-15	6549	TATA	ORD	VND	18-Jan-2008	ALP	48	60	697 TCIC	KSZ 145249	LSZ 017978	45
3321	RRC513	KL-15	6661	TATA	ORD	VND	18-Feb-2008	ALP	48	60	697 TCIC	697TC55KSZ148204	436062MSZ020915	45
3322	RRM491	KL-15	6677	TATA	ORD	VND	23-Feb-2008	KNPY	48	60	697 TCIC	MSZ 154121	MSZ 020925	87
3323	RRM489	KL-15	6675	TATA	ORD	VND	23-Feb-2008	KYLM	48	60	CUMMINS	LSZ 148116	LSZ 018391	41
3324	RRM488	KL-15	6646	TATA	ORD		14-Feb-2008	PKD	48	60	1510 TCIC	697 TC 55	436062LSZ	65
3325	RRM535	KL-15	6685	TATA	ORD	VND	25-Feb-2008	KNPY	48	60	CUMMINS	MSZ 153956	MSZ 020923	87
3326	RRM536	KL-15	6689	TATA	ORD	VND	27-Feb-2008	NTA	48	60	697 TCIC	KSZ 145628	MSZ 020924	22
3327	RRM538	KL-15	6712	TATA	ORD	VND	1-Mar-2008	CTLA	48	60	1512 CUMMINS	40H62350952	MSZ 021114	46
3328	RRC447	KL-15	6628	TATA	ORD	VND	11-Feb-2008	ALP	48	60	697 TCIC	KSZ 145445	LSZ 018111	45
3329	RRM542	KL-15	6762	TATA	ORD	VND	17-Mar-2008	ALP	48	60	697 TCIC	MSZ 158387	ARZ 000623	45
3330	RRM625	KL-15	6783	TATA	ORD	MLB	24-Mar-2008	MPM	48	60	697 TCIC	MSZ 158447	ARZ 000630	71
3331	RRM540	KL-15	6754	TATA	ORD	VND	14-Mar-2008	KYLM	48	60	697 TCIC	MSZ 155942	ARZ 000619	41
3332	RRM623	KL-15	6773	TATA	ORD	VND	19-Mar-2008	ALP	48	60	697 TCIC	MSZ 158443	ARZ 000628	45
3333	RRM539	KL-15	6730	TATA	ORD	VND	10-Mar-2008	VKBN	48	60	697 TCIC	MSZ 155838	ARZ 000618	29
3334	RRM624	KL-15	6782	TATA	ORD	VND	24-Mar-2008	MALA	48	60	697 TCIC	ARZ 103739	ARZ 000629	85
3335	RRM627	KL-15	6802	TATA	ORD	VND	27-Mar-2008	KNPY	48	60	697 TCIC	MSZ 158431	ARZ 000672	87
3336	RRM670	KL-15	6821	TATA	ORD	VND	31-Mar-2008	KNPY	48	60	CUMMINS	BRZ 100309	BRZ 002849	87
3337	RRM671	KL-15	6827	TATA	ORD	VND	1-Apr-2008	TSY	48	60	697 TCIC	BRZ 106303	BRZ 002845	73
3338	RRM672	KL-15	6881	TATA	ORD	VND	17-Apr-2008	KYLM	48	60	CUMMINS	ARZ 105614	BRZ 002973	41
3339	RRM673	KL-15	6882	TATA	ORD		17-Apr-2008	KMR	48	60	697 TCIC	KSZ 148228	BRZ 002969	30
3340	RRC676	KL-15	6832	TATA	ORD	VND	1-Apr-2008	CTNR	48	60	697 TCIC	BRZ 106308	BRZ 003097	97
3341	RRC679	KL-15	6834	TATA	ORD	VND	1-Apr-2008	CTLA	48	60	697 TCIC	BRZ 108198	BRZ 003326	46
3342	RRM628	KL-15	6813	TATA	ORD	VND	29-Mar-2008	KNPY	48	60	CUMMINS	MSZ 158416	ARZ 000627	87
3343	RRM712	KL-15	6901	TATA	ORD	VND	22-Apr-2008	CTLA	48	60	697 1512CUMMINS	E62146082	BRZ 003105	46
3344	RRM755	KL-15	6921	TATA	ORD	VND	29-Apr-2008	NTA	48	60	697 TCIC	BRZ 111515	BRZ 002833	22
3345	RRM773	KL-15	6962	TATA	ORD	VND	15-May-2008	ALP	48	60	697 TCIC	BRZ 107837	BRZ 003321	45
3346	RRM775	KL-15	6964	TATA	ORD	VND	15-May-2008	TDP	48	60	697 TCIC	BRZ 112195	CRZ 005854	53

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3347	RRM778	KL-15	6982	TATA	ORD	VND	21-May-2008	VKBN	48	60	697 TCIC	BRZ 144922	PRZ 005843	29
3348	RRM711	KL-15	6893	TATA	ORD	VND	21-Apr-2008	PKD	48	60	697 TCIC	BRZ 106555	BRZ 003107	65
3349	RRM756	KL-15	6930	TATA	ORD	VND	3-May-2008	VKBN	48	60	697 TCIC	BRZ 108706	BRZ 003588	29
3350	RRM865	KL-15	7054	TATA	ORD		21-Jun-2008	ALV	48	60	697 TCIC	BRZ 112226	CRZ 005834	61
3351	RRM866	KL-15	7055	TATA	ORD	MLB	21-Jun-2008	VDA	48	60	697 TCIC	DRZ 119379	DRZ 007846	92
3352	RRM867	KL-15	7062	TATA	ORD	VND	24-Jun-2008	PTA	48	60	697 TCIC	DRZ 119186	DRZ 007721	37
3353	RRM868	KL-15	7063	TATA	ORD	VND	24-Jun-2008	EDT	48	60	697 TCIC	CRZ 118658	DRZ 007719	98
3354	RRM869	KL-15	7064	TATA	ORD	VND	26-Jun-2008	KYLM	48	60	697 TCIC	C62140681	DRZ 007695	41
3355	RRM870	KL-15	7066	TATA	ORD	VND	1-Jul-2008	KTDA	48	60	697 TCIC	CRZ 115271	436062DR2007722	25
3356	RRM910	KL-15	7068	TATA	ORD	MLB	1-Jul-2008	IJK	48	60	697 TCIC	LRZ 115034	DRZ 007960	89
3357	RRM911	KL-15	7075	TATA	ORD	MLB	2-Jul-2008	IJK	48	60	697 TCIC 1510 TC BS II	FSZ 130651	DRZ 007963	89
3358	RRM914	KL-15	7089	TATA	ORD	VND	19-Jul-2008	KPM	48	60	697 TCIC	CRZ 115277	DRZ 007961	91
3359	RRM912	KL-15	7085	TATA	ORD	MLB	14-Jul-2008	PVM	48	60	697 TCIC	697TC55HSZ175965	DRZ 007724	83
3360	RRM915	KL-15	7096	TATA	ORD		25-Jul-2008	VKBN	48	60	697 TCIC	DRZ 119383	DRZ 007723	29
3361	RRM916	KL-15	7100	TATA	ORD	MLB	28-Jul-2008	MALA	48	60	697 TCIC	DRZ 120196	DRZ 008106	85
3362	RRM930	KL-15	7102	TATA	ORD	MLB	31-Jul-2008	MKD	48	60	697 TCIC 1510 II	CRZ 118644	DRZ 008044	08
3363	RRM931	KL-15	7104	TATA	ORD	VND	2-Aug-2008	TVL	48	60	697 TCIC	MSZ 154116	DRZ 008340	43
3364	RRM779	KL-15	7010	TATA	ORD	VND	2-Jun-2008	ALP	48	60	697 TCIC	CRZ 115028	CRZ 006294	45
3365	RRM932	KL-15	7131	TATA	ORD	VND	13-Aug-2008	TVL	48	60	697 TCIC	DRZ 112231	CRZ 005837	43
3366	RRM933	KL-15	7153	TATA	ORD	VND	27-Aug-2008	EDT	48	60	697 TCIC 1510 BS II	62141019	DRZ 007725 436062	98
3367	RRM935	KL-15	7168	TATA	ORD	VND	3-Sep-2008	PNKM	48	60	697 TCIC	DRZ 120912	DRZ 008338	49
3368	RAC 13	KL-15	7164	TATA	ORD	VND	2-Sep-2008	PNKM	48	60	697 TCIC	MSZ 155954 50C623937	MSZ 021118	49
3369	RAC 12	KL-15	7171	LL	ORD	SWB	3-Sep-2008	MLTM	48	60	697 TCIC	68H 548623	FNE 657032	54
3370	RAM 31	KL-15	7199	TATA	ORD	MLB	4-Oct-2008	KGD	48	60	697 TCIC	DRZ 119183	DRZ 007964	84
3371	RRM936	KL-15	7196	TATA	ORD	MLB	3-Oct-2008	MALA	48	60	697 TCIC	DRZ 120467	DRZ 008105	85
3372	RAM 32	KL-15	7213	TATA	ORD		18-Oct-2008	KHD	48	60	697 TCIC	CRZ 118738	DRZ 007966	106
3373	RAM 33	KL-15	7227	TATA	ORD	VND	14-Nov-2008	KYLM	48	60	CUMMINS	DRZ 119502	DRZ 007849	41
3374	RAM 34	KL-15	7228	TATA	ORD	VND	14-Nov-2008	KYLM	48	60	CUMMINS	CRZ 118739	DRZ 007899	41
3375	RRC259	KL-15	6433	TATA	ORD		12-Dec-2007	MALA	48	60	697 TCIC	697 TC55 GSZ 135482	436062 HSZ 013358	85
3376	RRA101	KL-15	6258	TATA	ORD	MLB	27-Sep-2007	PNR	48	60	697 TCIC	697 TC55 FSZ 130860	436062 FSZ 010453	78
3377	RRA106	KL-15	6287	TATA	ORD	MLB	15-Oct-2007	KHD	48	60	697 TCIC	697 TC55 FSZ 130651	436062 FSZ 010445	106
3378	RRC288	KL-15	6476	TATA	ORD	MLB	28-Dec-2007	KHD	48	60	697 TCIC	697 TC55 JSZ 140647	436062 JSZ 015238	106
3379	RRC296	KL-15	6484	TATA	ORD	MLB	31-Dec-2007	PNR	48	60	697 TCIC	697 TC55 JSZ 139614	436062 JSZ 014692	78
3380	RRC302	KL-15	6502	TATA	ORD	MLB	4-Jan-2008	PNR	48	60	697 TCIC	697 TC55 JSZ 140382	436062 JSZ 015332	78
3381	RRC299	KL-15	6490	TATA	ORD	MLB	1-Jan-2008	PNR	48	60	697 TCIC	697 TC55 JSZ 139559	436062 JSZ 014841	78
3382	RRC292	KL-15	6480	TATA	ORD	MLB	29-Dec-2007	PNR	48	60	697 TCIC	697 TC55 JSZ 139722	436062 JSZ 015232	78
3383	RRA318	KL-15	6519	TATA	ORD	MLB	10-Jan-2008	PNR	48	60	697 TCIC	697 TC55 GSZ 135645	436062 HSZ 013360	78
3384	RRC239	KL-15	6392	TATA	ORD	SWB	3-Dec-2007	PLR	48	60	697 TCIC	697 TC55 JSZ 140045	436042 JSZ 130013	36
3385	RRC303	KL-15	6460	TATA	ORD	SWB	22-Dec-2007	PLR	48	60	697 TCIC	697 TC55 JSZ 140218	436042 JSZ 130042	36
3386	RRM120	KL-15	6286	TATA	ORD		15-Oct-2007	VJMD	48	60	697 TCIC	697 TC55 FSZ 131099	436062 FSZ 010554	16
3387	RRC223	KL-15	6379	TATA	ORD	SWB	29-Nov-2007	CTY	48	60	697 TCIC	697 TC55 JSZ 139554	436042 JSZ 129944	28
3388	RRC238	KL-15	6389	TATA	ORD	SWB	3-Dec-2007	CTY	48	60	697 TCIC	697 TC55 JSZ 139752	436042 JSZ 129915	28
3389	RRC221	KL-15	6431	TATA	ORD	SWB	10-Dec-2007	CTY	48	60	697 TCIC	697 TC55 JSZ 140058	436042 JSZ 130041	28
3390	RRC304	KL-15	6464	TATA	ORD	SWB	27-Dec-2007	CTY	48	60	697 TCIC	62381744	436042 JSZ 129941	28
3391	RRC307	KL-15	6462	TATA	ORD	SWB	27-Dec-2007	IJK	48	60	697 TCIC 1510 TC BS II	40H62350052 TC	436042 JSZ 129918	89

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3392	RRM311	KL-15	6499	TATA	ORD	VND	4-Jan-2008	KKLM	48	60	697 TCIC	697 TC55 JSZ 140300	436062 JSZ 015330	108
3393	RRC675	KL-15	6831	TATA	ORD	VND	1-Apr-2008	NDD	48	60	697 TCIC	00E62150111 TC	BRZ 003100	31
3394	RRM714	KL-15	6908	TATA	ORD	MLB	24-Apr-2008	TLY	48	60	697 TCIC	MSZ 158429	ARZ 000626	18
3395	RRC 76	KL-15	6247	TATA	ORD	VND	24-Aug-2007	ADR	48	60	697 TCIC	697 TC55 FSZ 130763	436062 FSZ 010465	38
3396	RAC 6	KL-15	7166	LL	ORD	SWB	3-Sep-2008	TDY	48	60	697 TCIC	FNH 545554	FNE 656748	79
3397	RRC567	KL-15	6737	TATA	ORD	VND	10-Mar-2008	MALA	48	60	697 TCIC	ARZ 101013	ARZ 000905	85
3398	RRC692	KL-15	6847	TATA	ORD	VND	8-Apr-2008	KLM	48	60	697 TCIC	BRZ 106845	BRZ 003096	34
3399	RRC697	KL-15	6850	TATA	ORD	VND	8-Apr-2008	NPR	48	60	697 TCIC	BRZ 107822	BRZ 003350	62
3400	RRA351	KL-15	6567	TATA	ORD	VND	23-Jan-2008	NDD	48	60	697 TCIC	GSZ 135698	HSZ 013332	31
3401	RRC473	KL-15	6640	TATA	ORD	MLB	12-Feb-2008	EKM	48	60	697 TCIC	KSZ 148224	MSZ 020841	56
3402	RRA345	KL-15	6526	TATA	ORD	MLB	14-Jan-2008	TLY	48	60	697 TCIC	GSZ 132737	GSZ 011408	18
3403	RRC353	KL-15	6530	TATA	ORD	MLB	14-Jan-2008	TLY	48	60	697 TCIC	00C62141098	JSZ 015315	18
3404	RRC355	KL-15	6523	TATA	ORD	MLB	11-Jan-2008	TLY	48	60	697 TCIC	JSZ 138855	JSZ 015325	18
3405	RRC737	KL-15	6905	TATA	ORD	MLB	23-Apr-2008	TLY	48	60	697 TCIC	BRZ 108180	BRZ 003472	18
3406	RRC338	KL-15	6507	TATA	ORD	MLB	7-Jan-2008	PNR	48	60	697 TCIC	JSZ 139278	JSZ 014840	78
3407	RRM364	KL-15	6535	TATA	ORD	VND	14-Jan-2008	VZM	48	60	697 TCIC	40G62342485	KSZ 016243	24
3408	RRC549	KL-15	6708	TATA	ORD	MLB	29-Feb-2008	ALP	48	60	697 TCIC	LSZ 148911	MSZ 020914	45
3409	RRC555	KL-15	6714	TATA	ORD	VND	1-Mar-2008	PLR	48	60	697 TCIC	MSZ 154096	MSZ 020846	36
3410	RRC563	KL-15	6718	TATA	ORD	VND	1-Mar-2008	ALP	48	60	697 TCIC	ARZ 100508	ARZ 000858	45
3411	RRC586	KL-15	6747	TATA	ORD	VND	12-Mar-2008	PLR	48	60	697 TCIC	ARZ 101662	ARZ 000900	36
3412	RRC646	KL-15	6799	TATA	ORD	MLB	26-Mar-2008	CTY	48	60	697 TCIC	ARZ 105444	BRZ 002972	28
3413	RRA733	KL-15	6924	TATA	ORD	MLB	30-Apr-2008	NPR	48	60	697 TCIC	BRZ 106306	BRZ 003095	62
3414	RRC618	KL-15	6792	TATA	ORD	VND	25-Mar-2008	CDLM	48	60	697 TCIC	ARZ 105446	BRZ 002876	80
3415	RRC638	KL-15	6797	TATA	ORD	VND	26-Mar-2008	KKLM	48	60	697 TCIC	ARZ 105636	BRZ 002873	108
3416	RRC668	KL-15	6829	TATA	ORD	VND	1-Apr-2008	VZM	48	60	697 TCIC	GSZ 134927	BRZ 002850	24
3417	RRC691	KL-15	6838	TATA	ORD		3-Apr-2008	NPR	48	60	697 TCIC	ARZ 105068	BRZ 002834	62
3418	RRC696	KL-15	6849	TATA	ORD	VND	8-Apr-2008	KKLM	48	60	697 TCIC	BRZ 106311	BRZ 002869	108
3419	RRA811	KL-15	6998	TATA	ORD	VND	27-May-2008	MALA	48	60	697 TCIC	CRZ 115033	CRZ 006293	85
3420	RRA812	KL-15	7018	TATA	ORD		2-Jun-2008	ATL	48	60	697 TCIC	CRZ 115029	CRZ 006296	33
3421	RRC423	KL-15	6577	TATA	ORD		25-Jan-2008	CTNR	48	60	697 TCIC	KSZ 147736	LSZ 018319	97
3422	RRC462	KL-15	6616	TATA	ORD	VND	6-Feb-2008	PVR	48	60	697 TCIC	JSZ143060	436062 KSZ 016650	23
3423	RRC635	KL-15	6777	TATA	ORD	VND	24-Mar-2008	CTY	48	60	697 TCIC	FSZ 130862	BRZ 002964	28
3424	RRC649	KL-15	6810	TATA	ORD	VND	28-Mar-2008	PVR	48	60	697 TCIC	BRZ106001	436062 BRZ 002837	23
3425	RRC783	KL-15	6955	TATA	ORD	VND	12-May-2008	PVR	48	60	697 TCIC	BRZ111532	436062 CRZ 006581	23
3426	RRA731	KL-15	6909	TATA	ORD	VND	24-Apr-2008	PVR	48	60	697 TCIC	BRZ106315	436062 BRZ 002843	23
3427	RRM245	KL-15	6418	TATA	ORD		7-Dec-2007	PVR	48	60	697 TCIC	697TC55 HSZ 135652	436062 BRZ 003094	23
3428	RRC293	KL-15	6469	TATA	ORD	VND	27-Dec-2007	PVR	48	60	697 TCIC	697TC55 JSZ 139554	436062 CRZ 005847	23
3429	RRM309	KL-15	6465	TATA	ORD		27-Dec-2007	PVR	48	60	697 TCIC	697TC55 JSZ 140957	436062 JSZ 015223	23
3430	RRM713	KL-15	6916	TATA	ORD	VND	26-Apr-2008	PVR	48	60	697 TCIC	BRZ107082	436062 BRZ 003101	23
3431	RRM913	KL-15	7086	TATA	ORD	VND	14-Jul-2008	HPD	48	60	697 TCIC	DRZ 119186	DRZ 007726	42
3432	RRC373	KL-15	6527	TATA	ORD	MLB	14-Jan-2008	KNR	48	60	697 TCIC	KSZ 145298	LSZ 017976	77
3433	RRM934	KL-15	7160	TATA	ORD	VND	30-Aug-2008	HPD	48	60	697 TCIC	30J 62290370	DRZ 008108	42
3434	RRC820	KL-15	6987	TATA	ORD	VND	22-May-2008	CTNR	48	60	697 TCIC	BRZ 111531	CRZ 006589	97
3435	RRC815	KL-15	6966	TATA	ORD	VND	16-May-2008	VZM	48	60	697 TCIC	62140985	CRZ 006298	24
3436	RRC818	KL-15	6978	TATA	ORD	VND	20-May-2008	KTDA	48	60	697 TCIC	KSZ 148104	436062CR2006593	25

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3437	RRA813	KL-15	7053	TATA	ORD	VND	20-Jun-2008	NPR	48	60	697 TCIC	CRZ 115040	CRZ 006299	62
3438	RRC848	KL-15	7019	TATA	ORD		3-Jun-2008	VLRD	48	60	697 TCIC 1510 BSII	CRZ 115027	CRZ 006595	93
3439	RRC816	KL-15	6983	TATA	ORD		22-May-2008	KNPY	48	60	697 TCIC	BRZ 111524	CRZ 006587	87
3440	RAC 14	KL-15	7183	TATA	ORD	MLB	19-Sep-2008	KPA	48	60	697 TCIC	DRZ 120197	DRZ 008342	74
3441	RAC 15	KL-15	7189	TATA	ORD	VND	24-Sep-2008	VZM	48	60	697 TCIC	62140609	CRZ 005830	24
3442	RAC 16	KL-15	7197	TATA	ORD	MLB	3-Oct-2008	KHD	48	60	697 TCIC	CRZ 118632	DRZ 007567	106
3443	RRC614	KL-15	6769	TATA	ORD	MLB	18-Mar-2008	NBR	48	60	697 TCIC	JSZ 139614	BRZ 002832	86
3444	RRC828	KL-15	6988	TATA	ORD	MLB	23-May-2008	NBR	48	60	1512 CUMMINS	00M62171369	CRZ 006597	86
3445	RRA810	KL-15	6991	TATA	ORD	VND	24-May-2008	TVL	48	60	697 TCIC	40H 62349098	CRZ 006292	43
3446	RRC377	KL-15	6544	TATA	ORD	VND	16-Jan-2008	KPM	48	60	697 TCIC	KSZ 147741	LSZ 018224	91
3447	RRC772	KL-15	6943	TATA	ORD	VND	8-May-2008	CTLA	48	60	697 TCIC 1510 BSII	BRZ 111520	CRZ 005851	46
3448	RRC771	KL-15	6937	TATA	ORD	VND	6-May-2008	CTLA	48	60	1512 CUMMINS	CRZ 115024	CRZ 006582	46
3449	RRC770	KL-15	6936	TATA	ORD	VND	6-May-2008	NTA	48	60	697 TCIC	CRZ 115275	CRZ 006297	22
3450	RRC768	KL-15	6931	TATA	ORD	VND	3-May-2008	VLRD	48	60	697 TCIC 1510 BS II	BRZ 112241	CRZ 005850	93
3451	RRC769	KL-15	6929	TATA	ORD	VND	3-May-2008	CTLA	48	60	697 TCIC 1510 BSII	BRZ 111528	CRZ 006584	46
3452	RRC226	KL-15	6369	TATA	ORD		26-Nov-2007	MALA	48	60	697 TCIC	697 TC55 GSZ 135376	436042 HSZ 012704	85
3453	RT 786	KL-15	5964	TATA	ORD		23-Jun-2005	PPD	48	60	LP 1512 TC	62158058	412071 AUZ 104102	26
3454	RNM374	KL-15	8586	TATA	ORD	VND	26-Aug-2010	CGNR	48	60	LP 1512 TC/59 BSII	01C62862823	MAT412088A0D08745	40
3455	RNM399	KL-15	8647	TATA	ORD		17-Sep-2010	KPM	48	60	LP 1512 TC/59 BSII TURBO INTER COOLER	01G62907374	MAT412088A0G13682	91
3456	RNM400	KL-15	8648	TATA	ORD		17-Sep-2010	KPM	48	60	LP 1512 TC/59 BSII TURBO INTER COOLER	01G62907370	MAT412088A0G13678	91
3457	RNM701	KL-15	9070	TATA	ORD		14-Mar-2011	MPM	48	60	LP 1512 TC/59 BSIII	01H62920514	MAT412088A0J15474	71
3458	RAM220	KL-15	7448	TATA	ORD	VND	16-Feb-2009	VKM	48	60	LP 1512 TC 59 BSII	80K62718419	LRZ 019236	51
3459	RNC547	KL-15	8832	TATA	ORD	TK	19-Nov-2010	ANK	48	60	LP 1512 TC/59 BSII	01H62922659	MAT412088A0J15616	57
3460	RNM518	KL-15	8837	TATA	ORD		22-Nov-2010	ARND	48	60	LP 1512 TC/59 BSII	90G62768367	MAT412088A0G13686	19
3461	RAA256	KL-15	7441	TATA	ORD	VND	12-Feb-2009	VKM	48	60	LP 1512 TC BSII	80K62715318	LRZ 019230	51
3462	RAA257	KL-15	7442	TATA	ORD	VND	12-Feb-2009	VKM	48	60	LP 1512 TC BSII	80K62716440	LRZ 019231	51
3463	RNM 4	KL-15	8198	TATA	ORD	VND	2-Feb-2010	CDLM	48	60	LP 1512 TC/59 BSII	90F62764250	41208190G90G11186	80
3464	RNM138	KL-15	8365	TATA	ORD		4-Jun-2010	ANK	48	60	LP 1512 TC/59 BSII	01C62856957	MAT412088A0B07398	57
3465	RNM515	KL-15	8828	TATA	ORD		19-Nov-2010	PLR	48	60	LP 1512 TC/59 BSIII	01G62906917	MAT412088A0G13584	36
3466	RAA258	KL-15	7458	TATA	ORD	MLB	18-Feb-2009	KNR	48	60	LP 1512 TC BSII CUMMINS	80K62716439	LRZ 019232	77
3467	RNC663	KL-15	8918	TATA	ORD	SWB	15-Dec-2010	KKD	48	60	LP 1512 TC/59 BSIII	01H62918621	MAT412266A0J15794	72
3468	RNC664	KL-15	8925	TATA	ORD	SWB	18-Dec-2010	ALV	48	60	LP 1512 TC/59 BSII	01J62925311	MAT412266A0J15791	61
3469	RNC666	KL-15	8932	TATA	ORD	SWB	22-Dec-2010	ALV	48	60	LP 1512 TC/59 BSII	01J62929469	MAT412266A0J16459	61
3470	RNC668	KL-15	8950	TATA	ORD	SWB	3-Jan-2011	PPD	48	60	LP 1512 TC/48 BSII	01H62918632	MAT412266A0J15793	26
3471	RNC741	KL-15	9035	TATA	ORD	SWB	14-Feb-2011	PNI	48	60	LP 1512 TC/59 BSII	00C 62140608	MAT461302A0J15789	67
3472	RNC740	KL-15	9048	TATA	ORD	SWB	24-Feb-2011	ALV	48	60	LP 1512 TC/59 BSII	01J62929346	MAT461302A0J16467	61
3473	RNC752	KL-15	9085	TATA	ORD	SWB	19-Mar-2011	PNKM	48	60	LP 1512 TC/59 BSIII	01J62929466	MAT412266A0J16468	49
3474	RNC717	KL-15	8969	TATA	ORD	SWB	13-Jan-2011	TLY	48	60	LP 1512 TC/59 BSII	01J62930267	MAT412266A0J16474	18
3475	RNC712	KL-15	8970	TATA	ORD	SWB	14-Jan-2011	TLY	48	60	LP 1512 TC/59 BSII	01J62930281	MAT412266A0J16483	18
3476	RNC715	KL-15	8998	TATA	ORD	SWB	28-Jan-2011	TLY	48	60	LP 1512 TC/59 BSII	01J62929477	MAT412266A0J16465	18
3477	RNC734	KL-15	9004	TATA	ORD	SWB	1-Feb-2011	KNR	48	60	LP 1512 TC/59 BSII	01J62929345	MAT461302A0J16466	77
3478	RNC736	KL-15	9017	TATA	ORD	SWB	8-Feb-2011	MKD	48	60	LP 1512 TC/59 BSII	01J62929353	MAT412266A0J16470	08
3479	RAA302	KL-15	7488	TATA	ORD	MLB	26-Feb-2009	MALA	48	60	LP 1512 TC/59 BSII	80K62718423	LRZ 019243	85
3480	RAA303	KL-15	7489	TATA	ORD	MLB	26-Feb-2009	MALA	48	60	LP 1512 TC/59 BSII	80K62717748	LRZ 019304	85
3481	RAA425	KL-15	7573	TATA	ORD	VND	26-Mar-2009	GVR	48	60	LP 1512 TC/59 BSII	80M 62725111	412081 MRZ020007	66

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3482	RAA426	KL-15	7581	TATA	ORD	VND	28-Mar-2009	GVR	48	60	LP 1512 TC/59 BSII	80M 62725110	412081 MRZ020066	66
3483	RAM939	KL-15	8137	TATA	ORD		21-Dec-2009	MALA	48	60	LP 1512 TC/59 BSII	90F62759528	MAT41208190F09048	85
3484	RAA960	KL-15	8142	TATA	ORD		24-Dec-2009	VKM	48	60	LP 1512 TC/59 BSII	LLP 146001	MAT41208190G11185	51
3485	RAM971	KL-15	8175	TATA	ORD		13-Jan-2010	NPR	48	60	LP 1512 TC/59 BSII	90F62759922	MAT41208190F09056	62
3486	RNC216	KL-15	8386	TATA	ORD		14-Jun-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62863136	MB1PBEHEA0D08625	61
3487	RNC240	KL-15	8427	TATA	ORD		2-Jul-2010	ANK	48	60	LP 1512 TC/59 BSII	01C62853687	MAT412088A0C06910	57
3488	RNA299	KL-15	8464	TATA	ORD	TK	8-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62862918	MAT412088A0D08702	61
3489	RNC288	KL-15	8465	TATA	ORD	TK	8-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62854423	MAT412088A0C06164	61
3490	RNC291	KL-15	8466	TATA	ORD	TK	8-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62856390	MAT412088A0C06911	61
3491	RNC292	KL-15	8467	TATA	ORD	TK	8-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01B62841417	MAT412088A0B03692	61
3492	RNM280	KL-15	8469	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62862817	MAT412088A0D08547	61
3493	RNM281	KL-15	8470	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62862944	MAT412088A0D08549	61
3494	RNC293	KL-15	8471	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62856920	MAT412088A0C07192	61
3495	RNC294	KL-15	8472	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62856905	MAT412088A0C07127	61
3496	RNC295	KL-15	8473	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62855144	MAT412088A0C07133	61
3497	RNC296	KL-15	8474	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62856925	MAT412088A0C07201	61
3498	RNC297	KL-15	8475	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62856907	MAT412088A0C07316	61
3499	RNC298	KL-15	8476	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62855529	MAT412088A0C07401	61
3500	RNA300	KL-15	8477	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62855948	MAT412088A0C06570	61
3501	RNA301	KL-15	8478	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62855951	MAT412088A0C06571	61
3502	RNA302	KL-15	8479	TATA	ORD	TK	12-Jul-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62855954	MAT412088A0C06575	61
3503	RNA336	KL-15	8553	TATA	ORD	MLB	10-Aug-2010	PNI	48	60	LP 1512 TC/59 BSII	01B62847433	MAT412088A0C06907	67
3504	RNA337	KL-15	8554	TATA	ORD	VND	10-Aug-2010	PNI	48	60	LP 1512 TC/59 BSII	01C62856961	MAT412088A0C07315	67
3505	RNM477	KL-15	8758	TATA	ORD		1-Nov-2010	ALV	48	60	LP 1512 TC/59 BSII	01C62906906	MAT412088A0G13685	61
3506	RNC575	KL-15	8825	TATA	ORD	TK	18-Nov-2010	ALV	48	60	LP 1512 TC/59 BSII	01H62921025	MAT412088A0J15619	61
3507	RNC541	KL-15	8830	TATA	ORD	TK	19-Nov-2010	ALV	48	60	LP 1512 TC/59 BSII	01H62916004	MAT412088A0H14679	61
3508	RNC641	KL-15	8911	TATA	ORD	TK	13-Dec-2010	ANK	48	60	LP 1512 TC/59 BSII	01H62919482	MAT412088A0J15978	57
3509	RNC201	KL-15	8376	TATA	ORD	MLB	8-Jun-2010	KHD	48	60	LP 1512 TC/59 BSIII	01C62856904	MAT412081A0C07204	106
3510	RNC202	KL-15	8377	TATA	ORD		8-Jun-2010	KKD	48	60	LP 1512 TC/59 BSIII	01C62856960	MAT412081A0C07317	72
3511	RNC204	KL-15	8385	TATA	ORD		14-Jun-2010	TSY	48	60	LP 1512 TC/59 BSIII	01C62855137	MAT412088A0C06569	73
3512	RNC200	KL-15	8373	TATA	ORD		7-Jun-2010	TDP	48	60	LP 1512 TC/59 BSIII	01C62855139	MAT412088A0C07403	53
3513	RNC203	KL-15	8374	TATA	ORD		7-Jun-2010	TDP	48	60	LP 1512 TC/59 BSIII	01C62856913	MAT412088A0C07195	53
3514	RNC386	KL-15	8636	TATA	ORD	VND	15-Sep-2010	TDP	48	60	LP 1512 TC/59 BSIII	01C62863044	MAT412088A0D09115	53
3515	RNC638	KL-15	8909	TATA	ORD		13-Dec-2010	TLY	48	60	LP 1512 TC/59 BSII	01J62924672	MAT412088A0J15982	18
3516	RNC639	KL-15	8910	TATA	ORD		13-Dec-2010	TLY	48	60	LP 1512 TC/59 BSII	01J62926471	MAT412088A0J15980	18
3517	RNC245	KL-15	8508	TATA	ORD	MLB	22-Jul-2010	ANK	48	60	LP 1512 TC/59 BSIII	01C62852565	MAT412088A0C06752	57
3518	RNC244	KL-15	8511	TATA	ORD		26-Jul-2010	PBVR	48	60	LP 1512 TC/59 BSIII	90JE2793794	MAT412088A0C06750	59
3519	RAM940	KL-15	8143	TATA	ORD		28-Dec-2009	PNI	48	60	LP 1512 TC/59 BSII	LLP146390	MAT41208190F08983	67
3520	RAC628	KL-15	7801	TATA	ORD	SWB	20-Jun-2009	PPD	48	60	LP 1512/48 BSII	90C62735228	CQZ 002934	26
3521	RNC350	KL-15	8612	TATA	ORD	SWB	4-Sep-2010	NTA	48	60	LP 1512 TC/48 BSII	90E62752287	MAT412266A0D09394	22
3522	RNC464	KL-15	8715	TATA	ORD	SWB	11-Oct-2010	PPD	48	60	LP 1512 TC/48 BSII	01E62885645	MAT1412266A0F11037	26
3523	RT 762	KL-15	5940	TATA	ORD		4-Jun-2005	PPD	48	60	LP 1512/59	00H62162031	412071 AUZ 104262	26
3524	RRC233	KL-15	6393	TATA	ORD		4-Dec-2007	ANK	48	60	LP 1512/59 BSII	697 TC55 GSZ 135235	436042 HSZ 012700	57
3525	RNM189	KL-15	8391	TATA	ORD	MLB	16-Jun-2010	MKD	48	60	LP 1512 TC/59 BSII	01C62856972	MAT412088A0C07122	08
3526	RNM190	KL-15	8392	TATA	ORD	MLB	16-Jun-2010	MKD	48	60	LP 1512 TC/59 BSII	01C62856838	MAT412088A0C07194	08

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3527	RNC220	KL-15	8400	TATA	ORD	MLB	18-Jun-2010	MKD	48	60	LP 1512 TC/59 BSII	01C62857073	MAT412088A0C06869	08
3528	RNC241	KL-15	8428	TATA	ORD	MLB	2-Jul-2010	TSR	48	60	LP 1512 TC/59 BSIII	01C62862878	MAT412088A0D08700	63
3529	RNC580	KL-15	8842	TATA	ORD	TK	22-Nov-2010	ANK	48	60	LP 1512 TC/59 BSII	01J62924393	MAT412088A0J15686	57
3530	RRC227	KL-15	6370	TATA	ORD	VND	27-Nov-2007	KPM	48	60	LP 1512/TC BSII (HPV)	697 TC55 GSZ 132851	436042 HSZ 012587	91
3531	RRC235	KL-15	6424	TATA	ORD	VND	10-Dec-2007	KKLM	48	60	1510 BSII(HPV)(697TCIC)	697 TC55 GSZ 135533	436042 HSZ 012431	108
3532	RNC389	KL-15	8623	TATA	ORD	SWB	9-Sep-2010	KNR	48	60	LP 1512 TC/59 BSII	01C62863525	MAT412088A0D09401	77
3533	RNC438	KL-15	8684	TATA	ORD	SWB	4-Oct-2010	KNR	48	60	LP 1512 TC/59 BSII	01E62884681	MAT412264AOF11042	77
3534	RAC629	KL-15	7793	TATA	ORD	SWB	19-Jun-2009	VKBN	48	60	LP 48 BSII	90C 6273527Z	CQZ 002926	29
3535	RAC648	KL-15	7826	TATA	ORD	SWB	24-Jun-2009	TVL	48	60	LP 48 BSII TURBO INTER COLLER	90B62735067	CQZ 002940	43
3536	RAC632	KL-15	7803	TATA	ORD	SWB	20-Jun-2009	MPM	48	60	LP 48 BSII TURBO INTER COOLER 1512 TC			71
3537	RNC465	KL-15	8716	TATA	ORD	SWB	11-Oct-2010	PKDA	48	60	LP 1512 TC/59 BSIII	01E62885892	MAT1412266A0F11038	81
3538	RNC504	KL-15	8781	TATA	ORD	SWB	3-Nov-2010	VLND	48	60	LP 1512 TC/59 BSIII	01E62884683	MAT412266A0F11044	20
3539	RRC469	KL-15	6638	TATA	ORD	MLB	12-Feb-2008	CTLA	48	60	697 TCIC 1510 BSII	MSZ 158417	MSZ 020844	46
3540	RRC992	KL-15	7142	TATA	ORD	SWB	21-Aug-2008	NPR	48	60	697 TCIC	ERZ 128711	ERZ 121928	62
3541	RRC435	KL-15	6581	TATA	ORD	VND	28-Jan-2008	VJMD	48	60	LP 59 BSII TCIC	KSZ 145628	LSZ 017977	16
3542	RRC440	KL-15	6594	TATA	ORD	VND	31-Jan-2008	ALV	48	60	LP 59 BSII TURBO	KSZ 148228	LSZ 018297	61
3543	RRC441	KL-15	6595	TATA	ORD	VND	31-Jan-2008	TPLM	48	60	LP 59 BSII TURBO INTER COOLER	KSZ 145459	LSZ 018112	94
3544	RRC995	KL-15	7146	TATA	ORD	VND	22-Aug-2008	VKBN	48	60	LP 59 BSII TURBO INTER COOLER	ARZ 101091	ARZ 000852	29
3545	RRA762	KL-15	6944	TATA	ORD	VND	8-May-2008	KTR	48	60	697 TCIC	697TC555BRZ106841	46062 BRZ 003099	35
3546	RNC979	KL-15	9393	TATA	ORD	SWB	21-Feb-2012	EKM	48	60	LP 1512 TC/59 BSIII	11M63213033	MAT412021B0P23860	56
3547	RNC954	KL-15	9391	TATA	ORD	SWB	18-Feb-2012	EKM	48	60	LP 1512 TC/59 BSIII	11L63206153	MAT412031BOP22205	56
3548	RAC 1	KL-15	7216	TATA	ORD		3-Nov-2008	CTNR	48	60	6BT CUMMINS BSII	K 62609709	KSZ 017778	97
3549	RAC 2	KL-15	7217	TATA	ORD		3-Nov-2008	CTNR	48	60	6BT CUMMINS BSII	70K62610098	461295 KSZ017780	97
3550	RAC 3	KL-15	7224	TATA	ORD		5-Nov-2008	CTNR	48	60	6BT CUMMINS BSII	D 62666394	ERZ 009660	97
3551	RAC 4	KL-15	7218	TATA	ORD		3-Nov-2008	CTNR	48	60	6BT CUMMINS BSII	D 62666934	ERZ 009664	97
3552	RAC 5	KL-15	7225	TATA	ORD	MLB	7-Nov-2008	MDY	48	60	6BT CUMMINS BSII	C 62661183	ERZ 009663	76
3553	RR 201	KL-15	6394	TATA	ORD	VND	5-Dec-2007	KNPY	48	60	LPO 1616/62 BSII	70 C 62552099	410 292 GSZ 011263	87
3554	RR 203	KL-15	6396	TATA	ORD	VND	5-Dec-2007	KNPY	48	60	LPO 1616/62 BSII	70 C 62552424	410 292 HSZ 012253	87
3555	RR 204	KL-15	6397	TATA	ORD	VND	5-Dec-2007	KNPY	48	60	LPO 1616/62 BSII	70 C 62552102	410 292 GSZ 011780	87
3556	RR 206	KL-15	6399	TATA	ORD	VND	5-Dec-2007	CTY	48	60	LPO 1616/62 BSII	01 B62840565	410 292 GSZ 011781	28
3557	RR 218	KL-15	6416	TATA	ORD	VND	6-Dec-2007	ANK	48	60	LPO 1616/62 BSII	70 C 62552459	410 292 GSZ 011266	57
3558	RR 219	KL-15	6417	TATA	ORD	VND	6-Dec-2007	CTLA	48	60	LPO 1616/62 BSII	70 C 62569760	410 292 GSZ 010866	46
3559	RR 220	KL-15	6622	TATA	ORD	VND	7-Feb-2008	CTLA	48	60	LPO 1616/62 BSII	70 C 62552469	GSZ 011198	46
3560	RR 210	KL-15	6408	TATA	ORD	VND	6-Dec-2007	NPR	48	60	LPO 1616/62 BSII TCIC	70 C 62552468	410 292 HSZ 012427	62
3561	RR 211	KL-15	6409	TATA	ORD	VND	6-Dec-2007	KNPY	48	60	LPO 1616/62 BSII TCIC	70 C 62552100	410 292 GSZ 011264	87
3562	RR 212	KL-15	6410	TATA	ORD	VND	6-Dec-2007	CTLA	48	60	LPO 1616/62 BSII TCIC	70 C 62552103	410 292 GSZ 011265	46
3563	RR 214	KL-15	6412	TATA	ORD	VND	6-Dec-2007	NPR	48	60	LPO 1616/62 BSII TCIC	70 C 62552417	410 292 GSZ 011621	62
3564	RT 826	KL-15	6004	TATA	ORD		21-Jul-2005	PKD	48	60	LPO 1616/62 TCIC		410295BUZ001184	65
3565	RNK692	KL-15	9003	LL	ORD		1-Feb-2011	PLKD	48	60	NAE 129684Z BS 111	NAE129684Z	MB1PBEHC6AEND4763	69
3566	RNC349	KL-15	8614	TATA	ORD		6-Sep-2010	PVM	48	60	LP 1512 TC/59 BSII	01C62863063	MAT412088A0D09117	83
3567	RRM909	KL-15	7067	TATA	ORD	MLB	1-Jul-2008	PKD	48	60	1510 BSII	DRZ 119499	436062DRZ 007847	65
3568	RRC495	KL-15	6663	TATA	ORD		18-Feb-2008	PSL	48	60	1510 TCIC	697TC55MSZ154098	436062MSZ020845	21
3569	RRA814	KL-15	7035	TATA	ORD	VND	13-Jun-2008	PSL	48	60	697 TCIC	CRZ 115025	CRZ 006300	21
3570	RRC425	KL-15	6586	TATA	ORD		29-Jan-2008	CHRY	48	60	697 TCIC	FSZ 130654	LSZ 018296	44
3571	RRA427	KL-15	6611	TATA	ORD		4-Feb-2008	CHRY	48	60	697 TCIC	KSZ 146661	KSZ 016242	44

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3572	RRA705	KL-15	6891	TATA	ORD	VND	19-Apr-2008	ALV	48	60	697 TCIC	BRZ 105997	BRZ 002842	61
3573	RRA875	KL-15	7039	TATA	ORD	VND	16-Jun-2008	PVR	48	60	697 TCIC	CRZ115271	436062 CRZ 006428	23
3574	RRA900	KL-15	7087	TATA	ORD	VND	16-Jul-2008	PLR	48	60	697 TCIC	CRZ 118664	DRZ 007959	36
3575	RNM322	KL-15	8562	TATA	ORD	VND	13-Aug-2010	PSL	48	60	LP 1512 TC/59 BSII	01C62862844	MAT412088A0D08703	21
3576	RNM445	KL-15	8742	TATA	ORD	VND	20-Oct-2010	NDD	48	60	LP 1512 TC/59 BSIII	01G62903661	MAT412088A0G13492	31
3577	RNC502	KL-15	8740	TATA	ORD	SWB	20-Oct-2010	NTA	48	60	LP 1512 TC/59 48BSII	01E62884491	MAT412266A0F11045	22
3578	RNC344	KL-15	8572	TATA	ORD	MLB	17-Aug-2010	MDY	48	60	LP 1512 TC/59 BSII	01C62862643	MAT412088A0D08704	76
3579	RAA253	KL-15	7406	TATA	ORD	MLB	29-Jan-2009	CTR	48	60	TATA 1512 CUMMINS BSII	80K62716782	LRZ 019229	70
3580	RAM975	KL-15	8194	TATA	ORD		28-Jan-2010	PSL	48	60	6BT CUMMINS 1512 TC BSII	MAT41208190G11187		21
3581	RNC243	KL-15	8438	TATA	ORD	VND	6-Jul-2010	PSL	48	60	LP 1512 TC/59 BSII	01E62856430	MAT412088A0C06909	21
3582	RNA339	KL-15	8569	TATA	ORD	VND	16-Feb-2010	PSL	48	60	LP 1512 TC/59 BSII	01C62855470	MAT412088A0C07395	21
3583	RNM325	KL-15	8575	TATA	ORD		18-Aug-2010	CHRY	48	60	LP 1512 TC/59 BSII	01D62871920	MAT412088A0E09619	44
3584	RNM443	KL-15	8714	TATA	ORD	MLB	11-Oct-2010	CTR	48	60	LP 1512 TC/59 BSII	01G62903668	MAT412088A0G13493	70
3585	RNM444	KL-15	8735	TATA	ORD		18-Oct-2010	CTR	48	60	LP 1512 TC/59 BSII	01G62904220	MAT412088A0G13489	70
3586	RNM479	KL-15	8809	TATA	ORD	VND	15-Nov-2010	CHRY	48	60	LP 1512 TC/59 BSII	01G62907443	MAT412088A0G13684	44
3587	RNM480	KL-15	8810	TATA	ORD	VND	15-Nov-2010	CHRY	48	60	LP 1512 TC/59 BSII	01G62907249	MAT412088A0G13680	44
3588	RNM516	KL-15	8811	TATA	ORD	VND	15-Nov-2010	GVR	48	60	LP 1512 TC/59 BSIII	01G62907168	MAT412088A0G13583	66
3589	RNC585	KL-15	8854	TATA	ORD	TK	24-Nov-2010	ANK	48	60	LP 1512 TC/59 BSII	01J62924059	MAT412088A0J15683	57
3590	RNC607	KL-15	8874	TATA	ORD	TK	30-Nov-2010	ANK	48	60	LP 1512 TC/59 BSII	01H62922811	MAT412088A0J15638	57
3591	RNM746	KL-15	9095	TATA	ORD		22-Mar-2011	GVR	48	60	LP 1512 TC/59 BSII	01H62922665	MAT412088A0J15476	66
3592	RAC630	KL-15	7802	TATA	ORD	SWB	20-Jun-2009	ETPA	48	60	TATA 1512 TC BSII	90B62734039	412263CQZ002582	48
3593	RNM 89	KL-15	8293	TATA	ORD		5-May-2010	ETPA	48	60	LP 1512 TC/59 BSIII	01B62843440	MAT412081A0B03878	48
3594	RNC583	KL-15	8856	TATA	ORD		26-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62924095	MAT412088A0J15681	56
3595	RNC586	KL-15	8862	TATA	ORD		26-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62923898	MAT412088A0J15623	56
3596	RNC587	KL-15	8864	TATA	ORD		27-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01H62915336	MAT412088A0H14498	56
3597	RNC589	KL-15	8865	TATA	ORD		27-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62924064	MAT412088A0G15679	56
3598	RNC606	KL-15	8870	TATA	ORD		29-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62922662	MAT412088A0J15624	56
3599	RNC608	KL-15	8871	TATA	ORD		29-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62926467	MAT412088A0J15974	56
3600	RNC714	KL-15	9011	TATA	ORD	SWB	4-Feb-2011	VTRA	48	60	LP 1512 TC/48 BSII	01J62929459	MAT412266A0J16463	17
3601	RNC738	KL-15	9012	TATA	ORD	SWB	4-Feb-2011	VTRA	48	60	LP 1512 TC/48 BSII	01J62929478	MAT412266A0J16469	17
3602	RNC751	KL-15	9056	TATA	ORD	SWB	3-Mar-2011	EKM	48	60	LP 1512 TC/59 BSIII	01J62930200	MAT412266A0J16478	56
3603	RNM375	KL-15	8587	TATA	ORD	VND	26-Aug-2010	VLRD	48	60	LP 1512 TC/59 BSII	01C62871928	MAT412088A0E09618	93
3604	RNA379	KL-15	8592	TATA	ORD		1-Sep-2010	PLR	48	60	LP 1512 TC/59 BSIII	01C62863795	MAT412089A0E09613	36
3605	RNC463	KL-15	8712	TATA	ORD	SWB	8-Oct-2010	PLR	48	60	LP 1512 TC/59 BSIII	01E6288471Z	MAT1412266A0F11040	36
3606	RNM439	KL-15	8663	TATA	ORD		25-Sep-2010	PVR	48	60	LP 1512 TC/59 BSIII	01G62904210	MAT412088A0G13487	23
3607	RNM440	KL-15	8691	TATA	ORD		5-Oct-2010	CTY	48	60	LP 1512 TC/59 BSIII	01G62803567	MAT412088A0G13488	28
3608	RNM441	KL-15	8692	TATA	ORD		5-Oct-2010	PVR	48	60	LP 1512 TC/59 BSIII	01G62904579	MAT412088A0G13491	23
3609	RNM376	KL-15	8621	TATA	ORD		9-Sep-2010	CDLM	48	60	LP 1512 TC/59 BSIII	01D62871909	MAT412088A0E09617	80
3610	RNM139	KL-15	8366	TATA	ORD		4-Jun-2010	CHRY	48	60	LP 1512 TC/59 BSII	01C62856602	MAT412088A0B07406	44
3611	RT 962	KL-15	6140	TATA	ORD		25-Mar-2006	ALV	48	60	TATA 1616 TC/6255	40K62360349	CUZ 2002188	61
3612	RRM486	KL-15	6633	TATA	ORD	VND	11-Feb-2008	KPM	48	60	697 TCIC	KSZ 148218	LSZ 018295	91
3613	RRC410	KL-15	6564	TATA	ORD	VND	22-Jan-2008	GVR	48	60	1510 TCIC	697TC55JSZ143058	4306D62KSZ016653	66
3614	RNM442	KL-15	8699	TATA	ORD	VND	6-Oct-2010	KKLM	48	60	LP 1512 TC/59 BSII	01G62906938	MAT412088A0G13495	108
3615	RNM745	KL-15	9080	TATA	ORD	VND	16-Mar-2011	MVPA	48	60	LP 1512 TC/59 BSII	01H62923198	MAT412088A0J15494	52
3616	RNM230	KL-15	8522	TATA	CFP		29-Jul-2010	PPD	53	60	LP 1512 TC/59 BSIII	01C62856908	MAT412088A0C07199	26

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3617	RNA429	KL-15	8664	TATA	ORD		27-Sep-2010	VZM	48	60	LP 1512 TC/59 BSIII	01G62907498	MAT412088R0G13688	24
3618	RNA453	KL-15	8685	TATA	ORD		4-Oct-2010	MALA	48	60	LP 1512 TC/59 BSIII	01G62905733	MAT412088A0G13535	85
3619	RNA454	KL-15	8693	TATA	ORD		5-Oct-2010	KNPY	48	60	LP 1512 TC/59 BSIII	01G62906805	MAT412088A0G13536	87
3620	RNA382	KL-15	8629	TATA	ORD	VND	13-Sep-2010	ARK	48	60	LP 1512 TC/59 BSII	90A 62726433	MAT412088A0E09616	06
3621	RAC609	KL-15	7759	TATA	ORD	SWB	29-May-2009	VKBN	48	60	TATA CUMMINS 6BT 5.9	90C 62735262	CQZ 002936	29
3622	RAC610	KL-15	7760	TATA	ORD	SWB	29-May-2009	VKBN	48	60	TATA CUMMINS 6BT 5.9	90C 62735268	CQZ 002933	29
3623	RAC611	KL-15	7761	TATA	ORD	SWB	29-May-2009	VKBN	48	60	TATA CUMMINS 6BT 5.9	90B 62734331	CQZ 002924	29
3624	RNC435	KL-15	8682	TATA	ORD	SWB	4-Oct-2010	KPA	48	60	LP 1512 TC/59 BSIII	01E62887760	MAT412264AOF11253	74
3625	RNC542	KL-15	8820	TATA	ORD	TK	18-Nov-2010	ALV	48	60	LP 1512 TC/59 BSII	01H62915678	MAT412088A0H14499	61
3626	RNC543	KL-15	8821	TATA	ORD	TK	18-Nov-2010	ANK	48	60	LP 1512 TC/59 BSII	01H62922820	MAT412088A0J15614	57
3627	RNC579	KL-15	8834	TATA	ORD	TK	19-Nov-2010	ALV	48	60	LP 1512 TC/59 BSII	01H62921029	MAT412088A0J15640	61
3628	RNC582	KL-15	8849	TATA	ORD		23-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62923507	MAT412088A0J15576	56
3629	RNC739	KL-15	9027	TATA	ORD	SWB	10-Feb-2011	KPA	48	60	LP 1512 TC/59 BSIII	01J62929343	MAT461302A0J16471	74
3630	RNC742	KL-15	9028	TATA	ORD	SWB	10-Feb-2011	KPA	48	60	LP 1512 TC/59 BSIII	01J62929473	MAT461302A0J16462	74
3631	RNC581	KL-15	8848	TATA	ORD		23-Nov-2010	EKM	48	60	LP 1512 TC/59 BSII	01J62924068	MAT412088A0J15677	56
3632	RRC647	KL-15	6808	TATA	ORD	VND	28-Mar-2008	EKM	48	60	697 TCIC	BRZ 105940	BRZ 003090	56
3633	RRA171	KL-15	6341	TATA	ORD	VND	14-Nov-2007	CTY	48	60	697 TCIC	62163433	436062 FSZ 010529	28
3634	RRC677	KL-15	6833	TATA	ORD	VND	1-Apr-2008	KPM	48	60	697 TCIC	BRZ 107829	BRZ 003349	91
3635	RNM700	KL-15	8994	TATA	ORD		25-Jan-2011	TDP	48	60	LP 1512 TC/59 BSIII	01G62908220	MAT412088A0J15495	53
3636	RNC388	KL-15	8618	TATA	ORD		8-Sep-2010	KMGH	48	60	LP 1512 TC/59 BSII	01C62862834	MAT412088A0D09209	55
3637	RNM323	KL-15	8620	TATA	ORD		9-Sep-2010	KMGH	48	60	LP 1512 TC/59 BSII	01D62871922	MAT412088A0E09620	55
3638	RNA452	KL-15	8676	TATA	ORD		30-Sep-2010	PVM	48	60	LP 1512 TC/59 BSII	01G62905475	MAT412088A0G13494	83
3639	RRM197	KL-15	6367	TATA	ORD	VND	26-Nov-2007	PALA	48	60	TURBO INTER COOLER 697	HSZ 136563	HSZ 013455	50
3640	RRA257	KL-15	6444	TATA	ORD	VND	18-Dec-2007	KKLM	48	60	TURBO INTER COOLER 697TCIC	697 TC55 GSZ 135638	436062 HSZ 013330	108
3641	RRC376	KL-15	6538	TATA	ORD	VND	16-Jan-2008	KTM	48	60	TURBO INTER COOLER 697 TCIC	HSZ 138379	JSZ 015324	47
3642	RRA594	KL-15	6836	TATA	ORD	VND	3-Apr-2008	VKM	48	60	TURBO INTER COOLER	OOD 62145675	ARZ 000856	51
3643	RRA242	KL-15	6401	TATA	ORD	VND	5-Dec-2007	KKLM	48	60	TURBO INTER COOLER 697TCIC	697 TC55 GSZ 135780	436062 HSZ 013350	108
3644	RRA985	KL-15	7156	TATA	ORD	VND	30-Aug-2008	PLR	48	60	TURBO TCIC	CRZ 118752	DRZ 007967	36
3645	RNM 7	KL-15	8220	LL	ORD	VND	8-Mar-2010	KTDA	48	60	VIKING	WXE113853Z	MB1PBEHC19EWB4581	25
3646	RRK458	KL-15	6609	LL	ORD	MLB	4-Feb-2008	MPM	48	60	VIKING ALPSV 4/89 HINO EURO II TI	NPH 504721	NPE 639568	71
3647	RAK991	KL-15	8218	LL	ORD	MLB	22-Feb-2010	PNR	48	60	VIKING HINO BSII		MB1PBEHC69EYB2928	78
3648	RRK459	KL-15	6620	LL	ORD	MLB	6-Feb-2008	MPM	48	60	VIKING HINO EUROII TI	TPH 502327	TPE 637635	71
3649	RNK 83	KL-15	8276	LL	ORD		26-Apr-2010	PNR	48	60	VIKING HINOI EURO BSII	VAE121264Z	MB1PBEHC7AEVC5537	78
3650	RNC218	KL-15	8404	TATA	ORD		21-Jun-2010	KMR	48	60	LP 1512 TC/59 BSII	01C62856825	MAT412088AOCO7396	30
3651	RT 974	KL-15	6152	LL	ORD	VND	3-Apr-2006	KKLM	48	60	W06E BSII	VHP 25707	UDE 551369	108
3652	RRC358	KL-15	6503	LL	ORD	MLB	5-Jan-2008	MDY	48	60	W06ETI BSII	TPH 501993	TPE 637137	76
3653	RRC360	KL-15	6512	LL	ORD	MLB	8-Jan-2008	MDY	48	60	W06ETI BSII	TPH 500807	TPE 637323	76
3654	RRC845	KL-15	7005	LL	ORD		2-Jun-2008	EMLY	48	60	W06ETI BSII	KNH 537645	KNE 652865	95
3655	RAA279	KL-15	7424	LL	ORD	VND	3-Feb-2009	MLPY	48	60	W06ETI BSII	ZNE 104401Z	YNE 667559	96
3656	RRE601	KL-15	6785	LL	ORD	MLB	24-Mar-2008	PNR	48	60	W06ETI BSII ALPSV 4/89	PNH 513867	PNE 642344	78
3657	RRC950	KL-15	7109	LL	ORD		11-Aug-2008	SBY	48	60	HINO EURO II TURBO INTER COOLER	MNH 519632	MNE 644910	75
3658	RRC951	KL-15	7111	LL	ORD		11-Aug-2008	ARNR	48	60	W06FTI BSII	MNH 519956	MNE 645166	19
3659	RRC969	KL-15	7137	LL	ORD		13-Aug-2008	KLM	48	60	W06FTI BSII	MNH 519636	MNE 644837	34
3660	RNC992	KL-15	9411	LL	ORD	SWB	9-Mar-2012	TDY	48	60	HINO 6ETI3K BSIII	BMEZ400876	MB1PCEYC4BEMG5795	79
3661	RSC 14	KL-15	9428	LL	ORD	SWB	24-Mar-2012	CTY	48	60	HINO 6ETI3K BSIII	BMEZ400648	MB1PCEYC5BEMG5594	28

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3662	RNC990	KL-15	9420	TATA	ORD	SWB	16-Mar-2012	ALV	48	60	LP 1512 TC/59 BSIII	11M63213233	MAT412031BOP23851	61
3663	RNC991	KL-15	9426	TATA	ORD	SWB	22-Mar-2012	HPD	48	60	LP 1512 TC/59 BSIII	11M63213034	MAT412031BOP23854	42
3664	RSC 11	KL-15	9429	TATA	ORD	SWB	27-Mar-2012	HPD	48	60	LP 1512 TC/59 BSIII	21B63235737	MAT412031BOP23855	42
3665	RSC 15	KL-15	9465	LL	ORD	SWB	19-Apr-2012	TVL	48	60		BMEZ400655	MB1PCEYC7BEMG5595	43
3666	RSC 13	KL-15	9466	TATA	ORD	SWB	21-Apr-2012	VZM	48	60	TC/48 BSIII	11M63213783	MAT412031BOP23858	24
3667	RSC 44	KL-15	9470	LL	ORD	SWB	24-Apr-2012	MLTM	48	60	6EII 3KC BSIII	BMEZ400838	MB1PCEYC2BEMG5794	54
3668	RSC 43	KL-15	9476	TATA	ORD	SWB	27-Apr-2012	HPD	48	60	LP 1512 TC/159 BSIII	11M63213029	MAT412031BOP23859	42
3669	RSC 12	KL-15	9479	TATA	ORD	SWB	28-Apr-2012	ALP	48	60	BSIII	11M63213243	MAT412031BOP23857	45
3670	RSC 67	KL-15	9500	TATA	ORD	SWB	11-May-2012	KLM	48	60	BSIII	11M 63213229	MAT412031BOP23849	34
3671	RSC 62	KL-15	9503	LL	ORD	SWB	14-May-2012	MNR	48	60	HINO EURO BSIII	BMEZ400537	MB1PCEYCI BEMG5477	60
3672	RSC 68	KL-15	9507	TATA	ORD	SWB	16-May-2012	KNPY	48	60	LP 1512 TC/48 BSIII	11M 63213236	MAT412031BOP23852	87
3673	RSC 69	KL-15	9508	TATA	ORD	SWB	17-May-2012	PPD	48	60	CUMMINS 6BT 5.9 BSIII	11206266	MAT412031BOP23853	26
3674	RSC 63	KL-15	9516	LL	ORD	SWB	21-May-2012	SBY	48	60	LL BSIII 6ETI3K	BMEZ 401230	MB1PCEYC6BEMG6169	75
3675	RSC 65	KL-15	9518	LL	ORD	SWB	23-May-2012	PTA	48	60	6ETI3K LL BSIII	BMEZ400542	MB1PCEYC8BEMG5475	37
3676	RSC 64	KL-15	9521	LL	ORD	SWB	25-May-2012	ARNR	48	60	HINO BSIII	BMEZ400482	MB1PCEYC5BEMG5479	19
3677	RSC 66	KL-15	9527	LL	ORD	SWB	28-May-2012	KMR	48	60	LL HINO BS III	BMEZ400844	MB1PCEYC0BEMG5793	30
3678	RSC 82	KL-15	9528	LL	ORD	SWB	29-May-2012	TPLM	48	60		BMEZ400095	MB1PCEYC4BEMG5411	94
3679	RSC 80	KL-15	9533	LL	ORD	SWB	31-May-2012	MLTM	48	60		BMEZ400654	MB1PCEYC9BEMG5596	54
3680	RSC 81	KL-15	9534	LL	ORD	SWB	31-May-2012	NDD	48	60	BSIII	BMEZ400490	MB1PCEYC6BEMG5412	31
3681	RSC 84	KL-15	9536	TATA	ORD	SWB	1-Jun-2012	KLM	48	60	1512 TC BSIII	11M63213042	MAT412031BOP23861	34
3682	RNC993	KL-15	9409	LL	ORD	SWB	6-Mar-2012	MLPY	48	60	6ETI 3K BSIII	BMEZ401231	MB1PBEYC2BEMG6170	96
3683	RSC 83	KL-15	9543	LL	ORD	SWB	6-Jun-2012	PTA	48	60	6ETI3K LL BSIII	NBE158572Z	MB1PCEYC7BENG3820	37
3684	RSC115	KL-15	9569	TATA	ORD	SWB	22-Jun-2012	HPD	48	60	LP 1512 TC/159 BSIII	11M63213227	MAT412031B0923862	42
3685	RSC135	KL-15	9571	LL	ORD	SWB	23-Jun-2012	PALA	48	60		BMEZ401010	MB1PCEYCXBEMG5929	50
3686	RSC116	KL-15	9575	TATA	ORD	SWB	25-Jun-2012	MALA	48	60	LP 1512 TC/59 BSIII	11M63213226	MAT412031B0P23863	85
3687	RSC136	KL-15	9578	TATA	ORD	SWB	27-Jun-2012	PVM	48	60	LP 1512 TC 59 BS3	11M63213232	MAT412031BOP23864	83
3688	RSC145	KL-15	9593	TATA	ORD	SWB	2-Jul-2012	KYLM	48	60	1512TC BS III	11M84033834	MAT412021BOP23709	41
3689	RSC148	KL-15	9600	LL	ORD	SWB	4-Jul-2012	CLDY	48	60		BEMZ400495	MB1PCEYC8BEMG5413	58
3690	RSC149	KL-15	9609	LL	ORD	SWB	7-Jul-2012	MVPA	48	60	LL BS 111	CBEZ401780	MB1PCEYCXCEBH0835	52
3691	RSC146	KL-15	9616	TATA	ORD	SWB	9-Jul-2012	MLPY	48	60	LP 1512 TC/48 BSIII	11M63213035	MAT412031BOP23866	96
3692	RSC176	KL-15	9623	TATA	ORD	SWB	11-Jul-2012	KNPY	48	60	LP 1512 TC/48 BSIII	21A84040745	MAT412031COB02784	87
3693	RSC147	KL-15	9622	TATA	ORD	SWB	11-Jul-2012	ADR	48	60	LP 1512 TC/48 BSIII	11M63213045	MAT412031BOP23865	38
3694	RSC178	KL-15	9626	LL	ORD	SWB	12-Jul-2012	KTP	48	60	HINO EURO III	CBEZ401777	MB1PBEYC1CEBH0836	14
3695	RSC177	KL-15	9637	TATA	ORD	SWB	16-Jul-2012	PBVR	48	60	TATA LP 1512 TC 48 BSIII	21A84039686	MAT412031COB02785	59
3696	RSC179	KL-15	9641	LL	ORD	SWB	19-Jul-2012	PLKD	48	60	BS 111	CAEZ402265	MB1PCEYCI CEAH1188	69
3697	RSC180	KL-15	9642	LL	ORD	SWB	19-Jul-2012	PLKD	48	60	BS 111	CAEZ402161	MB1PBEYC7CEAH1115	69
3698	RSC207	KL-15	9666	LL	ORD	SWB	26-Jul-2012	PTPM	48	60	HINO 6ETI3K BSIII	NBE158713Z	MB1PCEYC6BENG3906	15
3699	RSC216	KL-15	9668	LL	ORD	SWB	27-Jul-2012	PTPM	48	60	HINO 6ETI3K BSIII	CAEZ402151	MB1PCEYC5CEAH1114	15
3700	RSC209	KL-15	9671	LL	ORD	SWB	28-Jul-2012	KTR	48	60	HINO 6ETI3K BSIII	CAEZ403823	MB1PBEYC6CEAH2983	35
3701	RSC255	KL-15	9685	LL	ORD	SWB	1-Aug-2012	MKD	48	60	6ETI 3K BSIII	CAEZ402152	MB1PCEYC3CEAH1113	08
3702	RSC208	KL-15	9682	LL	ORD	SWB	31-Jul-2012	VJMD	48	60	HINO EURO BSIII	CAEZ403726	MB1PCEYC8CEAH2984	16
3703	RSC257	KL-15	9690	TATA	ORD	SWB	3-Aug-2012	KNPY	48	60	LP 1512 TC/48 BSIII	21A84039696	MAT412031COB02786	87
3704	RSC258	KL-15	9694	TATA	ORD	SWB	4-Aug-2012	PMNA	48	60	LP 1512 TC/48 BSIII	21A84039523	MAT412031COB02787	68
3705	RSC259	KL-15	9710	TATA	ORD	SWB	14-Aug-2012	HPD	48	60	LP 1512 TC/159 BSIII	21A84040218	MAT412031COB02788	42
3706	RSC260	KL-15	9713	TATA	ORD	SWB	16-Aug-2012	PBVR	48	60	TATA CUMMINS	21B63237090	MAT412031COCO4478	59

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3707	RSC261	KL-15	9714	TATA	ORD	SWB	16-Aug-2012	KNPY	48	60	LP1512 TC/48 BSIII	21A84039502	MAT412031COB02783	87
3708	RSC286	KL-15	9719	LL	ORD	SWB	16-Aug-2012	PTPM	48	60	6ETI3KBSIII	NBE158716Z	MB1PCEYC2BENG3823	15
3709	RSC256	KL-15	9723	LL	ORD	SWB	17-Aug-2012	TDP	48	60	6ETI3KBSIII	CAEZ402263	MBIDCEYCXCEA1147	53
3710	RSC280	KL-15	9730	TATA	ORD	SWB	18-Aug-2012	PTA	48	60	CUMMIN 6BT 5.9 BSIII	21A84039702	MAT412031COB02790	37
3711	RSC284	KL-15	9731	LL	ORD	SWB	18-Aug-2012	KTP	48	60	HINO EURO III	NBE 158797Z	MBIPBEYC4BENG3905	14
3712	RSC287	KL-15	9732	LL	ORD	SWB	18-Aug-2012	VTRA	48	60	HINO EURO BSIII	NBE158720Z	MB1PBEYC6BENG3890	17
3713	RSC288	KL-15	9733	LL	ORD	SWB	18-Aug-2012	TDP	48	60		CYEZ405749	MB1PCEYC4CEYH5076	53
3714	RSC281	KL-15	9747	TATA	ORD	SWB	25-Aug-2012	KKD	48	60	CUMMINS 6BT 5.9	21A84039708	MAT412031COB02789	72
3715	RR 205	KL-15	6398	TATA	ORD	VND	5-Dec-2007	CTLA	48	60	LPO 1616/62 BSII	70 C 62552463	410 292 GSZ 011620	46
3716	RR 209	KL-15	6407	TATA	ORD	VND	6-Dec-2007	CTLA	48	60	CUMMINS 1512 BSII TC	70 C 62552466	410 292 GSZ 011140	46
3717	RR 202	KL-15	6395	TATA	ORD	VND	5-Dec-2007	KNPY	48	60	LPO 1616/62 BSII	70 C 62552423	410 292 GSZ 011026	87
3718	RR 213	KL-15	6411	TATA	ORD	VND	6-Dec-2007	KNPY	48	60	LPO 1616/62 BSII TCIC	70 C 62552464	410 292 GSZ 011199	87
3719	RR 217	KL-15	6415	TATA	ORD	VND	6-Dec-2007	CTNR	48	60	LPO 1616/62 BSII	70 C 62552467	410 292 GSZ 011622	97
3720	RR 215	KL-15	6413	TATA	ORD		6-Dec-2007	KNPY	48	60	LPO 1616/62 BSII	70C62552476	410 292 GSZ 011839	87
3721	RSC282	KL-15	9744	LL	ORD	SWB	24-Aug-2012	VTRA	48	60	HINO EURO BSIII	CAEZ402626	MB1PBEYC8CEAH1575	17
3722	RSC283	KL-15	9748	LL	ORD	SWB	25-Aug-2012	VTRA	48	60	HINO EURO BSIII	NBE158719Z	MB1PBEYCXBENG3839	17
3723	RSC289	KL-15	9749	LL	ORD	SWB	25-Aug-2012	ARND	48	60	HINO BSIII	CBEZ401776	MB1PCEYC8CEBH0834	19
3724	RSC285	KL-15	9751	LL	ORD	SWB	27-Aug-2012	KTP	48	60		BMEZ401225	MB1PBEYC6BEMG6172	14
3725	RSC290	KL-15	9757	LL	ORD	SWB	4-Sep-2012	NTA	48	60	HINO W06ETI3KBSIII	NBE158717Z	MB1PCEYC4BENG3824	22
3726	RSC291	KL-15	9771	LL	ORD	SWB	7-Sep-2012	PALA	48	60		CAEZ403665	MB1PCEYCXCEAH2985	50
3727	RSE427	KL-15	9959	LL	ORD		11-Apr-2013	KGD	48	60		CREZ415596	MB1PBEYC4CERJ6698	84
3728	RT 41	KL-15	5219	LL	ORD		12-Feb-2004	KTDA	48	60	HINO EURO	LXH573253	XVE 516788	25
3729	RSE428	KL-15	9974	LL	ORD		9-May-2013	KGD	48	60		CREZ415864	MB1PBEYC4CERJ7348	84
3730	RSE429	KL-15	9982	LL	ORD		23-May-2013	KGD	48	60		CNEZ419143	MB1PBEYC0CENK0736	84
3731	RSE455	KL-15	9984	LL	ORD		25-May-2013	KGD	48	60	HINO 6ETI3K BSIII	CPEZ419901	MB1PBEYC4CEDK1546	84
3732	RSA569	KL-15	9986	TATA	ORD		30-May-2013	KGD	48	60		31A84093889	MAT412021DOB00998	84
3733	RSA570	KL-15	9989	TATA	ORD		31-May-2013	KGD	48	60		21M84088939	MAT412021DOB01034	84
3734	RSC501	KL-15	9992	LL	ORD		3-Jun-2013	KGD	48	60		CREZ415835	MB1PBEYC6CERJ7044	84
3735	RSC502	KL-15	9993	LL	ORD		3-Jun-2013	KGD	48	60		CREZ415718	MB1PBEYC4CEPJ8283	84
3736	RSC503	KL-15	9994	LL	ORD		3-Jun-2013	KGD	48	60		CRHZ116837	MB1PBEYC4CERJ7480	84
3737	RSC504	KL-15	9995	LL	ORD		3-Jun-2013	KGD	48	60		CPEZ417066	MBIPBEYC0CEPJ8667	84
3738	RSC505	KL-15	9996	LL	ORD		3-Jun-2013	KGD	48	60		CDEZ420226	MBIPBEYC5CEDK1944	84
3739	RSC513	KL-15	9998	LL	ORD		4-Jun-2013	PNR	48	60		CPEZ416897	MB1PBEYC8CERJ7353	78
3740	RSC522	KL-15	9999	LL	ORD		4-Jun-2013	PNR	48	60		CDEZ419921	MB1PBEYC1CEDK1567	78
3741	RSC523	KL-15-A	1	LL	ORD		4-Jun-2013	KGD	48	60		CDEZ419902	MB1PBEYC4CEDK1563	84
3742	RSC524	KL-15-A	2	LL	ORD		5-Jun-2013	KGD	48	60		CDEZ419619	MB1PBEYXCEDK1275	84
3743	RSA572	KL-15-A	4	TATA	ORD		4-Jun-2013	PNR	48	60		31A84093642	MAT412021DOB00994	78
3744	RSK449	KL-15-A	5	LL	ORD		4-Jun-2013	PNR	48	60		CRHZ116521	MB1PBEYC5CERJ7486	78
3745	RSC525	KL-15-A	6	LL	ORD		6-Jun-2013	KNR	48	60	LL BSIII	CDEZ419529	MB1PBEYC7CEDK1167	77
3746	RSE459	KL-15-A	13	LL	ORD		10-Jun-2013	KGD	48	60		CREZ416556	MB1PBEYC9CERJ8067	84
3747	RSK574	KL-15-A	14	LL	ORD		10-Jun-2013	KGD	48	60		CNEZ418627	MB1PBEYC5CENK0280	84
3748	RSC528	KL-15-A	16	LL	ORD		12-Jun-2013	KGD	48	60		CNEZ419007	MB1PBEYC4CENK0707	84
3749	RSC583	KL-15-A	19	LL	ORD		14-Jun-2013	TLY	48	60	HINO BSIII	CDEZ420074	MBIPBEYC2CEDK1710	18
3750	RSE460	KL-15-A	23	LL	ORD		13-Jun-2013	KGD	48	60		CREZ415310	MB1PBEYC1CERJ6285	84
3751	RSK575	KL-15-A	24	LL	ORD		14-Jun-2013	KGD	48	60		CRHZ417297	MB1PBEYC5CERJ8065	84

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3752	RSE546	KL-15-A	28	LL	ORD		15-Jun-2013	KGD	48	60		CREZ415319	MB1PBEYC5CERJ6287	84
3753	RSK576	KL-15-A	29	LL	ORD		17-Jun-2013	KNR	48	60	BSIII	CREZ415813	MB1PBEYC1CEPJ7047	77
3754	RSE547	KL-15-A	32	LL	ORD		18-Jun-2013	KNR	48	60	LL BSIII	CPEZ416889	MB1PBEYC6CEPJ9365	77
3755	RSE548	KL-15-A	35	LL	ORD		20-Jun-2013	KNR	48	60	LL BSIII	CPEZ416815	MB1PSEYC4CEPJ8879	77
3756	RSE549	KL-15-A	43	LL	ORD		22-Jun-2013	KGD	48	60		CDEZ419455	MB1PSEYC7CEDK1105	84
3757	RSC596	KL-15-A	89	LL	ORD		26-Jul-2013	MNR	48	60	HINO EURO BSIII	CDEZ419524	MB1PBEYC5CEDK1166	60
3758	RSC675	KL-15-A	144	LL	SDLX		7-Sep-2013	KTM	53	50		DYEZ405963	MB1PBEYC4DEYL0518	47
3759	RSC674	KL-15-A	152	LL	SDLX		10-Sep-2013	RWE	53	50		DYEZ405579	MB1PBEYV2DEYL0517	12
3760	RSC676	KL-15-A	153	LL	SDLX	SBRI	10-Sep-2013	MDY	53	50	HA6ET13KN BS 111	DYEZ405790	MB1PBEYC2DEYL0131	76
3761	RSC677	KL-15-A	154	LL	SDLX	SBRI	11-Sep-2013	KTM	53	50	HA6ET 13KN BS 111	DYEZ405961	MB1PBEYC6DEYL0522	47
3762	RSC678	KL-15-A	155	LL	SDLX		11-Sep-2013	EKM	53	50	ALPSV 4/186	DYEZ405575	MB1PBEYC5DEYL0172	56
3763	RSC679	KL-15-A	156	LL	SDLX		11-Sep-2013	KTP	53	50	ALPSV 4/186	DYEZ405791	MB1PBEYC6DEYL0519	14
3764	RSC682	KL-15-A	173	LL	SDLX		15-Oct-2013	TVM	53	50		DYEZ405788	MB1PBEYC4DEYL0521	27
3765	RSC681	KL-15-A	178	LL	SDLX		22-Oct-2013	TVM	53	50		DYEZ405381	MB1PBEYC3DEYK9196	27
3766	RSC680	KL-15-A	175	LL	SDLX		17-Oct-2013	MDY	53	50	6ET 13KN	DPEZ405139	MB1PBEYC7DEYK8746	76
3767	RSC690	KL-15-A	180	LL	SDLX		24-Oct-2013	RWE	53	50	HINO EURO BSIII	DVEZ408612	MB1PBEYC1DEVL3433	12
3768	RSC688	KL-15-A	182	LL	SDLX		26-Oct-2013	RWE	53	50	HINO EURO BSIII	DVEZ408613	MB1PBEYC7DEVL3436	12
3769	RSC692	KL-15-A	195	TATA	ORD		5-Nov-2013	SBY	48	60	CUMMINS 6BTAA5.9	31F84115725	MAT412201DOF05237	75
3770	RSC693	KL-15-A	196	TATA	SDLX	SBRI	5-Nov-2013	PBVR	53	50		31F84116276	MAT412201DOF05239	59
3771	RSC697	KL-15-A	197	LL	SDLX		5-Nov-2013	TVM	53	50	BS 111	DVEZ408605	MB1PBEYCODEVL3438	27
3772	RSC689	KL-15-A	201	LL	SDLX		7-Nov-2013	KNR	53	50	LL BSIII	DVEZ408611	MB1PBEYC9DEVL3437	77
3773	RSC691	KL-15-A	202	LL	ORD		7-Nov-2013	SBY	48	60		DVEZ408604	MB1PBEYC5DEVL3435	75
3774	RSC696	KL-15-A	203	LL	SDLX		7-Nov-2013	TVM	53	50	BS 111	DVEZ408609	MB1PBEYC8DEVL3428	27
3775	RSC698	KL-15-A	208	LL	SDLX		11-Nov-2013	RWE	53	50	LL HINO BSIII	DVEZ408602	MB1PBEYC8DEVL3431	12
3776	RSC700	KL-15-A	209	LL	SDLX		11-Nov-2013	TVM	53	50	6ETI3KN BSIII	DVEZ408610	MB1PBEYC3DEVL3434	27
3777	RSC699	KL-15-A	210	LL	SDLX		12-Nov-2013	MDY	53	50	LL HINO BSIII	DVEZ408606	MB1PBEYCXDEVL3432	76
3778	RSC701	KL-15-A	211	LL	SDLX		13-Nov-2013	TVM	53	50	6ETI3KN BSIII	DVEZ408607	MB1PBEYCXDEVL3439	27
3779	RSC702	KL-15-A	212	LL	SDLX		13-Nov-2013	CHRY	53	50	BSIII	DVEZ408603	MB1PBEYC6DEVL3430	44
3780	RSC694	KL-15-A	225	TATA	SDLX	SBRI	21-Nov-2013	MVPA	53	50		31F84115744	MAT412201DOF05197	52
3781	RSC703	KL-15-A	226	TATA	SDLX		22-Nov-2013	KNR	53	50	TC BSIII	31F84115742	MAT412201DOF05192	77
3782	RSC695	KL-15-A	228	TATA	ORD		23-Nov-2013	SBY	48	60	CUMMINS 6BTAA 5.9	31F84115737	MAT412201DOF05194	75
3783	RSC764	KL-15-A	231	TATA	SDLX		25-Nov-2013	KNR	53	50	TC BSIII	31F84115882	MAT412201DOF05236	77
3784	RSC705	KL-15-A	234	TATA	SDLX		28-Nov-2013	PLR	53	50		31F84115721	MAT412201DOF05235	36
3785	RSC704	KL-15-A	238	TATA	SDLX		30-Nov-2013	CWS	53	50		31F84116164	MAT412201DOF05243	09
3786	RSC762	KL-15-A	240	TATA	SDLX		2-Dec-2013	CTY	53	50	LP 1512 TC/58 BSIII	31F84115741	MAT412201DOF05198	28
3787	RSC763	KL-15-A	241	TATA	ORD		2-Dec-2013	SBY	48	60	LP 1512 TC/58 BSIII	31F84115626	MAT412201DOF05199	75
3788	RSC766	KL-15-A	253	TATA	SDLX		12-Dec-2013	KTM	53	50	6BT59AA TC/BSIII	31F84115154	MAT412201DOF05195	47
3789	RSC767	KL-15-A	255	TATA	SDLX		13-Dec-2013	KTM	53	50	6BT59AA TC BSIII	31F84115892	MAT412201DOF05234	47
3790	RSC765	KL-15-A	261	TATA	SDLX		24-Jan-2014	RWE	53	50	LPO 1512 TC/58 BSIII	31F84115726	MAT412201DOF05193	12
3791	RSC770	KL-15-A	262	TATA	SDLX		3-Feb-2014	RWE	53	50		31F84116248	MAT412201DOF05240	12
3792	RSC769	KL-15-A	263	TATA	SDLX		17-Feb-2014	RWE	53	50		31F84115718	MAT412201DOF05232	12
3793	RSC771	KL-15-A	264	TATA	SDLX		20-Feb-2014	RWE	53	50		31F84115736	MAT412201DOF05191	12
3794	RSC772	KL-15-A	265	TATA	SDLX		22-Feb-2014	PLR	53	50		31F84115636	MAT412201DOF05201	36
3795	RSC775	KL-15-A	266	TATA	SDLX		24-Feb-2014	PBVR	53	50		31F84115719	MAT412201DOF05190	59
3796	RAK582	KL-15	7821	LL	ORD		23-Jun-2009	CWS	48	60	HINO BSII JAIVA VAIVIDHYA RADHAM	LXH 572697	LXE 670102	09

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3797	RAK671	KL-15	7822	LL	CFP		23-Jun-2009	PPD	53	66	HINO BSII	10VHC 1979	LXE 670117	26
3798	RNC 35	KL-15	8369	LL	ORD	ABUS	7-Jun-2010	NTA	48	60	ALPSV 4/89 HINO BSII	XH 605223	MB1PBEK5AH9A7516	22
3799	RNC 36	KL-15	8370	LL	ORD	ABUS	7-Jun-2010	VLRD	48	60	ALPSV 4/89 HINO BSII	UXH 605223	MB1PBEK7AH9A7517	93
3800	RNE 50	KL-15	8416	LL	ORD	ABUS	29-Jun-2010	NTA	48	60	ALPSV 4/106 EURO BSII	UXH 609645	MB1PBEHC9AHVA9418	22
3801	RNE 42	KL-15	8434	LL	ORD	ABUS	6-Jul-2010	PVM	48	60	HINO BSII	UXH 609024	MB1PBEHC5AH9A7743	83
3802	RNC 48	KL-15	8499	LL	ORD	ABUS	19-Jul-2010	NTA	48	60	ALPSV 4/89 HINO BSII	XUH 609028	MB1PBEHC6AHVA9411	22
3803	RNC 49	KL-15	8500	LL	ORD	ABUS	19-Jul-2010	PSL	48	60	ALPSV 4/89 HINO BSII	XUH 609647	MB1PBEHC01HVA9811	21
3804	RNE 43	KL-15	8503	LL	ORD	ABUS	20-Jul-2010	KHD	48	60	ALPSV 4/106 EURO BSII	UXH 605225	MB1PBEHC9AH9A7549	106
3805	RNE 54	KL-15	8520	LL	ORD	ABUS	28-Jul-2010	KPM	48	60	ALPSV 4/106 BSII	XUH 609643	MB1PBEHC1AHVA9459	91
3806	RNE 55	KL-15	8527	LL	ORD	ABUS	30-Jul-2010	KKLM	48	60	ALPSV 4/106 BSII	XUH 609644	MB1PBEHC9AHVA9452	108
3807	RNC660	KL-15	8946	TATA	ORD	ABUS	1-Jan-2011	KDLR	48	60	LP 1512 TC/59 BSII	01E62880623	MAT461302A0E10740	90
3808	RNC661	KL-15	8947	TATA	ORD	ABUS	1-Jan-2011	ALP	48	60	LP 1512 TC/59 BSII	01D62873216	MAT461302A0E10618	45
3809	RNC658	KL-15	8978	TATA	ORD	ABUS	18-Jan-2011	PVR	48	60	LP 1512 TC/59 BSII	01D62873141	MAT461302A0E10742	23
3810	RNC659	KL-15	8979	TATA	ORD	ABUS	18-Jan-2011	VKM	48	60	LP 1512 TC/59 BSII	01E62880622	MAT461302A0E10741	51
3811	RNC678	KL-15	9020	TATA	ORD	ABUS	8-Feb-2011	PPD	48	60	LP 1512 TC/59 BSII	62734441	MAT461302A0E10763	26
3812	RNC680	KL-15	9021	TATA	ORD	ABUS	8-Feb-2011	PVR	48	60	LP 1512 TC/59 BSII	01D62873178	MAT461302A0E10842	23
3813	RNC721	KL-15	9142	TATA	ORD	ABUS	18-May-2011	PNR	48	66	LP 1612 TC/59 BSIII	01D62873222	MAT461302A0E10469	78
3814	RNC757	KL-15	9150	TATA	ORD	ABUS	24-May-2011	PNR	48	66	LP 1612 TC/59 BSIII	01D62873125	MAT461302A0E09870	78
3815	RNC758	KL-15	9173	TATA	ORD	ABUS	29-Jun-2011	NTA	48	60	LP 1512 TC/59 BSII	01E62880641	MAT461302A0F10903	22
3816	RNC770	KL-15	9178	TATA	ORD	ABUS	7-Jul-2011	KPM	48	60	LP 1512 TC/59 BSII	01D62888597	MAT461302A0G12785	91
3817	RNC723	KL-15	9181	TATA	ORD	ABUS	20-Jul-2011	KPM	48	60	LP 1512 TC/59 BSII	01E62883264	MAT461302A0E10765	91
3818	RNC768	KL-15	9182	TATA	ORD	ABUS	21-Jul-2011	KPM	48	60	LP 1512 TC/59 BSII	01E62884314	MAT461302A0G12847	91
3819	RNC725	KL-15	9165	TATA	ORD	ABUS	14-Jun-2011	TSY	48	66	LP 1612 TC/59 BSIII	01D62873211	MAT461302A0E10517	73
3820	RNC724	KL-15	9166	TATA	ORD	ABUS	16-Jun-2011	CTY	48	66	LP 1612 TC/59 BSII	01D62873196	MAT461302A0E10681	28
3821	RNC755	KL-15	9167	TATA	ORD	ABUS	18-Jun-2011	KYLM	48	60	LP 1612 TC/59 BSII	01D62873193	MAT461302A0E10743	41
3822	RNC685	KL-15	9128	TATA	ORD	ABUS	19-Apr-2011	ATL	48	60	LP 1612 TC/59 BSII	01F62888608	MAT461302A0G12848	33
3823	RNC688	KL-15	9133	TATA	ORD	ABUS	6-May-2011	CGNR	48	60	LP 1512 TC/59 BSII	01E62884308	MAT461302A0F10904	40
3824	RNC771	KL-15	9188	TATA	ORD	ABUS	27-Jul-2011	KPM	48	60	LP 1512 TC/59 BSIII	01F62888600	MAT461302A0G12849	91
3825	RNC763	KL-15	9194	TATA	ORD	ABUS	24-Aug-2011	VKBN	48	60	LP 1512 TC/59 BSIII	01F62888605	MAT461302A0G12924	29
3826	RNC686	KL-15	9078	TATA	ORD	ABUS	16-Mar-2011	KHD	48	60	LP 1512 TC/59 BSIII	01F6288603	MAT461302A0G12784	106
3827	RNC687	KL-15	9084	TATA	ORD	ABUS	19-Mar-2011	KPM	48	60	LP 1512 TC/59 BSIII	01D62873200	MAT461302A0E10468	91
3828	RNC681	KL-15	9068	TATA	ORD	ABUS	8-Mar-2011	KNR	48	60	LP 1512 TC/59 BSII	01E62883297	MAT461302A0F10905	77
3829	RNC682	KL-15	9069	TATA	ORD	ABUS	9-Mar-2011	KNR	48	60	LP 1512 TC/59 BSII	01E62883258	MAT461302A0F10744	77
3830	RNC683	KL-15	9103	TATA	ORD	ABUS	25-Mar-2011	KNR	48	60	LP 1512 TC/59 BSII	01F62888598	MAT461302A0G12925	77
3831	RNC679	KL-15	9113	TATA	ORD	ABUS	1-Apr-2011	KNR	48	60	LP 1512 TC/59 BSII	01E62883265	MAT461302A0E10764	77
3832	RNC722	KL-15	9127	TATA	ORD	ABUS	16-Apr-2011	KNR	48	60	LP 1512 TC/59 BSII	01D62873132	MAT461302A0E10518	77
3833	RAK490	KL-15	7754	LL	ORD		27-May-2009	KTP	48	60	ALPSV 4/100 W06ETI BSII	LXH 572700	LXE 669907	14
3834	RAK580	KL-15	7780	LL	ORD		3-Jun-2009	KMY	48	60	HINO EURO VIKING BSII	LXH 573165	LXE 670053	05
3835	RNC 46	KL-15	8488	LL	ORD	ABUS	15-Jul-2010	PBVR	48	60	ALPSV 4/89 VIKING	YXH 609027	MB1PBEHC0AHVA9386	59
3836	RNC 47	KL-15	8489	LL	ORD	ABUS	15-Jul-2010	MVPA	48	60	ALPSV 4/89 VIKING	XUH 609648	MB1PBEHC8AHVA9460	52
3837	RNE 53	KL-15	8516	LL	ORD	ABUS	27-Jul-2010	VJMD	48	60	ALPSV W06ETI BSII	XUH 609026	MB1PBEHC2AHVA9387	16
3838	RNC720	KL-15	9138	TATA	ORD	ABUS	10-May-2011	NPR	48	66	LP 1612 TC/59 BSII	01D62873198	MAT461302A0E10616	62
3839	RNC769	KL-15	9201	TATA	ORD	ABUS	26-Aug-2011	KYLM	48	60	LP 1512 TC/59 BSIII	01F62888615	MAT461302A0G12850	41
3840	RNC674	KL-15	9018	TATA	ORD	ABUS	8-Feb-2011	VZM	48	60	LP 1512 TC/59 BSIII	01D62873127	MAT461302A0E10746	24
3841	RNC675	KL-15	9019	TATA	ORD	ABUS	8-Feb-2011	PBVR	48	60	LP 1512 TC/59 BSIII	01D62873126	MAT461302A0E10516	59

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3842	RNE 44	KL-15	8504	LL	ORD	ABUS	20-Jul-2010	MVPA	48	60	EURO BSII ALPSV 4/106	UXH 605222	MB1PBEHC8AH9A7753	52
3843	RNE 40	KL-15	8502	LL	ORD	ABUS	20-Jul-2010	CTY	48	60	HINO BSII	UXH 605219	MB1PBEHC1AH9A7514	28
3844	RAK 99	KL-15	7479	LL	ORD		24-Feb-2009	TPLM	48	60	HINO EURO	BNE 103618Z	BNE 665304	94
3845	RAK415	KL-15	7591	LL	ORD		1-Apr-2009	VDA	48	60	HINO EURO BSII	ZNE 104197Z	YNE 667570	92
3846	RAK579	KL-15	7779	LL	ORD		3-Jun-2009	MNR	48	60	HINO EURO BSII	LXH 572346	LXE 667345	60
3847	RNE 52	KL-15	8417	LL	ORD	ABUS	29-Jun-2010	CTY	48	60	HINO EURO BSII	XUH 609025	MB1PBEHC9AHVA9399	28
3848	RNE 41	KL-15	8433	LL	ORD	ABUS	6-Jul-2010	ARND	48	60	HINO EURO BSII	FMH 199489	MB1PBEHCOAH947567	19
3849	RNE 51	KL-15	8541	LL	CFP	ABUS	6-Aug-2010	PPD	53	60	HINO EURO BSII	XUH 609646	MB1PBEHC4AHVA9455	26
3850	RAK421	KL-15	7693	LL	ORD		6-May-2009	PALA	48	60	HINO EURO BSII VIKING	NXE 105287Z	NXE 669214	50
3851	RAK729	KL-15	7890	LL	ORD		7-Aug-2009	TVL	48	60	HINO EURO BSII VIKING	LXH 573751	KYE 670828	43
3852	RNC 34	KL-15	8368	LL	ORD	ABUS	7-Jun-2010	KKLM	48	60	HINO EURO II	UXH 605224	MB1PBEHC9AH9A7518	108
3853	RAK727	KL-15	7889	LL	ORD		4-Aug-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	LXH 573576	LXE 670589	47
3854	RAK675	KL-15	7873	LL	ORD		17-Jul-2009	ARND	48	60	HINO EURO II TURBO INTER COOLER	CNH 559582	LXE 670241	19
3855	RAK726	KL-15	7878	LL	ORD		22-Jul-2009	KTM	48	60	HINO EURO II TURBO INTER COOLER	LXH 572240	LXE 670601	47
3856	RAK578	KL-15	7778	LL	ORD		3-Jun-2009	TDP	48	60	HINO EURO VIKING	LXH 572203	LXE 652131	53
3857	RAK240	KL-15	7711	LL	ORD		15-May-2009	KTP	48	60	HINO EURO VIKING	NXE 105276Z	NXE 669215	14
3858	RAK488	KL-15	7733	LL	ORD		20-May-2009	VJMD	48	60	HINO EURO VIKING	NXE 105276Z	NXE 669215	16
3859	RAK489	KL-15	7739	LL	ORD		22-May-2009	MDY	48	60	HINO EURO VIKING	LXH 572210	LXE 670036	76
3860	RAK239	KL-15	7710	LL	ORD		15-May-2009	NDD	48	60	HINO EURO VIKING	10VHX7828	NXE 669247	31
3861	RAK581	KL-15	7784	LL	ORD		12-Jun-2009	EKM	48	60	HINO EURO VIKING	LXH 573253	LXE 670266	56
3862	RAK419	KL-15	7663	LL	ORD		27-Apr-2009	KMGH	48	60	HINO EURO VIKING BSII	XNE 104907Z	NXE 668407	55
3863	RAK416	KL-15	7620	LL	ORD		15-Apr-2009	KTM	48	60	HINO EURO/VIKING BSII	XNE 104918Z	NXE 668465	47
3864	RAK156	KL-15	7504	LL	ORD		2-Mar-2009	KNR	48	60	HINO W06ETI BSII	BNE 103643Z	BNE 665335	77
3865	RAK312	KL-15	7512	LL	ORD		4-Mar-2009	MDY	48	60	HINO W06ETI BSII	MNE 100150Z	ZNE 666320	76
3866	RAK315	KL-15	7554	LL	ORD		19-Mar-2009	KLM	48	60	HINO W06ETI BSII	ZNE 104376Z	ZNE 667915	34
3867	RAK412	KL-15	7572	LL	ORD		26-Mar-2009	TLY	48	60	HINO EURO BSII	ZNE 104375Z	XNE 667400	18
3868	RAK413	KL-15	7589	LL	ORD		1-Apr-2009	CHRY	48	60	HINO W06ETI BSII	YNE 104602Z	XNE 667913	44
3869	RAK577	KL-15	7769	LL	ORD		1-Jun-2009	VDA	48	60	HINO W06ETI BSII			92
3870	RAK672	KL-15	7838	LL	ORD		29-Jun-2009	PLD	48	60	HINO W06ETI BSII	NXE 105283Z	NXE 669308	32
3871	RAK420	KL-15	7692	LL	ORD		6-May-2009	MLTM	48	60	HINO W06ETI BSII	NXH 571569	NXE 669082	54
3872	RAK725	KL-15	7883	LL	ORD		30-Jul-2009	VLND	48	60	HINO W06ETI BSII	LXH 573670	KXE 670791	20
3873	RAK674	KL-15	7858	LL	ORD		8-Jul-2009	VLND	48	60	HINO W06ETI BSII	LXE 105771Z	LXE 670495	20
3874	RAK724	KL-15	7877	LL	ORD		22-Jul-2009	KNR	48	60	HINO W06ETI BSII	LXE 105918Z	KXE 670792	77
3875	RNE 39	KL-15	8414	LL	CFP	ABUS	29-Jun-2010	CTY	53	66	HINO W06ETI BSII	UGH 0324	MB1PBEHC3AH9A7515	28
3876	RNE 45	KL-15	8415	LL	CFP	ABUS	29-Jun-2010	PPD	53	66	HINO W06ETI BSII	UXH 605226	MB1PBEHC9AH9A7678	26
3877	RAK418	KL-15	7644	LL	ORD		21-Apr-2009	MNR	48	60	LL HINO/E BSII	VPH 488174	NXE 668399	60
3878	RNC684	KL-15	9055	TATA	ORD	ABUS	3-Mar-2011	KHD	48	60	LP 1512 TC/59 BSIII	01D62873123	MAT461302A0E10684	106
3879	RNC761	KL-15	9177	TATA	ORD	ABUS	4-Jul-2011	ATL	48	60	LP 1612 TC/59 BSIII	01D62873217	MAT461302A0E10470	33
3880	RNC773	KL-15	9195	TATA	ORD	ABUS	24-Aug-2011	TSY	48	60	LP 1512 TC/59 BSIII	01F62888610	MAT461302A0G12783	73
3881	RNC775	KL-15	9196	TATA	ORD	ABUS	24-Aug-2011	ATL	48	60	LP 1612 TC/62 BSII	01D62873122	MAT461302A0G12669	33
3882	RNC776	KL-15	9197	TATA	ORD	ABUS	24-Aug-2011	CTY	48	60	LP 1512 TC/59 BSIII	01D62873208	MAT461302A0G12786	28
3883	RNC779	KL-15	9199	TATA	ORD	ABUS	26-Aug-2011	CLDY	48	60	LP 1612 TC/62 BSII	01D62873218	MAT461302A0E10745	58
3884	RNC778	KL-15	9200	TATA	ORD	ABUS	26-Aug-2011	SBY	48	60	LP 1512 TC/59 BSII	01D62873134	MAT461302A0G12627	75
3885	RNC762	KL-15	9162	TATA	ORD	ABUS	7-Jun-2011	TSY	48	6	LP 1612 TC/59 BSIII	01F62888604	MAT461302A0E12851	73
3886	RNC764	KL-15	9175	TATA	ORD	ABUS	30-Jun-2011	CTY	48	60	LP 1612 TC/59 BSIII	01D62888504	MAT461302A0G12924	28

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3887	RNC756	KL-15	9172	TATA	ORD	ABUS	25-Jun-2011	VJMD	48	60	LP 1612 TC/59 BSIII	01D62873192	MAT461302A0E10617	16
3888	RNC760	KL-15	9176	TATA	ORD	ABUS	4-Jul-2011	KKD	48	60	LP 1612 TC/59 BSIII	01D62873199	MAT461302A0E10682	72
3889	RNC772	KL-15	9183	TATA	ORD	ABUS	22-Jul-2011	KHD	48	60	LP 1512 TC/59 BSIII	01D62873130	MAT461302A0G12780	106
3890	RNC774	KL-15	9184	TATA	ORD	ABUS	22-Jul-2011	KGD	48	60	LP 1512 TC/59 BSIII	01D62873215	MAT461302A0E10683	84
3891	RNC719	KL-15	9202	TATA	ORD	ABUS	26-Aug-2011	CHRY	48	60	LP 1612 TC/59 BSIII	01D62873213	MAT461302A0E10615	44
3892	RNC780	KL-15	9198	TATA	ORD	ABUS	26-Aug-2011	KPM	48	60	LP 1512 TC/62 BSII	01F62888599	MAT461302A0G12781	91
3893	RNC676	KL-15	9151	TATA	ORD	ABUS	26-May-2011	PNR	48	66	LP 1612 TC/59 BSIII	01D62873221	MAT461302A0E10467	78
3894	RNC759	KL-15	9161	TATA	ORD	ABUS	7-Jun-2011	PNR	48	66	LP 1612 TC/59 BSIII	01D62873223	MAT461302A0E10515	78
3895	RNC718	KL-15	9047	TATA	ORD	ABUS	23-Feb-2011	NPR	48	60	LP 1512 TC/59 BSIII	01D62873195	MAT461302A0E10466	62
3896	RNC677	KL-15	9046	TATA	ORD	ABUS	23-Feb-2011	TLY	48	60	LP 1512 TC/59 BSIII	01D62873201	MAT461302A0E10747	18
3897	RNC662	KL-15	8986	TATA	ORD	ABUS	22-Jan-2011	VZM	48	60	LP CUMMINS 1612 TC/59 BSII	01F62888609	MAT461302A0G13782	24
3898	RAK423	KL-15	7684	LL	ORD		4-May-2009	TSY	48	60	VIKING HINO EURO BSII		NKE 669255	73
3899	RAK422	KL-15	7688	LL	ORD		5-May-2009	VKM	48	60	VIKING HINO EURO BSII	CXE 108904Z	NXE 669032	51
3900	RAC549	KL-15	7694	LL	ORD		6-May-2009	VTRA	48	60	HINO BSII TURBO INTER COOLER	LXH 572405	LXE 670155	17
3901	RAC502	KL-15	7642	LL	ORD		20-Apr-2009	CHRY	48	60	HINO BSII TURBO INTER COOLER	LXE 105723Z	LXE 670592	44
3902	RAC745	KL-15	7900	LL	ORD		20-Aug-2009	KKLM	48	60	HINO BSII TURBO INTER COOLER	KXH 574243	KXE 671511	108
3903	RAC781	KL-15	7917	LL	ORD		31-Aug-2009	VKM	48	60	HINO BSII TURBO INTER COOLER	CXE 108799Z	MB1PBEHC29ECA5167	51
3904	RNE653	KL-15	8926	LL	ORD		20-Dec-2010	NTA	48	60	ALPSV 4/89 VIKING BSII	NAE130686Z	MB1PBEHC1AEMD5820	22
3905	RNE652	KL-15	8927	LL	ORD		21-Dec-2010	NTA	48	60	ALPSV 4/89 VIKING BSII	MAE132397Z	MB1PBEHC7AEMD7524	22
3906	RNE654	KL-15	8943	LL	ORD		31-Dec-2010	PTA	48	60	HINO EURO II	MAE132355Z	MB1PBEHC6AEMD7501	37
3907	RNC852	KL-15	9295	LL	ORD		12-Dec-2011	TVL	48	60	HINO 6ETI3K BSIII	MBE159629Z	MB1PBEYC6BEMG4862	43
3908	RNC853	KL-15	9296	LL	ORD		13-Dec-2011	KKLM	48	60	HINO 6ETI3K BSIII	BMEZ400241	MB1PBEYC8BEMG5141	108
3909	RNE892	KL-15	9394	LL	ORD		21-Feb-2012	MKD	48	66	HINO BSIII	BMEZ401402	MAT4126214BECG6459	08
3910	RNE893	KL-15	9400	LL	ORD		23-Feb-2012	MKD	48	66	LL HINO BSIII	BCEZ401558	MB1PBEYC4BECG6588	08
3911	RNE894	KL-15	9401	LL	ORD		25-Feb-2012	MKD	48	66	HINO BSIII	BCEZ401552	MB1PBEYC1BECG6581	08
3912	RNE895	KL-15	9410	LL	ORD		8-Mar-2012	ALV	48	66	HINO 6ETI3K BSIII	BCEZ401640	MB1PBEYC1BEMG6676	61
3913	RNE896	KL-15	9416	LL	ORD		12-Mar-2012	CGNR	48	66	HINO 6ETI3K BSIII	BCEZ401859	MB1PBEYC9BECG7008	40
3914	RNC319	KL-15	8556	TATA	ORD		11-Aug-2010	TSY	48	60	6BT CUMMINS BSII	O1C62853519	MAT412088A0C06757	73
3915	RNC354	KL-15	8563	LL	ORD		13-Aug-2010	EKM	48	60	LL BSIII	VAH617612	MB1PBEHC5AESD0561	56
3916	RNC357	KL-15	8573	LL	ORD		17-Aug-2010	KMY	48	60	LL BSIII	PAH636756	MB1PBEHC1AEPD2810	05
3917	RNE781	KL-15	9227	LL	ORD		8-Nov-2011	EKM	48	60	HINO 6ETI3K BSIII	BNH101473	MB1PBEYC1BENG3220	56
3918	RNC355	KL-15	8564	LL	ORD		13-Aug-2010	VTRA	48	60	6HETI BSIII	SAH632486	MB1PBEHC5AESD1094	17
3919	RRC708	KL-15	6872	LL	ORD		15-Apr-2008	PKDA	48	60	ALPSV 4/89 HINO BSII	LNE 100234	LNE 648514	81
3920	RAC749	KL-15	7927	LL	ORD		14-Sep-2009	CGNR	48	60	ALPSV 4/89 HINO EUROII TIC	KXH 106736Z	MB1PBEHC29EJA0142	40
3921	RAC750	KL-15	7928	LL	ORD		14-Sep-2009	CGNR	48	60	ALPSV 4/89 HINO EUROII TIC	KXE 106719Z	MB1PBEHC19EJA0102	40
3922	RRC721	KL-15	6879	LL	ORD		16-Apr-2008	PKDA	48	60	ALPSV 4/89 HINO W06 BSII	LNE 100245	LNE 648612	81
3923	RAK 98	KL-15	7308	LL	ORD		29-Dec-2008	MKD	48	60	ALPSV 4/89 HINO W06ETI BSII	BNE 103715Z	BNE 665490	08
3924	RAC290	KL-15	7449	LL	ORD		16-Feb-2009	PTA	48	60	ALPSV 4/89 HINO W06ETI BSII	ZNE 104399Z	YNE 667399	37
3925	RRK750	KL-15	6915	LL	ORD		26-Apr-2008	PKDA	48	60	ALPSV 4/89 VIKING	PNH 511627	PNE 643799	81
3926	RRK902	KL-15	7061	LL	ORD		24-Jun-2008	EMLY	48	60	ALPSV 4/89 VIKING	JNH 541433	JNE 653860	95
3927	RRK949	KL-15	7161	LL	ORD		1-Sep-2008	MPM	48	60	ALPSV 4/89 VIKING	JNH 539347	JNE 655544	71
3928	RAK 80	KL-15	7267	LL	ORD		10-Dec-2008	KMGD	48	60	ALPSV 4/89 VIKING	BNE 103590Z	BNE 665249	55
3929	RNK449	KL-15	8725	LL	ORD		12-Oct-2010	NDD	48	60	ALPSV 4/89 VIKING	NAE130119Z	MB1PBEHCXAEND5236	31
3930	RNE655	KL-15	8968	LL	ORD		13-Jan-2011	MPM	48	60	ALPSV 4/89 VIKING E-II	MAE132037Z	MB1PBEHCXAEMD7548	71
3931	RNK698	KL-15	9067	LL	ORD		8-Mar-2011	NTA	48	60	BSII	NAE130546Z	MB1PBEHCXAEND5673	22

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3932	RNC316	KL-15	8542	TATA	ORD		6-Aug-2010	PPD	48	60	LP 1512 TC/59 BSIII	O1C62854407	MAT412088A0C07151	26
3933	RNC358	KL-15	8579	LL	CFP		19-Aug-2010	PPD	53	66	BSIII	GAEZ413608	MB1PBEHC3AEPD2579	26
3934	RNA 32	KL-15	8225	TATA	ORD		10-Mar-2010	VZM	48	60	LP 1512 TC/59 BSII	62349100	MAT412085A0A01662	24
3935	RNC317	KL-15	8531	TATA	ORD		2-Aug-2010	GVR	48	60	LP 1512 TC/59 BSIII	90J62793793	MAT412088A0C06754	66
3936	RNC248	KL-15	8528	TATA	ORD		30-Jul-2010	KMR	48	60	LP 1512 TC/59 BSIII	M62726268	MAT412088A0C06756	30
3937	RNC315	KL-15	8529	TATA	ORD		31-Jul-2010	VLND	48	60	LP 1512 TC/59 BSIII	O1C62854406	MAT412088A0C06751	20
3938	RNE424	KL-15	8728	LL	ORD		12-Oct-2010	KDLR	48	60	EURO BSII	WAH1614449	MB1PBEHCXAEWC3932	90
3939	RNE651	KL-15	8948	LL	ORD		3-Jan-2011	KDLR	48	60	EURO BSII	MAE132388Z	MB1PBEHC9AEMD7525	90
3940	RNE656	KL-15	8985	LL	ORD		21-Jan-2011	PALA	48	60	EURO BSII	MAE130894Z	MB1PBEHC3AEMD6015	50
3941	RNE733	KL-15	9090	LL	ORD		21-Mar-2011	TPLM	48	60	EURO BSII	MAE132287Z	MB1PBEHC6AEMD7417	94
3942	RNE782	KL-15	9232	LL	ORD		10-Nov-2011	MVK	48	60	HINO 6ET13K BSIII	NBE158156Z	MB1PBEYC8BENG3280	88
3943	RAC723	KL-15	7880	LL	ORD		23-Jul-2009	MDY	48	60	HINO BS II	KXE 1065772	KXE 672517	76
3944	RAC233	KL-15	7407	LL	ORD	VND	29-Jan-2009	PTA	48	60	HINO BSII	ZNH 567841	ZNE 666674	37
3945	RAC260	KL-15	7425	LL	ORD	VND	3-Feb-2009	PTA	48	60	HINO BSII	XVH 248673	ZXE 1119682	37
3946	RAK311	KL-15	7463	LL	ORD	VND	19-Feb-2009	KTR	48	60	HINO BSII	ZNE 104135Z	ZNE 666570	35
3947	RAC503	KL-15	7657	LL	ORD		23-Apr-2009	PALA	48	60	HINO BSII	NXE 105197Z	NXE 669042	50
3948	RAC548	KL-15	7679	LL	ORD	VND	2-May-2009	KTR	48	60	HINO BSII	LXH 572306	LXE 670154	35
3949	RAC746	KL-15	7926	LL	ORD		14-Sep-2009	ARND	48	60	HINO BSII	KXH 574790	KXE 672105	19
3950	RNK304	KL-15	8507	LL	ORD		21-Jul-2010	VTRA	48	60	HINO BSII	WAE120664Z	MB1PBEHC7AEVC4680	17
3951	RNK329	KL-15	8552	LL	ORD		10-Aug-2010	KTP	48	60	HINO BSII	NPH508715	MB1PBEHC6AEVC6131	14
3952	RNK330	KL-15	8565	LL	ORD		16-Aug-2010	ANK	48	60	HINO BSII	VAE121868Z	MB1PBEHC1AEVC6358	57
3953	RNK361	KL-15	8574	LL	ORD		18-Aug-2010	ANK	48	60	HINO BSII	VAE121874Z	MB1PBEHCXAEVC6357	57
3954	RNK363	KL-15	8608	LL	ORD		3-Sep-2010	VLRD	48	60	HINO BSII	WAE120199Z	MB1PBEHC4AEVC4087	93
3955	RNK411	KL-15	8798	LL	ORD		10-Nov-2010	TDY	48	60	HINO BSII	VAE120832Z	MB1PBEHCXAEVC4852	79
3956	RNK412	KL-15	8799	LL	ORD		10-Nov-2010	VDA	48	60	HINO BSII	VAE120708Z	MB1PBEHCXAEVC4771	92
3957	RNE727	KL-15	9063	LL	ORD		8-Mar-2011	KNPY	48	60	HINO BSII	MAE132350Z	MB1PBEHC1AEMD7549	87
3958	RNE728	KL-15	9087	LL	ORD		21-Mar-2011	KTR	48	60	HINO BSII	MAE132280Z	MB1PBEHC8AEMD7547	35
3959	RNC356	KL-15	8567	LL	ORD		16-Feb-2010	MDY	48	60	HINO BSIII 6HETI	PAH636770	MB1PBEHC0AEPD2880	76
3960	RRK837	KL-15	7044	LL	ORD		17-Jun-2008	TLY	48	60	HINO EURO BSII	KNH 533605	KNE 651490	18
3961	RRE883	KL-15	7058	LL	ORD		23-Jun-2008	KTR	48	60	HINO EURO BSII	JNH 541527	JNE 653859	35
3962	RAK244	KL-15	7435	LL	ORD		9-Feb-2009	TSY	48	60	HINO EURO BSII	ZNE 104343Z	YNE 667394	73
3963	RAK243	KL-15	7428	LL	ORD		4-Feb-2009	SBY	48	60	HINO EURO BSII	CNH 561127	ZNE 666591	75
3964	RNK362	KL-15	8607	LL	ORD		3-Sep-2010	KTP	48	60	HINO EURO BSII TURBO INTER COOLER	VAE121429Z	MB1PBEHC1AEVC5940	14
3965	RNE461	KL-15	8726	LL	ORD		12-Oct-2010	PVM	48	60	HINO EURO BSII	NAE129742Z	MB1PBEHC2AEND4839	83
3966	RNE462	KL-15	8727	LL	ORD		12-Oct-2010	EMLY	48	60	HINO EURO BSII	NAE130120Z	MB1PBEHC5AEND5239	95
3967	RAC211	KL-15	7384	LL	ORD		21-Jan-2009	KLM	48	60	HINO EURO BSII ALPSV 4/89	ZNE 104143	ZNE 666690	34
3968	RAC560	KL-15	7725	LL	ORD		16-May-2009	KKLM	48	60	HINO EURO BSII ALPSV 4/89	LXH 573243	LXE 670240	108
3969	RAC766	KL-15	7923	LL	ORD		10-Sep-2009	TPLM	48	60	HINO EURO BSII ALPSV 4/89	KZE 1067423	MB1PBEHC19EJAO150	94
3970	RAK673	KL-15	7857	LL	ORD		20-Jul-2009	PBVR	48	60	HINO EURO BSII TURBO INTER COOLER	LXH 573583	LXE 670591	59
3971	RAC504	KL-15	7658	LL	ORD		24-Apr-2009	EKM	48	60	HINO EURO II ALPSV 4/89	LXH 572351	LXE 670116	56
3972	RAK155	KL-15	7319	LL	ORD		30-Dec-2008	PNI	48	60	HINO EURO II	CNH 560614	BNE 665157	67
3973	RAC391	KL-15	7548	LL	ORD		17-Mar-2009	PALA	48	60	HINO BSII TURBO INTER COOLER	XNE 104909Z	NXE 668398	50
3974	RNC352	KL-15	8557	LL	ORD		11-Aug-2010	KLM	48	60	HINO EURO II TURBO INTER COOLER	VAE120671Z	MB1PBEHC0AEVC4679	34
3975	RNC353	KL-15	8559	LL	ORD		12-Aug-2010	KLM	48	60	HINO EURO II TURBO INTER COOLER	VAE121947Z	MB1PBEHC0AEVC6478	34
3976	RAK313	KL-15	7525	LL	ORD		9-Mar-2009	PNR	48	60	HINO EURO VIKING BSII	ZNE 104378Z	YNE 667558	78

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
3977	RAK314	KL-15	7537	LL	ORD		13-Mar-2009	CDLM	48	60	HINO EURO VIKING BSII	ZNE 104191Z	YNE 667402	80
3978	RAC547	KL-15	7673	LL	ORD		29-Apr-2009	SBY	48	60	HINO EURO W06ETI BSII	LXH 572783	LXE 670087	75
3979	RAC396	KL-15	7596	LL	ORD		1-Apr-2009	EKM	48	60	HINO EUROII ALPSV 4/89	NXE 105218Z	NXE 669035	56
3980	RAC550	KL-15	7691	LL	ORD		8-May-2009	KMGH	48	60	HINO EUROII ALPSV 4/89	LXH 573250	LXE 670234	55
3981	RAC559	KL-15	7724	LL	ORD		16-May-2009	EKM	48	60	HINO EUROII ALPSV 4/89	LXH 573178	LXE 670135	56
3982	RAC767	KL-15	7929	LL	ORD		14-Sep-2009	VLND	48	60	HINO EUROII ALPSV 4/89	KXE 106728Z	MB1PBEHC89EJA0145	20
3983	RRE881	KL-15	7050	LL	ORD		19-Jun-2008	ALP	48	60	HINO W06ETI BSII	KNH 535555	JNE 653604	45
3984	RRE882	KL-15	7051	LL	ORD		20-Jun-2008	TLY	48	60	HINO W06ETI BSII	JNH 541435	JNE 653603	18
3985	RRE943	KL-15	7147	LL	ORD		25-Aug-2008	MPM	48	60	HINO W06ETI BSII	JNH 538741	JNE 654226	71
3986	RRE998	KL-15	7191	LL	ORD		29-Sep-2008	MVK	48	60	HINO W06ETI BSII	KNH 534965	JNE 654632	88
3987	RAK158	KL-15	7339	LL	ORD		6-Jan-2009	MDY	48	60	HINO W06ETI BSII	BNE 103591Z	BNE 665236	76
3988	RAK161	KL-15	7372	LL	ORD		15-Jan-2009	SBY	48	60	HINO W06ETI BSII	ZNE 104110Z	BNE 666577	75
3989	RAK153	KL-15	7310	LL	ORD		29-Dec-2008	MNR	48	60	HINO W06ETI BSII	CNH 565662	BNE 665310	60
3990	RAK241	KL-15	7418	LL	ORD		2-Feb-2009	KNR	48	60	HINO W06ETI BSII	ZNE 104274Z	YNE 667351	77
3991	RAC268	KL-15	7440	LL	ORD	VND	11-Feb-2009	PBVR	48	60	HINO W06ETI BSII	ZNE 104424Z	YNE 667350	59
3992	RAC291	KL-15	7450	LL	ORD		16-Feb-2009	MDY	48	60	HINO W06ETI BSII		ZNE 666574	76
3993	RAC389	KL-15	7546	LL	ORD		16-Mar-2009	NDD	48	60	HINO W06ETI BSII	XNE 104852Z	NXE 668468	31
3994	RAC393	KL-15	7593	LL	ORD		1-Apr-2009	PMNA	48	60	HINO W06ETI BSII	NXE 105194Z	NXE 669050	68
3995	RAC557	KL-15	7718	LL	ORD		15-May-2009	VJMD	48	60	HINO W06ETI BSII	LXE 105727Z	LXE 670494	16
3996	RAC563	KL-15	7721	LL	ORD		15-May-2009	MDY	48	60	HINO W06ETI BSII	LXH 572316	LXE 670133	76
3997	RNK235	KL-15	8443	LL	ORD		7-Jul-2010	NDD	48	60	HINO W06ETI BSII	VAE121546Z	MB1PBEHC6AEVC5884	31
3998	RAK414	KL-15	7590	LL	ORD		1-Apr-2009	VLRD	48	60	HINO W06ETI BSII	ZNE 104364Z	XNE 667916	93
3999	RAC232	KL-15	7401	LL	ORD		27-Jan-2009	KMY	48	60	HINO W06ETI BSII ALPSV 4/89	ZNH 567940	ZNE 666760	05
4000	RRE923	KL-15	7090	LL	ORD		22-Jul-2008	PNI	48	60	HINO W06ETI BSII	VPH 7153D3363	JNE 654699	67
4001	RRE927	KL-15	7094	LL	ORD		25-Jul-2008	ARND	48	60	HINO W06ETI BSII	JNH 540218	JNE 654193	19
4002	RRE855	KL-15	7031	LL	ORD		12-Jun-2008	KMY	48	60	HINO W06WTI BSII	KNH 533540	KNE 651488	05
4003	RNK303	KL-15	8506	LL	ORD		21-Jul-2010	VLND	48	60	LL BSII	WAE120126Z	MB1PBEHC8AEWC4027	20
4004	RNK328	KL-15	8551	LL	ORD		10-Aug-2010	KMY	48	60	LL BSII	WAE120017Z	MB1PBEHC5AEWC3868	05
4005	RNK446	KL-15	8722	LL	ORD		12-Oct-2010	MVPA	48	60	LL BSII 222	NAE130920Z	MB1PBEHC3AEAMD6001	52
4006	RNK364	KL-15	8609	LL	ORD		3-Sep-2010	HPD	48	60	LL EURO II	4FH409595	MB1PBEHCXAEVC4690	42
4007	RNE621	KL-15	8921	LL	ORD		18-Dec-2010	ALP	48	60	LL EURO II	NAE129991Z	MB1PBEHC3AEND5093	45
4008	RNE657	KL-15	8999	LL	ORD		29-Jan-2011	ALP	48	60	LL EURO II	NAE130586Z	MB1PBEHC5AEAMD5819	45
4009	RNE726	KL-15	9000	LL	ORD		29-Jan-2011	TSY	48	60	LL HINO BSII	MAE132170Z	MB1PBEHC3AEAMD7309	73
4010	RNK697	KL-15	9066	LL	ORD		8-Mar-2011	PSL	48	60	LL HINO BSII	MAE132353Z	MB1PBEHC4AEAMD7500	21
4011	RNK447	KL-15	8723	LL	ORD		12-Oct-2010	PVR	48	60	LL HINO EURO BSII	NAE129658	MB1PBEHC1AEND4735	23
4012	RNK448	KL-15	8724	LL	ORD		12-Oct-2010	PVR	48	60	LL HINO EURO BSII	NAE129737Z	MB1PBEHC0AEND4841	23
4013	RNE623	KL-15	8923	LL	ORD		18-Dec-2010	CTY	48	60	LL HINO EURO BSII	NAE129934Z	MB1PBEHC8AEND4991	28
4014	RAK417	KL-15	7643	LL	ORD		21-Apr-2009	TDY	48	60	LL HINO/E BSII	ZNE 104343Z	NXE 668469	79
4015	RNA 37	KL-15	8258	TATA	ORD		17-Apr-2010	VKM	48	60	LP 1512 TC/59 BSII	01A62829027	MAT412085A0B02798	51
4016	RNA 38	KL-15	8265	TATA	ORD		21-Apr-2010	CTY	48	60	LP 1512 TC/59 BSII	90M62822221	MAT412085A0B02999	28
4017	RNC987	KL-15	9419	LL	ORD		16-Mar-2012	MKD	48	60	HINO 6ETI3K BSIII	BMEZ400558	MB1PBEYCXBEMG5710	08
4018	RNE897	KL-15	9421	LL	ORD		15-Mar-2012	PKDA	48	66	HINO 6ETI3K BSIII	BCEZ401859	MB1PBEYCBCECG7006	81
4019	RNC989	KL-15	9427	LL	ORD		24-Mar-2012	CDLM	48	66	HINO 6ETI3K BSIII	BMEZ400765	MB1PBEYCBEMG5713	80
4020	RNE898	KL-15	9431	LL	ORD	VND	26-Mar-2012	KTR	48	60	HINO6ETI3KBSIII	BCHZ105205	MB1PBEYCBCECG7069	35
4021	RNE916	KL-15	9434	LL	ORD		29-Mar-2012	PNR	53	66	HINO 6ETI3K BSIII	BCHZ105415	MB1PBEYCBCECG7156	78

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4022	RNE917	KL-15	9435	LL	ORD	PINK	3-Apr-2012	NTA	48	66	HINO 6ETI BSIII	BCEZ402045	MB1PBEYC5BECG7295	22
4023	RNE918	KL-15	9454	LL	ORD		12-Apr-2012	PNI	48	60	HINO 6ETI BSIII	BCHZ105204	MB1PBEYC3BECG7070	67
4024	RSC 9	KL-15	9455	LL	ORD		13-Apr-2012	IJK	53	66	6ETI 3K BSIII	BCEZ401643	MB1PBEYCXBECG6675	89
4025	RNE919	KL-15	9463	LL	ORD		17-Apr-2012	ATL	48	60	ALPSV 4/89 VIKING BSIII	BCHZ105854	MB1PBEYC5BECG7538	33
4026	RSC 7	KL-15	9469	LL	ORD	MLB	24-Apr-2012	SBY	48	60		BCEZ401602	WB1PBEYC5BECG6647	75
4027	RSC 17	KL-15	9475	LL	ORD		26-Apr-2012	VDA	48	60		BCHZ105309	MB1PBEYC9BECG7073	92
4028	RSC 45	KL-15	9489	LL	ORD		4-May-2012	MVK	53	66		BCHZ105440	MB1PBEYC2BECG7447	88
4029	RSC 47	KL-15	9490	LL	ORD		7-May-2012	TDP	53	66		BCHZ105422	MB1PBEYC4BECG7157	53
4030	RNE945	KL-15	9506	LL	ORD		14-May-2012	VTRA	48	60	ALPSV 4/89 VIKING BSIII	BCEZ402626	MBIPBEYCXBECG7857	17
4031	RNE946	KL-15	9513	LL	ORD		17-May-2012	ADR	53	66	HINO BSIII	BCHZ106809	MB1PBEYC7BECG8013	38
4032	RNE947	KL-15	9517	LL	ORD		19-May-2012	PALA	53	66	HINO 6ETI3K BSIII TURBO INTER COOLER	BCEZ102744	MBIPBEYC1BECG7858	50
4033	RNE957	KL-15	9520	LL	ORD		22-May-2012	PMNA	53	66	HINO 6ETI BSIII	BCEZ402418	MB1PBEYC1BECG7861	68
4034	RNE958	KL-15	9523	LL	ORD		25-May-2012	KPA	53	66		BCHZ106193	MBIPBEYC3BECG8106	74
4035	RNE959	KL-15	9529	LL	ORD		28-May-2012	KTDA	53	66		BCEZ402903	MB1PBEYC3BECG8123	25
4036	RSK 72	KL-15	9530	LL	ORD		30-May-2012	TVL	53	66		BCHZ105544	MB1PBEYC9BECG7364	43
4037	RNE960	KL-15	9537	LL	ORD		31-May-2012	MNR	53	66	HINO EURO BSIII	BCEZ402902	MB1PBEYC1BECG8122	60
4038	RNE961	KL-15	9539	LL	ORD		1-Jun-2012	MPM	53	66		CBEZ401049	MB1PBEYC4CEBG9876	71
4039	RSK 73	KL-15	9540	LL	ORD	VND	4-Jun-2012	PALA	53	66	HINO 6ETI3K BSIII	BCHZ105420	MB1PBEYC9BECG7154	50
4040	RNE962	KL-15	9545	LL	ORD		5-Jun-2012	MKD	48	60	BSIII	CBHZ400659	MB1PBEYC3CEBG9657	08
4041	RSK 74	KL-15	9547	LL	ORD		8-Jun-2012	CHRY	53	66	HINO BSIII VIKING	BCHZ105412	MB1PBEYC0BECG7155	44
4042	RNE963	KL-15	9551	LL	ORD		8-Jun-2012	TVL	48	60	BSIII 222	CBEZ400758	MB1PBEYC6CEBG9653	43
4043	RNE964	KL-15	9552	LL	ORD		11-Jun-2012	TDP	48	60		BCHZ106092	MBIPBEYC1BECG7777	53
4044	RSK 75	KL-15	9559	LL	ORD		14-Jun-2012	CTR	48	60	HINO BS III	BCEZ402709	MB1PBEYC1BECG7908	70
4045	RNE966	KL-15	9562	LL	ORD		16-Jun-2012	KMY	53	66	HINO EURO III	BCEZ402851	MB1PBEYC9BECG8059	05
4046	RSK117	KL-15	9564	LL	ORD		18-Jun-2012	EKM	53	66	HINO BSIII	BCEZ402310	MB1PBEYC9BECG7445	56
4047	RNE965	KL-15	9566	LL	ORD		14-Jun-2012	PNI	53	66	6ETI BSIII	BCHZ 105932	MB1PBEYC3BECG7909	67
4048	RNE967	KL-15	9567	LL	ORD		19-Jun-2012	PLKD	53	66	BS 111	BCEZ402400	MB1PBEYC1BECG7536	69
4049	RSK118	KL-15	9568	LL	ORD		21-Jun-2012	PBVR	48	60	HINO EURO BSIII ALPSV 4/186	BMEZ400907	MB1PBEYC9BECG7770	59
4050	RNE968	KL-15	9570	LL	ORD		22-Jun-2012	GVR	53	66	BSIII	CBHZ100739	MB1PBEYCDCEBG9681	66
4051	RSK119	KL-15	9573	LL	ORD		23-Jun-2012	PNI	53	66	6ETI 3KN BSIII	BCHZ105755	MB1PBEYC4BECG7451	67
4052	RNE994	KL-15	9576	LL	ORD		23-Jun-2012	VZM	53	66	ALPSV 4/186 6ETI BSIII	CBEZ 401113	MB1PBEYCECEBH0141	24
4053	RNE995	KL-15	9579	LL	ORD		25-Jun-2012	PLKD	53	66	BS 111	CBHZ400687	MB1PBEYC9CEBG9730	69
4054	RNE996	KL-15	9580	LL	ORD		26-Jun-2012	PVM	48	60	ALPSV 4/186 6ETI BSIII	CBHZ400652	MB1PBEYC1CEBG9849	83
4055	RSC138	KL-15	9583	LL	ORD		28-Jun-2012	PTA	53	66	6ETI3K LL BSIII	BCHZ105964	MB1PBEYCXBECG7907	37
4056	RNE997	KL-15	9584	LL	ORD		28-Jun-2012	MPM	48	60		CBHZ400608	MB1PBEYC3CEBG9707	71
4057	RSK121	KL-15	9585	LL	ORD		28-Jun-2012	EMLY	48	66	ALPSV 4/186 6ETI BSIII	BCEZ402625	MB1PBEYC3BECG7859	95
4058	RSC137	KL-15	9588	LL	ORD		29-Jun-2012	TLY	48	60		BCHZ106191	MB1PBEYC6BECG8018	18
4059	RSK120	KL-15	9581	LL	ORD		26-Jun-2012	KPA	53	66		BCEZ402306	MB1PBEYC0BECG7446	74
4060	RSK122	KL-15	9598	LL	ORD		2-Jul-2012	SBY	53	66	HINO BSIII	BCHZ106176	MB1PBEYC7BECG7993	75
4061	RSK123	KL-15	9599	LL	ORD		2-Jul-2012	KMY	53	66	HINO 6ETI 3K BSIII	BCHZ106090	MB1PBEYC9BECG7798	05
4062	RSK124	KL-15	9601	LL	ORD		3-Jul-2012	MPM	48	60	HINO BSIII	VBH692958	MBIPBEYC3BECG7294	71
4063	RNE998	KL-15	9602	LL	ORD		3-Jul-2012	PTPM	48	66	HINO 6ETI BSIII	CBEZ401395	MB1PBEYC8CEBH0223	15
4064	RSE 31	KL-15	9610	LL	ORD		5-Jul-2012	KTM	53	66	HINO 6ETI3K BSIII	CBHZ101272	MB1PBEYCXCEBH0143	47
4065	RSE 32	KL-15	9611	LL	ORD		5-Jul-2012	MPM	48	60	HINO BSIII	BCHZ106176	MB1PBEYCXCEBH0109	71
4066	RSE 33	KL-15	9617	LL	ORD		7-Jul-2012	TSY	53	66		CBHZ101273	MB1PBEYCXCEBH0112	73

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4067	RSK160	KL-15	9621	LL	ORD		9-Jul-2012	TDP	53	66		BCHZ105312	MB1PBEYC9BECG7297	53
4068	RSE 34	KL-15	9624	LL	ORD		9-Jul-2012	KMGH	53	66	HINO EURO BSIII ALPSV 4/186	CBHZ100702	MB1PBEYC8CEBG9850	55
4069	RSE 35	KL-15	9625	LL	ORD		10-Jul-2012	EMLY	48	60	ALPSV 4/186 6ETI BSIII	CBHZ400787	MB1PBEYC7CEBG9970	95
4070	RSK161	KL-15	9629	LL	ORD		13-Jul-2012	PALA	53	66		BCHZ106190	MB1PBEYC5BECG8107	50
4071	RSK162	KL-15	9630	LL	ORD		13-Jul-2012	MVPA	53	66	LL BS 111	BCHZ106189	MB1PBEYC1BECG8105	52
4072	RSE125	KL-15	9640	LL	ORD		13-Jul-2012	TSY	53	66		CBHZ100737	MB1PBEYC7CEBG9791	73
4073	RSE126	KL-15	9644	LL	ORD		16-Jul-2012	GVR	53	66	6ETI BSIII	CBEZ401409	MB1PBEYC3CEBH0291	66
4074	RSE127	KL-15	9645	LL	ORD		17-Jul-2012	ATL	53	66	6ETI BSIII	CBEZ401521	MB1PBEYC8CEBHO366	33
4075	RSK163	KL-15	9646	LL	ORD		17-Jul-2012	VKM	48	60	ALPSV 4/186 6ETI BSIII	BCEZ402745	MB1PBEYC3BECG7991	51
4076	RSK164	KL-15	9647	LL	ORD		17-Jul-2012	PKD	48	60	LL HINO BSIII	BCEZ402797	MB1PBEYC4BECG8017	65
4077	RSC184	KL-15	9650	LL	ORD		23-Jul-2012	NTA	53	66	6ETI 3K BSIII	CBHZ100872	MB1PBEYCXCEBG9851	22
4078	RSC185	KL-15	9651	LL	ORD		23-Jul-2012	MDY	48	66	ALPSV 4/186 6ETI BSIII	CBEZ401311	MB1PBEYC8CEBG0108	76
4079	RSC186	KL-15	9652	LL	ORD		23-Jul-2012	VJMD	48	60	ALPSV 4/186 6ETI BSIII	CBHZ400798	MB1PBEYCOCEBG9969	16
4080	RSC201	KL-15	9655	LL	ORD		24-Jul-2012	MDY	53	66	6ETI 3K BSIII	CBHZ100741	MB1PBEYC5CEBG9790	76
4081	RSC128	KL-15	9657	LL	ORD		23-Jul-2012	CGNR	53	66	6ETI BSIII	CBHZ400650	MB1PBEYC1CEBG9639	40
4082	RSE129	KL-15	9658	LL	ORD		23-Jul-2012	RWE	53	66	6ETI BSIII	CBHZ101133	MB1PBEYC9CEBG9971	12
4083	RSE130	KL-15	9659	LL	ORD		23-Jul-2012	TSR	53	66		CBEZ401514	MB1PBEYCOCEBHO359	63
4084	RSK165	KL-15	9660	LL	ORD		24-Jul-2012	KTM	53	66	HINO 6ETI3K BSIII	CBEZ400822	MBIPBEYC6CEBG9636	47
4085	RSK166	KL-15	9661	LL	ORD		24-Jul-2012	KYLM	53	66	HINOEURO III	CBHZ101020	MBIPBEYC3CEBG9853	41
4086	RSC202	KL-15	9665	LL	ORD		26-Jul-2012	NTA	53	66	BSIII	CBEZ400816	MB1PBEYC4CEBG9649	22
4087	RSC203	KL-15	9669	LL	ORD		27-Jul-2012	MKD	48	66	6ETI 3K BSIII	CBEZ401048	MB1PBEYC2CEBG9973	08
4088	RSC204	KL-15	9670	LL	ORD		27-Jul-2012	KPA	53	66		CBHZ100868	MB1PBEYC4CEBH0221	74
4089	RSE131	KL-15	9673	LL	ORD		26-Jul-2012	TSR	53	66		CBHZ401205	MB1PBEYC3CEBH0226	63
4090	RSK167	KL-15	9674	LL	ORD		27-Jul-2012	TSR	53	66	HINO BSIII	CBHZ100748	MB1PBEYC8CEBG9704	63
4091	RSK168	KL-15	9679	LL	ORD		28-Jul-2012	MVPA	53	66		BCEZ402809	MB1PBEYC2BECG8016	52
4092	RSC205	KL-15	9680	LL	ORD		31-Jul-2012	VDCY	48	60	6ETI 3K BSIII	BCHZ106686	MB1PBEYCOCEBG9731	82
4093	RSE132	KL-15	9686	LL	ORD		30-Jul-2012	CTR	53	66	HINO BSIII	CBEZ401517	MB1PBEYCXCEBH0367	70
4094	RSE133	KL-15	9678	LL	ORD		27-Jul-2012	KPM	53	66		CAEZ402189	MB1PBEYC1CEAH1128	91
4095	RSK169	KL-15	9689	LL	ORD		31-Jul-2012	TPLM	53	66	LL BSIII	BCHZ106446	MB1PBEYC5BECG8253	94
4096	RSC206	KL-15	9692	LL	ORD		3-Aug-2012	MVPA	53	66	LL BS 111	CBEZ401053	MB1PBEYC1CEBG9852	52
4097	RSE134	KL-15	9695	LL	ORD		31-Jul-2012	VDA	53	66		CAEZ402545	MB1PBEYC6CEAH1531	92
4098	RSC217	KL-15	9696	LL	ORD		6-Aug-2012	CHRY	53	66	HINO BSIII	CBHZ400692	MB1PBEYC9CEBG9792	44
4099	RSK236	KL-15	9698	LL	ORD		4-Aug-2012	CDLM	53	66	HINO BSIII	BCEZ402801	MB1PBEYC0BECG8015	80
4100	RSE191	KL-15	9699	LL	ORD		3-Aug-2012	MDY	53	66		CAEZ402397	MB1PCEYCACAEH1320	76
4101	RSE192	KL-15	9700	LL	ORD		6-Aug-2012	TDY	53	66	BSIII	CBEZ401406	MB1PBEYC5CEBH0292	79
4102	RSK237	KL-15	9701	LL	ORD		7-Aug-2012	CTR	48	60	HINO BSIII	CBEZ400820	MB1PBEYC8CEBG9640	70
4103	RSE193	KL-15	9704	LL	ORD		9-Aug-2012	MPM	53	66		CAEZ402396	MB1PBEYC3CEAH1387	71
4104	RSK238	KL-15	9705	LL	ORD		9-Aug-2012	IJK	53	66	HINO BSIII	BCHZ105933	MB1PBEYC5BECG7992	89
4105	RSK239	KL-15	9711	LL	ORD		13-Aug-2012	MVPA	48	60	LL BSIII	CBHZ100699	MB1PBEYCXCEBG9705	52
4106	RSE194	KL-15	9726	LL	SFP		14-Aug-2012	PLKD	53	66	BS III	BCHZ105649	MB1PBEYC2BECG7366	69
4107	RSE195	KL-15	9727	LL	SFP		14-Aug-2012	KDLR	53	66		CAEZ402392	MB1PBEYC2CEAH1350	90
4108	RSC300	KL-15	9739	LL	SFP		23-Aug-2012	PLKD	53	66		CBEZ401336	MB1PBEYC1CEBH0225	69
4109	RSE196	KL-15	9740	LL	SFP		23-Aug-2012	PLKD	53	66	BS III	CBHZ101748	MB1PBEYC7CEAH1053	69
4110	RSC301	KL-15	9752	LL	SFP		27-Aug-2012	TSR	53	66	6ETI 3K BSIII	CAEZ402565	MB1PBEYCOCEAH1525	63
4111	RSE197	KL-15	9741	LL	SFP		18-Aug-2012	TSR	53	66	6ETI BSIII	CBEZ402098	MBIPBEYC6CEAH1044	63

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4112	RSC299	KL-15	9759	LL	SFP		4-Sep-2012	GVR	53	66		CAEZ402400	MB1PBEYC8CEAH1319	66
4113	RSE199	KL-15	9760	LL	SFP		27-Aug-2012	KTP	53	66	HINO EURO III	CBEZ402099	MB1PBEYC4CEAH1057	14
4114	RSE200	KL-15	9761	LL	ORD	VND	1-Sep-2012	NTA	53	66	ALPSV 4/186 6ETI BSIII	CBEZ402071	MB1PBEYC2CEAH1042	22
4115	RSC297	KL-15	9762	LL	SFP		5-Sep-2012	MDY	53	66		CBEZ401700	MB1PBEYC3CEBH0579	76
4116	RSC298	KL-15	9766	LL	ORD	VND	6-Sep-2012	KTDA	53	66	ALPSV 4/186 6ETI BSIII	CAEZ402731	MB1PBEYC9CEAH1720	25
4117	RSE198	KL-15	9769	LL	FP		24-Aug-2012	PTA	53	66	ALPSV 4/186 6ETI BSIII	CBHZ101277	MB1PBEYC8CEBH0111	37
4118	RSK334	KL-15	9844	LL	SFP		9-Oct-2012	ARND	53	66	HINO BSIII	CBEZ401462	MB1PBEYC9CEBH0358	19
4119	RSK335	KL-15	9846	LL	SFP		12-Oct-2012	MLPY	53	66		CAEZ401129	MB1PBEYC6CEBG9958	96
4120	RSE303	KL-15	9843	LL	ORD		8-Oct-2012	PKDA	48	66		CAEZ402552	MB1PBEYC9CEAH1040	81
4121	RSE304	KL-15	9849	LL	SFP		11-Oct-2012	PKDA	53	66		CBHZ101793	MB1PBEYC3CEAH0856	81
4122	RSE305	KL-15	9855	LL	SFP		20-Oct-2012	PNR	53	66	ALPSV 4/186 6ETI BSIII	CAEZ402874	MB1PBEYC3CEAH1874	78
4123	RSC356	KL-15	9868	LL	SFP	VND	2-Nov-2012	PALA	53	66	HINO 6ETI3K BSIII	CBEZ401681	MB1PBEYC6CEBH0723	50
4124	RSC395	KL-15	9869	LL	SFP		2-Nov-2012	RWM	53	66		CAEZ403043	MB1PBEYC2CEAH2045	10
4125	RSC396	KL-15	9875	LL	SFP		7-Nov-2012	RWM	53	66		CBEZ402110	MB1PBEYC4CEAH1043	10
4126	RSC397	KL-15	9879	LL	SFP		15-Nov-2012	TVM	53	66	AIPSV 4/186 6ETI BSIII	CAEZ402430	MB1PBEYC7CEAH1389	27
4127	RSC351	KL-15	9881	LL	SFP		17-Nov-2012	SBY	53	66		CAEZ402742	MB1PBEYC6CEAH1724	75
4128	RSC466	KL-15	9943	LL	SFP		25-Mar-2013	TVM	53	66	ALPSV 4/186 6ETI BSIII	CREZ415861	MB1PBEYC4CERJ7043	27
4129	RSC496	KL-15	9969	LL	SFP		27-Apr-2013	GVR	53	66		CREZ415335	MB1PBEYC5CEPJ6323	66
4130	RSC495	KL-15	9971	LL	SFP		29-Apr-2013	KNR	53	66	LL BSIII	CPEZ416829	MB1PBEYC3CEPJ8355	77
4131	RSC497	KL-15	9972	LL	SFP		30-Apr-2013	KNR	53	66	LL BSIII	CDEZ419600	MB1PBEYC5CEDK1233	77
4132	RSC499	KL-15	9973	LL	SFP		2-May-2013	TSY	53	66		CPEZ417134	MB1PBEYC5CEPJ8891	73
4133	RSC498	KL-15	9975	LL	SFP		13-May-2013	KTM	53	66	HINO 6ETI3K BSIII	CDEZ419547	MB1PBEYC5CEDK1216	47
4134	RSC500	KL-15	9976	LL	SFP		13-May-2013	PLKD	53	66	BS III	CSHZ114750	MB1PBEYC2CERJ7073	69
4135	RSK446	KL-15	9980	LL	SFP		20-May-2013	MNR	53	66	HINO EURO BSIII	CREZ415935	MB1PBEYC4CERJ7155	60
4136	RSK447	KL-15	9983	LL	SFP		24-May-2013	ALV	53	66	HINO BSIII	CRHZ116668	MB1PBEYC6CERJ7352	61
4137	RSC512	KL-15	9985	LL	SFP		31-May-2013	MPM	53	66		CPEZ416897	MB1PBEYC9CEPJ8439	71
4138	RSK448	KL-15	9987	LL	SFP		30-May-2013	TSY	53	66		CRHZ416625	MB1PBEYC6CERJ7481	73
4139	RSC511	KL-15	9988	LL	SFP		1-Jun-2013	NTA	53	66		CREZ415962	MB1PBEYC8CERJ7207	22
4140	RSC526	KL-15-A	12	LL	SFP		10-Jun-2013	MDY	53	66		CDEZ419535	MB1PBEYC9CEDK1168	76
4141	RSC527	KL-15-A	15	LL	SFP		12-Jun-2013	TVM	53	66	ALPSV 4/186 6ETI BSIII	CDEZ419967	MBIPBEYC3CEDK1683	27
4142	RSC584	KL-15-A	27	LL	SFP		18-Jun-2013	MALA	53	66		CNEZ418650	MB1PBEYC4CENK0285	85
4143	RSC585	KL-15-A	34	LL	SFP		20-Jun-2013	NBR	53	66		CDEZ420128	MB1PBEYC7CEDK1802	86
4144	RSK577	KL-15-A	36	LL	SFP		20-Jun-2013	TLY	53	66	HINO 6ET13KN BSIII	CREZ416457	MB1PBEYC0CEPJ8068	18
4145	RSC586	KL-15-A	38	LL	SFP		22-Jun-2013	NBR	53	66		CPEZ417417	MB1PBEYC9CEPJ8912	86
4146	RSK578	KL-15-A	44	LL	SFP		24-Jun-2013	SBY	53	66	HINO BSIII	CPEZ416757	MB1PBEYC9CEPJ8893	75
4147	RSC587	KL-15-A	45	LL	SFP		25-Jun-2013	ADR	53	66	6ETI13K (BSIII)	CNEZ418916	MB1PBEYC0CENK0526	38
4148	RSK579	KL-15-A	51	LL	SFP		27-Jun-2013	TLY	53	66	HINO 6ET13KN BSIII	CPEZ417011	MB1PBEYC7CEPJ8441	18
4149	RSC588	KL-15-A	52	LL	SFP		28-Jun-2013	PLKD	53	66	BS 111	CDEZ420046	MB1PBEYC4CEDK1711	69
4150	RSE550	KL-15-A	53	LL	SFP		27-Jun-2013	SBY	53	66	HINO BSIII	CPEZ416811	MB1PSEYC7CEPJ8357	75
4151	RSC590	KL-15-A	54	LL	SFP		29-Jun-2013	TVM	53	66	ALPSV 4/186 6ETI BSIII	CNEZ418652	MB1PBEYC0CENK0283	27
4152	RSC591	KL-15-A	59	LL	SFP		1-Jul-2013	TVM	53	66	ALPSV 4/186 6ETI BSIII	CDEZ420238	MB1PBEYC7CEDK1945	27
4153	RSK580	KL-15-A	60	LL	SFP		1-Jul-2013	MVK	53	66		CPEZ416761	MB1PBEYC6CEPJ8625	88
4154	RSC592	KL-15-A	61	LL	SFP		3-Jul-2013	GVR	53	66		CDEZ419977	MB1PBEYC8CEDK1632	66
4155	RSE551	KL-15-A	62	LL	SFP		2-Jul-2013	KTDA	53	66	BS 111	CPEZ416768	MB1PBEYCXCEPJ8286	25
4156	RSK581	KL-15-A	67	LL	SFP		4-Jul-2013	PNI	53	66	6ETI BKN BSIII	CPEZ417198	MB1PBEYC6CEPJ8690	67

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4157	RSC594	KL-15-A	68	LL	SFP		6-Jul-2013	TSR	53	66		CDEZ419523	MB1PBEYC1CEDK1164	63
4158	RSK582	KL-15-A	70	LL	SFP		8-Jul-2013	KNR	53	66	BSIII	CREZ415736	MB1PBEYC6CERJ6945	77
4159	RSE552	KL-15-A	71	LL	SFP		8-Jul-2013	ALP	53	66		CREZ416648	MB1PBEYC9CEPJ8442	45
4160	RSK638	KL-15-A	76	LL	SFP		12-Jul-2013	GVR	53	66		CREZ415588	MB1PBEYC2CERJ6697	66
4161	RSE553	KL-15-A	79	LL	SFP		16-Jul-2013	TVM	53	66	ALPSV 4/186 BSIII	CPEZ416771	MB1PBEYC3CEPJ8291	27
4162	RSK639	KL-15-A	80	LL	SFP		18-Jul-2013	PALA	53	66	VIKING HINO BSIII	CREZ415298	MB1PBEYC1CERJ6321	50
4163	RSE554	KL-15-A	82	LL	SFP		20-Jul-2013	PNI	53	66	LL BSIII	CPEZ416978	MB1PBEYC2CEPJ8444	67
4164	RSC593	KL-15-A	85	LL	SFP		24-Jul-2013	ETPA	53	66	HA6ETI13KN BSIII	CPEZ417444	MB1PBEYC7CEPJ8892	48
4165	RSC595	KL-15-A	86	LL	SFP		24-Jul-2013	MVK	53	66		CDEZ419634	MB1PBEYC0CEDK1267	88
4166	RSK640	KL-15-A	87	LL	SFP		23-Jul-2013	ALP	53	66		CNEZ418673	MB1PBEYC9CENK0282	45
4167	RSK641	KL-15-A	90	LL	SFP		25-Jul-2013	NTA	53	66		CRHZ417302	MB1PBEYC8CERJ7479	22
4168	RSE555	KL-15-A	93	LL	ORD		26-Jul-2013	PNI	48	60	6ETI BSIII	CDEZ419602	MB1PBEYC9CEDK1252	67
4169	RSC600	KL-15-A	95	LL	SFP		31-Jul-2013	PSL	53	66		CDEZ419474	MB1PBEYC3CEDK1165	21
4170	RSK642	KL-15-A	99	LL	SFP		30-Jul-2013	MALA	53	66		CPEZ416821	MB1PBEYC5CEPJ8356	85
4171	RSK643	KL-15-A	100	LL	SFP		1-Aug-2013	ALP	53	66		CDEZ420020	MB1PBEYC5CEDK1684	45
4172	RSE556	KL-15-A	102	LL	SFP		1-Aug-2013	IJK	53	66	HINO BSIII	CDEZ419584	MB1PBEYCOCEK1219	89
4173	RSC603	KL-15-A	104	LL	SFP		7-Aug-2013	TVM	53	66	ALPSV 4/186 6ETI BSIII	CDEZ419465	MB1PBEYC3CEDK1084	27
4174	RSE557	KL-15-A	105	LL	SFP		3-Aug-2013	GVR	53	66		CDEZ419846	MB1PBEYC5CEDK1801	66
4175	RSK644	KL-15-A	106	LL	SFP		5-Aug-2013	SBY	53	66		CREZ416650	MBIPBEYC5CEPJ8289	75
4176	RSC601	KL-15-A	108	LL	SFP		12-Aug-2013	MDY	53	66		CDEZ420155	MB1PBEYC9CEDK1865	76
4177	RSC605	KL-15-A	109	LL	SFP		12-Aug-2013	MPM	53	66		CDEZ420236	MB1PBEYXCEDK1941	71
4178	RSE558	KL-15-A	112	LL	SFP		12-Aug-2013	PNI	53	66	6ETI BSIII	CDEZ420222	MB1PBEYC3CEDK1943	67
4179	RSC604	KL-15-A	114	LL	SFP		16-Aug-2013	NTA	53	66		CDEZ419636	MB1PBEYC7CEDK1346	22
4180	RSC602	KL-15-A	116	LL	SFP		19-Aug-2013	EKM	53	66	ALPSV 1/186 6ETI BSIII	CDEZ419585	MB1PBEYC3CEDK1232	56
4181	RSC606	KL-15-A	117	LL	ORD		19-Aug-2013	KGD	53	66	ALPSV 4/186 6ETI BSIII	CNEZ418661	MB1PBEYC7CENK0281	84
4182	RSC608	KL-15-A	118	LL	FP		19-Aug-2013	PLKD	53	66	HINO BSIII	CDEZ420162	MB1PBEYC3CEDK1862	69
4183	RSK645	KL-15-A	119	LL	SFP		16-Aug-2013	SBY	53	66		CREZ415593	MB1PBEYC9CEPJ6695	75
4184	RSE559	KL-15-A	120	LL	SFP		16-Aug-2013	ETPA	53	66	HINO BS III	CNEZ418983	MB1PBEYC6CENK0580	48
4185	RSE560	KL-15-A	121	LL	SFP		23-Aug-2013	MKD	53	66		CDEZ419421	MB1PBEYC5CEDK1085	08
4186	RSE614	KL-15-A	122	LL	SFP		23-Aug-2013	PLKD	53	66	BS III	CNEZ418646	MB1PBEYC6CENK0286	69
4187	RSE615	KL-15-A	126	LL	SFP		27-Aug-2013	PLKD	53	66	BS 111	CDEZ420228	MB1PBEYCOCEK1947	69
4188	RSK646	KL-15-A	127	LL	SFP		29-Aug-2013	TSY	53	66		CREZ415865	MB1PBEYC2CERJ7347	73
4189	RSK647	KL-15-A	128	LL	SFP		29-Aug-2013	TSR	53	66	LL HINO BSIII	CREZ416601	MB1PBEYC6CEPJ8057	63
4190	RSK648	KL-15-A	129	LL	SFP		29-Aug-2013	PNI	53	66	6ETI BKN BSIII	CREZ415591	MB1PBEYCOCEPJ6696	67
4191	RSC607	KL-15-A	130	LL	SFP		30-Aug-2013	CGNR	53	66		CNEZ418938	MB1PBEYC6CENK0529	40
4192	RSC706	KL-15-A	131	LL	SFP		30-Aug-2013	MALA	53	66	6ETIJ3K BSIII	CDEZ420150	MB1PBEYCOCEK1866	85
4193	RSC707	KL-15-A	132	LL	SFP		30-Aug-2013	IJK	53	66	6ETI3K BSIII	CNEZ418984	MB1PBEYC1CENK0583	89
4194	RSC708	KL-15-A	133	LL	SFP		30-Aug-2013	GVR	53	66		CDEZ420169	MB1PBEYC5CEDK1863	66
4195	RSC709	KL-15-A	134	LL	SFP		30-Aug-2013	PNI	53	66	6ETI BSIII	CDEZ420031	MB1PBEYCOCEK1687	67
4196	RSE616	KL-15-A	140	LL	SFP		30-Aug-2013	PSL	53	66		CDEZ420235	MB1PBEYC2CEDK1948	21
4197	RSE617	KL-15-A	145	LL	SFP		5-Sep-2013	PLKD	53	66	BS 111	CNEZ418986	MB1PBEYXCENK0582	69
4198	RSC710	KL-15-A	147	LL	SFP		9-Sep-2013	NDD	53	66		CDEZ420164	MB1PBEYC7CEDK1864	31
4199	RSK649	KL-15-A	148	LL	SFP		5-Sep-2013	MDY	53	66		CREZ415968	MB1PBEYXCERJ7208	76
4200	RSK650	KL-15-A	149	LL	SFP		9-Sep-2013	MPM	53	66		CPEZ416802	MB1PBEYC1CEPJ8287	71
4201	RSC711	KL-15-A	150	LL	SFP		10-Sep-2013	SBY	53	66		CDEZ420151	MB1PBEYC1CEDK1858	75

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4202	RSK651	KL-15-A	159	LL	SFP		12-Sep-2013	ALV	53	66	HINO BSIII	CNEZ418981	MB1PBEYC8CENK0581	61
4203	RSK652	KL-15-A	162	LL	SFP		24-Sep-2013	KMG	53	66	HINO EURO BSIII	CDEZ420129	MB1PBEYC9CEDK1978	55
4204	RSE619	KL-15-A	165	LL	SFP		28-Sep-2013	MALA	53	66		CNEZ420232	MB1PBEYC1CEDK1942	85
4205	RSK653	KL-15-A	166	LL	SFP		30-Sep-2013	CHRY	53	66		CDEZ419633	MB1PBEYC5CEPK1345	44
4206	RSE777	KL-15-A	170	LL	SFP		7-Oct-2013	GVR	53	66		CPEZ416764	MB1PBEYC4CEPJ8624	66
4207	RSE618	KL-15-A	160	LL	SFP		12-Sep-2013	EKM	53	66	BSIII	CNEZ419004	MB1PBEYC7CENK0717	56
4208	RSK655	KL-15-A	183	LL	SFP		24-Oct-2013	SBY	53	66	LL HINO BSIII	CNEZ418953	MB1PBEYC4CENK0531	75
4209	RSK656	KL-15-A	191	LL	SFP		31-Oct-2013	TDP	53	66	LL HINO BSIII	CNEZ419018	MB1PBEYC0CENK0705	53
4210	RSK657	KL-15-A	192	LL	SFP		1-Nov-2013	PTA	53	66	6ETI3K LL BSIII	CPEZ417419	MB1PBEYC5CEPJ8907	37
4211	RSK658	KL-15-A	198	LL	SFP		5-Nov-2013	SBY	53	66		CREZ420125	MB1PBEYC7CEDK1797	75
4212	RSC717	KL-15-A	200	LL	FP		7-Nov-2013	TLY	53	66	6ET13KBS III	CDEZ419578	MB1PBEYC7CEDK1217	18
4213	RSE625	KL-15-A	207	LL	FP		8-Nov-2013	PLKD	53	66	HBS III	CNEZ418657	MB1PBEYC7CENK0278	69
4214	RSC716	KL-15-A	213	LL	SFP		13-Nov-2013	TPLM	53	66		CDEZ420076	MB1PBEYC7CEDK1721	94
4215	RSE626	KL-15-A	214	LL	SFP		12-Nov-2013	SBY	53	66	BSIII	CDEZ419986	MB1PBEYC4CEDK1630	75
4216	RSK719	KL-15-A	215	LL	SFP		12-Nov-2013	MVK	53	66	BSIII	CDEZ419986	MB1PBEYC6CEDK1631	88
4217	RSC715	KL-15-A	218	LL	SFP		15-Nov-2013	MKD	53	66	BSIII	CDEZ420081	MB1PBEYC0CEDK1723	08
4218	RSC718	KL-15-A	219	LL	SFP		15-Nov-2013	PMNA	53	66	BSIII	CDEZ419449	MB1PBEYC7CEDK1086	68
4219	RSE627	KL-15-A	223	LL	SFP		15-Nov-2013	RWE	53	66	HBS III	CDEZ419452	MB1PBEYC0CEDK1107	12
4220	RSK722	KL-15-A	227	LL	SFP		21-Nov-2013	PNR	53	66		CDEZ419988	MB1PBEYC6CEDK1645	78
4221	RSC723	KL-15-A	230	LL	SFP		25-Nov-2013	PNR	53	66		CNEZ418920	MB1PBEYC2CENK0527	78
4222	RSE628	KL-15-A	233	LL	SFP		26-Nov-2013	PNI	53	66	6ETI BSIII	CDEZ419576	MB1PBEYC9CEDK1218	67
4223	RSC720	KL-15-A	235	LL	SFP		29-Nov-2013	PALA	53	66		CDEZ420239	MB1PBEYC9CEDK1946	50
4224	RSC724	KL-15-A	239	LL	SFP		2-Dec-2013	MKD	53	66		CNEZ418728	MB1PBEYC8CENK0306	08
4225	RSE629	KL-15-A	242	LL	SFP		30-Nov-2013	EKM	53	66		CDEZ419900	MB1PBEYC2CEDK1545	56
4226	RSC721	KL-15-A	243	LL	SFP		4-Dec-2013	KTM	53	66	HINO BSIII	CDEZ419928	MB1PBEYC8CEDK1629	47
4227	RSC712	KL-15-A	171	LL	SFP		11-Oct-2013	PTA	53	66	6ETI3K LL BSIII	CDEZ419897	MB1PBEYC0CEDK1544	37
4228	RSC714	KL-15-A	174	LL	SFP		15-Oct-2013	SBY	53	66		CDEZ420130	MB1PBEYC0CEDK1799	75
4229	RSK654	KL-15-A	177	LL	SFP		18-Oct-2013	KNR	53	66	BSIII	CNEZ418667	MB1PBEYC9CENK0279	77
4230	RSC725	KL-15-A	246	LL	SFP		6-Dec-2013	KTM	53	66	HINO BSIII	CDEZ420135	MB1PBEYC3CEDK1800	47
4231	RSE630	KL-15-A	247	LL	SFP		5-Dec-2013	KPA	53	66		CDEZ419911	MB1PBEYC6CEDK1628	74
4232	RSE631	KL-15-A	251	LL	SFP		19-Dec-2013	PBVR	53	66	LL BS III	CNEZ418918	MB1PBEYC2CENK0530	59
4233	RSC713	KL-15-A	257	LL	SFP		20-Dec-2013	TVM	53	66	ALPSV 4/186 6ETI BSIII	CDEZ420077	MB1PBEYC9CEDK1722	27
4234	RN 777	KL-15	9049	LL	VB	CFP	26-Feb-2011	PKDA	53	75	BSIII 123 KW	CNH 561316	CNH136277	81
4235	RSC773	KL-15-A	267	TATA	SDLX		3-Mar-2014	CHRY	53	50		31F84116272	MAT412201DOF05244	44
4236	RSC778	KL-15-A	268	TATA	SDLX		3-Mar-2014	CHRY	53	50		31F84115627	MAT412201DOF05231	44
4237	RSC774	KL-15-A	270	TATA	SDLX		6-Mar-2014	PVM	53	50		31F84116273	MAT412201DOF05245	83
4238	RSC768	KL-15-A	269	TATA	SDLX		5-Mar-2014	PVM	53	50		31F84115648	MAT412201DOF05202	83
4239	RSC780	KL-15-A	271	TATA	SDLX		7-Mar-2014	PVM	53	50	TC13S 111	31F84115624	MAT412201DOF05200	83
4240	RSC776	KL-15-A	272	TATA	SDLX		10-Mar-2014	KGD	53	50		31F84115181	MAT412201DOF05196	84
4241	RSC779	KL-15-A	273	TATA	SDLX		10-Mar-2014	RWE	53	50		31F84116159	MAT412201DOF05242	12
4242	RSC637	KL-15-A	274	TATA	SDLX		12-Mar-2014	KGD	53	50		31F84115879	MAT412201DOF05233	84
4243	RSC636	KL-15-A	275	TATA	SDLX		14-Mar-2014	RWE	53	50	LPO 1512 TC BSIII	31F84115418	MAT412201DOF05157	12
4244	RSC634	KL-15-A	276	TATA	SDLX		17-Mar-2014	RWE	53	50		31F84116275	MAT412201DOF05238	12
4245	RSC633	KL-15-A	277	TATA	SDLX		21-Mar-2014	RWE	53	50		31F84115722	MAT412201DOF05189	12
4246	RSC635	KL-15-A	278	TATA	SDLX		25-Mar-2014	RWE	53	50	LPO 1512 TC BSIII	31F84116249	MAT412201DOF05241	12

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4247	RS 781	KL-15-A	279	VOLV	GARU	CLUB	26-Apr-2014	TVM	53	66	VOLVO 9400 B9R EOROIII	189532	YV3SSL524D8159750K16	27
4248	RS 782	KL-15-A	280	VOLV	GARU	CLUB	26-Apr-2014	EKM	53	66	VOLVO 9400 B9R EUROIII	189528	YV3S5L52XD8159753A17	56
4249	RS 783	KL-15-A	281	VOLV	GARU	CLUB	26-Apr-2014	TVM	53	66	VOLVO 9400B9R EUROIII	189529	YV3S5L521D8159754A17	27
4250	RS 784	KL-15-A	282	VOLV	GARU	CLUB	26-Apr-2014	EKM	53	66		189699	YV3S5L524D8160025A17	56
4251	RS 785	KL-15-A	283	VOLV	GARU	CLUB	26-Apr-2014	KKD	53	66				72
4252	RS 786	KL-15-A	284	VOLV	GARU	CLUB	26-Apr-2014	TVM	53	66	VOLVO 9400 B9R EUROIII	189708	YV3SGL528D8160027A17	27
4253	RS 787	KL-15-A	285	VOLV	GARU	CLUB	26-Apr-2014	KTM	53	66		189712	YV3S5L52XD8160028A17	47
4254	RS 788	KL-15-A	286	VOLV	GARU	CLUB	26-Apr-2014	KTM	53	66		189697	YV3S5L521D8160029A17	47
4255	RS 789	KL-15-A	287	VOLV	GARU	CLUB	26-Apr-2014	TVM	53	66	VOLVO 9400 B9R EUROIII	189701	YV3S5L528D8160030A17	27
4256	RS 790	KL-15-A	288	VOLV	GARU	CLUB	26-Apr-2014	TVM	53	66	VOLVO 9400 B9R EURO III	189706	YV355L52XD8160031A17	27
4257	RT 885	KL-15	6063	TATA	ORD		27-Aug-2005	CTY	48	60	1512TC CUMMINS	40F62331229	412071 CUZ 110769	28
4258	RSC795	KL-15-A	289	LL	FP		14-Oct-2014	PLR	53	66		ESEZ422159	MB1PBEYC6EESP4553	36
4259	RSA804	KL-15-A	290	LL	FP		17-Nov-2014	TVM	53	66		ESEZ422161	MB1PBEYC4EESP4552	27
4260	RSK791	KL-15-A	291	LL	FP		17-Nov-2014	TVM	53	66		ESEZ422164	MB1PBEYC7EESP4559	27
4261	RSE793	KL-15-A	292	LL	FP		18-Nov-2014	TVM	53	66		ESEZ422290	MB1PBEYC1EESP4671	27
4262	RSM798	KL-15-A	293	LL	FP		18-Nov-2014	TVM	53	66		ESEZ422200	MB1PBEYC7EESP4562	27
4263	RSC796	KL-15-A	294	LL	FP		24-Nov-2014	PLKD	53	66	BS 111	ESEZ422165	MB1PBEYC8EESP4554	69
4264	RSC797	KL-15-A	295	LL	FP		27-Nov-2014	PLKD	53	66	BS 111	ESEZ422202	MBIPBEYC3EESP4560	69
4265	RSK792	KL-15-A	296	LL	FP		28-Nov-2014	PLKD	53	66	BS 111	ESEZ422201	MB1PBEYC2EESP4565	69
4266	RSC805	KL-15-A	297	LL	FP		15-Dec-2014	TVM	53	66		ESEZ422400	MB1PBEYC9EESP4739	27
4267	RSK820	KL-15-A	298	LL	FP		15-Dec-2014	GVR	53	66		ESEZ422205	MB1PBEYC1EESP4864	66
4268	RSM799	KL-15-A	299	LL	FP		16-Dec-2014	KKD	53	66		ESEZ422371	MB1PBEYC1EESP4699	72
4269	RSA837	KL-15-A	300	LL	FP		16-Dec-2014	KTR	53	66	HBS III	ESEZ422376	MB1PBEYC0EESP4709	35
4270	RSE794	KL-15-A	301	LL	FP		16-Dec-2014	KTR	53	66	6ETI3KNBS111	ESEZ422198	MB1PBEYC0EESP4564	35
4271	RSK821	KL-15-A	302	LL	FP		19-Dec-2014	MKD	53	66		ESEZ422426	MB1PBEYC8EESP4859	08
4272	RSC806	KL-15-A	303	LL	FP		19-Dec-2014	ALV	53	66		ESEZ422373	MB1PBEYC2EESP4713	61
4273	RSM800	KL-15-A	304	LL	FP		20-Dec-2014	KTP	53	66		ESEZ422357	MB1PBEYC6EESP4696	14
4274	RSC809	KL-15-A	305	LL	FP		20-Dec-2014	PNKM	53	66	HINO BS 111	ESEZ422381	MB1PBEYC6EESP4746	49
4275	RSK822	KL-15-A	306	LL	FP		22-Dec-2014	NDM	53	66		ESEZ422507	MB1PBEYC8EESP4862	110
4276	RSE834	KL-15-A	307	LL	FP		22-Dec-2014	CTR	53	66		ESEZ422367	MBIPBEYC9EESP4711	70
4277	RSM801	KL-15-A	308	LL	FP		23-Dec-2014	CTR	53	66	HINO BS III	ESEZ422370	MB1PBEYC4EESP4700	70
4278	RSC808	KL-15-A	309	LL	FP		23-Dec-2014	PLKD	53	66	BS III	ESEZ422394	MB1PBEYC0EESP4743	69
4279	RSA838	KL-15-A	310	LL	FP		24-Dec-2014	KTM	53	66	LL BS III	ESEZ422361	MB1PBEYCXEESP4698	47
4280	RSK823	KL-15-A	311	LL	FP		26-Dec-2014	EKM	53	66		ESEZ422196	MB1PBEYC4EESP4857	56
4281	RSE835	KL-15-A	312	LL	FP		26-Dec-2014	KNR	53	66		ESEZ422369	MB1PBEYC0EESP4712	77
4282	RSM803	KL-15-A	313	LL	FP		27-Dec-2014	PALA	53	66		ESEZ422288	MB1PBEYCXEESP4684	50
4283	RSE836	KL-15-A	314	LL	FP		29-Dec-2014	KNR	53	66		ESEZ422289	MB1PBEYCXEESP4670	77
4284	RSK824	KL-15-A	315	LL	FP		30-Dec-2014	KGD	53	66		ESEZ422430	MB1PBEYC6EESP4858	84
4285	RA 102	KL-15	7232	VOLV	GARU	SRDI	20-Nov-2008	ALP	53	66	VOLVO 9400 B7R EURO III	10655181	72998129394	45
4286	RSA862	KL-15-A	316	LL	FP		31-Dec-2014	KDLR	53	66		ESEZ422291	MB1PBEYC3EESP4672	90
4287	RSK825	KL-15-A	317	LL	FP		1-Jan-2015	TLY	53	66	6ET13 KN BSIII	ESEZ422505	MB1PBEYCXEESP4863	18
4288	RSE857	KL-15-A	318	LL	FP		1-Jan-2015	PALA	53	66		ESEZ422247	MB1PBEYC3EESP4686	50
4289	RSM802	KL-15-A	319	LL	FP		5-Jan-2015	TSR	53	66		ESEZ422360	MB1PBEYC8EESP4697	63
4290	RSK826	KL-15-A	320	LL	FP		5-Jan-2015	CLDY	53	66		ESEZ422510	MB1PBEYC5EESP4866	58
4291	RSE858	KL-15-A	321	LL	FP		5-Jan-2015	TLY	53	66	66TI3KN BS III	ESEZ422368	MB1PBEYC9EESP4708	18

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4292	RSA868	KL-15-A	322	LL	FP		7-Jan-2015	KGD	53	66		ESEZ422199	MB1PBEYC9EESP4563	84
4293	RSE859	KL-15-A	323	LL	FP		7-Jan-2015	KNR	53	66		ESEZ422396	MB1PBEYC7EESP4738	77
4294	RSM863	KL-15-A	324	LL	FP		8-Jan-2015	TSY	53	66		ESEZ423259	MB1PBEYC8EERP5580	73
4295	RSK827	KL-15-A	325	LL	FP		9-Jan-2015	PALA	53	66		ESEZ421028	MB1PBEYC6EESP4861	50
4296	RSE860	KL-15-A	326	LL	FP		9-Jan-2015	VKM	53	66		ESEZ422421	MB1PBEYC4EESP4860	51
4297	RSC807	KL-15-A	327	LL	FP		12-Jan-2015	KGD	53	66		ESEZ422375	MB1PBEYC7EESP4710	84
4298	RSC810	KL-15-A	328	LL	FP		12-Jan-2015	KGD	53	66		ESEZ422204	MB1PBEYC5EESP4561	84
4299	RSK828	KL-15-A	329	LL	FP		12-Jan-2015	KGD	53	66		ESEZ422506	MB1PBEYC3EESP4865	84
4300	RSM864	KL-15-A	330	LL	FP		12-Jan-2015	KTM	53	66		ESEZ423118	MB1PBEYC5EERP5407	47
4301	RSC811	KL-15-A	331	LL	FP		13-Jan-2015	KHD	53	66		ESEZ422391	MB1PBEYC2EESP4744	106
4302	RSC812	KL-15-A	332	LL	FP		13-Jan-2015	KHD	53	66		ESEZ421586	MB1PBEYC9EESP4742	106
4303	RSE861	KL-15-A	333	LL	FP		13-Jan-2015	PALA	53	66		ESEZ422509	MB1PBEYC7EESP4867	50
4304	RSA869	KL-15-A	334	LL	FP		13-Jan-2015	PALA	53	66		EREZ423490	MB1PBEYC4EERP5849	50
4305	RSC813	KL-15-A	335	LL	FP		14-Jan-2015	TLY	53	66	6ET13KN BSIII	ESEZ420833	MB1PBEYC1EESP4685	18
4306	RSK829	KL-15-A	336	LL	FP		16-Jan-2015	EMLY	53	66		EREZ423486	MB1PBEYC4EERP5754	95
4307	RSM865	KL-15-A	337	LL	FP		16-Jan-2015	EKM	53	66		ESEZ422399	MB1PBEYC1EERP5226	56
4308	RSC814	KL-15-A	338	LL	FP		16-Jan-2015	KLM	53	66		ESEZ422395	MB1PBEYC5EESP4737	34
4309	RSC815	KL-15-A	339	LL	FP		16-Jan-2015	KTM	53	66		ESEZ422393	MB1PBEYC5EESP4740	47
4310	RSE870	KL-15-A	340	LL	FP		17-Jan-2015	KNR	53	66		ESEZ422883	MB1PBEYC4EERP5317	77
4311	RSA875	KL-15-A	341	LL	FP		17-Jan-2015	VDA	53	66		EREZ423286	MB1PBEYC6EERP5853	92
4312	RSC816	KL-15-A	342	LL	FP		17-Jan-2015	TSR	53	66		ESEZ422398	MB1PBEYC4EESP4745	63
4313	RSC817	KL-15-A	343	LL	FP		17-Jan-2015	TPLM	53	66		ESEZ422374	MB1PBEYC7EESP4707	94
4314	RSK830	KL-15-A	344	LL	FP		19-Jan-2015	KNR	53	66		EREZ424409	MB1PBEYCXEERP6620	77
4315	RSM866	KL-15-A	345	LL	FP		19-Jan-2015	CHRY	53	66		EREZ423147	MB1PBEYC6EERP5450	44
4316	RSC818	KL-15-A	346	LL	FP		19-Jan-2015	SBY	53	66		ESEZ422397	MB1PBEYC7EESP4741	75
4317	RSC819	KL-15-A	347	LL	FP		19-Jan-2015	PVM	53	66		ESEZ422359	MB1PBEYC4EESP4695	83
4318	RSC839	KL-15-A	348	LL	FP		19-Jan-2015	PNKM	53	66	HINO BS 111	EREZ423150	MB1PBEYC8EERP5451	49
4319	RSE871	KL-15-A	349	LL	FP		20-Jan-2015	KKD	53	66		EREZ423262	MB1PBEYC5EERP5777	72
4320	RSC840	KL-15-A	350	LL	FP		20-Jan-2015	PALA	53	66		EREZ423097	MB1PBEYC1EERP5405	50
4321	RSC841	KL-15-A	351	LL	FP		20-Jan-2015	PALA	53	66		EREZ424405	MB1PBEYC7EERP6624	50
4322	RSK831	KL-15-A	352	LL	FP		23-Jan-2015	PALA	53	66		EREZ424407	MB1PBEYC1EERP6621	50
4323	RSM867	KL-15-A	353	LL	FP		23-Jan-2015	EMLY	53	66		EREZ423100	MB1PBEYC0EERP5413	95
4324	RSA876	KL-15-A	354	LL	FP		23-Jan-2015	NDM	53	66	6ET13KN BSIII	EREZ423827	MB1PBEYC3EERP6135	110
4325	RSC842	KL-15-A	355	LL	FP		23-Jan-2015	EKM	53	66		EREZ424238	MB1PBEYC6EERP6436	56
4326	RSC843	KL-15-A	356	LL	FP		23-Jan-2015	ADR	53	66	6ET13KN BS III	EREZ423116	MB1PBEYC3EERP5406	38
4327	RSE872	KL-15-A	357	LL	SFP		24-Jan-2015	EMLY	53	66		EREZ423807	MB1PBEYC6EERP6064	95
4328	RSC844	KL-15-A	358	LL	FP		24-Jan-2015	PVM	53	66		EREZ423117	MB1PBEYC4EERP5415	83
4329	RSE873	KL-15-A	361	LL	SFP		28-Jan-2015	PNKM	53	66	HINO BS 111	EREZ424243	MB1PBEYC4EERP6441	49
4330	RSK832	KL-15-A	359	LL	FP		28-Jan-2015	PVM	53	66		EREZ423333	MB1PBEYC4EERP5852	83
4331	RSM892	KL-15-A	360	LL	FP		28-Jan-2015	KTM	53	66		EREZ424698	MB1PBEYC7EERP6882	47
4332	RSC845	KL-15-A	362	LL	FP		28-Jan-2015	KTM	53	66		EREZ423835	MB1PBEYC1EERP6134	47
4333	RSC846	KL-15-A	363	LL	FP		28-Jan-2015	PNKM	53	66	HINO BS III	EREZ424240	MB1PBEYC0EERP6433	49
4334	RSC847	KL-15-A	364	LL	FP		29-Jan-2015	EKM	53	66		EREZ424508	MB1PBEYCXEERP6665	56
4335	RSK833	KL-15-A	410	LL	FP		30-Jan-2015	KKD	53	66		EREZ424236	MB1PBEYCXEERP6438	72
4336	RSA877	KL-15-A	411	LL	FP		30-Jan-2015	TPLM	53	66		EREZ423488	MB1PBEYC2EERP5851	94

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4337	RSC848	KL-15-A	412	LL	FP		30-Jan-2015	KKD	53	66		EREZ423006	MB1PBEYC1EERP5324	72
4338	RSC849	KL-15-A	413	LL	FP		30-Jan-2015	EMLY	53	66		EREZ423263	MB1PBEYC1EERP5579	95
4339	RSE874	KL-15-A	414	LL	SFP		2-Feb-2015	PSL	53	66		EREZ424506	MB1PBEYC8EERP6664	21
4340	RSM893	KL-15-A	415	LL	FP		2-Feb-2015	CTR	53	66		EREZ423810	MB1PBEYC9EERP6060	70
4341	RSK902	KL-15-A	416	LL	FP		2-Feb-2015	CTR	53	66	HINO BS III	EREZ425388	MB1PBEYC7EERP7599	70
4342	RSC850	KL-15-A	417	LL	FP		2-Feb-2015	PLKD	53	66	BS 111	EREZ423835	MB1PBEYC1EERP6134	69
4343	RSE897	KL-15-A	418	LL	SFP		4-Feb-2015	EKM	53	66	HINO BS III	EREZ425444	MB1PBEYC6EERP7688	56
4344	RSC851	KL-15-A	419	LL	FP		4-Feb-2015	PLKD	53	66	BS 111	EREZ423114	MB1PBEYC2EERP5414	69
4345	RSC852	KL-15-A	420	LL	FP		4-Feb-2015	PLKD	53	66	BS 111	EREZ423291	MB1PBEYC6EERP5576	69
4346	RSA878	KL-15-A	421	LL	FP		5-Feb-2015	KTR	53	66	HBS 111	EREZ423829	MB1PBEYC5EERP6136	35
4347	RSM894	KL-15-A	422	LL	FP		5-Feb-2015	NTA	53	66		EREZ423042	MB1PBEYCXEERP5578	22
4348	RSK903	KL-15-A	423	LL	FP		5-Feb-2015	KKD	53	66		EREZ425464	MB1PBEYC4EERP7690	72
4349	RSC854	KL-15-A	424	EML	FP		6-Feb-2015	TVM	53	66		ER13CDEL010153	MC2R1NRT0EL040185	27
4350	RSC853	KL-15-A	425	LL	FP		6-Feb-2015	MNR	53	66	HINO EURO BS 111	EREZ424416	MB1PBEYC0EERP6660	60
4351	RSM895	KL-15-A	426	LL	FP		9-Feb-2015	TSR	53	66		EREZ423146	MB1PBEYC8EERP5448	63
4352	RSE898	KL-15-A	427	LL	SFP		9-Feb-2015	MNR	53	66	HINO EURO BS111	EFEZ425621	MB1PBEYC1EERP7923	60
4353	RSC855	KL-15-A	428	LL	FP		10-Feb-2015	PLKD	53	66	BS 111	EREZ423658	MB1PBEYC6EERP6145	69
4354	RSC856	KL-15-A	429	LL	FP		11-Feb-2015	KKD	53	66		EREZ423995	MB1PBEYC6EERP6212	72
4355	RSC879	KL-15-A	430	LL	FP		11-Feb-2015	KPA	53	66		EREZ424406	MB1PBEYC0EERP6626	74
4356	RSK904	KL-15-A	431	LL	FP		10-Feb-2015	MDY	53	66		EREZ425491	MB1PBEYC8EERP7689	76
4357	RSC880	KL-15-A	432	LL	FP		12-Feb-2015	TLY	53	66		EREZ424239	MB1PBEYC8EERP6437	18
4358	RSC881	KL-15-A	433	LL	FP		12-Feb-2015	SBY	53	66		EREZ423491	MB1PBEYCXEERP5757	75
4359	RSA917	KL-15-A	434	LL	FP		9-Feb-2015	EKM	53	66		EREZ423953	MB1PBEYC8EERP6166	56
4360	RSM896	KL-15-A	435	LL	FP		13-Feb-2015	KKD	53	66		EREZ423808	MB1PBEYC0EERP6061	72
4361	RSC882	KL-15-A	436	LL	FP		13-Feb-2015	CTR	53	66		EREZ423834	MB1PBEYC1EERP6120	70
4362	RSC883	KL-15-A	437	LL	FP		13-Feb-2015	TSR	53	66		EREZ424212	MB1PBEYC4EERP6435	63
4363	RSE899	KL-15-A	438	LL	SFP		12-Feb-2015	GVR	53	66		EFEZ425785	MB1PBEYC5EERP7925	66
4364	RSK905	KL-15-A	439	LL	FP		13-Feb-2015	VDA	53	66	BS III	EFEZ425552	MB1PBEYC2EERP7929	92
4365	RSC884	KL-15-A	440	LL	FP		16-Feb-2015	KTM	53	66		EREZ424241	MB1PBEYC1EERP6439	47
4366	RSC885	KL-15-A	441	LL	FP		16-Feb-2015	KTM	53	66		EREZ424419	MB1PBEYC5EERP6623	47
4367	RSA918	KL-15-A	442	LL	FP		12-Feb-2015	MVPA	53	66	LL BS III	EREZ424697	MB1PBEYC5EERP6881	52
4368	RSC886	KL-15-A	443	EML	FP		18-Feb-2015	KTDA	53	66		E613CDEL010157	MC2R1NRT0EL040186	25
4369	RSC887	KL-15-A	444	EML	FP		18-Feb-2015	TVM	53	66		E613CDEL010187	MC2R1NRT0EL040192	27
4370	RSM922	KL-15-A	445	LL	FP		18-Feb-2015	CHRY	53	66	HINO BSIII	EREZ423998	MB1PBEYC2EERP6210	44
4371	RSE900	KL-15-A	446	LL	SFP		16-Feb-2015	EKM	53	66	HINO BS III	EXEZ411107	MB1PBEYC9EERP7927	56
4372	RSA919	KL-15-A	447	LL	FP		16-Feb-2015	KTM	53	66		ESEZ422802	MB1PBEYC2EERP5316	47
4373	RSK906	KL-15-A	448	LL	FP		16-Feb-2015	CLDY	53	66		EFEZ425784	MB1PBEYCXEERP7919	58
4374	RSC888	KL-15-A	449	LL	FP		19-Feb-2015	KLM	53	66		EREZ424466	MB1PBEYC6EERP6663	34
4375	RSC889	KL-15-A	450	LL	FP		20-Feb-2015	ATL	53	66	BS III	EREZ423977	MB1PBEYC6EERP6243	33
4376	RSC890	KL-15-A	451	LL	FP		21-Feb-2015	PVR	53	66		EREZ424074	MB1PBEYC1EERP6246	23
4377	RSE901	KL-15-A	452	LL	SFP		19-Feb-2015	MDY	53	66		EFEZ425786	MB1PBEYC2EERP7932	76
4378	RSK907	KL-15-A	453	LL	FP		20-Feb-2015	TSR	53	66		EFEZ426879	MB1PBEYC6EERP9019	63
4379	RSM923	KL-15-A	454	LL	FP		23-Feb-2015	KTP	53	66		EREZ423161	MB1PBEYC7EERP5487	14
4380	RSA920	KL-15-A	455	LL	FP		19-Feb-2015	MLTM	53	66		EREZ423115	MB1PBEYC9EERP5412	54
4381	RSC891	KL-15-A	456	LL	FP		24-Feb-2015	KTP	53	66		EREZ424467	MB1PBEYC9EERP6625	14

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4382	RSE912	KL-15-A	457	LL	SFP		23-Feb-2015	KMGH	53	66		EFEZ426507	MB1PBEYC9EEFP8625	55
4383	RSK908	KL-15-A	458	LL	FP		23-Feb-2015	TSY	53	66		EBEZ405518	MB1PBEYCXEEFP9024	73
4384	RSA921	KL-15-A	459	LL	FP		23-Feb-2015	NBR	53	66		ESEZ422888	MB1PBEYC3EERP5325	86
4385	RSC926	KL-15-A	460	EML	FP		25-Feb-2015	TVM	53	66		E613CDEL010068	MC2R1NRT0EL040184	27
4386	RSM924	KL-15-A	461	LL	FP		27-Feb-2015	MDY	53	66		EREZ423087	MB1PBEYCXEERP5449	76
4387	RSC927	KL-15-A	462	EML	FP		27-Feb-2015	TVM	53	66		E613CDEL009785	MC2R1NRT0EL040151	27
4388	RSE913	KL-15-A	463	LL	SFP		26-Feb-2015	SBY	53	66		EFEZ426763	MB1PBEYC1EEFP8943	75
4389	RSA952	KL-15-A	464	LL	FP		26-Feb-2015	NDM	53	66		EREZ423288	MB1PBEYC2EERP5848	110
4390	RSC930	KL-15-A	465	LL	FP		26-Feb-2015	KTM	53	66		EREZ423338	MB1PBEYC3EERP5759	47
4391	RSM925	KL-15-A	466	LL	FP		2-Mar-2015	PALA	53	66		EREZ423102	MB1PBEYC7EERP5411	50
4392	RSC931	KL-15-A	467	LL	FP		2-Mar-2015	PALA	53	66		EREZ424411	MB1PBEYC2EERP6627	50
4393	RSK909	KL-15-A	468	LL	FP		26-Feb-2015	NBR	53	66		EFEZ426675	MB1PBEYC6EEFP9022	86
4394	RA 101	KL-15	7231	VOLV	GARU	SRDI	20-Nov-2008	TVM	53	66	VOLVO 9400 B7R EURO III	10656207	72888129207	27
4395	RSE914	KL-15-A	469	LL	FP		28-Feb-2015	KMY	53	66		EFEZ426878	MB1PBEYC2EEFP9020	05
4396	RSC932	KL-15-A	470	LL	FP		3-Mar-2015	KTDA	53	66	BS 111	EREZ423005	MB1PBEYC0EERP5329	25
4397	RSK910	KL-15-A	471	LL	FP		2-Mar-2015	PVM	53	66		EFEZ426765	MB1PBEYC8EEFP9023	83
4398	RSC933	KL-15-A	472	LL	FP		4-Mar-2015	PALA	53	66		EREZ423633	MB1PBEYC9EERP5944	50
4399	RSA953	KL-15-A	473	LL	FP		2-Mar-2015	PALA	53	66		EREZ423465	MB1PBEYC1EERP5758	50
4400	RSM958	KL-15-A	474	LL	FP		6-Mar-2015	MLTM	53	66		EFEZ425704	MB1PBEYC0EEFP7931	54
4401	RSC934	KL-15-A	475	LL	FP		6-Mar-2015	TDP	53	66		EREZ423332	MB1PBEYC0EERP5850	53
4402	RSA954	KL-15-A	476	LL	FP		5-Mar-2015	TDP	53	66		EREZ423098	MB1PBEYC8EERP5417	53
4403	RSE915	KL-15-A	477	LL	FP		5-Mar-2015	TDP	53	66		EFEZ426886	MB1PBEYC4EEFP9021	53
4404	RSK911	KL-15-A	478	LL	FP		5-Mar-2015	PTA	53	66	LL BS III	EFEZ426526	MB1PBEYC4EEFP9018	37
4405	RSC937	KL-15-A	479	LL	FP		7-Mar-2015	PLR	53	66		EREZ424242	MB1PBEYC8EERP5577	36
4406	RSE916	KL-15-A	480	LL	FP		7-Mar-2015	KMY	53	66		EFEZ426797	MB1PBEYC1EEFP9025	05
4407	RSM959	KL-15-A	481	LL	FP		10-Mar-2015	NDM	53	66		EWEZ413971	MB1PBEYC9EEFP7930	110
4408	RSC938	KL-15-A	482	LL	FP		10-Mar-2015	PALA	53	66		EREZ423284	MB1PBEYC8EERP5577	50
4409	RSC939	KL-15-A	483	LL	FP		10-Mar-2015	MDY	53	66		EREZ424237	MB1PBEYC2EERP6434	76
4410	RSK963	KL-15-A	484	LL	FP		9-Mar-2015	VLND	53	66		FEEZ400108	MB1PBEYC1FEER0041	20
4411	RSA955	KL-15-A	485	LL	FP		9-Mar-2015	MNR	53	66	HINO EURO BSIII	ESEZ422822	MB1PBEYC0EERP5315	60
4412	RSC928	KL-15-A	486	EML	FP		12-Mar-2015	TVM	53	66		E613CDEL010341	MC2R1NRT0EL040203	27
4413	RSC929	KL-15-A	487	EML	FP		12-Mar-2015	TVM	53	66		E613CDEL010197	MC2R1NRT0EL040194	27
4414	RSM960	KL-15-A	488	LL	FP		12-Mar-2015	CGNR	53	66		EFEZ426796	MB1PBEYC8EEFP8941	40
4415	RSC935	KL-15-A	489	EML	FP		12-Mar-2015	TVM	53	66		E613CDEL010069	MC2R1NRT0EL040183	27
4416	RSC940	KL-15-A	490	LL	FP		12-Mar-2015	EMLY	53	66		EREZ424414	MB1PBEYC4EERP6662	95
4417	RSC941	KL-15-A	491	LL	FP		17-Mar-2015	ADR	53	66	6ETI 3KN (BS III)	EREZ424413	MB1PBEYC2EERP6661	38
4418	RSE947	KL-15-A	492	LL	FP		12-Mar-2015	MNR	53	66	HINO EURO BS III	EFEZ426795	MB1PBEYC2EEFP9017	60
4419	RSK964	KL-15-A	493	LL	FP		12-Mar-2015	KDLR	53	66		FEEZ400592	MB1PBEYC5FEER0673	90
4420	RSC942	KL-15-A	494	LL	FP		17-Mar-2015	CTR	53	66		EREZ425468	MB1PBEYC2EEFP7686	70
4421	RSA956	KL-15-A	495	LL	FP		12-Mar-2015	TSR	53	66		ESEZ422689	MB1PBEYC0EERP5251	63
4422	RSA957	KL-15-A	496	LL	FP		13-Mar-2015	TSY	53	66		EFEZ425550	MB1PBEYC6EEFP8193	73
4423	RSM961	KL-15-A	497	LL	FP		18-Mar-2015	VKM	53	66		EFEZ426413	MB1PBEYC8EEFP8521	51
4424	RSC943	KL-15-A	498	LL	FP		18-Mar-2015	KTR	53	66	6EIT3KN BS III	EREZ425503	MB1PBEYC4EEFP7687	35
4425	RSK965	KL-15-A	499	LL	FP		17-Mar-2015	PTA	53	66		EFEZ427681	MB1PBEYC7FEER9853	37
4426	RSE948	KL-15-A	500	LL	SFP		17-Mar-2015	TVM	53	66		FEEZ400028	MB1PBEYC7FEER0044	27

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4427	RSC946	KL-15-A	501	EML	SFP		20-Mar-2015	EKM	53	66		E613CDEM012564	MC2R1NRT0EM040282	56
4428	RSC973	KL-15-A	502	LL	SFP		20-Mar-2015	TVM	53	66	BS III	ESEZ422884	MB1PBEYCXEERP5323	27
4429	RSE949	KL-15-A	503	LL	SFP		19-Mar-2015	TVL	53	66		FEEZ400029	MB1PBEYC9FEER0045	43
4430	RSC974	KL-15-A	504	LL	SFP		20-Mar-2015	KNR	53	66		FREZ425399	MB1PBEYC3EEFP7602	77
4431	RSK966	KL-15-A	505	LL	FP		19-Mar-2015	GVR	53	66		FEEZ400113	MB1PBEYCXFEER0085	66
4432	RSA968	KL-15-A	506	LL	FP		19-Mar-2015	VDCY	53	66		EFEZ426043	MB1PBEYC5EEFP8234	82
4433	RSC988	KL-15-A	507	EML	SFP		21-Mar-2015	SBY	53	66		E613CDEM012261	MC2RINRT0EM040263	75
4434	RSE950	KL-15-A	508	LL	SFP		21-Mar-2015	TVM	53	66		FEEZ400025	MB1PBEYC4FEER0048	27
4435	RSM962	KL-15-A	509	LL	FP		23-Mar-2015	KKLM	53	66		EREZ423812	MB1PBEYC8EEFP8194	108
4436	RSC944	KL-15-A	510	LL	FP		23-Mar-2015	VZM	53	66		EREZ425489	MB1PBEYC0EEFP7685	24
4437	RSA969	KL-15-A	511	LL	FP		20-Mar-2015	NTA	53	66		EFEZ426391	MB1PBEYC5EEFP8489	22
4438	RSC945	KL-15-A	512	LL	FP		24-Mar-2015	PLKD	53	66	BS 111	EWEZ412592	MB1PBEYC3EEFP7924	69
4439	RSK967	KL-15-A	513	LL	FP		23-Mar-2015	EMLY	53	66		FDEZ404075	MB1PBEYC1FEDR4023	95
4440	RSA970	KL-15-A	514	LL	FP		23-Mar-2015	EMLY	53	66		EFEZ426401	MB1PBEYC5EEFP8525	95
4441	RSE951	KL-15-A	515	LL	SFP		24-Mar-2015	TVM	53	66		FEEZ400109	MB1PBEYC3FEER0087	27
4442	RSM997	KL-15-A	516	LL	FP		27-Mar-2015	PLKD	53	66	BS 111	EREZ423099	MB1PBEYC6EEFP5416	69
4443	RSC936	KL-15-A	517	EML	FP		27-Mar-2015	TVM	53	66		E613CDEL010317	MC2R1NRT0EL040202	27
4444	RSC975	KL-15-A	518	LL	FP		27-Mar-2015	TVM	53	66		EREZ425466	MB1PBEYCXEEFP7693	27
4445	RSA971	KL-15-A	519	LL	FP		26-Mar-2015	PTA	53	66	LL BS 111	EFEZ426504	MB1PBEYC4EEFP8645	37
4446	RSC989	KL-15-A	520	EML	SFP		28-Mar-2015	EKM	53	66		E613CDEL010188	MC2R1NRT0EL040193	56
4447	RSC976	KL-15-A	521	LL	FP		30-Mar-2015	EMLY	53	66		EREZ423976	MB1PBEYCXEERP6245	95
4448	RPA 7	KL-15-A	527	LL	FP		1-Apr-2015	TSR	53	66		FEEZ400637	MB1PBEYC5FEER0835	63
4449	RSC977	KL-15-A	528	LL	FP		4-Apr-2015	ETPA	53	66	HINO BS III	EREZ423636	MB1PBEYC0EERP5945	48
4450	RSM998	KL-15-A	529	LL	FP		4-Apr-2015	KTR	53	66	HBS 111	EFEZ426386	MB1PBEYCXEEFP8486	35
4451	RSM999	KL-15-A	530	LL	FP		4-Apr-2015	TVM	53	66		EFEZ426380	MB1PBEYC8EEFP8485	27
4452	RSE994	KL-15-A	531	LL	SFP		4-Apr-2015	MPM	53	66		FDEZ403055	MB1PBEYC3FEDR3052	71
4453	RPK 4	KL-15-A	532	LL	SFP		4-Apr-2015	KTM	53	66	HINO BS III	FDEZ404146	MB1PBEYC4FEDR4078	47
4454	RPA 8	KL-15-A	533	LL	FP		6-Apr-2015	PLKD	53	66	BS 111	FEEZ400519	MB1PBEYC7FEER0495	69
4455	RSC978	KL-15-A	534	LL	FP		7-Apr-2015	PLKD	53	66	BS 111	ESEZ422889	MB1PBEYC5EERP5926	69
4456	RSC979	KL-15-A	535	LL	FP		7-Apr-2015	PLKD	53	66	BS 111	EREZ423630	MB1PBEYC2EERP5326	69
4457	RSC980	KL-15-A	536	LL	FP		7-Apr-2015	PLKD	53	66	BS 111	EREZ423335	MB1PBEYC8EERP6244	69
4458	RSC990	KL-15-A	537	EML	SFP		7-Apr-2015	KTM	53	66		E613CDEM012269	MC2R1NRT0EM040262	47
4459	RSC991	KL-15-A	538	EML	SFP		9-Apr-2015	KTM	53	66		E613CDEMO12581	MC2R1NRT0EM040280	47
4460	17000	KL-15-A	539	LL	FP		9-Apr-2015	CGNR	53	66		EREZ425467	MB1PBEYC8EEFP7692	40
4461	RPK 2	KL-15-A	522	LL	SFP		26-Mar-2015	SBY	53	66		FDEZ404070	MB1PBEYC2FEDR4029	75
4462	RSE992	KL-15-A	523	LL	SFP		27-Mar-2015	MDY	53	66		FDEZ403150	MB1PBEYC3FEDR3049	76
4463	RSA972	KL-15-A	524	LL	FP		30-Mar-2015	KNPY	53	66		FEEZ400492	MB1PBEYC9FEER0496	87
4464	RSE993	KL-15-A	525	LL	SFP		31-Mar-2015	PLKD	53	66	BS 111	FDEZ403146	MB1PBEYCXFEDR3050	69
4465	RPK 3	KL-15-A	526	LL	SFP		31-Mar-2015	EKM	53	66		FDEZ404054	MB1PEYC3FEDR4024	56
4466	RPK 5	KL-15-A	540	LL	SFP		7-Apr-2015	TPLM	53	66		FDEZ404074	MB1PBEYCOFEDR4031	94
4467	RPA 9	KL-15-A	558	LL	FP		9-Apr-2015	KNPY	53	66		FEEZ400030	MB1PBEYC0FEER0046	87
4468	RSE995	KL-15-A	559	LL	SFP		10-Apr-2015	KNR	53	66		FDEZ403154	MB1PBEYC3FEDR3053	77
4469	RPK 6	KL-15-A	560	LL	SFP		10-Apr-2015	KMY	53	66		FDEZ404118	MB1PBEYC2FEDR4032	05
4470	RSC981	KL-15-A	561	LL	FP		13-Apr-2015	PLKD	53	66	BS 111	EREZ423334	MB1PBEYC8EERP5756	69
4471	RSC982	KL-15-A	562	LL	FP		16-Apr-2015	KTM	53	66		EREZ423997	MB1PBEYC4EERP6211	47

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4472	RSC983	KL-15-A	563	LL	FP		16-Apr-2015	KTM	53	66		EREZ424634	MB1PBEYC9EERP6849	47
4473	RSC984	KL-15-A	564	LL	FP		16-Apr-2015	KTM	53	66		EREZ424410	MB1PBEYC3EERP6622	47
4474	RSE996	KL-15-A	565	LL	SFP		13-Apr-2015	VZM	53	66		FDEZ403151	MB1PBEYC7FEDR3054	24
4475	RPA 10	KL-15-A	566	LL	FP		13-Apr-2015	PNR	53	66		EFEZ425928	MB1PBEYCOFEERP9855	78
4476	RSC985	KL-15-A	580	LL	FP		17-Apr-2015	TPLM	53	66		EREZ424075	MB1PBEYC3EERP6247	94
4477	RSC986	KL-15-A	581	LL	FP		17-Apr-2015	KKD	53	66		EREZ423635	MB1PBEYC4EERP5947	72
4478	RSC987	KL-15-A	582	LL	FP		17-Apr-2015	MDY	53	66		EREZ423805	MB1PBEYC4EERP6063	76
4479	RPC 17	KL-15-A	583	LL	FP		17-Apr-2015	EMLY	53	66		EREZ424699	MB1PBEYC5EERP6850	95
4480	RPK 32	KL-15-A	584	LL	SFP		16-Apr-2015	TVM	53	66		FDEZ404153	MB1PBEYC6FEDR4079	27
4481	RPA 11	KL-15-A	585	LL	FP		17-Apr-2015	TVL	53	66	BS 111	EFEZ426522	MB1PBEYC2EERP8627	43
4482	RPC 18	KL-15-A	586	LL	FP		21-Apr-2015	PALA	53	66	HBS 111	EREZ423007	MB1PBEYC7EERP5327	50
4483	RPC 19	KL-15-A	587	LL	FP		21-Apr-2015	RNI	53	66		ESEZ422573	MB1PBEYC3EERP5227	101
4484	RPM 1	KL-15-A	588	LL	FP		21-Apr-2015	MDY	53	66		EFEZ426392	MB1PBEYC7EERP8526	76
4485	RPE 12	KL-15-A	594	LL	SFP		21-Apr-2015	KMGH	53	66		FDEZ404072	MB1PBEYCXFEDR4022	55
4486	RPK 33	KL-15-A	595	LL	SFP		21-Apr-2015	SBY	53	66		FDEZ403802	MB1PBEYC3FEDR3679	75
4487	RPA 40	KL-15-A	596	LL	FP		21-Apr-2015	VTRA	53	66	HINO EURO BSIII	EFEZ426793	MB1PBEYCXEERP8942	17
4488	RPC 20	KL-15-A	597	LL	FP		24-Apr-2015	GVR	53	66		EREZ424415	MB1PBEYC4EERP6659	66
4489	RPC 21	KL-15-A	598	EML	SFP		24-Apr-2015	TVM	53	66	EICHER 20.15	E613CDEMO12260	MC2R1NRT0EM040259	27
4490	RPC 22	KL-15-A	599	LL	FP		24-Apr-2015	CGNR	53	66		EFEZ426798	MB1PBEYC7EERP8946	40
4491	RPM 37	KL-15-A	600	LL	FP		25-Apr-2015	CDLM	53	66		EFEZ426105	MB1PBEYC2EERP8191	80
4492	RPA 41	KL-15-A	601	LL	FP		24-Apr-2015	ALP	53	66		EFEZ426754	MB1PBEYC3EERP8944	45
4493	RPC 23	KL-15-A	602	LL	FP		27-Apr-2015	KMR	53	66	LL HINO BSIII	EFEZ426753	MB1PBEYC5EERP8945	30
4494	RPC 24	KL-15-A	603	LL	FP		27-Apr-2015	KTM	53	66	6ET1 3KN BSIII	EFEZ425620	MB1PBEYC7EERP7926	47
4495	RPC 26	KL-15-A	604	LL	FP		28-Apr-2015	MVPA	53	66	LL BS 111	EFEZ426040	MB1PBEYC7EERP8235	52
4496	RPE 13	KL-15-A	605	LL	SFP		27-Apr-2015	TDP	53	66		EDEZ404058	MB1PBEYC9FEDR4027	53
4497	RPK 34	KL-15-A	606	LL	SFP		27-Apr-2015	TDP	53	66		FDEZ404059	MB1PBEYC5FEDR4025	53
4498	RPM 38	KL-15-A	607	LL	FP		29-Apr-2015	ATL	53	66		EFEZ426385	MB1PBEYC2EERP8496	33
4499	RPC 25	KL-15-A	608	EML	SFP		29-Apr-2015	PTA	53	66	EMO 40281	EM040281	MC2RINRT0EM040281	37
4500	RPA 42	KL-15-A	609	LL	FP		27-Apr-2015	ATL	53	66		EFEZ426523	MB1PBEYC2EERP8630	33
4501	RPK 35	KL-15-A	610	LL	SFP		28-Apr-2015	EKM	53	66		FDEZ404073	MB1PBEYC9FEDR4030	56
4502	RPC 27	KL-15-A	611	LL	FP		2-May-2015	KLM	53	66	LL BS 111	EFEZ426505	MB1PBEYC7EERP8624	34
4503	RPE 14	KL-15-A	612	LL	SFP		29-Apr-2015	MVPA	53	66	LL BS 111	FDEZ404136	MB1PBEYC2FEDR4077	52
4504	RPC 29	KL-15-A	613	LL	FP		4-May-2015	KLM	53	66	LL BS III	EFEZ426518	MB1PBEYC2EERP8644	34
4505	RPA 43	KL-15-A	614	LL	FP		4-May-2015	KLM	53	66	LL BS III	FEEZ400782	MB1PBEYC0FEERP0810	34
4506	RPE 15	KL-15-A	615	LL	SFP		5-May-2015	VKM	53	66		FDEZ404151	MB1PBEYC2FEDR4080	51
4507	RPK 36	KL-15-A	616	LL	SFP		5-May-2015	GVR	53	66		FDEZ403993	MB1PBEYC0FEDR4028	66
4508	RPM 39	KL-15-A	617	LL	FP		7-May-2015	TSR	53	66		EFEZ426428	MB1PBEYC2EERP8529	63
4509	RPC 28	KL-15-A	618	LL	FP		7-May-2015	PLKD	53	66	BS 111	EFEZ426414	MB1PBEYC1EERP8523	69
4510	RPA 44	KL-15-A	619	LL	FP		6-May-2015	CTR	53	66		FEEZ400100	MB1PBEYC1FEERP0038	70
4511	RPE 16	KL-15-A	620	LL	SFP		7-May-2015	KYLM	53	66	HE 111	FDEZ404156	MB1PBEYC4FEDR4081	41
4512	RPA 72	KL-15-A	621	LL	FP		8-May-2015	MVK	53	66	FEE2400525	FEEZ400525	MB1PBEYC2FEERP0680	88
4513	RPM 77	KL-15-A	622	LL	FP		11-May-2015	KTM	53	66	LL BS III	EFEZ 426041	MB1PBEYCAEERP8192	47
4514	RPC 30	KL-15-A	623	LL	FP		11-May-2015	ALP	53	66		EREZ 423806	MB1PBEYC2EERP6062	45
4515	RPC 55	KL-15-A	624	LL	FP		11-May-2015	TVM	53	66	ALPSV 4/186 BS III	EFEZ426381	MB1PBEYC3EERP8488	27
4516	RPE 50	KL-15-A	628	LL	SFP		12-May-2015	NDD	53	66		FDEZ403766	MB1PBEYCXFEDR3677	31

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4517	RPA 73	KL-15-A	629	LL	FP		12-May-2015	KPA	53	66		FEEZ400111	MB1PBEYC2FEER0047	74
4518	RPM 78	KL-15-A	630	LL	FP		15-May-2015	TVM	53	66	VIKING HINO BS III	EFEZ426382	MB1PBEYC4EEFP8483	27
4519	RPC 57	KL-15-A	631	LL	FP		15-May-2015	TVM	53	66	EFEZ426383	ALPSV 4186	MB1PBEYC3EEFP8491	27
4520	RPK 45	KL-15-A	646	LL	SFP		18-May-2015	TVM	53	66	HINO BS III	FDEZ403815	MB1PBEYC3FEDR3682	27
4521	RPC 31	KL-15-A	647	EML	SFP		18-May-2015	PLKD	53	66	BS 111	E613CDEMO12262	MC2RINRTOEMO40261	69
4522	RPC 56	KL-15-A	648	EML	SFP		18-May-2015	SBY	53	66		E613CDEMO012248	MC2RINRTOEMO40260	75
4523	RPC 58	KL-15-A	649	LL	FP		18-May-2015	PBVR	53	66	LL BSIII	EVE2415336	MB1PBEYCOEEFP7928	59
4524	RPC 60	KL-15-A	650	LL	FP		18-May-2015	PBVR	53	66	LL BSIII	EFE2426384	MB1PBEYCOEEFP8495	59
4525	RPK 46	KL-15-A	658	LL	SFP		15-May-2015	KNPY	53	66	LL BS 111	FDEZ403685	MB1PBEYCSFEDR3683	87
4526	RPE 51	KL-15-A	659	LL	SFP		15-May-2015	TVM	53	66	ALPSV 4/186	FDEZ403799	MB1PBEYCFEDR3678	27
4527	RPA 74	KL-15-A	660	LL	FP		15-May-2015	KTDA	53	66	BS III	EREZ425398	MB1PBEYCXEEFP7600	25
4528	RPK 47	KL-15-A	661	LL	SFP		18-May-2015	MNR	53	66	HINO EURO BS 111	FDEZ403770	MB1PBEYC8FEDR3676	60
4529	RPM 79	KL-15-A	662	LL	FP		20-May-2015	PALA	53	66		FEEZ400103	MB1PBEYCXFEER0040	50
4530	RPC 59	KL-15-A	663	EML	SFP		20-May-2015	GVR	53	66		E613CDEM012582	MC2RINRTOEMO40278	66
4531	RPC 62	KL-15-A	668	LL	FP		22-May-2015	ATL	53	66		EREZ425386	MB1PBEYCXEEFP7601	33
4532	RPK 48	KL-15-A	664	LL	SFP		19-May-2015	TVM	53	66	VIKING HINO BS III	FDEZ403689	MB1PBEYCXFEDR3680	27
4533	RPC 61	KL-15-A	665	LL	FP		21-May-2015	VTRA	53	66	HINO EURO BSIII	EFEZ426484	MB1PBEYCOEEFP8626	17
4534	RPA 75	KL-15-A	666	LL	FP		19-May-2015	ATL	53	66		FEEZ401119	MB1PBEYC3FEER1093	33
4535	RPE 52	KL-15-A	667	LL	SFP		20-May-2015	KNPY	53	66		FDEZ403798	MB1PBEYC1FEDR3681	87
4536	RPC 63	KL-15-A	669	LL	FP		23-May-2015	KNR	53	66		EFEZ426387	MBJPBEYLIEEFP8487	77
4537	RPE 53	KL-15-A	670	LL	SFP		22-May-2015	KYLM	53	66	HE 111	FDEZ404150	MB1PBEYC6FEDR4082	41
4538	RPC 64	KL-15-A	671	LL	FP		25-May-2015	TLY	53	66	BS III 6ET1 3KN	EREZ425443	WB1PBEYCGEEFP 7691	18
4539	RPC 65	KL-15-A	672	LL	FP		25-May-2015	TLY	53	66	BS III 6ET1 3KN	EFEZ426521	MB1PBEYCGEEFP8629	18
4540	RPM 80	KL-15-A	673	LL	FP		25-May-2015	PNKM	53	66	HINO BS III	FEEZ401117	MB1PBEYC9FEER1096	49
4541	RPC 66	KL-15-A	674	LL	FP		26-May-2015	KMR	53	66	LL HINO BS III	EREZ423255	MB1PBEYCEERP5755	30
4542	RPC 67	KL-15-A	675	LL	FP		26-May-2015	HPD	53	66		EFEZ426400	MB1PBEYC7EEFP8493	42
4543	RPK 49	KL-15-A	676	LL	SFP		25-May-2015	TVM	53	66	VIKING BS III	FCEZ405553	MB1PBEYC5FEER5415	27
4544	RPC 70	KL-15-A	677	LL	FP		27-May-2015	KMGM	53	66		EFEZ426427	MB1PBEYC9EEFP8527	55
4545	RPK 82	KL-15-A	678	LL	SFP		26-May-2015	TVM	53	65	VIKING BS III HINO	FDEZ404955	MB1PBEYC5FEDR4784	27
4546	RPC 71	KL-15-A	679	LL	FP		28-May-2015	ATL	53	66		EFEZ425804	MB1PBEYC1EEFP8103	33
4547	RPC 99	KL-15-A	680	LL	FP		28-May-2015	KMR	53	66	LL HINO BS III	EFEZ426398	MB1PBEYC1EEFP8490	30
4548	RPA 91	KL-15-A	681	LL	FP		26-May-2015	NDD	53	66		FEEZ400654	MB1PBEYC2FEER0677	31
4549	RPM 81	KL-15-A	682	LL	FP		29-May-2015	KLM	53	66	LL BS III	FEEZ400657	MB1PBEYC9FEER0675	34
4550	RPC100	KL-15-A	683	LL	FP		29-May-2015	EDT	53	66		EFEZ426419	MB1PBEYCXEEFP8522	98
4551	RPE 54	KL-15-A	694	LL	SFP		27-May-2015	ADR	53	66	HINO BS III	FEEZ400104	MB1PBEYC6FEER0049	38
4552	RPA 76	KL-15-A	695	LL	FP		28-May-2015	PLKD	53	66	BS 111	FEEZ401118	MB1PBEYC1FEER1092	69
4553	RPK 83	KL-15-A	696	LL	SFP		29-May-2015	ADR	53	66	HINO BS III	FCEZ405444	MB1PBEYC7FEER5416	38
4554	RPE 86	KL-15-A	697	LL	SFP		29-May-2015	TVM	53	66	VIKING ALPSV 4/186	FDEZ404719	MB1PBEYC1FEDR3678	27
4555	RPA 92	KL-15-A	698	LL	FP		29-May-2015	PLKD	53	66		EFEZ426377	MB1PBEYC3FEER9848	69
4556	RPM 96	KL-15-A	699	LL	FP		1-Jun-2015	CHRY	53	66		ESEZ422886	MB1PBEYC9EEFP5328	44
4557	RPC102	KL-15-A	700	LL	FP		1-Jun-2015	TVM	53	66		EREZ423831	MB1PBEYC3EEFP6121	27
4558	RPC103	KL-15-A	701	LL	FP		1-Jun-2015	KTR	53	66	HINO6ET13KN BS III	EFEZ426520	MB1PBEYC4EEFP8628	35
4559	RPC104	KL-15-A	702	LL	FP		2-Jun-2015	ATL	53	66		EREZ425387	MB1PBEYC5EEFP7598	33
4560	RPC105	KL-15-A	703	LL	FP		3-Jun-2015	PTPM	53	66		EFEZ426390	MB1PBEYC5EEFP8492	15
4561	RPC107	KL-15-A	710	LL	FP		4-Jun-2015	SBY	53	66		FDEZ403141	MB1PBEYC8FEDR3046	75

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4562	RPK 84	KL-15-A	711	LL	SFP		2-Jun-2015	PBVR	53	66	LL BS 111	FCEZ405485	MB1PBEYC5FELR5446	59
4563	RPA 93	KL-15-A	712	LL	FP		2-Jun-2015	CHRY	53	66		FEEZ400699	MB1PBEYC3FEER0820	44
4564	RPM 97	KL-15-A	713	LL	FP		5-Jun-2015	TVL	53	66		FEEZ400660	MB1PBEYC7FEER0674	43
4565	RPC108	KL-15-A	714	LL	FP		5-Jun-2015	GVR	53	66		FDEZ403143	MB1PBEYC9FEDR3041	66
4566	RPE 87	KL-15-A	715	LL	SFP		4-Jun-2015	PLKD	53	66	BS 111	FDEZ404813	MB1PBEYC7FEDR4687	69
4567	RPK 85	KL-15-A	716	LL	SFP		5-Jun-2015	MVPA	53	66	LL BS 111	FDEZ404970	MB1PBEYC4FEDR4792	52
4568	RPC110	KL-15-A	717	LL	FP		8-Jun-2015	ETPA	53	66	HINO BSIII	FEEZ400491	MB1PBEYC0FEER0497	48
4569	RPA 94	KL-15-A	718	LL	FP		5-Jun-2015	ANK	53	66	LEYLAND BS III	EFEZ427728	MB1PBEYC9FEER9854	57
4570	RPC109	KL-15-A	719	LL	FP		9-Jun-2015	MVPA	53	66	LL BS 111	FDEZ403147	MB1PBEYCXFEDR3047	52
4571	RPE 88	KL-15-A	720	LL	SFP		8-Jun-2015	PMNA	53	66	HINO BS III	FDEZ404604	MB1PBEYC9FEDR4691	68
4572	RPC111	KL-15-A	721	LL	FP		10-Jun-2015	KMR	53	66	LL HINO BS III	FEEZ401116	MB1PBEYC7FEER1095	30
4573	RPC112	KL-15-A	722	LL	FP		11-Jun-2015	KNI	53	66		FDEZ403765	MB1PBEYC6FEDR3675	107
4574	RPM118	KL-15-A	723	LL	FP		11-Jun-2015	KMY	53	66		FEEZ401241	MB1PBEYC3FEER1143	05
4575	RPA 95	KL-15-A	724	LL	FP		9-Jun-2015	PVM	53	66		FDEZ404968	MB1PBEYC2FEDR4791	83
4576	RPE 89	KL-15-A	725	LL	SFP		10-Jun-2015	PNKM	53	66	HINO BS III	FDEZ404827	MB1PBEYC0FEDR4692	49
4577	RPK123	KL-15-A	726	LL	SFP		11-Jun-2015	ADR	53	66	HINO BS 111	FBEZ409050	MB1PBEYC3FEER8925	38
4578	RPA133	KL-15-A	727	LL	FP		12-Jun-2015	EDT	53	66		FCEZ405558	MB1PBEYC9FEER5448	98
4579	RPC114	KL-15-A	728	LL	FP		15-Jun-2015	NDM	53	66		FEER401101	MB1PBEYC0FEER1097	110
4580	RPM119	KL-15-A	729	LL	FP		15-Jun-2015	KMY	53	66		FEEZ400801	MB1PBEYC4FEER0809	05
4581	RPK124	KL-15-A	730	LL	SFP		15-Jun-2015	PMNA	53	66	FBEZ 408906	FBEZ408906	MB1PBEYC6FEER8787	68
4582	RPC139	KL-15-A	731	TATA	FP		16-Jun-2015	ALP	53	66		51B84209141	MAT412316FOCO1762	45
4583	RPC115	KL-15-A	732	LL	FP		17-Jun-2015	KPZA	53	66		FEEZ400698	MB1PBEYC0FEER0676	07
4584	RPC116	KL-15-A	733	LL	FP		18-Jun-2015	PDM	53	66		EFEZ426418	MB1PBEYC3FEER8524	39
4585	RPE 90	KL-15-A	734	LL	SFP		16-Jun-2015	TVM	53	66	VIKING ALPSV 4/186	FDEZ404840	MB1PBEYC4FEER4694	27
4586	RPA134	KL-15-A	735	LL	FP		16-Jun-2015	PSL	53	66	EFEZ426388 BS111	EFEZ426388	MB1PBEYC1FEER9847	21
4587	RPE128	KL-15-A	736	LL	SFP		17-Jun-2015	TSR	53	66		FBEZ409047	MB1PBEYC7FEER8927	63
4588	RPC155	KL-15-A	737	LL	FP		19-Jun-2015	PTA	53	66		FDEZ404960	MB1PBEYC9FEDR4786	37
4589	RPC117	KL-15-A	738	LL	FP		20-Jun-2015	CTR	53	66		FDEZ404055	MB1PBEYC7FEDR4026	70
4590	RPC144	KL-15-A	739	LL	FP		23-Jun-2015	RNI	53	66		FDEZ404686	MB1PBEYCXFEDR4554	101
4591	RPM120	KL-15-A	740	LL	FP		22-Jun-2015	MVPA	53	66	LL BS 111	FEEZ401120	MBZPBEYC5FEER1094	52
4592	RPE129	KL-15-A	741	LL	SFP		22-Jun-2015	TVM	53	66		FBEZ409271	MB1PBEYC2FEER9533	27
4593	RPA135	KL-15-A	742	LL	FP		22-Jun-2015	MVPA	53	66	LL BS III	EFEZ427686	MB1PBEYC5FEER9849	52
4594	RPC145	KL-15-A	743	LL	FP		24-Jun-2015	PALA	53	66		FDEZ404973	MB1PBEYCXFEDR4781	50
4595	RPK125	KL-15-A	744	LL	SFP		19-Jun-2015	TVM	53	66		FBEZ409053	MB1PBEYC5FEER8926	27
4596	RPM121	KL-15-A	745	LL	FP		24-Jun-2015	VLRD	53	66	LL BS III	FEEZ401121	MBJPBEYV5FEER1144	93
4597	RPC146	KL-15-A	746	LL	FP		25-Jun-2015	PLR	53	66		FDEZ404720	MB1PBEYC6FEDR4552	36
4598	RPK126	KL-15-A	747	LL	SFP		24-Jun-2015	EMLY	53	66		FBEZ409032	MB1PBEYC4FEER8934	95
4599	RPA136	KL-15-A	748	LL	FP		24-Jun-2015	KTDA	53	66		FBEZ408945	MB1PBEYC9FEER8783	25
4600	RPA137	KL-15-A	749	LL	FP		26-Jun-2015	PLD	53	66		FBEZ409067	MB1PBEYC6FEER8935	32
4601	RPM122	KL-15-A	750	LL	FP		29-Jun-2015	PNKM	53	66		FEEZ400656	MB1PBEYC6FEER0679	49
4602	RPK127	KL-15-A	751	LL	SFP		29-Jun-2015	MVPA	53	66	LL BS III	FAEZ410678	MB1PBEYCI FEASO463	52
4603	RPE130	KL-15-A	752	LL	SFP		29-Jun-2015	PLKD	53	66	BS 111	FBEZ409086	MB1PBEYC6FEER9535	69
4604	RPA138	KL-15-A	753	LL	FP		30-Jun-2015	ATL	53	66		FBEZ408921	MB1PBEYC2FEER8799	33
4605	RPM175	KL-15-A	754	LL	FP		2-Jul-2015	PKD	53	66		EFEZ426389	MB1PBEYC9FEER8494	65
4606	RPC 69	KL-15-A	755	LL	SLJ	SLJ	3-Jul-2015	TVM	53	66	ALPSV 4186	EFEZ 426373	MBIPBEYC6FEER8484	27

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4607	RPC98	KL-15-A	756	LL	SLJ	SLJ	3-Jul-2015	TVM	53	66	ALPSC 4/186	EFEZ426412	MB1PBEOCQEEFP8528	27
4608	RPE131	KL-15-A	757	LL	SFP		2-Jul-2015	TVM	53	66		FBEZ409101	MB1PBEOCXFEBR9537	27
4609	RPK165	KL-15-A	758	LL	SFP		2-Jul-2015	TVM	53	66		FAEZ410614	MB1PBEOC4FEAS0473	27
4610	RPC140	KL-15-A	759	TATA	FP		8-Jul-2015	KLM	53	66	TATA BS III	51B84210570	MAT412316FODO2703	34
4611	RPK166	KL-15-A	760	LL	SFP		7-Jul-2015	EKM	53	66		FAEZ410548	MB1PBEOC9FEAS 9467	56
4612	RPC148	KL-15-A	761	LL	FP		9-Jul-2015	PTA	53	66		FDEZ404835	MB1PBEOC7FEDR4690	37
4613	RPM176	KL-15-A	762	LL	FP		9-Jul-2015	TVM	53	66		EWEZ414367	MB1PBEOCXEEFP7922	27
4614	RPC101	KL-15-A	763	LL	SLJ	SLJ	13-Jul-2015	TVM	53	66	ALPSV4/86	EREZ423331	MB1PBEOC3EERP5776	27
4615	RPC106	KL-15-A	764	LL	SLJ	SLJ	13-Jul-2015	MNR	53	66		FDEZ403148	MB1PBEOC1FEDR3048	60
4616	RPC113	KL-15-A	765	LL	SLJ	SLJ	13-Jul-2015	PTA	53	66		FDEZ403145	MB1PBEOC2FEDR3043	37
4617	RPK167	KL-15-A	766	LL	SFP		10-Jul-2015	KLM	53	66	LL BS 111	FAEZ410597	MB1PBEOC0FEAS0468	34
4618	RPC147	KL-15-A	767	LL	FP		15-Jul-2015	TVM	53	66		FDEZ404727	MB1PBEOC7FEDR4558	27
4619	RPE132	KL-15-A	768	LL	SFP		14-Jul-2015	KLM	53	66	LL BS III	FBEZ409211	MB1PBEOCXFEBR9540	34
4620	RPC157	KL-15-A	769	LL	FP		16-Jul-2015	KTM	53	66	6ET1 3KN BSIII	FDEZ404722	MB1PBEOC8FEDR4553	47
4621	RPA182	KL-15-A	770	LL	FP		14-Jul-2015	KTP	53	66		EBEZ408924	MB1PBEOC3FEBR8794	14
4622	RPC156	KL-15-A	771	LL	FP		17-Jul-2015	TVM	53	66		FDEZ404726	MB1PBEOC9FEDR4562	27
4623	RPC149	KL-15-A	772	LL	FP		20-Jul-2015	GVR	53	66		FDEZ404843	MB1PBEOC2FEDR4693	66
4624	RPC150	KL-15-A	773	LL	FP		20-Jul-2015	KTM	53	66	6ET1 3KN BS III	FEEZ400655	MB1PBEOC2FEER0811	47
4625	RPK168	KL-15-A	774	LL	SFP		16-Jul-2015	IJK	53	66		FAEZ410720	MB1PBEOC6FEAS0474	89
4626	RPE170	KL-15-A	775	LL	SFP		16-Jul-2015	NTA	53	66		FAEZ410955	MB1PBEOC6FEAS1124	22
4627	RPA183	KL-15-A	776	LL	FP		16-Jul-2015	ETPA	53	66		FBEZ409016	MB1PBEOC8FEBR8922	48
4628	RPC142	KL-15-A	777	TATA	FP		21-Jul-2015	KYLM	53	66	LP 1S12TC/58 BS111	51C84214229	MAT412316FOCO2423	41
4629	RPC151	KL-15-A	778	LL	FP		21-Jul-2015	KNR	53	66		FDEZ404954	MB1PBEOC4FEDR4789	77
4630	RPC143	KL-15-A	779	TATA	FP		21-Jul-2015	ATL	53	66		51C84214233	MAT412316FOCO2422	33
4631	RPC153	KL-15-A	780	LL	FP		22-Jul-2015	EMLY	53	66		FDEZ404838	MB1PBEOC9FEDR4688	95
4632	RPK169	KL-15-A	781	LL	SFP		21-Jul-2015	TDP	53	66		FAEZ410681	MB1PBEOC3FEAS0464	53
4633	RPC152	KL-15-A	782	LL	FP		23-Jul-2015	PALA	53	66		FDEZ404725	MB1PBEOC7FEDR4561	50
4634	RPM188	KL-15-A	783	LL	FP		22-Jul-2015	MLTM	53	66		FEEZ400802	MB1PBEOC4FEER0812	54
4635	RPC141	KL-15-A	784	TATA	FP		24-Jul-2015	CLDY	53	66		51B84210321	MAT41216FODO2801	58
4636	RPA184	KL-15-A	785	LL	FP		23-Jul-2015	TVL	53	66		FBEZ409102	MB1PBEOCXFEBR8923	43
4637	RPC154	KL-15-A	786	LL	FP		25-Jul-2015	TVM	53	66		FDEZ404723	MB1PBEOC9FEDR4545	27
4638	RPA185	KL-15-A	787	LL	FP		25-Jul-2015	TVM	53	66	ALPSV 411865639 CM	FEEZ400502	MB1PBEOC2FEER0498	27
4639	RPC158	KL-15-A	788	LL	FP		27-Jul-2015	TVM	53	66		FDEZ404744	MB1PBEOC0FEDR4787	27
4640	RPE171	KL-15-A	789	LL	SFP		24-Jul-2015	KNR	53	66		FAEZ411221	MB1PBEOC8FEAS1125	77
4641	RPM189	KL-15-A	790	LL	FP		27-Jul-2015	TVM	53	66		FEEZ400653	MB1PBEOC4FEER0678	27
4642	RPC 68	KL-15-A	791	EML	SFP		29-Jul-2015	TSR	53	66		E613CDEMO12574	MC2R1NRT0EM040279	63
4643	RPC178	KL-15-A	792	TATA	FP		29-Jul-2015	KYLM	53	66		5184210606	MAT412312FODO2800	41
4644	RPK191	KL-15-A	825	LL	SFP		28-Jul-2015	KNR	53	66		FAEZ410523	MB1PBEOC2FEAS0469	77
4645	RPA186	KL-15-A	826	LL	FP		28-Jul-2015	TPLM	53	66		FBEZ409065	MB1PBEOC9FEBR8931	94
4646	RPE172	KL-15-A	827	LL	SFP		29-Jul-2015	EKM	53	66		FAEZ411008	MB1PBEOCXFEAS1126	56
4647	RPM190	KL-15-A	828	LL	FP		30-Jul-2015	CGNR	53	66		FDEZ403142	MB1PBEOC0FEDR3042	40
4648	RPC160	KL-15-A	829	LL	FP		31-Jul-2015	KTR	53	66	HBSIII	FDEZ411283	MB1PBEOC1FEDR3051	35
4649	RPK192	KL-15-A	830	LL	SFP		30-Jul-2015	PVR	53	66		FAEZ411283	MB1PBEOC9FEAS1120	23
4650	RPC159	KL-15-A	831	LL	FP		1-Aug-2015	TVM	53	66		FDEZ404949	MB1PBEOC0FEDR4790	27
4651	RPM212	KL-15-A	838	LL	FP		3-Aug-2015	TVM	53	66		FBEZ408949	MB1PBEOC2FEBR8785	27

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4652	RPE173	KL-15-A	839	LL	SFP		3-Aug-2015	CHRY	53	66		FAEZ411277	MB1PBEYCFEAS1127	44
4653	RPA187	KL-15-A	840	LL	FP		3-Aug-2015	TVM	53	66	FBEZ 409045	FBEZ409045	MB1PBEYC6EEBR8932	27
4654	RPE174	KL-15-A	841	LL	SFP		4-Aug-2015	CHRY	53	66		FAEZ411226	MB1PBEYC3FEAS1128	44
4655	RPC161	KL-15-A	842	LL	FP		6-Aug-2015	TVM	53	66		FDEZ404712	MB1PBEYC2FEDR4547	27
4656	RPC177	KL-15-A	843	TATA	FP		6-Aug-2015	KLM	53	66	TATA BS III	51B84210327	MAT412316FODO2803	34
4657	RPC179	KL-15-A	844	TATA	FP		6-Aug-2015	ATL	53	66		51C84210565	MAT412316FODO2707	33
4658	RPC180	KL-15-A	845	TATA	FP		6-Aug-2015	ALP	53	66		51B84210565	MAT412316FODO2998	45
4659	RPM211	KL-15-A	846	LL	FP		6-Aug-2015	PLKD	53	66	BS 111	FBEZ408927	MB1PBEYC9FEBR8797	69
4660	RPC162	KL-15-A	847	LL	FP		7-Aug-2015	PLKD	53	66	BS 111	FDEZ404728	MB1PBEYC2FEDR4564	69
4661	RPE196	KL-15-A	848	LL	SFP		6-Aug-2015	EKM	53	66		FAEZ411278	MB1PBEYC6FEAS1267	56
4662	RPA214	KL-15-A	849	TATA	FP		7-Aug-2015	PVR	53	66		51B84210566	MAT412316FODO2994	23
4663	RPM213	KL-15-A	850	LL	FP		10-Aug-2015	PLKD	53	66	BS 111	FBEZ408905	MB1PBEYC5FEBR8795	69
4664	RPK194	KL-15-A	858	LL	SFP		10-Aug-2015	PLKD	53	66	BS 111	FAEZ411224	MB1PBEYC2FEAS1122	69
4665	RPE197	KL-15-A	859	LL	ORD		10-Aug-2015	KMY	48	60	HINO BS III	FAEZ411344	MB1PBEYC6FEAS1270	05
4666	RPC181	KL-15-A	860	TATA	FP		12-Aug-2015	KPM	53	66		51B84212075	MAT412316FODO2805	91
4667	RPA215	KL-15-A	861	TATA	FP		11-Aug-2015	VKM	53	66		51884212071	MAT412316FODO3017	51
4668	RPE198	KL-15-A	862	LL	SFP		11-Aug-2015	KTP	53	66		FAEZ411456	MB1PBEYC0FEAS1278	14
4669	RPC163	KL-15-A	875	LL	FP		18-Aug-2015	TVM	53	66		FDEZ404946	MB1PBEYC8FEDR4794	27
4670	RPC164	KL-15-A	876	LL	FP		18-Aug-2015	TVM	53	66		FDEZ405443	MB1PBEYC2FECR5405	27
4671	RPK195	KL-15-A	877	LL	SFP		17-Aug-2015	HPD	53	66		FAEZ411205	MB1PBEYC4FEAS1123	42
4672	RPK229	KL-15-A	878	LL	SFP		18-Aug-2015	VLRD	53	66	LL BS 111	FAEZ411275	MB1PBEYC0FEAS1281	93
4673	RPE199	KL-15-A	879	LL	SFP		18-Aug-2015	ALV	53	66	LL BS III	FAEZ411594	MB1PBEYC7FEAS1522	61
4674	RPC203	KL-15-A	880	LL	FP		20-Aug-2015	PLKD	53	66	BS 111	FDEZ404717	MB1PBEYCFEDR4546	69
4675	RPM234	KL-15-A	881	LL	FP		20-Aug-2015	TVM	53	66		FBEZ408947	MB1PBEYC8FEBR8788	27
4676	RPC201	KL-15-A	882	LL	FP		21-Aug-2015	KMGM	53	66		FCEZ405538	MB1PBEYC6FECR5407	55
4677	RPC208	KL-15-A	883	LL	SLJ	SLJ	21-Aug-2015	PLKD	53	66	BS 111	FCEZ405555	MB1PBEYCOFECR5449	69
4678	RPC209	KL-15-A	884	LL	SLJ	SLJ	21-Aug-2015	PLKD	53	66	BS 111	EDE2405236	MB1PBEYC3FECR5414	69
4679	RPC210	KL-15-A	885	LL	SLJ	SLJ	21-Aug-2015	TVM	53	66		EDEZ405539	MB1PBEYCXFECR5409	27
4680	RPC205	KL-15-A	891	LL	FP		22-Aug-2015	PTA	53	66	LL BS III	FDEZ404724	MB1PBEYC0FEDR4563	37
4681	RPE200	KL-15-A	892	LL	SFP		20-Aug-2015	PALA	53	66		FAEZ410784	MB1PBEYC9FEAS1523	50
4682	RPA217	KL-15-A	893	TATA	FP		21-Aug-2015	GVR	53	66		51B84211130	MAT412316FODO3048	66
4683	RPC202	KL-15-A	894	LL	FP		24-Aug-2015	ETPA	53	66		FDEZ405395	MB1PBEYC8FECR5408	48
4684	RPM235	KL-15-A	895	LL	FP		24-Aug-2015	PLD	53	66		FBEZ408917	MB1PBEYC4FEBR8786	32
4685	RPC204	KL-15-A	896	TATA	FP		25-Aug-2015	CTLA	53	66		51C84216425	MAT412316FODO3073	46
4686	RPK193	KL-15-A	897	LL	SFP		6-Aug-2015	KMY	53	66		FAEZ411254	MB1PBEYCOFEAS1121	05
4687	RPA218	KL-15-A	898	TATA	FP		24-Aug-2015	TVM	53	66		51C84217346	MAT412316FODO3047	27
4688	RPK230	KL-15-A	899	LL	SFP		24-Aug-2015	ANK	53	66	HINO BS III	FAEZ411345	MB1PBEYC2FEAS1282	57
4689	RPE237	KL-15-A	900	LL	SFP		24-Aug-2015	KDLR	53	66		FAEZ411665	MB1PBEYC0FEAS1524	90
4690	RPA216	KL-15-A	916	TATA	FP		18-Aug-2015	TVM	53	66		51C84216420	MAT412316FODO3013	27
4691	RPM236	KL-15-A	917	LL	FP		26-Aug-2015	VKM	53	66		FBEZ409035	MB1PBEYC0FEBR8929	51
4692	RPC206	KL-15-A	918	TATA	FP		31-Aug-2015	ALP	53	66		5184210569	MAT412316FODO2992	45
4693	RPC207	KL-15-A	919	LL	FP		31-Aug-2015	VKM	53	66		FDEZ404837	MB1PBEYC0FEDR4689	51
4694	RPE238	KL-15-A	920	LL	SFP		26-Aug-2015	MVPA	53	66	LL BS III	FAEZ411680	MB1PBEYC2FEAS1525	52
4695	RPC219	KL-15-A	921	LL	FP		3-Sep-2015	ADR	53	66	HINO 6ET13KNBSIII	FEEZ400023	MB1PBEYC3FEER0039	38
4696	RPA242	KL-15-A	922	LL	FP		1-Sep-2015	KTM	53	66		FAEZ411821	MB1PBEYC8FEAS1674	47

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4697	RPC220	KL-15-A	923	LL	FP		4-Sep-2015	GVR	53	66	HINO 6ET13KN BS III	FEEZ400102	MB1PBEYC3FEER0042	66
4698	RPC221	KL-15-A	924	LL	SFP		4-Sep-2015	PVR	53	66		FCEZ405556	MB1PBEYC3FEER5445	23
4699	RPK231	KL-15-A	925	LL	SFP		1-Sep-2015	PMNA	53	66		FAEZ411458	MB1PBEYC8FEAS1271	68
4700	RPC222	KL-15-A	926	LL	FP		7-Sep-2015	CGNR	53	66		FEEZ400706	MB1PBEYC3FEER0672	40
4701	RPC223	KL-15-A	927	LL	FP		8-Sep-2015	NBR	53	66		FDEZ403144	MB1PBEYC4FEDR3044	86
4702	RPK232	KL-15-A	928	LL	SFP		7-Sep-2015	PVM	53	66		FAEZ411427	MB1PBEYC4FEAS1283	83
4703	RPA243	KL-15-A	929	LL	FP		7-Sep-2015	CHRY	53	66		FAEZ411666	MB1PBEYC2FEAS1668	44
4704	RPC224	KL-15-A	930	LL	FP		9-Sep-2015	CLDY	53	66		FEEZ400106	MB1PBEYC1FFER0086	58
4705	RPE239	KL-15-A	931	LL	SFP		8-Sep-2015	TPLM	53	66		FAEZ411676	MB1PBEYC4FEAS1526	94
4706	RPC225	KL-15-A	932	TATA	FP		10-Sep-2015	MVK	53	66		5184214240	MAT412316FOCO2421	88
4707	RPK233	KL-15-A	933	LL	SFP		9-Sep-2015	NDD	53	66		FAEZ411462	MB1PBEYC2FEAS1279	31
4708	RPC226	KL-15-A	934	LL	FP		11-Sep-2015	EMLY	53	66		FDEZ403140	MB1PBEYC6FEDR3045	95
4709	RPE240	KL-15-A	935	LL	SFP		10-Sep-2015	NDD	53	66		FAEZ411559	MB1PBEYC6FEAS1527	31
4710	RPA244	KL-15-A	936	LL	FP		10-Sep-2015	TDP	53	66		FAEZ412079	MB1PBEYC0FEAS1944	53
4711	RPM264	KL-15-A	937	LL	FP		11-Sep-2015	KYLM	53	66		FBEZ408941	MB1PBEYC0FEBR8784	41
4712	RPC227	KL-15-A	938	TATA	FP		14-Sep-2015	GVR	53	66		51C84216208	MAT412316FODO2995	66
4713	RPC228	KL-15-A	939	LL	FP		14-Sep-2015	KPZA	53	66		FCEZ405552	MB1PBEYC6FEER5410	07
4714	RPC252	KL-15-A	940	TATA	FP		15-Sep-2015	ATL	53	66		51C84214230	MAT412316FOCO2424	33
4715	RPE241	KL-15-A	941	LL	SFP		14-Sep-2015	TDP	53	66		FAEZ411774	MB1PBEYC5FEAS1597	53
4716	RPA245	KL-15-A	942	LL	FP		14-Sep-2015	TDP	53	66		FAEZ411778	MB1PBEYC4FEAS1669	53
4717	RPK268	KL-15-A	943	LL	SFP		14-Sep-2015	TDY	53	66		FAEZ412673	MB1PBEYC7FEYS2951	79
4718	RPM265	KL-15-A	944	LL	FP		14-Sep-2015	CTLA	53	66	HINO BS III	FBEZ408918	MB1PBEYC9FEBR8802	46
4719	RPC253	KL-15-A	945	LL	FP		16-Sep-2015	CDLM	53	66		FDEZ404812	MB1PBEYC1FEER5444	80
4720	RPC254	KL-15-A	946	LL	FP		17-Sep-2015	PTPM	53	66		FDEZ404948	MB1PBEYC1FEDR4782	15
4721	RPE247	KL-15-A	947	LL	SFP		15-Sep-2015	PALA	53	66		FYEZ412933	MB1PBEYC7FEYS2948	50
4722	RPC255	KL-15-A	948	LL	FP		18-Sep-2015	TVL	53	66		FDEZ404953	MB1PBEYC3FEDR4783	43
4723	RPA246	KL-15-A	949	LL	FP		17-Sep-2015	VDCY	53	66		FAEZ411557	MB1PBEYC2FEAS1945	82
4724	RPE248	KL-15-A	950	LL	SFP		17-Sep-2015	KMY	53	66		FYEZ412835	MB1PBEYC5FEYS3001	05
4725	RPK269	KL-15-A	951	LL	SFP		17-Sep-2015	TVL	53	66		FYEZ412936	MB1PBEYC9FEYS2952	43
4726	RPM266	KL-15-A	952	LL	FP		18-Sep-2015	TPLM	53	66		FBEZ409030	MB1PBEYC9FEBR8928	94
4727	RPA273	KL-15-A	955	LL	FP		19-Sep-2015	PSL	53	66	BS 111	FAEZ411773	MB1PBEYCXFEAS1627	21
4728	RPM267	KL-15-A	956	LL	FP		22-Sep-2015	KTP	53	66		FBEZ409015	MB1PBEYC1FEBR8924	14
4729	RPE249	KL-15-A	957	LL	SFP		22-Sep-2015	TVM	53	66		FAEZ412933	MB1PBEYC7FEYS3002	27
4730	RPK270	KL-15-A	958	LL	SFP		22-Sep-2015	ALP	53	66		FYEZ412968	MB1PBEYC5FEYS2950	45
4731	RPC256	KL-15-A	959	TATA	FP		25-Sep-2015	KYLM	53	66		51B84210607	MB1PBEYCFQDQ2993	41
4732	RPC257	KL-15-A	960	LL	FP		25-Sep-2015	VKM	53	66		FDEZ405419	MB1PBEYC4FEER5406	51
4733	RPE250	KL-15-A	961	LL	SFP		25-Sep-2015	SBY	53	66		FBES410430	MB1PBEYC2FEYS3005	75
4734	RPA274	KL-15-A	962	LL	FP		25-Sep-2015	MLPY	53	66		FYEZ413477	MB1PBEYCFEYS3567	96
4735	RPC258	KL-15-A	963	TATA	FP		28-Sep-2015	KTR	53	66	1512 BS III	51B84210315	MAT412316FQDQ2802	35
4736	RPC259	KL-15-A	964	LL	FP		28-Sep-2015	ALP	53	66		FCEZ405557	MB1PBEYC7FEER5447	45
4737	RPC260	KL-15-A	965	TATA	FP		28-Sep-2015	CTNR	53	66		51C84216212	MAT412316FQDQ2997	97
4738	RPC261	KL-15-A	966	LL	FP		28-Sep-2015	PTA	53	66	LL BS III	FDEZ403104	MB1PBEYC7FEDR3040	37
4739	RPC262	KL-15-A	967	LL	FP		28-Sep-2015	CGNR	53	66		FDEZ404957	MB1PBEYC7FEDR4785	40
4740	RPM284	KL-15-A	975	LL	FP		28-Sep-2015	CGNR	53	66		FAEZ411424	MB1PBEYC9FEAS1277	40
4741	RPK271	KL-15-A	976	LL	SFP		28-Sep-2015	SBY	53	66	HINO BSIII	FAEZ412373	MB1PBEYC5FEYS3015	75

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4742	RPA275	KL-15-A	977	LL	FP		28-Sep-2015	PSL	53	66	BS 111	FYES413477	MB1PBEYC2FEYS3568	21
4743	RPC263	KL-15-A	978	LL	FP		29-Sep-2015	TVL	53	66		FDEZ404957	MB1PBEYC2FEDR4788	43
4744	RPE251	KL-15-A	979	LL	SFP		30-Sep-2015	PTA	53	66	BS III	FAEZ412611	MB1PBEYC9FEYS3017	37
4745	RPK272	KL-15-A	980	LL	SFP		30-Sep-2015	KNR	53	66		FAEZ412620	MB1PBEYCCQFEYS3004	77
4746	RPC287	KL-15-A	981	LL	FP		1-Oct-2015	ALV	53	66	6ET13KN BS III	FEEZ400101	MB1PBEYC5FEER0043	61
4747	RPC288	KL-15-A	982	TATA	FP		1-Oct-2015	KYLM	53	66		51B84211234	MAT412316FQDQ2809	41
4748	RPM285	KL-15-A	983	LL	FP		1-Oct-2015	ARK	53	66		FAEZ410507	MB1PBEYC8FEAS1268	06
4749	RPC289	KL-15-A	984	TATA	FP		3-Oct-2015	KLM	53	66		51B84210602	MAT412316FQDQ2704	34
4750	RPA276	KL-15-A	985	LL	FP		1-Oct-2015	PLR	53	66		FAEZ411610	MB1PBEYC2FEYS3120	36
4751	RPC290	KL-15-A	986	LL	FP		5-Oct-2015	KGD	53	66		FDEZ404950	MB1PBEYC6FEDR4793	84
4752	RPC291	KL-15-A	992	LL	FP		6-Oct-2015	PDM	53	66		FCEZ407575	MB1PBEYC1FEFCR7260	39
4753	RPE279	KL-15-A	993	LL	FP		5-Oct-2015	PVR	53	66		FYEZ413689	MB1PBEYC8FEYS3803	23
4754	RPC292	KL-15-A	994	LL	FP		7-Oct-2015	KTR	53	66	HBS III	FCEZ407571	MB1PBEYC8FEFCR7269	35
4755	RPC293	KL-15-A	996	LL	FP		8-Oct-2015	RNI	53	66		FCEZ407573	MB1PBEYC5FEFCR7259	101
4756	RPA277	KL-15-A	998	LL	FP		6-Oct-2015	ADR	53	66	HINO BS III	FYEZ413425	MB1PBEYC7FEYS3565	38
4757	RPC294	KL-15-A	999	TATA	FP		9-Oct-2015	KLM	53	66		51B84211231	MAT412316FQDQ2806	34
4758	RPC295	KL-15-A	1000	LL	FP		12-Oct-2015	CDLM	53	66		FCEZ407637	MB1PBEYCCQFEFCR7489	80
4759	RPC296	KL-15-A	1001	LL	FP		12-Oct-2015	PTPM	53	66		FCEZ407460	MB1PBEYCCQFEFCR7413	15
4760	RPE280	KL-15-A	1002	LL	FP		8-Oct-2015	PLR	53	66		FYEZ413626	MB1PBEYC7FEYS3808	36
4761	RPM286	KL-15-A	1003	LL	FP		9-Oct-2015	CGNR	53	66		FAEZ411468	MB1PBEYCXFEAS1269	40
4762	RPC297	KL-15-A	1004	LL	FP		13-Oct-2015	KMR	53	66	LL HINO BS III	FCEZ407395	MB1PBEYC2FEFCR7414	30
4763	RPA278	KL-15-A	1005	LL	FP		9-Oct-2015	PTA	53	66	LL BS111	FYEZ414177	MB1PBEYC4FEYS4592	37
4764	RPE281	KL-15-A	1006	LL	FP		12-Oct-2015	KTM	53	66		FYEZ413714	MB1PBEYC2FEYS3909	47
4765	RPK305	KL-15-A	1007	LL	SFP		12-Oct-2015	TVM	53	66		FYEZ413066	MB1PBEYC1FEYS3125	27
4766	RPC298	KL-15-A	1008	TATA	FP		14-Oct-2015	PVR	53	66		51C84214248	MAT412316FQDQ3001	23
4767	RPC299	KL-15-A	1009	LL	FP		15-Oct-2015	EKM	53	66		FCEZ407579	MB1PBEYC4FEFCR7270	56
4768	RPA317	KL-15-A	1010	LL	FP		13-Oct-2015	ALV	53	66	LL BS III	FYEZ413928	MB1PBEYC9FEYS4586	61
4769	RPC300	KL-15-A	1011	LL	FP		16-Oct-2015	ETPA	53	66	6ET13KN BS 111	FCEZ405739	MB1PBEYC5FEFCR7410	48
4770	RPM309	KL-15-A	1012	LL	FP		15-Oct-2015	KLM	53	66		FAEZ411467	MB1PBEYC9FEAS1280	34
4771	RPE282	KL-15-A	1013	LL	FP		15-Oct-2015	PMNA	53	66		FYEZ413330	MB1PBEYC2FEYS3912	68
4772	RPC301	KL-15-A	1014	LL	FP		17-Oct-2015	PALA	53	66		FCEZ407591	MB1PBEYC6FEFCR7271	50
4773	RPK306	KL-15-A	1015	LL	SFP		15-Oct-2015	TVM	53	66		FYEZ412967	MB1PBEYC9FEYS2949	27
4774	RPE283	KL-15-A	1016	LL	FP		16-Oct-2015	ADR	53	66	HINO BS III	FYEZ413784	MB1PBEYC4FEYS3913	38
4775	RPM310	KL-15-A	1017	LL	FP		17-Oct-2015	EMLY	53	66		FAEZ411461	MB1PBEYCXFEAS1272	95
4776	RPC302	KL-15-A	1018	LL	FP		21-Oct-2015	EKM	53	66		FCEZ406053	MB1PBEYC8FEFCR7496	56
4777	RPC303	KL-15-A	1019	TATA	FP		21-Oct-2015	KYLM	53	66		51C84216429	MAT412316FCDO3054	41
4778	RPC324	KL-15-A	1020	LL	FP		26-Oct-2015	PTA	53	66	LL BS III	FCEZ 407594	MB1PBEYC1FEFCR7422	37
4779	RPA318	KL-15-A	1021	LL	FP		16-Oct-2015	KTM	53	66		FYEZ414226	MB1PBEYC2FEYS4591	47
4780	RPC323	KL-15-A	1022	LL	FP		21-Oct-2015	CGNR	53	66		FCEZ407638	MB1PBEYC7FEFCR7411	40
4781	RPC325	KL-15-A	1023	TATA	FP		26-Oct-2015	VZM	53	66	TC BS 111	51B84211232	MAT412316FODO2807	24
4782	RPC326	KL-15-A	1024	LL	FP		26-Oct-2015	CGNR	53	66		FCEZ407296	MB1PBEYC4FEFCR7494	40
4783	RPK307	KL-15-A	1025	LL	SFP		19-Oct-2015	TVM	53	66		FAEZ411609	MB1PBEYC8FEYS3123	27
4784	RPA319	KL-15-A	1026	LL	FP		20-Oct-2015	KGD	53	66		FYEZ413927	MB1PBEYC5FEYS4620	84
4785	RPM311	KL-15-A	1027	LL	FP		21-Oct-2015	KGD	53	66		FAEZ411780	MB1PBEYCCOFEAS1667	84
4786	RPM344	KL-15-A	1028	LL	FP		26-Oct-2015	KGD	53	66		FAEZ411603	MB1PBEYCCOFEAS1670	84

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4787	RPC327	KL-15-A	1029	LL	FP		27-Oct-2015	KGD	53	66		FCEZ407555	MB1PBEYC1FEFCR7484	84
4788	RPK308	KL-15-A	1030	LL	SFP		26-Oct-2015	TPLM	53	66		FYEZ413082	MB1PBEYC2FEYS3117	94
4789	RPA320	KL-15-A	1031	LL	FP		26-Oct-2015	PTA	53	66	LL BS III	FCEZ414212	MB1PBEYC6FFYS4593	37
4790	RPC328	KL-15-A	1032	LL	FP		28-Oct-2015	KYLM	53	66	LL BS III	FCEZ407570	MB1PBEYC6FEFCR7481	41
4791	RPE312	KL-15-A	1033	LL	FP		26-Oct-2015	TSR	53	66		FXEZ415558	MB1PBEYC2FEXS6127	63
4792	RPE313	KL-15-A	1034	LL	FP		27-Oct-2015	TSR	53	66		FXEZ415559	MB1PBEYC4FEXS6128	63
4793	RPC329	KL-15-A	1035	LL	FP		29-Oct-2015	PDM	53	66		FCEZ407633	MB1PBEYCXFEFCR7421	39
4794	RPC330	KL-15-A	1036	TATA	FP		30-Oct-2015	ATL	53	66		51C84216432	MAT412316F0D03041	33
4795	RPA321	KL-15-A	1037	LL	FP		29-Oct-2015	NTA	53	66		FYEZ413885	MB1PBEYC4FEYS4608	22
4796	RPK348	KL-15-A	1038	LL	SFP		29-Oct-2015	TVM	53	66		FXEZ415575	MB1PBEYCXFEXS6151	27
4797	RPM345	KL-15-A	1039	LL	FP		30-Oct-2015	PMNA	53	66		FAEZ411777	MB1PBEYC2FEAS1671	68
4798	RPK349	KL-15-A	1040	LL	SFP		30-Oct-2015	TVM	53	66		FXEZ415580	MB1PBEYC1FEXS6152	27
4799	RPA322	KL-15-A	1041	LL	FP		30-Oct-2015	TDP	53	66		FYEZ414174	MB1PBEYC2FEYS4607	53
4800	RPE314	KL-15-A	1042	LL	FP		2-Nov-2015	EDT	53	66		FXEZ415569	MB1PBEYC6FEXS6129	98
4801	RPC331	KL-15-A	1043	LL	FP		3-Nov-2015	TDP	53	66		FCEZ407540	MB1PBEYC9FEFCR7488	53
4802	RPM346	KL-15-A	1044	LL	FP		3-Nov-2015	KGD	53	66		FAEZ411754	MB1PBEYC8FEAS1626	84
4803	RPE315	KL-15-A	1045	LL	FP		3-Nov-2015	PNI	53	66	6ET1 3KN BS 111	FXEZ415582	MB1PBEYC1FEXS6149	67
4804	RPK351	KL-15-A	1046	LL	FP		5-Nov-2015	NTA	53	66		FXEZ415603	MB1PBEYC6FEXS6213	22
4805	RPA352	KL-15-A	1047	LL	FP		6-Nov-2015	GVR	53	66		FCEZ407376	MB1PBEYC7FEYS4621	66
4806	RPE316	KL-15-A	1048	LL	FP		6-Nov-2015	KTP	53	66		FXEZ415583	MB1PBEYC8FEXS6150	14
4807	RPK350	KL-15-A	1049	LL	FP		9-Nov-2015	PVM	53	66		FXEZ415572	MB1PBEYC5FEXS6154	83
4808	RPM347	KL-15-A	1050	LL	FP		11-Nov-2015	PLKD	53	66	BS 111	FAEZ411820	MB1PBEYCXFEAS1675	69
4809	RPA353	KL-15-A	1121	LL	FP		11-Nov-2015	ETPA	53	66		FYEZ414265	MB1PBEYC0FEYS4637	48
4810	RPA354	KL-15-A	1122	LL	FP		12-Nov-2015	VJMD	53	66		FYEZ414221	MB1PBEYC2FEYS4638	16
4811	RPE358	KL-15-A	1123	LL	FP		12-Nov-2015	KKLM	53	66		FXEZ415605	MB1PBEYC8FEXS6214	108
4812	RPK378	KL-15-A	1124	LL	FP		12-Nov-2015	PVM	53	66		FXEZ415581	MB1PBEYC8FEXS6245	83
4813	RPM383	KL-15-A	1125	LL	FP		12-Nov-2015	CDLM	53	66		FAEZ412694	MB1PBEYC9FEYS3003	80
4814	RPM384	KL-15-A	1126	LL	FP		16-Nov-2015	KTM	53	66		FAEZ412681	MB1PBEYC3FEYS2946	47
4815	RPA355	KL-15-A	1127	LL	FP		16-Nov-2015	MLPY	53	66		FYEZ413421	MB1PBEYC1FEYS3805	96
4816	RPC332	KL-15-A	1128	TATA	FP		19-Nov-2015	PBVR	53	66	LPO 1512 TC/58 BS 111	51C84214228	MAT412316F0D03011	59
4817	RPC333	KL-15-A	1129	LL	FP		19-Nov-2015	KTDA	53	66	BS III	FCEZ407574	MB1PBEYC3FEFCR7258	25
4818	RPC334	KL-15-A	1130	LL	FP		19-Nov-2015	NDD	53	66		FCEZ407639	MB1PBEYC6FEFCR7416	31
4819	RPC335	KL-15-A	1131	LL	FP		19-Nov-2015	PALA	53	66		FCEZ407162	MB1PBEYC7FEFCR7490	50
4820	RPC336	KL-15-A	1132	LL	FP		19-Nov-2015	CGNR	53	66		FCEZ407556	MB1PBEYC8FEFCR7482	40
4821	RPC337	KL-15-A	1133	LL	FP		19-Nov-2015	TVL	53	66		FCEZ407636	MB1PBEYC9FEFCR7412	43
4822	RPC338	KL-15-A	1134	LL	FP		19-Nov-2015	PMNA	53	66		FCEZ407194	MB1PBEYC0FEFCR7492	68
4823	RPC339	KL-15-A	1135	LL	FP		19-Nov-2015	MLTM	53	66		FCEZ407640	MB1PBEYC2FEFCR7476	54
4824	RPC340	KL-15-A	1136	TATA	FP		19-Nov-2015	KDLR	53	66		51C84217337	MAT412316F0D03038	90
4825	RPC341	KL-15-A	1137	TATA	FP		19-Nov-2015	KLM	53	66		51C84216575	MAT412316F0D02999	34
4826	RPC363	KL-15-A	1138	LL	FP		19-Nov-2015	NTA	53	66		FCEZ407632	MB1PBEYC4FEFCR7415	22
4827	RPC364	KL-15-A	1139	LL	FP		19-Nov-2015	MPM	53	66		FCEZ407561	MB1PBEYC3FEFCR7485	71
4828	RPC365	KL-15-A	1140	LL	FP		19-Nov-2015	KTDA	53	66	BS 111	FCEZ407558	MB1PBEYC7FEFCR7487	25
4829	RPK379	KL-15-A	1141	LL	FP		16-Nov-2015	MVPA	53	66	LL BS 111	FXEZ415635	MB1PBEYC1FEXS6247	52
4830	RPE359	KL-15-A	1142	LL	FP		17-Nov-2015	PLR	53	66		FXEZ415664	MB1PBEYCXFEXS6215	36
4831	RPM385	KL-15-A	1143	LL	FP		19-Nov-2015	MKD	53	66		FYEZ412940	MB1PBEYC5FEYS2947	08

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4832	RPC366	KL-15-A	1144	LL	FP		20-Nov-2015	PSL	53	66	BS 111	FCEZ407590	MB1PBEYCXFEFCR7483	21
4833	RPA356	KL-15-A	1145	LL	FP		19-Nov-2015	KTR	53	66	HBS 111	FYEZ413069	MB1PBEYCXFEYS3804	35
4834	RPE360	KL-15-A	1146	LL	FP		19-Nov-2015	ADR	53	66	HINO BSIII	FXEZ415609	MB1PBEYC1FEFS6216	38
4835	RPK380	KL-15-A	1147	LL	FP		19-Nov-2015	TVL	53	66		FXEZ415660	MB1PBEYC3FEFS6248	43
4836	RPC367	KL-15-A	1148	LL	FP		21-Nov-2015	KMR	53	66		FCEZ407500	MB1PBEYC2FEFCR7493	30
4837	RPC368	KL-15-A	1149	LL	FP		23-Nov-2015	PDM	53	66		FCEZ407557	MB1PBEYC5FEFCR7486	39
4838	RPM386	KL-15-A	1150	LL	FP		23-Nov-2015	KMR	53	66		FYEZ414028	MB1PBEYCXFEYS4273	30
4839	RPC342	KL-15-A	1151	TATA	FP		24-Nov-2015	ATL	53	66		51B84210596	MAT412316F0D02706	33
4840	RPC369	KL-15-A	1152	LL	FP		24-Nov-2015	VDCY	53	66		FCEZ407206	MB1PBEYC6FEFCR7495	82
4841	RPE361	KL-15-A	1153	LL	FP		23-Nov-2015	CLDY	53	66		FXEZ415396	MB1PBEYC3FEFS6217	58
4842	RPC370	KL-15-A	1154	LL	FP		25-Nov-2015	CLDY	53	66		FCEZ407278	MB1PBEYC9FEFCR7491	58
4843	RPA357	KL-15-A	1155	LL	FP		23-Nov-2015	PALA	53	66		FYEZ413690	MB1PBEYC5FEYS3087	50
4844	RPK381	KL-15-A	1156	LL	FP		23-Nov-2015	CTR	53	66		FXEZ415691	MB1PBEYC5FEFS6297	70
4845	RPA393	KL-15-A	1157	LL	FP		25-Nov-2015	KTR	53	66	HBS III	FYEZ413263	MB1PBEYC3FEYS3806	35
4846	RPM387	KL-15-A	1158	LL	FP		26-Nov-2015	MVPA	53	66	LL BS 111	FYEZ414086	MB1PBEYC8FEYS4272	52
4847	RPC371	KL-15-A	1159	LL	FP		27-Nov-2015	PLR	53	66		FBEZ408940	MB1PBEYC0FEBR8798	36
4848	RPC372	KL-15-A	1160	LL	FP		27-Nov-2015	KTDA	53	66	BS 111	FBEZ408582	MB1PBEYC1FEBR9538	25
4849	RPE362	KL-15-A	1161	LL	FP		26-Nov-2015	ADR	53	66	HINO BS III	FXEZ415606	MB1PBEYC5FEFS6218	38
4850	RPK382	KL-15-A	1162	LL	FP		26-Nov-2015	PALA	53	66		FXEZ415753	MB1PBEYC3FEFS6301	50
4851	RPC373	KL-15-A	1163	LL	FP		28-Nov-2015	NTA	53	66		FBEZ408925	MB1PBEYC7FEBR8796	22
4852	RPC343	KL-15-A	1164	TATA	FP		30-Nov-2015	ALP	53	66		51B84212076	MAT412316F0D02804	45
4853	RPA394	KL-15-A	1165	LL	FP		27-Nov-2015	PLKD	53	66	BS 111	FYEZ413426	MB1PBEYC1FEYS3562	69
4854	RPM405	KL-15-A	1166	LL	FP		30-Nov-2015	KMR	53	66		FYEZ414004	MB1PBEYC8FEYS4255	30
4855	RPA395	KL-15-A	1167	TATA	FP		30-Nov-2015	CTNR	53	66		51C84216428	MAT412316F0D03080	97
4856	RPK399	KL-15-A	1168	LL	FP		30-Nov-2015	PTPM	53	66		FYEZ415754	MB1PBEYC1FEYS2945	15
4857	RPC407	KL-15-A	1169	TATA	FP		30-Nov-2015	GVR	53	66		51C84217344	MAT412316F0D03039	66
4858	RPC408	KL-15-A	1170	TATA	FP		2-Dec-2015	PNI	53	66	LP 1512 TC BS111	51C84216581	MAT412316F0D03006	67
4859	RPE388	KL-15-A	1171	LL	SFP		1-Dec-2015	KTR	53	66	HBS 111	FYEZ414217	MB1PBEYC0FEYS4413	35
4860	RPC374	KL-15-A	1172	LL	FP		3-Dec-2015	NBR	53	66		FBEZ409048	MB1PBEYC7FEBR8930	86
4861	RPC375	KL-15-A	1173	LL	FP		4-Dec-2015	VDCY	53	66		FBEZ409664	MB1PBEYC9FEBR9531	82
4862	RPM406	KL-15-A	1174	LL	FP		4-Dec-2015	KTDA	53	66		FYEZ413810	MB1PBEYC6FEYS4013	25
4863	RPC376	KL-15-A	1175	LL	FP		5-Dec-2015	CTR	53	66		FBEZ409406	MB1PBEYC4FEBR9534	70
4864	RPK400	KL-15-A	1176	LL	SFP		4-Dec-2015	TVM	53	66		FYEZ413324	MB1PBEYC9FEYS3566	27
4865	RPE389	KL-15-A	1177	LL	SFP		4-Dec-2015	KMY	53	66		FYEZ414222	MB1PBEYC2FEYS4414	05
4866	RPA396	KL-15-A	1178	TATA	FP		5-Dec-2015	PVR	53	66		51B84210572	MAT412316F0D02705	23
4867	RPM427	KL-15-A	1179	LL	FP		7-Dec-2015	KTR	53	66	HBS 111	FYEZ413747	MB1PBEYC9FEYS3910	35
4868	RPC409	KL-15-A	1180	TATA	FP		8-Dec-2015	VZM	53	66		51C84210974	MAT412316F0D03012	24
4869	RPC410	KL-15-A	1181	TATA	FP		8-Dec-2015	CTNR	53	66		51C84215936	MAT412316F0D03050	97
4870	RPC411	KL-15-A	1182	TATA	FP		9-Dec-2015	KYLM	53	66		51C84216582	MAT412316F0D03004	41
4871	RPK402	KL-15-A	1183	LL	SFP		8-Dec-2015	TVM	53	66		FYEZ413509	MB1PBEYC5FEYS3564	27
4872	RPC412	KL-15-A	1184	TATA	FP		10-Dec-2015	KLM	53	66		51C84217350	MAT412316F0D03044	34
4873	RPA397	KL-15-A	1185	TATA	FP		9-Dec-2015	VKM	53	66		51C84217351	MAT412316F0D03085	51
4874	RPC413	KL-15-A	1186	TATA	FP		11-Dec-2015	KDLR	53	66		51C84214237	MAT412316F0D03009	90
4875	RPK401	KL-15-A	1187	LL	SFP		11-Dec-2015	TVM	53	66		FXEZ415529	MB1PBEYC3FEFS6153	27
4876	RPM428	KL-15-A	1188	LL	FP		11-Dec-2015	KTR	53	66	HBS 111	FYEZ413530	MB1PBEYCXFEYS3561	35

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4877	RPC377	KL-15-A	1189	LL	FP		14-Dec-2015	TSR	53	66		FBEZ409018	MB1PBEYC2FEBR8933	63
4878	RPC414	KL-15-A	1190	TATA	FP		14-Dec-2015	HPD	53	66		51C84216207	MAT412316F0D03071	42
4879	RPE390	KL-15-A	1191	LL	SFP		10-Dec-2015	PLKD	53	66		FYEZ414179	MB1PBEYC1FEYS4453	69
4880	RPE391	KL-15-A	1192	LL	SFP		14-Dec-2015	PLKD	53	66		FYEZ413751	MB1PBEYC3FEYS4454	69
4881	RPC418	KL-15-A	1193	TATA	SFP		16-Dec-2015	CTLA	53	66		51C84216427	MAT412316F0D03083	46
4882	RPM429	KL-15-A	1194	LL	FP		15-Dec-2015	VDCY	53	66		FYEZ413474	MB1PBEYC4FEYS3569	82
4883	RPC422	KL-15-A	1195	TATA	SFP		17-Dec-2015	CLDY	53	66		51C84216577	MAT412316F0D03014	58
4884	RPK403	KL-15-A	1196	LL	FP		15-Dec-2015	PALA	53	66		FYEZ414684	MB1PBEYC6FEYS5224	50
4885	RPA398	KL-15-A	1197	TATA	FP		15-Dec-2015	KDLR	53	66		51C84216415	MAT412316F0D03082	90
4886	RPA455	KL-15-A	1198	TATA	FP		17-Dec-2015	KYLM	53	66		51C84216417	MAT412316F0D03084	41
4887	RPE392	KL-15-A	1199	LL	SFP		17-Dec-2015	MPM	53	66		FYEZ414178	MB1PBEYC7FEYS4456	71
4888	RPM461	KL-15-A	1200	LL	FP		18-Dec-2015	ETPA	53	66		FAEZ411614	MB1PBEYC6FEYS3119	48
4889	RPA456	KL-15-A	1201	TATA	FP		18-Dec-2015	MVK	53	66		51D84223256	MAT412316F0E03288	88
4890	RPK404	KL-15-A	1202	LL	SFP		21-Dec-2015	CTLA	53	66		FYEZ414692	MB1PBEYC9FEYS5220	46
4891	RPE430	KL-15-A	1203	LL	SFP		21-Dec-2015	PSL	53	66	BS III	FYEZ414689	MB1PBEYCZFEXS1522	21
4892	RPA457	KL-15-A	1204	TATA	FP		21-Dec-2015	TPLM	53	66		51C84215939	MAT412316F0D03078	94
4893	RPM462	KL-15-A	1205	LL	FP		22-Dec-2015	TPLM	53	66		FYEZ413387	MB1PBEYC0FEYS3911	94
4894	RPK465	KL-15-A	1206	LL	SFP		23-Dec-2015	PNR	53	66		FBEZ408034	MB1PBEYC7FEYS3016	78
4895	RPA458	KL-15-A	1207	TATA	FP		23-Dec-2015	KNPY	53	66		51C84216416	MAT412316F0D03072	87
4896	RPM463	KL-15-A	1208	LL	FP		28-Dec-2015	KMY	53	66		FYEZ414030	MB1PBEYC6FEYS4271	05
4897	RPK466	KL-15-A	1209	LL	SFP		28-Dec-2015	NTA	53	66		FYEZ413368	MB1PBEYC3FEYS3563	22
4898	RPA459	KL-15-A	1210	TATA	FP		29-Dec-2015	VZM	53	66		51D84223251	MAT412316F0E03287	24
4899	RPE431	KL-15-A	1211	LL	SFP		31-Dec-2015	NTA	53	66		FAEZ412492	MB1PBEYC0FEYS3116	22
4900	RPE432	KL-15-A	1212	LL	SFP		31-Dec-2015	NTA	53	66		FYEZ414087	MB1PBEYC7FEYS4411	22
4901	RPK467	KL-15-A	1213	LL	SFP		31-Dec-2015	PNR	53	66		FYEZ412834	MB1PBEYC4FEYS3006	78
4902	RPC415	KL-15-A	1214	LL	FP		1-Jan-2016	PNKM	53	66		FBEZ408760	MB1PBEYC3FEBR9539	49
4903	RPM464	KL-15-A	1215	LL	FP		1-Jan-2016	PTPM	53	66		FYEZ413934	MB1PBEYC6FEYS4254	15
4904	RPC416	KL-15-A	1216	TATA	FP		4-Jan-2016	VKM	53	66		51C84216213	MAT412316F0D02996	51
4905	RPC420	KL-15-A	1217	TATA	FP		4-Jan-2016	ALP	53	66		51C84217349	MAT412316F0D03032	45
4906	RPC424	KL-15-A	1218	TATA	FP		4-Jan-2016	KDLR	53	66		51B84212074	MAT412316F0D03008	90
4907	RPC426	KL-15-A	1219	TATA	SFP		4-Jan-2016	KNPY	53	66		51C84215944	MAT412316F0D03046	87
4908	RPC435	KL-15-A	1220	TATA	SFP		4-Jan-2016	EKM	53	66		51C84217342	MAT412316F0D03037	56
4909	RPC436	KL-15-A	1221	TATA	FP		4-Jan-2016	CLDY	53	66		51C84217340	MAT412316F0D03034	58
4910	RPC437	KL-15-A	1222	TATA	SFP		4-Jan-2016	KDLR	53	66		51C84217345	MAT412316F0D03036	90
4911	RPC438	KL-15-A	1223	TATA	FP		4-Jan-2016	PTA	53	66	BS III	51C84216580	MAT412316F0D03005	37
4912	RPC439	KL-15-A	1224	TATA	FP		4-Jan-2016	PKD	53	66		51B84210955	MAT412316F0D03007	65
4913	RPC440	KL-15-A	1225	TATA	SFP		4-Jan-2016	MVK	53	66		51C84216418	MAT412316F0D03075	88
4914	RPC441	KL-15-A	1226	TATA	FP		4-Jan-2016	KLM	53	66		51C84215940	MAT412316F0D03049	34
4915	RPA460	KL-15-A	1227	TATA	FP		1-Jan-2016	KTM	53	66		51C84216413	MAT412316F0D03074	47
4916	RPC417	KL-15-A	1228	LL	FP		5-Jan-2016	TDY	53	66		FBEZ409279	MB1PBEYC8FEBR9536	79
4917	RPC442	KL-15-A	1229	TATA	SFP		6-Jan-2016	EKM	53	66		51B84212078	MAT412316F0D03015	56
4918	RPE433	KL-15-A	1230	LL	SFP		4-Jan-2016	EKM	53	66		FAEZ411504	MB1PBEYC8FEAS1528	56
4919	RPM474	KL-15-A	1231	LL	FP		5-Jan-2016	KTP	53	66		FYEZ413393	MB1PBEYCXFEYS4256	14
4920	RPA477	KL-15-A	1232	TATA	FP		5-Jan-2016	ATL	53	66		51C84215937	MAT412316F0D03081	33
4921	RPC443	KL-15-A	1233	TATA	FP		7-Jan-2016	KTM	53	66		51C84217343	MAT412316F0D03035	47

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4922	RPC444	KL-15-A	1234	TATA	SFP		8-Jan-2016	PMNA	53	66		51C84214243	MAT412316F0D03010	68
4923	RPK468	KL-15-A	1235	LL	SFP		7-Jan-2016	KPA	53	66		FYEZ413067	MB1PBEYCXFEYS3124	74
4924	RPE434	KL-15-A	1236	LL	SFP		7-Jan-2016	TVM	53	66		FAEZ411220	MB1PBEYC5FEAS1941	27
4925	RPA478	KL-15-A	1237	TATA	FP		8-Jan-2016	ATL	53	66		51C84216430	MAT412316F0D03040	33
4926	RPC419	KL-15-A	1238	LL	FP		11-Jan-2016	NDD	53	66		FBEZ409044	MB1PBEYCXFEBR8940	31
4927	RPC445	KL-15-A	1239	TATA	SFP		11-Jan-2016	TPLM	53	66	LP01512TC158 BS 111	51C84217339	MAT412316F0D03045	94
4928	RPM475	KL-15-A	1240	LL	FP		11-Jan-2016	PLD	53	66		FYEZ414571	MB1PBEYCOFEYS5221	32
4929	RPE470	KL-15-A	1241	LL	SFP		11-Jan-2016	PBVR	53	66	LL BS III	FAEZ412091	MB1PBEYC2FEAS1962	59
4930	RPK469	KL-15-A	1242	LL	SFP		11-Jan-2016	MDY	53	66		FAEZ411908	MB1PBEYCGFEAS1960	76
4931	RPC421	KL-15-A	1243	LL	FP		13-Jan-2016	KMG	53	66		FAEZ410718	MB1PBEYC9FEAS0470	55
4932	RPC446	KL-15-A	1244	TATA	SFP		13-Jan-2016	TVM	53	66		51C84217347	MAT412316F0D03033	27
4933	RPA479	KL-15-A	1245	TATA	FP		12-Jan-2016	ATL	53	66		51C84214241	MAT412316F0D03077	33
4934	RPC447	KL-15-A	1246	TATA	FP		14-Jan-2016	KYLM	53	66		51B84217368	MAT412316F0D03016	41
4935	RPK485	KL-15-A	1247	LL	SFP		13-Jan-2016	KHD	53	66	HINO BS III	FAEZ411875	MB1PBEYC3FEAS1937	106
4936	RPM476	KL-15-A	1248	LL	FP		14-Jan-2016	KMG	53	66		FYEZ414324	MB1PBEYC6FEYS4609	55
4937	RPC448	KL-15-A	1249	TATA	SFP		16-Jan-2016	KTM	53	66		51C84214238	MAT412316F0D03043	47
4938	RPC423	KL-15-A	1250	LL	FP		16-Jan-2016	ARND	53	66		FAEZ410723	MB1PBEYC0FEAS0471	19
4939	RPE471	KL-15-A	1251	LL	SFP		14-Jan-2016	KNR	53	66		FAEZ411463	MB1PBEYC1FEAS1273	77
4940	RPK486	KL-15-A	1252	LL	SFP		15-Jan-2016	KHD	53	66	HINO BS III	FAEZ412610	MB1PBEYC3FEYS3000	106
4941	RPA480	KL-15-A	1253	TATA	FP		15-Jan-2016	CLDY	53	66		51C84214227	MAT412316F0D03076	58
4942	RPM507	KL-15-A	1254	LL	FP		18-Jan-2016	MVPA	53	66	LL BS 111	FYEZ413924	MB1PBEYCFEYS4610	52
4943	RPC449	KL-15-A	1255	TATA	FP		19-Jan-2016	IJK	53	66	BS 111	51C84216423	MAT412316F0D03088	89
4944	RPC495	KL-15-A	1256	TATA	SFP		20-Jan-2016	TPLM	53	66		51C84216431	MAT412316F0D03087	94
4945	RPE472	KL-15-A	1257	LL	SFP		18-Jan-2016	PLKD	53	66	HINO BS III	FAEZ411793	MB1PBEYC0FEAS1961	69
4946	RPK487	KL-15-A	1258	LL	SFP		19-Jan-2016	KTM	53	66		FAEZ411576	MB1PBEYC5FEAS1938	47
4947	RPC497	KL-15-A	1259	TATA	SFP		21-Jan-2016	TVM	53	66		51C84216421	MAT412316F0D03055	27
4948	RPA481	KL-15-A	1260	TATA	FP		19-Jan-2016	CTLA	53	66	BS III CUMMINS	51C84214249	MAT412316F0D03003	46
4949	RPM508	KL-15-A	1261	LL	FP		21-Jan-2016	MVPA	53	66	LL BS III	FYEZ414270	MB1PBEYC6FEYS4612	52
4950	RPC496	KL-15-A	1262	TATA	FP		22-Jan-2016	HPD	53	66		51A84201470	MAT412316F0D02808	42
4951	RPC498	KL-15-A	1263	TATA	FP		22-Jan-2016	KLM	53	66		51C84216419	MAT412316F0D03057	34
4952	RPK488	KL-15-A	1264	LL	SFP		21-Jan-2016	CHRY	53	66	HINO BS 111	FAEZ411739	MB1PBEYC7FEAS1603	44
4953	RPA482	KL-15-A	1265	TATA	FP		22-Jan-2016	ANK	53	66	1512 TC BSIII	51C84216578	MAT412316F0D03000	57
4954	RPA483	KL-15-A	1266	TATA	FP		25-Jan-2016	CTLA	53	66		51C84216578	MAT412316F0D03002	46
4955	RPK489	KL-15-A	1267	LL	SFP		25-Jan-2016	CHRY	53	66	BS 111	FAEZ411872	MB1PBEYC7FEAS1942	44
4956	RPE490	KL-15-A	1268	LL	SFP		25-Jan-2016	PVM	53	66		FAEZ411384	MB1PBEYC5FEAS1521	83
4957	RPM509	KL-15-A	1269	LL	FP		25-Jan-2016	CHRY	53	66		FYEZ414306	MB1PBEYC4FEYS4611	44
4958	RPE492	KL-15-A	1270	LL	SFP		28-Jan-2016	TVL	53	66		FAEZ411935	MB1PBEYC3FEAS1940	43
4959	RPM512	KL-15-A	1271	LL	FP		29-Jan-2016	KTM	53	66		FAEZ109887	MB1PBEYC9FEAS1943	47
4960	RPA484	KL-15-A	1272	TATA	FP		29-Jan-2016	ANK	53	66	1512 TC BS111	51C84215934	MAT412316F0D03056	57
4961	RPA520	KL-15-A	1273	LL	FP		30-Jan-2016	KTM	53	66		FAEZ410527	MB1PBEYC5FEAS0465	47
4962	RPK515	KL-15-A	1274	LL	SFP		20-Jan-2016	PALA	53	66		FAEZ411757	MB1PBEYC9FEAS1599	50
4963	RPE491	KL-15-A	1275	LL	SFP		1-Feb-2016	PALA	53	66		FAEZ411776	MB1PBEYC1FEAS1600	50
4964	RPK516	KL-15-A	1276	LL	SFP		1-Feb-2016	KGD	53	66		FAEZ411782	MB1PBEYC6FEAS1673	84
4965	RPM513	KL-15-A	1277	LL	FP		2-Feb-2016	KTM	53	66		FAEZ411775	MB1PBEYC7FEAS1598	47
4966	RPC499	KL-15-A	1278	TATA	SFP		6-Feb-2016	ALP	53	66		51C84216414	MAT412316F0D03070	45

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
4967	RPK517	KL-15-A	1279	LL	SFP		4-Feb-2016	NDD	53	66		FAEZ411958	MB1PB EYC7FEAS1939	31
4968	RPC425	KL-15-A	1280	LL	FP		8-Feb-2016	PALA	53	66		FAEZ410724	MB1PB EYCXFEAS0462	50
4969	RPC500	KL-15-A	1281	TATA	SFP		8-Feb-2016	ATL	53	66		51C84215935	MAT412316F0D03079	33
4970	RPC501	KL-15-A	1282	TATA	SFP		8-Feb-2016	PSL	53	66	BS 111	51D84223259	MAT412316F0E03294	21
4971	RPC503	KL-15-A	1283	TATA	FP		8-Feb-2016	CTLA	53	66		51D84223233	MAT412316F0E03295	46
4972	RPC504	KL-15-A	1284	TATA	FP		8-Feb-2016	ATL	53	66		51D84223252	MAT412316F0E03289	33
4973	RPC505	KL-15-A	1285	TATA	FP		8-Feb-2016	PVR	53	66		51D84224451	MAT412316F0E03403	23
4974	RPC526	KL-15-A	1286	TATA	FP		8-Feb-2016	KLM	53	66		51D84224456	MAT412316F0E03401	34
4975	RPC450	KL-15-A	1287	LL	FP		8-Feb-2016	KTM	53	66		FAEZ410679	MB1PB EYC6FEAS0460	47
4976	RPC451	KL-15-A	1288	LL	FP		8-Feb-2016	KKLM	53	66		FAEZ410680	MB1PB EYC8FEAS0461	108
4977	RPC452	KL-15-A	1289	LL	FP		8-Feb-2016	PVM	53	66		FBEZ409660	MB1PB EYC0FEBR9532	83
4978	RPC453	KL-15-A	1290	LL	FP		8-Feb-2016	VTRA	53	66	HINO EURO BS III	FBEZ408900	MB1PB EYC5FEBR8800	17
4979	RPE510	KL-15-A	1291	LL	SFP		8-Feb-2016	CTR	53	66		FAEZ411756	MB1PB EYC3FEAS1601	70
4980	RPM514	KL-15-A	1292	LL	FP		8-Feb-2016	CTR	53	66		FAEZ411365	MB1PB EYC3FEAS1520	70
4981	RPK518	KL-15-A	1293	LL	SFP		8-Feb-2016	EKM	53	66		FYEZ414691	MB1PB EYC4FEFS5223	56
4982	RPM541	KL-15-A	1294	LL	FP		9-Feb-2016	KTR	53	66	HBS 111	FAEZ411742	MB1PB EYC5FEAS1602	35
4983	RPC454	KL-15-A	1295	LL	FP		10-Feb-2016	NDM	53	66	BS 111	FBEZ408926	MB1PB EYC7FEBR8801	110
4984	RPC527	KL-15-A	1296	TATA	FP		11-Feb-2016	PVR	53	66		51D84224072	MAT412316F0E03400	23
4985	RPA521	KL-15-A	1297	LL	FP		10-Feb-2016	VJMD	53	66		FAEZ410631	MB1PB EYC7FEAS0466	16
4986	RPA522	KL-15-A	1298	LL	FP		10-Feb-2016	PLD	53	66		FAEZ410611	MB1PB EYC2FEAS0472	32
4987	RPC528	KL-15-A	1299	TATA	FP		12-Feb-2016	HPD	53	66		51D84222039	MAT412316F0E03291	42
4988	RPK519	KL-15-A	1300	LL	SFP		11-Feb-2016	TVM	53	66		FAEZ411261	MB1PB EYC5FEAS1129	27
4989	RPM542	KL-15-A	1301	LL	FP		12-Feb-2016	GVR	53	66		FAEZ411488	MB1PB EYC4FEAS1266	66
4990	RPC529	KL-15-A	1302	TATA	FP		15-Feb-2016	ANK	53	66	1512TC BSIII	51C84216424	MAT412316F0D03086	57
4991	RPE511	KL-15-A	1303	LL	SFP		15-Feb-2016	CGNR	53	66		FAEZ411792	MB1PB EYC4FEAS1672	40
4992	RPC530	KL-15-A	1304	TATA	FP		12-Feb-2016	ATL	53	66		51D84224464	MAT412316F0E03405	33
4993	RPA523	KL-15-A	1305	TATA	FP		15-Feb-2016	KLM	53	66	TC BS 111	51J84257330	MAT412317F0N07776	34
4994	RPM543	KL-15-A	1306	LL	FP		16-Feb-2016	MVPA	53	66	LL BSIII	FAEZ413496	MB1PB EYC8FEYS4451	52
4995	RPC531	KL-15-A	1307	LL	FP		18-Feb-2016	MVPA	53	66	LL BS III	GFEZ401635	MB1PB EYD0GGEFU2527	52
4996	RPK536	KL-15-A	1308	LL	SFP		15-Feb-2016	NDM	53	66		GFEZ401448	MB1PB EYDXGEFU2406	110
4997	RPE473	KL-15-A	1309	LL	SFP		16-Feb-2016	ADR	53	66	HINO BSIII	FYEZ413086	MB1PB EYC6FEYS3122	38
4998	RPA524	KL-15-A	1310	TATA	FP		16-Feb-2016	MVK	53	66		51J84255073	MAT412317F0N07789	88
4999	RPC532	KL-15-A	1311	TATA	FP		16-Feb-2016	CTLA	53	66		51D84223226	MAT412317F0E03410	46
5000	RPC533	KL-15-A	1312	LL	FP		20-Feb-2016	ETPA	53	66		GFEZ401633	MB1PB EYD9GGEFU2526	48
5001	RPK537	KL-15-A	1313	LL	SFP		18-Feb-2016	KTR	53	66	HBS III	GFEZ401451	MB1PB EYD3GGEFU2408	35
5002	RPE544	KL-15-A	1314	LL	SFP		18-Feb-2016	TVM	53	66		GFEZ400888	MB1PB EYD2GGEFU1895	27
5003	RPA525	KL-15-A	1315	TATA	FP		20-Feb-2016	CLDY	53	66		51J84257377	MAT412317F0N07793	58
5004	RPM554	KL-15-A	1316	LL	FP		20-Feb-2016	MLPY	53	66		FYEZ414122	MB1PB EYC5FEYS4410	96
5005	RPM555	KL-15-A	1317	LL	FP		23-Feb-2016	EKM	53	66		GFEZ414122	MB1PB EYD5FEYS4410	56
5006	RPC557	KL-15-A	1318	LL	FP		24-Feb-2016	PTA	53	66	BS III	GFEZ401565	MB1PB EYD6GGEFU2467	37
5007	RPC558	KL-15-A	1319	LL	FP		24-Feb-2016	TVL	53	66		GFEZ401528	MB1PB EYD4GGEFU2501	43
5008	RPC534	KL-15-A	1320	TATA	FP		26-Feb-2016	EKM	53	66		51D84224462	MAT412317F0E03404	56
5009	RPE545	KL-15-A	1321	LL	SFP		22-Feb-2016	EKM	53	66		GFEZ400898	MB1PB EYDXGEFU1899	56
5010	RPK538	KL-15-A	1322	LL	SFP		23-Feb-2016	NDM	53	66		GFEZ401436	MB1PB EYD2GGEFU2402	110
5011	RPE546	KL-15-A	1323	LL	SFP		23-Feb-2016	TVM	53	66		GFEZ401398	MB1PB EYD9GGEFU2400	27

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5012	RPA574	KL-15-A	1324	TATA	FP		23-Feb-2016	NDD	53	66		51K84259754	MAT412317F0N07794	31
5013	RPK540	KL-15-A	1325	LL	FP		24-Feb-2016	MDY	53	66		GFEZ401801	MB1PBEYD2GEFU2674	76
5014	RPC535	KL-15-A	1326	TATA	FP		26-Feb-2016	ALP	53	66		51D84223257	MAT412317F0E03408	45
5015	RPA575	KL-15-A	1328	TATA	FP		25-Feb-2016	EKM	53	66		51K84259755	MAT412317F0N07795	56
5016	RPE547	KL-15-A	1327	LL	SFP		25-Feb-2016	EKM	53	66		GFEZ401446	MB1PBEYD0GEFU2401	56
5017	RPM556	KL-15-A	1329	LL	FP		26-Feb-2016	PVM	53	66		GFEZ400886	MB1PBEYD4GEFU1896	83
5018	RPC559	KL-15-A	1330	LL	FP		27-Feb-2016	KPZA	53	66		GFEZ401544	MB1PBEYD9GEFU2493	07
5019	RPC560	KL-15-A	1331	LL	FP		29-Feb-2016	TDP	53	66		GFEZ401529	MB1PBEYD8GEFU2551	53
5020	RPK304	KL-15-A	995	LL	SFP		6-Oct-2015	TVM	53	66		FYEZ413056	MB1PBEYC4FEYS3121	27
5021	RPK539	KL-15-A	1332	LL	SFP		26-Feb-2016	KGD	53	66		GFEZ401439	MB1PBEYD1GEFU2407	84
5022	RPE548	KL-15-A	1333	LL	SFP		26-Feb-2016	MNR	53	66	HINO EURO BS 111	GFEZ401435	MB1PBEYD4GEFU2403	60
5023	RPK569	KL-15-A	1334	LL	FP		29-Feb-2016	PNKM	53	66		GFEZ401798	MB1PBEYD0GEFU2673	49
5024	RPA576	KL-15-A	1335	TATA	FP		29-Feb-2016	KMR	53	66		51J84255059	MAT412317F0N07796	30
5025	RPM581	KL-15-A	1336	LL	FP		1-Mar-2016	PALA	53	66		GFEZ400917	MB1PBEYD6GEFU1897	50
5026	RPC561	KL-15-A	1338	TATA	FP		2-Mar-2016	CLDY	53	66		51D54224466	MAT412316F0E03402	58
5027	RPC562	KL-15-A	1339	LL	FP		2-Mar-2016	TPLM	53	66		GFEZ401489	MB1PBEYD3GEFU2490	94
5028	RPC563	KL-15-A	1340	TATA	FP		4-Mar-2016	EKM	53	66		51D84223250	MAT412316F0E03407	56
5029	RPA577	KL-15-A	1341	TATA	FP		3-Mar-2016	HPD	53	66		51J84255060	MAT412317F0N07798	42
5030	RPC564	KL-15-A	1342	TATA	FP		5-Mar-2016	KLM	53	66		51D84223244	MAT412316F0E03406	34
5031	RPE549	KL-15-A	1343	LL	FP		3-Mar-2016	VDCY	53	66		GFEZ400922	MB1PBEYD7GEFU1889	82
5032	RPK570	KL-15-A	1344	LL	FP		3-Mar-2016	PMNA	53	66		GFEZ401839	MB1PBEYD9GEFU2686	68
5033	RPM582	KL-15-A	1345	LL	FP		5-Mar-2016	TDP	53	66		GFEZ400921	MB1PBEYD3GEFU1890	53
5034	RPC565	KL-15-A	1346	LL	FP		9-Mar-2016	KTP	53	66		GFEZ401399	MB1PBEYD7GEFU2492	14
5035	RPC566	KL-15-A	1347	TATA	FP		9-Mar-2016	ATL	53	66		51D84223236	MAT412316F0E03409	33
5036	RPK571	KL-15-A	1348	LL	FP		8-Mar-2016	EMLY	53	66		GFEZ401561	MB1PBEYD7GEFU2556	95
5037	RPC567	KL-15-A	1349	LL	FP		11-Mar-2016	KTM	53	66		GFEZ401397	MB1PBEYD5GEFU2491	47
5038	RPE550	KL-15-A	1350	LL	FP		10-Mar-2016	ETPA	53	66		GFEZ401545	MB1PBEYD0GEFU2494	48
5039	RPE551	KL-15-A	1351	LL	FP		13-Mar-2016	TDP	53	66		GFEZ401530	MB1PBEYD8GEFU2498	53
5040	RPK572	KL-15-A	1352	LL	FP		10-Mar-2016	KTR	53	66	HBS III	GFEZ401810	MB1PBEYD0GEFU2687	35
5041	RPC568	KL-15-A	1353	TATA	FP		14-Mar-2016	CTLA	53	66		51D84222231	MAT412316F0E03290	46
5042	RPA578	KL-15-A	1354	TATA	FP		10-Mar-2016	ALV	53	66		51J84257389	MAT412317F0N07799	61
5043	RPA579	KL-15-A	1355	TATA	FP		10-Mar-2016	ALP	53	66		51J84257337	MAT412317F0N07801	45
5044	RPM583	KL-15-A	1356	LL	FP		14-Mar-2016	NTA	53	66		GFEZ401072	MB1PBEYD2GEFU1273	22
5045	RPC599	KL-15-A	1357	TATA	FP		15-Mar-2016	MALA	53	66		51D84222044	MAT412316F0E03292	85
5046	RPE552	KL-15-A	1358	LL	FP		14-Mar-2016	PALA	53	66		GFEZ401614	MB1PBEYDXGEFU2499	50
5047	RPK573	KL-15-A	1359	LL	FP		14-Mar-2016	PTA	53	66	LL BS III	GFEZ401527	MB1PBEYD2GEFU2495	37
5048	RPA580	KL-15-A	1360	TATA	FP		14-Mar-2016	GVR	53	66		51J84256566	MAT412317F0N07802	66
5049	RPC600	KL-15-A	1361	TATA	FP		16-Mar-2016	CLDY	53	66		51C84216422	MAT412316F0D03042	58
5050	RPC493	KL-15-A	1362	EML	SLJ	SLJ	16-Mar-2016	TSR	53	66		E613CDFL056565	MC2RINRT0FL045559	63
5051	RPC494	KL-15-A	1363	EML	SLJ	SLJ	16-Mar-2016	TSR	53	66		E613CFFL056575	MC2RINRT0FL045562	63
5052	RPK584	KL-15-A	1364	LL	FP		15-Mar-2016	PSL	53	66		GFEZ401613	MB1PBEYD2GEFU2500	21
5053	RPC502	KL-15-A	1365	EML	SEXP		17-Mar-2016	EKM	53	66		E613CDFL056408	MC2RINRT0FL045550	56
5054	RPC506	KL-15-A	1366	EML	SEXP		17-Mar-2016	EKM	53	66		E613CDFL056553	MC2RINRT0FL045560	56
5055	RPC601	KL-15-A	1367	LL	FP		17-Mar-2016	PLKD	53	66	BS 111	GFEZ401531	MB1PBEYD4GEFU2496	69
5056	RPM617	KL-15-A	1368	LL	FP		17-Mar-2016	KKD	53	66		GFEZ401613	MB1PBEYD2GEFU2500	72

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5057	RPC602	KL-15-A	1369	LL	FP		18-Mar-2016	PNI	53	66		GFEZ401971	MB1PBEYD7GEFU2816	67
5058	RPA611	KL-15-A	1370	LL	FP		17-Mar-2016	CHRY	53	66		FXEZ415566	MB1PBEYC1FEXS6300	44
5059	RPC603	KL-15-A	1371	TATA	FP		19-Mar-2016	CHRY	53	66		51D84223254	MAT412316F0E03293	44
5060	RPE553	KL-15-A	1372	LL	FP		18-Mar-2016	MVPA	53	66	LL BS III	GFEZ401631	MB1PBEYD5GEFU2524	52
5061	RPK585	KL-15-A	1373	LL	FP		18-Mar-2016	KGD	53	66		GFEZ401434	MB1PBEYD8GEFU2405	84
5062	RPM618	KL-15-A	1374	LL	FP		21-Mar-2016	SBY	53	66		GFEZ402079	MB1PBEYD0GEFU2916	75
5063	RPC605	KL-15-A	1375	TATA	FP		22-Mar-2016	ADR	53	66		51J84256571	MAT412317F0N07791	38
5064	RPC606	KL-15-A	1376	TATA	FP		22-Mar-2016	GVR	53	66		51J84254061	MAT412317F0N07742	66
5065	RPC607	KL-15-A	1377	TATA	FP		23-Mar-2016	CHRY	53	66		51J84255056	MAT412317F0N07729	44
5066	RPE589	KL-15-A	1378	LL	FP		21-Mar-2016	CHRY	53	66		GFEZ401634	MB1PBEYD2GEFU2528	44
5067	RPA612	KL-15-A	1379	LL	FP		21-Mar-2016	KLM	53	66	LL HEIII	FYEZ414211	MB1PBEYC9FEYS4412	34
5068	RPC609	KL-15-A	1380	TATA	FP		26-Mar-2016	KLM	53	66		51J84256583	MAT412317F0N07746	34
5069	RPK586	KL-15-A	1381	LL	FP		22-Mar-2016	NDD	53	66		GFEZ401460	MB1PBEYD7GEFU2525	31
5070	RPA613	KL-15-A	1382	LL	FP		22-Mar-2016	ETPA	53	66		FYEZ414088	MB1PBEYC4FEYS4415	48
5071	RPM619	KL-15-A	1383	LL	FP		26-Mar-2016	KTM	53	66		GFEZ401933	MB1PBEYD4GEFU2918	47
5072	RPC610	KL-15-A	1384	TATA	FP		28-Mar-2016	CTLA	53	66		51J84254073	MAT412317F0N07741	46
5073	RPC620	KL-15-A	1385	TATA	FP		30-Mar-2016	ANK	53	66	1512TC BSIII	51J84256576	MAT412317F0N07709	57
5074	RPK587	KL-15-A	1386	LL	FP		28-Mar-2016	KGD	53	66		GFEZ401417	MB1PBEYD6GEFU2404	84
5075	RPE590	KL-15-A	1387	LL	FP		28-Mar-2016	CLDY	53	66		GFEZ401720	MB1PBEYD5GEFU2670	58
5076	RPK588	KL-15-A	1388	LL	FP		31-Mar-2016	KTR	53	66	HBS III	GFEZ401432	MB1PBEYDXGEFU2552	35
5077	RPA614	KL-15-A	1389	LL	FP		31-Mar-2016	PTA	53	66	LL BS III	FYEZ414130	MB1PBEYCXFEYS4452	37
5078	RPA615	KL-15-A	1390	LL	FP		31-Mar-2016	CHRY	53	66		FYEZ414010	MB1PBEYC5FEYS4455	44
5079	RPM638	KL-15-A	1391	LL	FP		31-Mar-2016	VLRD	53	66	BS III	GFEZ402059	MB1PBEYD5GEFU2013	93
5080	RPC621	KL-15-A	1392	TATA	FP		1-Apr-2016	ATL	53	66		51J84257380	MAT412317F0N07775	33
5081	RPC622	KL-15-A	1393	LL	FP		1-Apr-2016	CDLM	53	66		GFEZ401969	MB1PBEYD8GEFU2811	80
5082	RPE591	KL-15-A	1394	LL	FP		1-Apr-2016	ALP	53	66		GFEZ401717	MB1PBEYD7GEFU2671	45
5083	RPC623	KL-15-A	1395	TATA	FP		1-Apr-2016	MVK	53	66		51J84255068	MAT412317F0N07743	88
5084	RPM639	KL-15-A	1396	LL	FP		2-Apr-2016	KNR	53	66		GFEZ402089	MB1PBEYD7GEFU2914	77
5085	RPC624	KL-15-A	1397	TATA	FP		4-Apr-2016	CLDY	53	66		51J84256572	MAT412317F0N07747	58
5086	RPE592	KL-15-A	1398	LL	FP		4-Apr-2016	CHRY	53	66		GFEZ401799	MB1PBEYD9GEFU2672	44
5087	RPA616	KL-15-A	1399	LL	FP		4-Apr-2016	TSY	53	66		GFEZ402366	MB2PBEYD8GEFU3179	73
5088	RPC625	KL-15-A	1400	LL	FP		5-Apr-2016	KTP	53	66		GFEZ400919	MB1PBEYD0GEFU1894	14
5089	RPC626	KL-15-A	1401	TATA	FP		6-Apr-2016	KNPY	53	66		51J84257329	MAT412317F0N07777	87
5090	RPC627	KL-15-A	1402	TATA	FP		7-Apr-2016	ATL	53	66		51J84257338	MAT412317F0N07792	33
5091	RPK641	KL-15-A	1403	LL	FP		5-Apr-2016	ADR	53	66	HINO BS III	GFEZ401395	MB1PBEYD5GEFU2555	38
5092	RPM640	KL-15-A	1404	LL	FP		7-Apr-2016	KMY	53	66		GFEZ402001	MB1PBEYD3GEFU2814	05
5093	RPK642	KL-15-A	1405	LL	FP		7-Apr-2016	KNR	53	66		GFEZ401612	MB1PBEYD1GEFU2553	77
5094	RPA646	KL-15-A	1406	LL	FP		7-Apr-2016	PLR	53	66		GFEZ402373	MB1PBEYD8GEFU3182	36
5095	RPE593	KL-15-A	1407	LL	FP		8-Apr-2016	PLKD	53	66	BS 111	GFEZ401802	MB1PBEYD4GEFU2675	69
5096	RPM669	KL-15-A	1408	LL	FP		8-Apr-2016	PLKD	53	66	BS III	GFEZ401822	MB1PBEYD0GEFU2818	69
5097	RPC629	KL-15-A	1409	TATA	FP		11-Apr-2016	ALP	53	66		51J84257335	MAT412317F0N07725	45
5098	RPC630	KL-15-A	1410	TATA	FP		11-Apr-2016	ANK	53	66	1512TC BS 111	51J84256591	MAT412317F0N07732	57
5099	RPE594	KL-15-A	1411	LL	FP		11-Apr-2016	PTA	53	66	LL BS III	GFEZ401817	MB1PBEYD3GEFU2683	37
5100	RPK643	KL-15-A	1412	LL	FP		11-Apr-2016	EMLY	53	66		GFEZ401566	MB1PBEYD3GEFU2554	95
5101	RPC631	KL-15-A	1413	TATA	FP		13-Apr-2016	ATL	53	66		51J84257388	MAT412317F0N07730	33

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5102	RPC632	KL-15-A	1432	TATA	FP		15-Apr-2016	CLDY	53	66		51J84257395	MAT412317F0N07724	58
5103	RPC636	KL-15-A	1433	LL	FP		15-Apr-2016	PALA	53	66		GFEZ401922	MB1PB EYD9G EFU2817	50
5104	RPA647	KL-15-A	1434	LL	FP		15-Apr-2016	KMR	53	66		GFEZ402371	MB1PB EYD6G EFU3181	30
5105	RPK644	KL-15-A	1435	LL	FP		15-Apr-2016	KPZA	53	66		GFEZ401636	MB1PB EYD3G EFU2523	07
5106	RPM670	KL-15-A	1436	LL	FP		15-Apr-2016	ETPA	53	66		GFEZ401972	MB1PB EYD9G EFU2915	48
5107	RPC637	KL-15-A	1437	LL	FP		18-Apr-2016	KMR	53	66		GFEZ401966	MB1PB EYD1G EFU2813	30
5108	RPC633	KL-15-A	1438	TATA	FP		19-Apr-2016	GVR	53	66		51J84256586	MAT412317F0N07731	66
5109	RPC634	KL-15-A	1439	LL	FP		19-Apr-2016	MALA	53	66		GFEZ402000	MB1PB EYD5G EFU2815	85
5110	RPE595	KL-15-A	1440	LL	FP		15-Apr-2016	CDLM	53	66		GFEZ401804	MB1PB EYD5G EFU2684	80
5111	RPE596	KL-15-A	1441	LL	FP		16-Apr-2016	NDD	53	66		GFEZ402181	MB1PB EYD4G EFU2983	31
5112	RPK645	KL-15-A	1442	LL	FP		18-Apr-2016	EKM	53	66		GFEZ400923	MB1PB EYD5G EFU1888	56
5113	RPM671	KL-15-A	1443	LL	FP		19-Apr-2016	PALA	53	66		GFEZ402090	MB1PB EYD2G EFU2917	50
5114	RP 651	KL-15-A	1414	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6869802	YS2K6X2SQF1894055	27
5115	RP 652	KL-15-A	1415	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6877400	YS2K6X2SQF1894564	27
5116	RP 653	KL-15-A	1416	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6877393	YS2K6X2SQF1894563	27
5117	RP 654	KL-15-A	1417	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6877441	YS2K6X2SQF1894567	27
5118	RP 655	KL-15-A	1418	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6877902	YS2K6X2SQG1894570	27
5119	RP 656	KL-15-A	1419	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6886674	YS2K6X2SQG1895165	27
5120	RP 657	KL-15-A	1420	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6880892	YS2K6X2SQG1894730	27
5121	RP 658	KL-15-A	1421	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6877876	YS2K6X2SQF1894568	27
5122	RP 659	KL-15-A	1422	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6881164	YS2K6X2SQG1894732	27
5123	RP 660	KL-15-A	1423	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6880903	YS2K6X2SQG1894731	27
5124	RP 661	KL-15-A	1424	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6877428	YS2K6X2SQF1894566	27
5125	RP 662	KL-15-A	1425	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6870096	YS2K6X2SQF1894067	27
5126	RP 663	KL-15-A	1426	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6876022	YS2K6X2SQF1894476	27
5127	RP 664	KL-15-A	1427	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6877883	YS2K6X2SQG1894569	27
5128	RP 665	KL-15-A	1428	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6886682	YS2K6X2SQG1895166	27
5129	RP 666	KL-15-A	1429	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6870090	YS2K6X2SQF1894066	27
5130	RP 667	KL-15-A	1430	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6877415	YS2K6X2SQF1894565	27
5131	RP 668	KL-15-A	1431	SCNA	MRAJ	MRAJ	15-Apr-2016	TVM	53	66		6870068	YS2K6X2SQF1894064	27
5132	RPC687	KL-15-A	1444	LL	FP		21-Apr-2016	KPZA	53	66		GFEZ401970	MB1PB EYD6G EFU2810	07
5133	RPE597	KL-15-A	1445	LL	FP		21-Apr-2016	ETPA	53	66		GFEZ402088	MB1PB EYD6G EFU2984	48
5134	RPA648	KL-15-A	1446	LL	FP		21-Apr-2016	KTR	53	66	HBS III	GFEZ402365	MB1PB EYD6G EFU3178	35
5135	RPA649	KL-15-A	1447	LL	FP		21-Apr-2016	PTA	53	66	LL BS III	GFEZ402383	MB1PB EYD3G EFU3185	37
5136	RPM701	KL-15-A	1448	LL	FP		22-Apr-2016	KMY	53	66		GFEZ402140	MB1PB EYD1G EFU3122	05
5137	RPC690	KL-15-A	1449	LL	FP		25-Apr-2016	HPD	53	66		GFEZ401818	MB1PB EYD7G EFU2685	42
5138	RPC691	KL-15-A	1450	LL	FP		25-Apr-2016	PLR	53	66		GFEZ401926	MB1PB EYDXG EFU2812	36
5139	RPC692	KL-15-A	1451	EML	FP		25-Apr-2016	CLDY	53	66		E613CDGB070694	MC2RINRTGBO47665	58
5140	RPE598	KL-15-A	1452	LL	FP		23-Apr-2016	TSR	53	66		GFEZ402180	MB1PB EYDXG EFU2986	63
5141	RPC693	KL-15-A	1453	LL	FP		26-Apr-2016	NDD	53	66		GFEZ400887	MB1PB EYD2G EFU1900	31
5142	RPM702	KL-15-A	1454	LL	FP		26-Apr-2016	ATL	53	66		GFEZ402382	MB1PB EYD7G EFU3187	33
5143	RPC694	KL-15-A	1455	LL	FP		27-Apr-2016	TVL	53	66		GFEZ402609	MB1PB EYD3G EFU3491	43
5144	RPA650	KL-15-A	1456	EML	FP		26-Apr-2016	VZM	53	66		E613CDGB070705	MC2RINRTGBO47681	24
5145	RPE672	KL-15-A	1457	LL	FP		28-Apr-2016	PALA	53	66		GFEZ402058	MB1PB EYD1G EFU2987	50
5146	RPA704	KL-15-A	1458	LL	FP		28-Apr-2016	EKM	53	66		GFEZ401924	MB1PB EYD8G EFU2985	56

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5147	RPM703	KL-15-A	1459	LL	ORD	VND	29-Apr-2016	KTP	48	66		GFEZ402313	MB1PBEYDXGEFU3121	14
5148	RPC695	KL-15-A	1460	EML	FP		2-May-2016	ATL	53	66		E613CDGB070872	MC2RINRT0GBO47677	33
5149	RPC696	KL-15-A	1461	LL	FP		2-May-2016	GVR	53	66		GFEZ402611	MB1PBEYD3GEFU3443	66
5150	RPA705	KL-15-A	1462	LL	FP		29-Apr-2016	TSR	53	66		GFEZ402726	MB1PBEYD3GEFU3569	63
5151	RPC697	KL-15-A	1463	LL	FP		3-May-2016	ETPA	53	66		GFEZ402655	MB1PBEYD3GEEU3488	48
5152	RPE673	KL-15-A	1464	LL	FP		30-Apr-2016	TSR	53	66		GFEZ402179	MB1PBEYD3GEFU2988	63
5153	RPA706	KL-15-A	1465	LL	FP		2-May-2016	KTR	53	66	HBS III	GEEZ403394	MB1PBEYD6GEEU4313	35
5154	RPM725	KL-15-A	1466	LL	ORD	VND	3-May-2016	KTP	48	66		GEEZ402756	MB1PBEYD3GEEU3572	14
5155	RPC698	KL-15-A	1467	LL	FP		4-May-2016	CDLM	53	66		GFEZ402699	MB1PBEYD1GEEU3568	80
5156	RPE674	KL-15-A	1468	LL	FP		3-May-2016	NDD	53	66		GFEZ402212	MB1PBEYD0GEFU3032	31
5157	RPK682	KL-15-A	1469	LL	FP		3-May-2016	CLDY	53	66		GFEZ402744	MB1PBEYDXGEEU3570	58
5158	RPK683	KL-15-A	1470	LL	FP		3-May-2016	MKD	53	66		GFEZ402580	MB1PBEYD7GEEU3445	08
5159	RPK684	KL-15-A	1471	LL	FP		3-May-2016	VZM	53	66		GFEZ402672	MB1PBEYDX6EEU3486	24
5160	RPK685	KL-15-A	1472	LL	FP		3-May-2016	ANK	53	66	HINO BSIII	GFEZ402657	MB1PBEYD5GEEU3489	57
5161	RPC699	KL-15-A	1473	EML	FP		6-May-2016	MVK	53	66		E613CDGB070831	MC2R1NRT0GBO47669	88
5162	RPC700	KL-15-A	1474	LL	FP		7-May-2016	HPD	53	66		GFEZ402653	MB1PBEYD1GEEU3490	42
5163	RPK686	KL-15-A	1475	LL	FP		7-May-2016	KMY	53	66		GEEZ402987	MB1PBEYD5GEEU3766	05
5164	RPE675	KL-15-A	1476	LL	FP		6-May-2016	KTM	53	66		GFEZ402209	MB1PBEYD2GEFU3033	47
5165	RPM726	KL-15-A	1477	LL	ORD	VND	7-May-2016	PLKD	48	66	BS 111	GEEZ402683	MB1PBEYD1GEEU3571	69
5166	RPC715	KL-15-A	1478	EML	FP		10-May-2016	TSR	53	66		E613CDGB70699	MC2RINRT0GBO47664	63
5167	RPC716	KL-15-A	1479	LL	FP		10-May-2016	ETPA	53	66		GFEZ402670	MB1PBEYD1GEEU3487	48
5168	RPA707	KL-15-A	1480	LL	FP		9-May-2016	PVM	53	66		GEEZ403759	MB1PBEYD1GEEU4509	83
5169	RPK728	KL-15-A	1481	LL	FP		9-May-2016	TPLM	53	66		GEEZ403221	MB1PBEYD4GEEU3953	94
5170	RPC717	KL-15-A	1482	LL	FP		11-May-2016	PALA	53	66		GFEZ402141	MB1PBEYD7GEEU3574	50
5171	RPE676	KL-15-A	1483	LL	FP		10-May-2016	KTM	53	66		GFEZ402210	MB1PBEYD4GEFU3034	47
5172	RPM727	KL-15-A	1484	LL	ORD		12-May-2016	PLKD	48	66	BS 111	GFEZ402730	MB1PBEYD0GEEU3576	69
5173	RPC718	KL-15-A	1485	LL	FP		13-May-2016	GVR	53	66		GFEZ402316	MB1PBEYD4GEFU3163	66
5174	RPK729	KL-15-A	1486	LL	FP		12-May-2016	TDP	53	66		GEEZ403198	MB1PBEYD1GEEU3957	53
5175	RPM733	KL-15-A	1487	LL	ORD		13-May-2016	MKD	48	66		GFEZ402729	MB1PBEYD2GEEU3577	08
5176	RPA708	KL-15-A	1488	LL	FP		13-May-2016	EKM	53	66		GEEZ403789	MB1PBEYD8GEEU4507	56
5177	RPA711	KL-15-A	1498	LL	FP		19-May-2016	MDY	53	66		GEEZ403762	MB1PBEYDXGEEU4508	76
5178	RPC722	KL-15-A	1499	EML	FP		20-May-2016	ATL	53	66		E613CDGB070562	MC2RINRT0GBO47643	33
5179	RPE677	KL-15-A	1489	LL	FP		13-May-2016	KTR	53	66	HBS III	GFEZ401819	MB1PBEYD1GEFU2682	35
5180	RPK731	KL-15-A	1493	LL	FP		18-May-2016	ADR	53	66	HINO BS III	GEEZ402869	MB1PBEYD1GEEU3702	38
5181	RPK730	KL-15-A	1490	LL	FP		13-May-2016	TPLM	53	66		GEEZ403201	MB1PBEYD3GEEU3958	94
5182	RPA710	KL-15-A	1497	LL	FP		19-May-2016	PNR	53	66		GEEZ403778	MB1PBEYD5GEEU4514	78
5183	RPA709	KL-15-A	1496	LL	FP		19-May-2016	KKD	53	66		GEEZ403782	MB1PBEYD8GEEU4510	72
5184	RPC719	KL-15-A	1491	EML	FP		18-May-2016	TSR	53	66		E613CDGB075748	MC2RINRT0GBO47668	63
5185	RPC721	KL-15-A	1494	LL	FP		19-May-2016	KTM	53	66		GFEZ402314	MB1PBEYD1GEFU3184	47
5186	RPC720	KL-15-A	1492	LL	FP		18-May-2016	EDT	53	66		GFEZ402369	MB1PBEYD4GEFU3180	98
5187	RPM734	KL-15-A	1495	LL	ORD		19-May-2016	MKD	48	66		GFEZ402368	MB1PBEYDXGEFU3183	08
5188	RPC723	KL-15-A	1500	LL	FP		20-May-2016	NTA	53	66		GEEZ402884	MB1PBEYD3GEEU3698	22
5189	RPE678	KL-15-A	1501	LL	FP		20-May-2016	KPA	53	66		GFEZ402608	MB1PBEYD1GEFU3442	74
5190	RPM735	KL-15-A	1502	LL	ORD		23-May-2016	CTR	48	66		GFEZ402315	MB1PBEYD8GEFU3120	70
5191	RPC724	KL-15-A	1503	LL	FP		24-May-2016	SBY	53	66		GFEZ402494	MB1PBEYDXGEEU3813	75

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5192	RPC746	KL-15-A	1504	EML	FP		24-May-2016	CTNR	53	66		E613CDGB070741	MC2RINRT0GB047675	97
5193	RPE679	KL-15-A	1505	LL	FP		23-May-2016	KMY	53	66		GFEZ402607	MB1PBEYD5GEFU3444	05
5194	RPC747	KL-15-A	1506	LL	FP		25-May-2016	PLR	53	66		GEEZ403597	MB1PBEYD7GEEU4305	36
5195	RPA712	KL-15-A	1507	LL	FP		24-May-2016	PLD	53	66		GEEZ403780	MB1PBEYDXGEEU4511	32
5196	RPC748	KL-15-A	1508	EML	FP		28-May-2016	KPM	53	66		E613CDGB070838	MC2RINRT0GB047672	91
5197	RPE680	KL-15-A	1509	LL	ORD		26-May-2016	MNR	48	66	HINO EURO BS III	GFEZ402578	MB1PBEYD9GEFU3446	60
5198	RPM767	KL-15-A	1510	LL	ORD		27-May-2016	MNR	48	66	HINO EURO BS III	GFEZ402381	MB1PBEYD9GEFU3188	60
5199	RPC749	KL-15-A	1511	LL	FP		28-May-2016	VJMD	53	66		GEEZ403546	MB1PBEYD9GEEU4306	16
5200	RPM768	KL-15-A	1512	LL	FP		28-May-2016	PSL	53	66		GFEZ402300	MB1PBEYDXGEFU3118	21
5201	RPC750	KL-15-A	1513	LL	FP		30-May-2016	PLD	53	66		GEEZ403343	MB1PBEYD0GEEU4307	32
5202	RPE681	KL-15-A	1514	LL	ORD		28-May-2016	KPA	48	66		GFEZ402610	MB1PBEYD0GEFU3447	74
5203	RPC752	KL-15-A	1515	LL	FP		31-May-2016	VTRA	53	66		GEEZ403415	MB1PBEYD4GEEU4309	17
5204	RPK732	KL-15-A	1516	LL	FP		30-May-2016	KHD	53	66	HINO BS III ABS TYPE	GEEZ402897	MB1PBEYD6GEEU3808	106
5205	RPC751	KL-15-A	1517	EML	FP		2-Jun-2016	KLM	53	66		E613CDGB070837	MC2RINRT0GB047671	34
5206	RPA713	KL-15-A	1518	LL	FP		27-May-2016	NTA	53	66		GEEZ403720	MB1PBEYD6GEEU4506	22
5207	RPA714	KL-15-A	1519	LL	FP		31-May-2016	EDT	53	66		GEEZ403758	MB1PBEYD1GEEU4512	98
5208	RPA770	KL-15-A	1520	LL	FP		31-May-2016	KMR	53	66		GEEZ404529	MB1PBEYD7GEEU5227	30
5209	RPK763	KL-15-A	1521	LL	FP		31-May-2016	KTM	53	66		GEEZ403218	MB1PBEYD9GEEU3950	47
5210	RPK764	KL-15-A	1522	LL	FP		31-May-2016	KTM	53	66		GEEZ403200	MB1PBEYDXGEEU3956	47
5211	RPM769	KL-15-A	1523	LL	ORD		2-Jun-2016	KPA	48	66		GFEZ402298	MB1PBEYD1GEFU3119	74
5212	RPM784	KL-15-A	1524	LL	ORD		4-Jun-2016	SBY	48	66		GFEZ402299	MB1PBEYD8GEFU3117	75
5213	RPK762	KL-15-A	1525	LL	FP		2-Jun-2016	KNR	53	66		GEEZ403217	MB1PBEYD2GEEU3952	77
5214	RPE736	KL-15-A	1526	LL	ORD		2-Jun-2016	SBY	48	66		GFEZ402630	MB1PBEYD0GEEU3450	75
5215	RPE737	KL-15-A	1527	LL	ORD		4-Jun-2016	SBY	48	66		GEEZ402875	MB1PBEYD1GEEU3697	75
5216	RPA771	KL-15-A	1528	LL	FP		6-Jun-2016	MLPY	53	66		GEEZ404530	MB1PBEYD7GEEU5230	96
5217	RPK765	KL-15-A	1529	LL	FP		6-Jun-2016	MKD	53	66		GEEZ404114	MB1PBEYD6GEEU5008	08
5218	RPK766	KL-15-A	1530	LL	FP		7-Jun-2016	VLRD	53	66	LL BS III	GEEZ404093	MB1PBEYD8GEEU5009	93
5219	RPE738	KL-15-A	1531	LL	ORD		7-Jun-2016	TSR	48	66		GEEZ402873	MB1PBEYD5GEEU3699	63
5220	RPA772	KL-15-A	1532	LL	FP		9-Jun-2016	EKM	53	66		GFEZ401800	MB1PBEYD0GEEU5232	56
5221	RPA773	KL-15-A	1533	LL	FP		10-Jun-2016	KMGH	53	66		GEEZ404240	MB1PBEYD3GEEU5233	55
5222	RPM785	KL-15-A	1534	LL	FP		10-Jun-2016	EKM	53	66		GFEZ402379	MB1PBEYD5GEFU3186	56
5223	RPE739	KL-15-A	1535	LL	ORD		10-Jun-2016	TSR	48	66		GEEZ402887	MB1PBEYD8GEEU3700	63
5224	RPK779	KL-15-A	1536	LL	FP		10-Jun-2016	CDLM	53	66		GEEZ404317	MB1PBEYD5GEEU5016	80
5225	RPE740	KL-15-A	1537	LL	ORD		14-Jun-2016	TSR	48	66		GFEZ402211	MB1PBEYDXGEEU3701	63
5226	RPK780	KL-15-A	1538	LL	ORD	MLB	14-Jun-2016	TSR	48	66		GEEZ404146	MB1PBEYD2GEEU5006	63
5227	RPM786	KL-15-A	1539	LL	ORD	VND	14-Jun-2016	TSR	48	66		GEEZ403220	MB1PBEYD6GEEU3954	63
5228	RPE741	KL-15-A	1540	LL	ORD		16-Jun-2016	KMY	48	66		GEEZ402886	MB1PBEYD3GEEU3703	05
5229	RPA774	KL-15-A	1541	LL	FP		16-Jun-2016	KTR	53	66	HBS III	GEEZ404098	MB1PBEYD9GEEU5228	35
5230	RPM814	KL-15-A	1542	LL	ORD		17-Jun-2016	KMY	48	66		GEEZ402942	MB1PBEYD5GEEU3816	05
5231	RPA775	KL-15-A	1543	LL	FP		17-Jun-2016	ALP	53	66		GEEZ404237	MB1PBEYD4GEEU5234	45
5232	RPE742	KL-15-A	1544	LL	ORD		18-Jun-2016	KNR	48	66		GEEZ402889	MB1PBEYD5GEEU3704	77
5233	RPE743	KL-15-A	1545	LL	ORD		21-Jun-2016	PNR	48	66		GEEZ402936	MB1PBEYD7GEEU3767	78
5234	RPK781	KL-15-A	1546	EML	FP		21-Jun-2016	CDLM	53	66		E613CDGB070561	MC2RINRT0GB047639	80
5235	RPC754	KL-15-A	1547	LL	FP		23-Jun-2016	KKD	53	66		GEEZ403235	MB1PBEYD2GEEU4311	72
5236	RPE744	KL-15-A	1548	LL	ORD		23-Jun-2016	KKD	48	66		GEEZ402898	MB1PBEYD9GEEU3768	72

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5237	RPM815	KL-15-A	1549	LL	ORD	VND	23-Jun-2016	MNR	48	66	HINO EURO BSIII	GEEZ402976	MB1PBEYD8GEEU3809	60
5238	RPA776	KL-15-A	1550	LL	FP		23-Jun-2016	KDLR	53	66		GDEZ407047	MB1PBEYD3GEDU7764	90
5239	RPC753	KL-15-A	1551	LL	FP		25-Jun-2016	KKD	53	66		GEEZ403239	MB1PBEYD0GEEU4310	72
5240	RPC756	KL-15-A	1552	LL	FP		25-Jun-2016	CTLA	53	66	BS III	GEEZ403476	MB1PBEYD4GEEU4312	46
5241	RPC760	KL-15-A	1553	LL	FP		25-Jun-2016	KTP	53	66		GFEZ402698	MB1PBEYD5GEEU3573	14
5242	RPC755	KL-15-A	1554	EML	FP		25-Jun-2016	ATL	53	66		E613CDGB070740	MC2RINRT0GB047670	33
5243	RPC757	KL-15-A	1555	EML	FP		25-Jun-2016	KYLM	53	66		E613CDGB071168	MC2RINRT0GB047708	41
5244	RPC758	KL-15-A	1556	EML	FP		25-Jun-2016	KDLR	53	66		E613CDGB070693	MC2RINRT0GB047663	90
5245	RPC759	KL-15-A	1557	EML	FP		25-Jun-2016	KTM	53	66		E613CDGB070732	MC2RINRT0GB047676	47
5246	RPC790	KL-15-A	1562	EML	FP		25-Jun-2016	KPA	53	66		E613CDGC074353	MC2RINRT0GC048224	74
5247	RPC791	KL-15-A	1563	EML	FP		25-Jun-2016	PDM	53	66		E613CDGC074842	MC2RINRT0GC048305	39
5248	RPC792	KL-15-A	1564	EML	FP		25-Jun-2016	PSL	53	66	BS 111	E613CDGC073143	MC2RINRT0GC048073	21
5249	RPC793	KL-15-A	1565	EML	FP		25-Jun-2016	ATL	53	66		E613CDGC074482	MC2RINRT0GC048248	33
5250	RPC794	KL-15-A	1566	LL	FP		25-Jun-2016	ETPA	53	66		GFEZ402723	MB1PBEYD9GEEU3575	48
5251	RPK782	KL-15-A	1567	EML	FP		24-Jun-2016	PNR	53	66		E613CDGB070700	MC2RINRT0GB047666	78
5252	RPM816	KL-15-A	1568	EML	FP		28-Jun-2016	TVL	53	66		E613CDGB071203	MC2RINRT0GB047716	43
5253	RPC795	KL-15-A	1569	LL	FP		29-Jun-2016	TVM	53	66		GEEZ402755	MB1PBEYD4GEEU3578	27
5254	RPC604	KL-15-A	1570	EML	SLJ		30-Jun-2016	KKD	53	66		E613CDFL056400	MC2RINRT0FL045551	72
5255	RPC608	KL-15-A	1571	EML	SLJ		30-Jun-2016	KKD	53	66		E613CDFJ050849	MC2RINRT0FL045525	72
5256	RPC628	KL-15-A	1572	EML	SEXP		30-Jun-2016	PNR	53	66		E613CDEL056574	MC2RINRT0FL045561	78
5257	RPC635	KL-15-A	1573	EML	SEXP		30-Jun-2016	PNR	53	66		E613CDFL056562	MC2RINRT0FL045558	78
5258	RPC688	KL-15-A	1574	EML	SEXP		30-Jun-2016	KKD	53	66		E613CDFL056395	MC2RINRT0FL045552	72
5259	RPC689	KL-15-A	1575	EML	SEXP		30-Jun-2016	KKD	53	66		E613CDFL056389	MC2RINRT0FL045553	72
5260	RPC796	KL-15-A	1576	EML	FP		30-Jun-2016	KNPY	53	66		E613CDFL074487	MC2RINRT0FL048249	87
5261	RPC797	KL-15-A	1577	EML	FP		30-Jun-2016	PLD	53	66		E613CDFL074352	MC2RINRT0FL048223	32
5262	RPE745	KL-15-A	1578	LL	ORD		27-Jun-2016	TSR	48	66		GEEZ402489	MB1PBEYD0GEEU3769	63
5263	RPA777	KL-15-A	1579	LL	FP		28-Jun-2016	ADR	53	66		GFEZ401820	MB1PBEYD7GEDU7766	38
5264	RPA778	KL-15-A	1580	LL	FP		28-Jun-2016	PLR	53	66		GDEZ407044	MB1PBEYD7GEDU7752	36
5265	RPC761	KL-15-A	1558	EML	FP		25-Jun-2016	KMY	53	66		E613CDGB070830	MC2RINRT0GB047673	05
5266	RPC787	KL-15-A	1559	EML	FP		25-Jun-2016	CGNR	53	66		E613CDGC073151	MC2RINRT0GC048069	40
5267	RPC788	KL-15-A	1560	EML	FP		25-Jun-2016	PALA	53	66		E613CDGC073126	MC2RINRT0GC048067	50
5268	RPC789	KL-15-A	1561	EML	FP		25-Jun-2016	PLR	53	66		E613CDGC073142	MC2RINRT0GC048066	36
5269	RPE804	KL-15-A	1581	LL	ORD		30-Jun-2016	KKD	48	66		GEEZ402983	MB1PBEYD7GEEU3770	72
5270	RPA837	KL-15-A	1582	EML	FP		30-Jun-2016	PALA	53	66		E613CDGB070882	MC2RINRT0GB047682	50
5271	RPC798	KL-15-A	1583	LL	FP		1-Jul-2016	KTP	53	66		GFEZ402517	MB1PBEYD6GEEU3579	14
5272	RPM834	KL-15-A	1584	EML	FP		1-Jul-2016	ALP	53	66		E613CDGB071193	MC2RINRT0GB047715	45
5273	RPC799	KL-15-A	1585	LL	FP		2-Jul-2016	TVM	53	66		GEEZ402874	MB1PBEYDXGEEU3696	27
5274	RPM835	KL-15-A	1586	EML	FP		4-Jul-2016	MALA	53	66		E613CDGB071197	MC2RINRT0GB047714	85
5275	RPC800	KL-15-A	1587	EML	FP		5-Jul-2016	KPM	53	66		E613CDGB075086	MC2RINRT0GB048336	91
5276	RPC801	KL-15-A	1588	LL	FP		5-Jul-2016	PNKM	53	66		GEEZ402972	MB1PBEYD1GEEU3814	49
5277	RPC817	KL-15-A	1589	LL	FP		7-Jul-2016	TDP	53	66		GEEZ402812	MB1PBEYD4GEEU3810	53
5278	RPE805	KL-15-A	1590	LL	ORD		5-Jul-2016	KHD	48	66		GEEZ402986	MB1PBEYD9GEEU3771	106
5279	RPA838	KL-15-A	1591	EML	FP		5-Jul-2016	PSL	53	66	LL BS III	E613CDGB071037	MC2RINRT0GB047692	21
5280	RPC822	KL-15-A	1592	LL	FP		8-Jul-2016	VLRD	53	66	LL BS III	GEEZ404918	MB1PBEYD9GEEU5553	93
5281	RPK830	KL-15-A	1593	EML	FP		7-Jul-2016	TLY	53	66		E613CDGB070392	MC2RINRT0GB047627	18

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5282	RPK831	KL-15-A	1594	EML	FP		7-Jul-2016	MPM	53	66		E613CDGB069556	MC2RINRT0GB047626	71
5283	RPC818	KL-15-A	1595	LL	FP		11-Jul-2016	KPA	53	66		GEEZ404720	MB1PBEYC4GEEU5475	74
5284	RPC823	KL-15-A	1596	EML	FP		11-Jul-2016	PVR	53	66		E613CDGC074367	MC2RINRT0GC048229	23
5285	RPC824	KL-15-A	1597	EML	FP		11-Jul-2016	TSY	53	66		E613CDGC074359	MC2RINRT0GC048225	73
5286	RPA839	KL-15-A	1598	EML	FP		8-Jul-2016	CTNR	53	66		E613CDGC071035	MC2RINRT0GB047694	97
5287	RPM836	KL-15-A	1599	EML	FP		11-Jul-2016	PALA	53	66		E613CDGB071023	MC2RINRT0GB047691	50
5288	RPC825	KL-15-A	1600	EML	FP		12-Jul-2016	CGNR	53	66		E613CDGC075082	MC2RINRT0GB048338	40
5289	RPC826	KL-15-A	1601	EML	FP		12-Jul-2016	PLR	53	66		E613CDGC075071	MC2RINRT0GB048335	36
5290	RPM856	KL-15-A	1602	EML	FP		12-Jul-2016	TDP	53	66		E613CDGB070391	MC2RINRT0GB047630	53
5291	RPC819	KL-15-A	1603	LL	FP		13-Jul-2016	KTP	53	66		GEEZ404721	MB1PBEYCXGEEU5478	14
5292	RPE806	KL-15-A	1604	LL	ORD		12-Jul-2016	MNR	48	66	HINO EURO BS III	GEEZ402980	MB1PBEYC6GEEU3811	60
5293	RPC827	KL-15-A	1605	EML	FP		14-Jul-2016	EKM	53	66		E613CDGC075078	MC2RINRT0GC048337	56
5294	RPA840	KL-15-A	1606	EML	FP		12-Jul-2016	MDY	53	66		E613CDGC070848	MC2RINRT0GB047679	76
5295	RPC820	KL-15-A	1607	LL	FP		15-Jul-2016	NTA	53	66		GEEZ404722	MB1PBEYD2GEEU5474	22
5296	RPC828	KL-15-A	1608	LL	FP		16-Jul-2016	ARND	53	66		GEEZ402901	MB1PBEYD8GEEU3812	19
5297	RPM857	KL-15-A	1609	EML	FP		16-Jul-2016	PDM	53	66		E613CDGC068865	MC2RINRT0GB047412	39
5298	RPC821	KL-15-A	1610	LL	FP		18-Jul-2016	KMGM	53	66		GEEZ404936	MB1PBEYDXGEEU5559	55
5299	RPC844	KL-15-A	1611	LL	FP		18-Jul-2016	KNR	53	66		GEEZ404630	MB1PBEYD2GEEU5331	77
5300	RPC845	KL-15-A	1612	EML	FP		19-Jul-2016	KTR	53	66	BS III	E613CDGC074007	MC2RINRT0GC048307	35
5301	RPE807	KL-15-A	1613	LL	ORD		15-Jul-2016	TLY	48	66		GEEZ402988	MB1PBEYD3GEEU3815	18
5302	RPM858	KL-15-A	1614	EML	FP		19-Jul-2016	PBVR	53	66		E613CDGC068873	MC2RINRT0GB047411	59
5303	RPK783	KL-15-A	1615	EML	FP		19-Jul-2016	TLY	53	66		E613CDGB070567	MC2RINRT0GB047642	18
5304	RPC846	KL-15-A	1616	EML	FP		20-Jul-2016	RNI	53	66		E613CDGB074373	MC2RINRT0GC048226	101
5305	RPE808	KL-15-A	1617	LL	ORD		19-Jul-2016	PLR	48	66		GEEZ403216	MB1PBEYD0GEEU3951	36
5306	RPC847	KL-15-A	1618	EML	FP		21-Jul-2016	CGNR	53	66		E613CDGB074429	MC2RINRT0GC048245	40
5307	RPA841	KL-15-A	1619	EML	FP		19-Jul-2016	NPR	53	66		E613CDGB071038	MC2RINRT0GB047696	62
5308	RPA842	KL-15-A	1620	EML	FP		19-Jul-2016	MLPY	53	66		E613CDGB071036	MC2RINRT0GB047693	96
5309	RPC849	KL-15-A	1621	EML	FP		23-Jul-2016	EKM	53	66		E613CDGB075088	MC2RINRT0GC048339	56
5310	RPK832	KL-15-A	1622	EML	FP		21-Jul-2016	KTDA	53	66		E613CDGB070733	MC2RINRT0GB047667	25
5311	RPM875	KL-15-A	1623	EML	FP		23-Jul-2016	CTLA	53	66		E613CDGB066931	MC2RINRT0GB047117	46
5312	RPC848	KL-15-A	1624	EML	FP		26-Jul-2016	KNR	53	66		E613CDGB074841	MC2RINRT0GC048304	77
5313	RPA843	KL-15-A	1625	EML	FP		25-Jul-2016	VKM	53	66		E613CDGB071024	MC2RINRT0GB047695	51
5314	RPM876	KL-15-A	1626	EML	FP		26-Jul-2016	ARND	53	66		E613CDGB068872	MC2RINRT0GB047410	19
5315	RPK833	KL-15-A	1627	EML	FP		25-Jul-2016	EMLY	53	66		E613CDGB069663	MC2RINRT0GB047628	95
5316	RPK879	KL-15-A	1628	EML	FP		28-Jul-2016	MVPA	53	66	E 683 TC1	E613CDGB069665	MC2RINRT0GB047629	52
5317	RPE874	KL-15-A	1629	EML	FP		28-Jul-2016	KTR	53	66	BSIII	E613CDGB070526	MC2RINRT0GB047640	35
5318	RPE809	KL-15-A	1630	LL	ORD		4-Aug-2016	TSR	48	66		GEEZ403215	MB1PBEYD8GEEU3955	63
5319	RPC850	KL-15-A	1631	LL	FP		6-Aug-2016	MLTM	53	66		GEEZ404617	MB1PBEYD4GEEU5296	54
5320	RPK878	KL-15-A	1632	EML	FP		5-Aug-2016	TDP	53	66		E613CDGB069560	MC2RINRT0GB047625	53
5321	RPC851	KL-15-A	1633	LL	FP		8-Aug-2016	KTP	53	66		GEEZ404624	MB1PBEYD8GEEU5298	14
5322	RPC853	KL-15-A	1634	LL	FP		9-Aug-2016	TLY	53	66		GEEZ404527	MB1PBEYD0GEEU5229	18
5323	RPM877	KL-15-A	1635	EML	FP		8-Aug-2016	KKD	53	66		E613CDGB071202	MC2RINRT0GB047713	72
5324	RPC852	KL-15-A	1636	EML	FP		10-Aug-2016	KKD	53	66		E613CDGB070749	MC2RINRT0GB047674	72
5325	RPC854	KL-15-A	1637	LL	FP		11-Aug-2016	RNI	53	66		GEEZ404623	MB1PBEYD0GEEU5327	101
5326	RPM883	KL-15-A	1638	EML	FP		11-Aug-2016	GVR	53	66		E613CDGC073134	MC2RINRT0GC048068	66

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5327	RPC855	KL-15-A	1639	LL	FP		12-Aug-2016	SBY	53	66		GEEZ404654	MB1PBEYDXGEEU5335	75
5328	RPC890	KL-15-A	1640	LL	FP		12-Aug-2016	KKLM	53	66		GEEZ404880	MB1PBEYD8GEEU6063	108
5329	RPK829	KL-15-A	1641	EML	FP		12-Aug-2016	TLY	53	66		E613CDGB071155	MC2RINRT0GB047707	18
5330	RPM884	KL-15-A	1642	EML	FP		12-Aug-2016	CGNR	53	66		E613CDGB073118	MC2RINRT0GC048072	40
5331	RPC889	KL-15-A	1643	LL	FP		16-Aug-2016	VDCY	53	66		GEEZ405043	MB1PBEYD1GEEU5689	82
5332	RPC891	KL-15-A	1644	LL	FP		16-Aug-2016	KNR	53	66		GEEZ404959	MB1PBEYD1GEEU6051	77
5333	RPC892	KL-15-A	1645	LL	FP		16-Aug-2016	TSY	53	66		GEEZ404823	MB1PBEYD1GEEU5479	73
5334	RPC893	KL-15-A	1646	LL	FP		16-Aug-2016	NPR	53	66		GEEZ405507	MB1PBEYD3GEEU6066	62
5335	RPC894	KL-15-A	1647	LL	FP		16-Aug-2016	NPR	53	66		GEEZ405037	MB1PBEYD4GEEU6058	62
5336	RPC895	KL-15-A	1648	LL	FP		16-Aug-2016	PTA	53	66	LL BS 111	GEEZ405414	MB1PBEYDXGEEU6050	37
5337	RPM885	KL-15-A	1649	EML	FP		16-Aug-2016	VKM	53	66		E613CDGC073135	MC2RINRT0GC048074	51
5338	RPC896	KL-15-A	1650	LL	FP		18-Aug-2016	MLTM	53	66		GEEZ405426	MB1PBEYD0GEEU6056	54
5339	RPC897	KL-15-A	1651	LL	FP		19-Aug-2016	KKD	53	66		GEEZ405485	MB1PBEYD4GEEU6061	72
5340	RPA869	KL-15-A	1652	EML	FP		12-Aug-2016	MALA	53	66		E613CDGB071147	MC2RINRT0GB047706	85
5341	RPE810	KL-15-A	1653	LL	ORD		16-Aug-2016	KMY	48	66		GEEZ404418	MB1PBEYDXGEEU5223	05
5342	RPA870	KL-15-A	1654	EML	FP		16-Aug-2016	PNI	53	66		E613CDGB070706	MC2RINRT0GB047680	67
5343	RPK880	KL-15-A	1655	LL	ORD		16-Aug-2016	PMNA	48	66		GEEZ405040	MB1PBEYD2GEEU5684	68
5344	RPK881	KL-15-A	1656	LL	ORD		16-Aug-2016	PMNA	48	66		GEEZ405015	MB1PBEYD8GEEU5690	68
5345	RPA871	KL-15-A	1668	EML	FP		18-Aug-2016	PNI	53	66		E613CDGC073432	MC2RINRT0GC048106	67
5346	RPK882	KL-15-A	1669	LL	ORD		18-Aug-2016	SBY	48	66	HINO BS III	GEEZ404780	MB1PBEYD3GEEU5564	75
5347	RPC898	KL-15-A	1670	LL	FP		22-Aug-2016	KPA	53	66		GEEZ405503	MB1PBEYD1GEEU6065	74
5348	RPE811	KL-15-A	1671	LL	ORD		19-Aug-2016	KMY	48	66		GEEZ403620	MB1PBEYD1GEEU5224	05
5349	RPE812	KL-15-A	1672	LL	ORD		19-Aug-2016	SBY	48	66	LL BS III	GEEZ403602	MB1PBEYD3GEEU5225	75
5350	RPA872	KL-15-A	1673	EML	FP		22-Aug-2016	NTA	53	66		E613CDGC073415	MC2RINRT0GC048110	22
5351	RPM887	KL-15-A	1674	EML	FP		23-Aug-2016	PSL	53	66		E613CDGC073305	MC2RINRT0GC048084	21
5352	RPC911	KL-15-A	1675	LL	FP		25-Aug-2016	VTRA	53	66		GEEZ405846	MB1PBEYD8GEDU6500	17
5353	RPC912	KL-15-A	1676	LL	FP		25-Aug-2016	KTR	53	66		GDEZ405932	MB1PBEYD3GEDU6498	35
5354	RPE813	KL-15-A	1677	LL	ORD		23-Aug-2016	TSR	48	66		GEEZ404331	MB1PBEYD5GEEU5226	63
5355	RPE859	KL-15-A	1678	LL	ORD		23-Aug-2016	TSR	48	66		GEEZ404178	MB1PBEYD9GEEU5231	63
5356	RPC915	KL-15-A	1679	LL	ORD		26-Aug-2016	KNR	48	66		GDEZ405906	MB1PBEYD7GEDU6486	77
5357	RPM886	KL-15-A	1680	EML	FP		26-Aug-2016	VLND	53	66		E613CDGC073324	MC2RINRT0GC048083	20
5358	RPC913	KL-15-A	1681	LL	ORD		29-Aug-2016	CTR	48	66		GDEZ405910	MB1PBEYD1GEDU6497	70
5359	RPK946	KL-15-A	1683	LL	ORD		30-Aug-2016	TSR	48	60		GEEZ404826	MB1PBEYD6GEEU5557	63
5360	RPK947	KL-15-A	1684	LL	ORD		30-Aug-2016	TSR	48	60		GEEZ404681	MB1PBEYD2GEEU5555	63
5361	RPC914	KL-15-A	1685	LL	ORD		2-Sep-2016	PMNA	48	60		GEEZ405856	MB1PBEYD5GEDU6499	68
5362	RPC802	KL-15-A	1686	LL	SEXP		3-Sep-2016	KMG	53	66		GEEZ405084	MB1PBEYD5GEEU5873	55
5363	RPC803	KL-15-A	1687	LL	SEXP		3-Sep-2016	EKM	53	66		GEEZ404972	MB1PBEYD9GEEU6007	56
5364	RPC899	KL-15-A	1688	LL	SDLX		3-Sep-2016	KKD	53	66		GEEZ405080	MB1PBEYD6GEEU5705	72
5365	RPC900	KL-15-A	1689	LL	SDLX		3-Sep-2016	TVL	53	66		GEEZ404869	MB1PBEYD3GEEU5869	43
5366	RPC901	KL-15-A	1690	LL	SDLX		3-Sep-2016	TVL	53	66		GEEZ404868	MB1PBEYD9GEEU5875	43
5367	RPC902	KL-15-A	1691	LL	SDLX		3-Sep-2016	NBR	53	66		GEEZ404707	MB1PBEYD2GEEU5420	86
5368	RPC941	KL-15-A	1692	LL	SDLX		3-Sep-2016	KKD	53	66		GEEZ403372	MB1PBEYC3GEEU4227	72
5369	RPC903	KL-15-A	1693	LL	SDLX		5-Sep-2016	KKD	53	66		GEEZ405175	MB1PBEYCXGEEU5982	72
5370	RPC942	KL-15-A	1694	LL	SDLX		5-Sep-2016	KTR	53	66		GEEZ403501	MB1PBEYC5GEEU4228	35
5371	RPC943	KL-15-A	1695	LL	SDLX		5-Sep-2016	KTR	53	66		GEEZ403502	MB1PBEYC7GEEU4229	35

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5372	RPC944	KL-15-A	1696	LL	SDLX		5-Sep-2016	GVR	53	66		GEEZ403503	MB1PBEYC5GEEU4231	66
5373	RPC945	KL-15-A	1697	LL	SDLX		5-Sep-2016	GVR	53	66		GEEZ405171	MB1PBEYD4GEEU5847	66
5374	RPE860	KL-15-A	1698	LL	ORD		1-Sep-2016	MNR	48	60		GEEZ404225	MB1PBEYD6GEEU5235	60
5375	RPC916	KL-15-A	1699	LL	ORD		6-Sep-2016	MNR	48	60		GDEZ405909	MB1PBEYD2GEDU6492	60
5376	RPC917	KL-15-A	1700	LL	ORD		6-Sep-2016	MNR	48	60		GDEZ406547	MB1PBEYDXGEDU7230	60
5377	RPC918	KL-15-A	1701	LL	ORD		6-Sep-2016	PMNA	48	60		FXEZ417306	MB1PBEYD8GEDU6660	68
5378	RPE861	KL-15-A	1702	LL	ORD		5-Sep-2016	PMNA	48	60		GEEZ404526	MB1PBEYDXGEEU5237	68
5379	RPE862	KL-15-A	1703	LL	ORD		6-Sep-2016	KNR	48	60		GEEZ404597	MB1PBEYD0GEEU5294	77
5380	RPM888	KL-15-A	1704	EML	FP		6-Sep-2016	PVM	53	66		E613CDGC073315	MC2RINRT0GC048086	83
5381	RPK948	KL-15-A	1705	LL	SFP		6-Sep-2016	PVM	53	66		GEEZ404922	MB1PBEYD0GEEU5554	83
5382	RPC919	KL-15-A	1706	LL	ORD		8-Sep-2016	TLY	48	60		GFEZ401608	MB1PBEYD6GEDU6656	18
5383	RPC920	KL-15-A	1707	LL	ORD		8-Sep-2016	TLY	48	60		GEEZ403600	MB1PBEYD8GEEU5236	18
5384	RPE863	KL-15-A	1708	LL	ORD		17-Sep-2016	TLY	48	60		GEEZ404177	MB1PBEYD2GEEU5295	18
5385	RPA873	KL-15-A	1709	EML	FP		17-Sep-2016	KKLM	53	66		E613CDGC073412	MC2RINRT0GC048112	108
5386	RPM981	KL-15-A	1710	EML	FP		17-Sep-2016	ATL	53	66		E613CDGC074837	MC2RINRT0GC048306	33
5387	RPM982	KL-15-A	1711	EML	FP		17-Sep-2016	KLM	53	66		E613CDGC074836	MC2RINRT0GC048303	34
5388	RPC967	KL-15-A	1713	LL	SDLX		17-Sep-2016	KNR	53	66		GEEZ404870	MB1PBEYD4GEEU5704	77
5389	RPC968	KL-15-A	1714	LL	SDLX		17-Sep-2016	KNR	53	66		GEEZ405260	MB1PBEYD3GEEU5872	77
5390	RPC921	KL-15-A	1715	LL	ORD		17-Sep-2016	TSY	48	60		GEEZ404147	MB1PBEYD0GEEU4873	73
5391	RPC922	KL-15-A	1716	LL	ORD		17-Sep-2016	TSY	48	60		GDEZ406089	MB1PBEYDXGEDU6739	73
5392	RPC923	KL-15-A	1717	LL	ORD		17-Sep-2016	KNR	48	60		GDEZ406652	MB1PBEYD9GEDU7378	77
5393	RPC924	KL-15-A	1718	LL	ORD		17-Sep-2016	KGD	48	60		GDEZ406740	MB1PBEYD7GEDU7377	84
5394	RPC925	KL-15-A	1719	LL	ORD		17-Sep-2016	KGD	48	60		GDEZ406639	MB1PBEYD7GEDU7332	84
5395	RPC926	KL-15-A	1720	LL	ORD		19-Sep-2016	KGD	48	60		GDEZ406703	MB1PBEYD3GEDU7375	84
5396	RPA904	KL-15-A	1721	EML	FP		9-Sep-2016	TSR	53	66		E613CDGC074368	MC2RINRT0GC048227	63
5397	RPK949	KL-15-A	1722	LL	SFP		9-Sep-2016	ADR	53	66		GEEZ404967	MB1PBEYD8GEEU5561	38
5398	RPE864	KL-15-A	1723	LL	ORD		17-Sep-2016	KGD	48	60		GEEZ404628	MB1PBEYDXGEEU5299	84
5399	RPE865	KL-15-A	1724	LL	ORD		19-Sep-2016	KGD	48	60		GEEZ404530	MB1PBEYD2GEEU5300	84
5400	RPA905	KL-15-A	1725	EML	FP		19-Sep-2016	TSR	53	66		E613CDGC075089	MC2RINRT0GC048341	63
5401	RPK950	KL-15-A	1726	LL	SFP		19-Sep-2016	ADR	53	66		GEEZ404719	MB1PBEYD4GEEU5556	38
5402	RPM983	KL-15-A	1727	EML	FP		19-Sep-2016	HPD	53	66		E613CDGC074443	MC2RINRT0GC048243	42
5403	RPM984	KL-15-A	1728	EML	FP		19-Sep-2016	MALA	53	66		E613CDGC074471	MC2RINRT0GC074471	85
5404	RPC927	KL-15-A	1729	LL	ORD		22-Sep-2016	KGD	48	60		GDEZ406524	MB1PBEYD7GEDU7329	84
5405	RPC928	KL-15-A	1730	LL	FP		22-Sep-2016	ETPA	53	66		GDEZ406525	MB1PBEYD3GEDU7327	48
5406	RPA906	KL-15-A	1731	EML	FP		20-Sep-2016	MVPA	53	66	E6837C BS111	E613CDGC074829	MC2RINRT0GC048302	52
5407	RPA907	KL-15-A	1732	EML	FP		20-Sep-2016	PTPM	53	66		E613CDGC073483	MC2RINRT0GC048108	15
5408	RPA909	KL-15-A	1733	EML	FP		22-Sep-2016	PTA	53	66	EML BS III	E613CDGC073150	MC2RINRT0GC048113	37
5409	RPC929	KL-15-A	1734	LL	FP		24-Sep-2016	TVL	53	66		GDEZ406539	MB1PBEYD5GEDU7300	43
5410	RPC930	KL-15-A	1735	LL	FP		24-Sep-2016	TVL	53	66		GDEZ406631	MB1PBEYD7GEDU7380	43
5411	RPC931	KL-15-A	1736	LL	FP		24-Sep-2016	VZM	53	66		GDEZ406472	MB1PBEYD9GEDU7297	24
5412	RPM985	KL-15-A	1737	LL	ORD		22-Sep-2016	KGD	48	60		GDEZ406698	MB1PBEYD3GEDU7330	84
5413	RPK986	KL-15-A	1738	LL	SFP		22-Sep-2016	KKD	53	66		GEEZ404932	MB1PBEYD8GEEU5558	72
5414	RPK987	KL-15-A	1739	LL	SFP		22-Sep-2016	KKD	53	66		GEEZ404965	MB1PBEYD6GEEU5560	72
5415	RPE866	KL-15-A	1740	LL	ORD		22-Sep-2016	KGD	48	60		GEEZ404333	MB1PBEYD6GEEU5302	84
5416	RPE867	KL-15-A	1741	LL	ORD		23-Sep-2016	KGD	48	60		GEEZ404620	MB1PBEYD2GEEU5328	84

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5417	RPA908	KL-15-A	1742	EML	FP		23-Sep-2016	KLM	53	66		E613CDGC073406	MC2RINRT0GC048109	34
5418	RPM996	KL-15-A	1743	LL	ORD		24-Sep-2016	CTR	48	60		GDEZ406742	MB1PBEYD0GEDU7673	70
5419	RPA910	KL-15-A	1744	EML	FP		26-Sep-2016	KLM	53	66		E613CDGC073405	MC2RINRT0GC048111	34
5420	RPK988	KL-15-A	1745	LL	SFP		26-Sep-2016	MPM	53	66		GEEZ405204	MB1PBEYD4GEEU5802	71
5421	RPK989	KL-15-A	1746	LL	SFP		26-Sep-2016	SBY	53	66		GEEZ405012	MB1PBEYD7GEEU5681	75
5422	RPM997	KL-15-A	1747	LL	ORD		26-Sep-2016	KGD	48	60		GDEZ406565	MB1PBEYD4GEDU7675	84
5423	RPC932	KL-15-A	1750	LL	FP		29-Sep-2016	TVM	53	66		GFEZ402380	MB1PBEYD0GEFU3189	27
5424	RPC935	KL-15-A	1751	LL	FP		29-Sep-2016	EKM	53	66		GEEZ405509	MB1PBEYDXGEEU6064	56
5425	RPC933	KL-15-A	1752	LL	FP		29-Sep-2016	PLKD	53	66	BS 111	GEEZ405479	MB1PBEYD7GEEU6054	69
5426	RPC939	KL-15-A	1753	LL	ORD		29-Sep-2016	KGD	48	60		GEEZ404753	MB1PBEYD9GEEU5472	84
5427	RPC940	KL-15-A	1754	LL	ORD		29-Sep-2016	TSY	48	60		GEEZ404790	MB1PBEYD8GEEU5477	73
5428	RPC937	KL-15-A	1755	LL	FP		29-Sep-2016	KTR	53	66		GEEZ404807	MB1PBEYD1GEEU5482	35
5429	RPA951	KL-15-A	1756	LL	FP		27-Sep-2016	PSL	53	66		GDEZ406535	MB1PBEYD1GEDU7326	21
5430	RPE868	KL-15-A	1757	LL	ORD		27-Sep-2016	CTR	48	60		GEEZ404631	MB1PBEYD4GEEU5329	70
5431	RPM998	KL-15-A	1758	LL	ORD		29-Sep-2016	PLKD	48	60	BS 111	GDEZ406797	MB1PBEYD1GEDU7438	69
5432	RPC934	KL-15-A	1759	LL	FP		30-Sep-2016	KTR	53	66		GEEZ405060	MB1PBEYD6GEEU6062	35
5433	RPC936	KL-15-A	1760	LL	FP		30-Sep-2016	VZM	53	66		GEEZ404765	MB1PBEYD0GEEU5473	24
5434	RPK990	KL-15-A	1761	LL	SFP		28-Sep-2016	KTR	53	66		GEEZ405034	MB1PBEYD6GEEU5686	35
5435	RPK991	KL-15-A	1762	LL	SFP		29-Sep-2016	PALA	53	66		GEEZ404957	MB1PBEYD3GEEU5693	50
5436	RPE971	KL-15-A	1763	LL	ORD		29-Sep-2016	SBY	48	60		GEEZ404655	MB1PBEYD8GEEU5334	75
5437	RPK992	KL-15-A	1764	LL	SFP		30-Sep-2016	NPR	53	66		GEEZ404730	MB1PBEYD0GEEU5747	62
5438	RPC938	KL-15-A	1765	LL	ORD		3-Oct-2016	CTR	48	60		GEEZ404824	MB1PBEYD3GEEU5483	70
5439	RPC961	KL-15-A	1766	LL	ORD		4-Oct-2016	KGD	48	60		GEEZ404825	MB1PBEYDXGEEU5481	84
5440	18000	KL-15-A	1767	LL	FP		5-Oct-2016	KPA	53	66		GDEZ406088	MB1PBEYD1GEDU6743	74
5441	RPK993	KL-15-A	1782	LL	SFP		25-Oct-2016	PTA	53	66	HINO BS III	GEEZ405804	MB1PBEYD0GEDU6359	37
5442	RPC964	KL-15-A	1768	LL	ORD	VND	14-Oct-2016	KGD	48	60		GEEZ404940	MB1PBEYD1GEEU5563	84
5443	RPC962	KL-15-A	1769	LL	ORD	VND	15-Oct-2016	KGD	48	60		GEEZ404806	MB1PBEYD6GEEU5476	84
5444	ATM 14	KL-15-A	1770	LL	FP		15-Oct-2016	KDLR	53	66		GDEZ406793	MB1PBEYD5GEDU7443	90
5445	ATM 13	KL-15-A	1776	LL	ORD	VND	14-Oct-2016	KGD	48	60		GEEZ405804	MB1PBEYD0GEDU6359	84
5446	ATM 15	KL-15-A	1777	LL	ORD	VND	18-Oct-2016	KGD	48	60		GDEZ406741	MB1PBEYD7GEDU7671	84
5447	RPA952	KL-15-A	1778	LL	FP		18-Oct-2016	TSR	53	66		GDEZ406699	MB1PBEYD1GEDU7374	63
5448	RPE972	KL-15-A	1779	LL	ORD		18-Oct-2016	PLR	48	60		GEEZ404155	MB1PBEYD5GEEU4870	36
5449	ATM 16	KL-15-A	1780	LL	FP		20-Oct-2016	KMGH	53	66		GEEZ405512	MB1PBEYD5GEDU7670	55
5450	RPE973	KL-15-A	1781	LL	ORD		20-Oct-2016	KGD	48	60		GEEZ404316	MB1PBEYD0GEEU5005	84
5451	RPK994	KL-15-A	1783	LL	SFP		25-Oct-2016	KPA	53	66		GEEZ405782	MB1PBEYD9GEDU6361	74
5452	ATM 17	KL-15-A	1784	LL	ORD		22-Oct-2016	KGD	48	60		GDEZ406748	MB1PBEYD3GEDU7442	84
5453	RPE974	KL-15-A	1785	LL	ORD		24-Oct-2016	MDY	48	60		GEEZ404315	MB1PBEYD4GEEU5007	76
5454	ATM 43	KL-15-A	1786	LL	FP		25-Oct-2016	KNR	53	66		FSEZ427942	MB1PBEYD1GEDU7441	77
5455	RPC963	KL-15-A	1787	LL	ORD	VND	26-Oct-2016	KGD	48	60		GEEZ404941	MB1PBEYDXGEEU5562	84
5456	RPC965	KL-15-A	1788	LL	ORD	VND	26-Oct-2016	KGD	48	60		GEEZ404808	MB1PBEYD8GEEU5480	84
5457	RPC966	KL-15-A	1789	LL	ORD	VND	26-Oct-2016	SBY	48	60		GEEZ405737	MB1PBEYD2GEDU6654	75
5458	RPC969	KL-15-A	1790	LL	SDLX		26-Oct-2016	KTR	53	66		GEEZ405365	MB1PBEYD5GEEU6005	35
5459	RPC970	KL-15-A	1791	LL	SDLX		26-Oct-2016	KTR	53	66		GEEZ404971	MB1PBEYD7GEEU5874	35
5460	ATC 1	KL-15-A	1792	LL	FP		26-Oct-2016	KNR	53	66		GEEZ405861	MB1PBEYDXGEDU6661	77
5461	ATC 2	KL-15-A	1793	LL	ORD	VND	26-Oct-2016	SBY	48	60		GEEZ405881	MB1PBEYD5GEDU6440	75

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5462	ATC 3	KL-15-A	1794	LL	ORD	VND	26-Oct-2016	SBY	48	60		GDEZ406629	MB1PBEYD8GEDU7372	75
5463	ATC 4	KL-15-A	1795	LL	SFP		26-Oct-2016	CTLA	53	66	LL HINO BS III	GDEZ406648	MB1PBEYDXGEDU7373	46
5464	ATC 12	KL-15-A	1796	LL	SFP		26-Oct-2016	TSR	53	66		GEEZ405817	MB1PBEYDXGEDU6742	63
5465	RPE975	KL-15-A	1797	LL	ORD		25-Oct-2016	MDY	48	60		GEEZ404245	MB1PBEYD6GEEU5011	76
5466	RPK995	KL-15-A	1798	LL	SFP		25-Oct-2016	KKD	53	66		GEEZ405876	MB1PBEYD9GEDU6358	72
5467	RPA953	KL-15-A	1799	LL	FP		26-Oct-2016	VZM	53	66		GDEZ406502	MB1PBEYD7GEDU7301	24
5468	RPA954	KL-15-A	1800	LL	FP		26-Oct-2016	KLM	53	66		GDEZ405921	MB1PBEYD0GEDU7737	34
5469	RPA955	KL-15-A	1801	LL	FP		26-Oct-2016	TSR	53	66		FGEZ430600	MB1PBEYD2GEDU7755	63
5470	ATC 5	KL-15-A	1802	LL	ORD		27-Oct-2016	KGD	48	60		GDEZ406324	MB1PBEYD5GEDU7376	84
5471	ATM 44	KL-15-A	1803	LL	ORD		27-Oct-2016	KGD	48	60		GDEZ406747	MB1PBEYD3GEDU7439	84
5472	ATC 6	KL-15-A	1804	LL	ORD		28-Oct-2016	SBY	48	60		GEEZ405819	MB1PBEYD2GEDU7674	75
5473	RPA956	KL-15-A	1805	LL	FP		27-Oct-2016	VDCY	53	66		GDEZ406641	MB1PBEYD0GEDU7379	82
5474	ATC 7	KL-15-A	1806	LL	ORD	VND	31-Oct-2016	SBY	48	60		GEEZ405623	MB1PBEYD5GEDU7734	75
5475	ATC 11	KL-15-A	1807	LL	FP		31-Oct-2016	TLY	53	66		GEEZ405802	MB1PBEYD9GEDU6487	18
5476	RPE976	KL-15-A	1808	LL	ORD		28-Oct-2016	KGD	48	60		GEEZ404172	MB1PBEYDXGEEU5013	84
5477	ATK 46	KL-15-A	1809	LL	SFP		31-Oct-2016	TVM	53	66		GEEZ405800	MB1PBEYD3GEDU6355	27
5478	ATC 8	KL-15-A	1810	LL	SFP		2-Nov-2016	KPA	53	66		GDEZ406995	MB1PBEYD7GEDU7735	74
5479	ATC 19	KL-15-A	1811	LL	FP		2-Nov-2016	NTA	53	66		GDEZ405957	MB1PBEYDXGEDU6501	22
5480	RPE977	KL-15-A	1812	LL	SFP		1-Nov-2016	GVR	53	66		GEEZ404621	MB1PBEYD6GEEU5297	66
5481	ATC 10	KL-15-A	1813	LL	FP		4-Nov-2016	KTM	53	66		FTEZ424501	MB1PBEYD1GEDU7732	47
5482	ATC 9	KL-15-A	1814	LL	SFP		4-Nov-2016	TVM	53	66		GDEZ407048	MB1PBEYD8GEDU7789	27
5483	ATC 28	KL-15-A	1815	LL	SFP		4-Nov-2016	PALA	53	66		GDEZ406562	MB1PBEYD3GEDU7229	50
5484	ATM 45	KL-15-A	1816	LL	FP		5-Nov-2016	KPM	53	66	LL HINO BS III	GDEZ406632	MB1PBEYD5GEDU7328	91
5485	ATC 22	KL-15-A	1817	LL	FP		7-Nov-2016	KKD	53	66		GEEZ405773	MB1PBEYD1GEDU7147	72
5486	ATC 23	KL-15-A	1818	LL	FP		7-Nov-2016	GVR	53	66		GEEZ404735	MB1PBEYD1GEDU7150	66
5487	ATC 25	KL-15-A	1819	LL	FP		7-Nov-2016	KKD	53	66		GDEZ406045	MB1PBEYDXGEDU7146	72
5488	RPE978	KL-15-A	1822	LL	SFP		4-Nov-2016	TVM	53	66		GEEZ404243	MB1PBEYD4GEEU5301	27
5489	ATC 18	KL-15-A	1823	LL	FP		8-Nov-2016	PBVR	53	66		GDEZ405907	MB1PBEYDXGEDU6496	59
5490	ATC 27	KL-15-A	1824	LL	SFP		8-Nov-2016	TSR	53	66		GDEZ406515	MB1PBEYD1GEDU7228	63
5491	ATC 24	KL-15-A	1825	LL	FP		9-Nov-2016	TSR	53	66		GDEZ406537	MB1PBEYD4GEDU7224	63
5492	RPA957	KL-15-A	1826	LL	FP		7-Nov-2016	ALP	53	66		GEEZ405649	MB1PBEYD4GEDU6493	45
5493	RPA958	KL-15-A	1827	LL	FP		8-Nov-2016	ARK	53	66		GDEZ407045	MB1PBEYD9GEDU7767	06
5494	RPA959	KL-15-A	1828	LL	FP		8-Nov-2016	IJK	53	66	LL BS 111	GDEZ405997	MB1PBEYD9GEDU7736	89
5495	ATM 51	KL-15-A	1829	LL	FP		10-Nov-2016	KMY	53	66		GEEZ405481	MB1PBEYD9GEEU6055	05
5496	ATK 47	KL-15-A	1830	LL	SFP		10-Nov-2016	KNR	53	66		GEEZ405779	MB1PBEYD5GEDU6356	77
5497	ATK 48	KL-15-A	1831	LL	SFP		10-Nov-2016	KKD	53	66		GDEZ406091	MB1PBEYD8GEDU6738	72
5498	ATK 49	KL-15-A	1832	LL	SFP		10-Nov-2016	KKD	53	66		GDEZ406093	MB1PBEYD8GEDU6741	72
5499	RPE980	KL-15-A	1833	LL	SFP		10-Nov-2016	PMNA	53	66		GEEZ404625	MB1PBEYD6GEEU5333	68
5500	RPE979	KL-15-A	1834	LL	SFP		11-Nov-2016	KKD	53	66		GEEZ404656	MB1PBEYD4GEEU5332	72
5501	ATM 52	KL-15-A	1835	LL	FP		11-Nov-2016	TLY	53	66		GEEZ405482	MB1PBEYD9GEEU6069	18
5502	ATC 30	KL-15-A	1836	LL	SFP		14-Nov-2016	KTR	53	66		GEEZ405542	MB1PBEYD3GEDU7148	35
5503	RPC999	KL-15-A	1837	LL	SDLX	SBRI	14-Nov-2016	KNR	53	66		GDEZ407313	MB1PBEYD3GEDU8445	77
5504	ATC 32	KL-15-A	1838	LL	SDLX	SBRI	14-Nov-2016	KTR	53	66		GDEZ406399	MB1PBEYD8GEDU7310	35
5505	ATC 33	KL-15-A	1839	LL	SDLX	SBRI	14-Nov-2016	SBY	53	66		GDEZ407311	MB1PBEYD4GEDU8454	75
5506	ATC 34	KL-15-A	1840	LL	SDLX	SBRI	14-Nov-2016	SBY	53	66		GDEZ406227	MB1PBEYD0GEDU8452	75

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5507	ATK 50	KL-15-A	1841	LL	SFP		14-Nov-2016	PNI	53	66		GDEZ415651	MB1PBEYD8GEDU6657	67
5508	ATE 54	KL-15-A	1842	LL	SFP		15-Nov-2016	ATL	53	66		GFEZ402612	MB1PBEYD2GEEU3448	33
5509	RPA960	KL-15-A	1843	LL	FP		11-Nov-2016	KPZA	53	66		GEEZ403647	MB1PBEYD0GEDU7754	07
5510	ATM 53	KL-15-A	1844	LL	FP		17-Nov-2016	EDT	53	66		GEEZ404653	MB1PBEYD5GEEU6053	98
5511	ATE 55	KL-15-A	1845	LL	SFP		18-Nov-2016	TDP	53	66		GEEZ404626	MB1PBEYD0GEEU5330	53
5512	ATC 20	KL-15-A	1846	LL	FP		21-Nov-2016	ETPA	53	66		FYEZ414089	MB1PBEYDXGEDU6658	48
5513	ATA 64	KL-15-A	1847	LL	FP		18-Nov-2016	KTM	53	66		GEEZ403735	MB1PBEYD9GEDU7672	47
5514	ATA 65	KL-15-A	1848	LL	FP		18-Nov-2016	KYLM	53	66		GFEZ402547	MB1PBEYD4GEDU6655	41
5515	ATM 99	KL-15-A	1849	LL	FP		19-Nov-2016	IJK	53	66	BS 111	GEEZ405467	MB1PBEYD2GEEU6057	89
5516	ATC 21	KL-15-A	1850	LL	FP		22-Nov-2016	ATL	53	66		GEEZ405844	MB1PBEYD0GEDU6491	33
5517	ATA 66	KL-15-A	1851	LL	FP		21-Nov-2016	KNPY	53	66		GDEZ406517	MB1PBEYD2GEDU7223	87
5518	ATC 31	KL-15-A	1852	LL	SFP		23-Nov-2016	MVK	53	66		GEEZ405740	MB1PBEYD1GEDU6659	88
5519	ATA 67	KL-15-A	1853	LL	FP		22-Nov-2016	MPM	53	66		GDEZ406982	MB1PBEYD8GDEZ7792	71
5520	ATC 26	KL-15-A	1854	LL	FP		25-Nov-2016	MLTM	53	66		GEEZ405771	MB1PBEYD3GEDU7151	54
5521	ATC 29	KL-15-A	1855	LL	SFP		25-Nov-2016	ADR	53	66		GEEZ405783	MB1PBEYD6GEDU7144	38
5522	ATE 56	KL-15-A	1856	LL	SFP		22-Nov-2016	PMNA	53	66		GEEZ405013	MB1PBEYD5GEEU5680	68
5523	ATA 68	KL-15-A	1857	LL	FP		24-Nov-2016	NDM	53	66		GEEZ404964	MB1PBEYDOGEDU7964	110
5524	ATK 80	KL-15-A	1858	EML	SFP		24-Nov-2016	TVM	53	66		E613CDUC073293	MC2RINRTOGCO48092	27
5525	ATM100	KL-15-A	1859	LL	FP		25-Nov-2016	TDP	53	66		GEEZ405370	MB1PBEYD3GEEU6052	53
5526	ATM101	KL-15-A	1860	LL	FP		25-Nov-2016	PTPM	53	66		GDEZ406983	MB1PBEYD2GEDU7738	15
5527	ATE 57	KL-15-A	1861	LL	SFP		25-Nov-2016	KTP	53	66		GEEZ405063	MB1PBEYD9GEEU5682	14
5528	ATA 69	KL-15-A	1862	LL	FP		29-Nov-2016	VDCY	53	66		GEEZ405818	MB1PBEYD8GEEU6495	82
5529	ATA 70	KL-15-A	1863	LL	FP		29-Nov-2016	KDLR	53	66		GDEZ405904	MB1PBEYD6GEDU6494	90
5530	ATK 81	KL-15-A	1864	EML	SFP		29-Nov-2016	CTR	53	66		E613CDGCO73301	MC2RINRTOGCO48089	70
5531	ATM119	KL-15-A	1865	LL	FP		29-Nov-2016	PTA	53	66	LL BS III	GEEZ400519	MB1PBEYD3GEDU7750	37
5532	ATE 58	KL-15-A	1866	LL	SFP		1-Dec-2016	KPA	53	66		GEEZ405042	MB1PBEYDOGEEU5683	74
5533	ATE 59	KL-15-A	1867	LL	SFP		1-Dec-2016	KTDA	53	66		GEEZ405038	MB1PBEYD4GEEU5685	25
5534	ATK 82	KL-15-A	1868	EML	SFP		1-Dec-2016	TVL	53	66		E613CDGCO73285	MC2RINRTOGCO48088	43
5535	ATM120	KL-15-A	1869	LL	FP		2-Dec-2016	VZM	53	66		GFEZ402060	MB1PBEYD4GEDU7790	24
5536	ATA 71	KL-15-A	1870	LL	FP		2-Dec-2016	KGD	53	66		GEEZ405778	MB1PBEYD4GEDU7143	84
5537	ATA 72	KL-15-A	1871	LL	FP		2-Dec-2016	NDM	53	66		GEEZ405637	MB1PBEYD8GEDU7145	110
5538	ATA 73	KL-15-A	1872	LL	FP		3-Dec-2016	MDY	53	66		GDEZ405541	MB1PBEYD9GEDU6490	76
5539	ATE 60	KL-15-A	1900	LL	SFP		3-Dec-2016	KMY	53	66	BS III	GEEZ404952	MB1PBEYD8GEEU5687	05
5540	ATM121	KL-15-A	1901	LL	FP		5-Dec-2016	MLPY	53	66		FTEZ426195	MB1PBEYDXGEDU7731	96
5541	ATA 74	KL-15-A	1902	LL	FP		5-Dec-2016	MDY	53	66		GDEZ405908	MB1PBEYD5GEDU6485	76
5542	ATK 83	KL-15-A	1916	EML	SFP		5-Dec-2016	MNR	53	66		E613CDGCO73320	MC2RINRTOGCO48091	60
5543	ATE 61	KL-15-A	1917	LL	SFP		8-Dec-2016	MPM	53	66		GEEZ405036	MB1PBEYDXGEEU5688	71
5544	ATE 62	KL-15-A	1918	LL	SFP		9-Dec-2016	KTR	53	66		GEEZ405017	MB1PBEYDXGEEU5691	35
5545	ATC 35	KL-15-A	1919	LL	SDLX	SBRI	23-Dec-2016	KTR	53	66		GDEZ406291	MB1PBEYD1GEDU8444	35
5546	ATC 36	KL-15-A	1920	LL	SDLX	SBRI	23-Dec-2016	TSR	53	66		GDEZ407312	MB1PBEYD2GEDU8453	63
5547	ATC 37	KL-15-A	1921	LL	SDLX	SBRI	23-Dec-2016	TSR	53	66		GDEZ407314	MB1PBEYDXGEDU8443	63
5548	ATC 38	KL-15-A	1922	LL	SDLX	SBRI	23-Dec-2016	MNR	53	66		GEEZ403320	MB1PBEYD4GEEU5239	60
5549	ATC 39	KL-15-A	1923	LL	SDLX	SBRI	23-Dec-2016	MNR	53	66		GEEZ403373	MB1PBEYD3GEEU4230	60
5550	ATC 40	KL-15-A	1924	LL	SDLX	SBRI	23-Dec-2016	EKM	53	66		GEEZ403861	MB1PBEYD2GEEU5241	56
5551	ATC 41	KL-15-A	1925	LL	SDLX	SBRI	23-Dec-2016	EKM	53	66		GEEZ404274	MB1PBEYD2GEEU5238	56

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5552	ATC 42	KL-15-A	1926	LL	SDLX	SBRI	23-Dec-2016	KTM	53	66		GEEZ404275	MB1PBEYD4GEEU5242	47
5553	ATC 85	KL-15-A	1927	LL	SDLX	SBRI	23-Dec-2016	KTM	53	66		GEEZ403857	MB1PBEYC2GEEU5417	47
5554	ATC 86	KL-15-A	1928	LL	SDLX	SBRI	23-Dec-2016	EKM	53	66		GEEZ403374	MB1PBEYC0GEEU5240	56
5555	ATC 87	KL-15-A	1929	LL	SDLX	SBRI	23-Dec-2016	EKM	53	66		GEEZ404705	MB1PBEYCOGEEU5416	56
5556	ATC 88	KL-15-A	1930	LL	SDLX	SBRI	23-Dec-2016	PLKD	53	66		GEEZ402719	MB1PBEYC6GEEU5419	69
5557	ATC 89	KL-15-A	1931	LL	SDLX	SBRI	23-Dec-2016	PLKD	53	66		GEEZ405082	MB1PBEYD8GEEU5706	69
5558	ATC 90	KL-15-A	1932	LL	SDLX	SBRI	23-Dec-2016	TLY	53	66		GEEZ405083	MB1PBEYD1GEEU5708	18
5559	ATC 91	KL-15-A	1933	LL	SDLX	SBRI	23-Dec-2016	TLY	53	66		GEEZ405174	MB1PBEYDXGEEU5870	18
5560	ATC 92	KL-15-A	1934	LL	SDLX	SBRI	23-Dec-2016	SBY	53	66		GEEZ405259	MB1PBEYD1GEEU5871	75
5561	ATC 93	KL-15-A	1935	LL	SEXP		23-Dec-2016	CHRY	53	66	6ET1 3KN BS111	GEEZ405172	MB1PBEYD6GEEU5848	44
5562	ATC 95	KL-15-A	1936	LL	SEXP		23-Dec-2016	CHRY	53	66	6ET1 3KNBS 111	GDEZ406855	MBIPBEYD6GEDU7631	44
5563	ATA 75	KL-15-A	1937	LL	FP		9-Dec-2016	PNKM	53	66		GDEZ406073	MB1PBEYD6GEDU6740	49
5564	ATK 84	KL-15-A	1938	EML	SFP		13-Dec-2016	SBY	53	66		E613CGC073310	MC2RINRT0GC048087	75
5565	ATA 76	KL-15-A	1939	LL	FP		15-Dec-2016	PNKM	53	66		GDEZ406041	MB1PBEYD3GEDU7149	49
5566	ATE 63	KL-15-A	1940	LL	SFP		15-Dec-2016	VDA	53	66		GEEZ404663	MB1PBEYD1GEEU5692	92
5567	ATE169	KL-15-A	1941	LL	SFP		17-Dec-2016	NDM	53	66		GEEZ405033	MB1PBEYD5GEEU5694	110
5568	ATA 77	KL-15-A	1942	LL	FP		19-Dec-2016	PALA	53	66		GEEZ403757	MB1PBEYD3GEEU4513	50
5569	ATE170	KL-15-A	1943	LL	SFP		20-Dec-2016	TVM	53	66		GEEZ404931	MB1PBEYD7GEEU5745	27
5570	ATK164	KL-15-A	1944	EML	SFP		24-Dec-2016	PNR	53	66		E613COGC074360	MC2RINRT0GC048228	78
5571	ATK165	KL-15-A	1945	EML	SFP		26-Dec-2016	KGD	53	66	BS 111	E613CDGC074438	MC2RINRT0GCO48247	84
5572	ATK166	KL-15-A	1946	EML	SFP		26-Dec-2016	KHD	53	66	BS 111	E613CDGC074433	MC2RINRT0GCO48244	106
5573	ATK167	KL-15-A	1947	EML	SFP		26-Dec-2016	NPR	53	66		E613CDGC075097	MC2RINRT0GCO48340	62
5574	AT 300	KL-15-A	1950	LL	SFP		14-Mar-2017	KYLM	53	66				41
5575	ATC111	KL-15-A	1951	TATA	SFP		14-Mar-2017	TVM	53	66				27
5576	ATC 94	KL-15-A	1952	LL	SEXP		18-Mar-2017	TSY	53	66		GDEZ406317	MB1PBEYD4GEDU7630	73
5577	ATC 96	KL-15-A	1953	LL	SEXP		18-Mar-2017	TSY	53	66		GEEZ405081	MB1PBEYDXGEEU5107	73
5578	ATC 97	KL-15-A	1954	LL	SDLX	SBRI	18-Mar-2017	KTP	53	66		GEEZ405173	MB1PBEYD8GEEU5849	14
5579	ATC 98	KL-15-A	1955	LL	SDLX	SBRI	18-Mar-2017	KTP	53	66		GEEZ405079	MB1PBEYD7GEEU6006	14
5580	ATC122	KL-15-A	1956	LL	SDLX	SBRI	18-Mar-2017	TVM	53	66		GEEZ405364	MB1PBEYD1GEEU5983	27
5581	ATC123	KL-15-A	1957	LL	SDLX	SBRI	18-Mar-2017	TVM	53	66		GEEZ405170	MB1PBEYD0GEEU6008	27
5582	ATC124	KL-15-A	1958	LL	SDLX	SBRI	18-Mar-2017	MNR	53	66		GEEZ404706	MB1PBEYD4GEEU5418	60
5583	ATC125	KL-15-A	1959	LL	SDLX	SBRI	18-Mar-2017	MNR	53	66		GEEZ405261	MB1PBEYD8GEEU5981	60
5584	ATC126	KL-15-A	1960	TATA	SDLX	SBRI	18-Mar-2017	PLKD	53	66		51K84257649	MAT412202F0P08367	69
5585	ATC127	KL-15-A	1961	TATA	SEXP		18-Mar-2017	PNR	53	66		51K84262559	MAT412202F0P08420	78
5586	ATC128	KL-15-A	1962	TATA	SEXP		18-Mar-2017	PNR	53	66		51K84262572	MAT412202F0P08427	78
5587	ATC129	KL-15-A	1963	TATA	SEXP		18-Mar-2017	TLY	53	66		51K84257645	MAT412202F0P08368	18
5588	ATC130	KL-15-A	1964	TATA	SEXP		18-Mar-2017	TLY	53	66		51K84259785	MAT412202F0P08433	18
5589	ATC131	KL-15-A	1965	TATA	SEXP		18-Mar-2017	KNR	53	66		51K84259756	MAT412202F0P08369	77
5590	ATC132	KL-15-A	1966	TATA	SEXP		18-Mar-2017	KNR	53	66		51K84262580	MAT412202F0P08417	77
5591	ATC133	KL-15-A	1967	TATA	SEXP		18-Mar-2017	KNR	53	66		51K84259800	MAT412202F0P08370	77
5592	ATC134	KL-15-A	1968	TATA	SEXP		18-Mar-2017	KNR	53	66		51K84259759	MAT412202F0P08371	77
5593	ATC135	KL-15-A	1969	TATA	SEXP		18-Mar-2017	KNR	53	66		51K84262557	MAT412202F0P08418	77
5594	ATC136	KL-15-A	1970	TATA	SEXP		18-Mar-2017	KNR	53	66		51K84262569	MAT412202F0P08425	77
5595	ATC137	KL-15-A	1971	TATA	SEXP		18-Mar-2017	KTM	53	66		51K84242568	MAT412202F0P08432	47
5596	ATC138	KL-15-A	1972	TATA	SEXP		18-Mar-2017	KTM	53	66		51K84262565	MAT412202F0P08419	47

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5597	ATC139	KL-15-A	1973	TATA	SEXP		18-Mar-2017	TPLM	53	66		51K84262579	MAT412202F0P08429	94
5598	ATC140	KL-15-A	1974	TATA	SEXP		18-Mar-2017	TVM	53	66		51K84262558	MAT412202F0P08428	27
5599	ATC141	KL-15-A	1975	TATA	SEXP		18-Mar-2017	KNR	53	66		51K84259776	MAT412202F0P08424	77
5600	ATC142	KL-15-A	1976	TATA	SEXP		18-Mar-2017	KKD	53	66		51K84259774	MAT412202F0P08423	72
5601	ATC143	KL-15-A	1977	TATA	SEXP		18-Mar-2017	KKD	53	66		61A84275951	MAT412202GOA00262	72
5602	ATC144	KL-15-A	1978	TATA	SEXP		18-Mar-2017	PNR	53	66		61A84275948	MAT412202GOA00265	78
5603	ATC145	KL-15-A	1979	TATA	SEXP		18-Mar-2017	PNR	53	66		61A84281010	MAT412202G0B00883	78
5604	ATC146	KL-15-A	1980	TATA	SEXP		18-Mar-2017	KGD	53	66		51K84262552	MAT412202FOPO8420	84
5605	ATC239	KL-15-A	1981	TATA	SEXP		18-Mar-2017	KKD	53	66		61B84288524	MAT412202G0D02678	72
5606	ATC240	KL-15-A	1982	TATA	SEXP		18-Mar-2017	KKD	53	66		61C84289266	MAT412202G0D02675	72
5607	ATC241	KL-15-A	1983	TATA	SEXP		18-Mar-2017	KKD	53	66		61E84289266	MAT412202G0E03540	72
5608	ATC242	KL-15-A	1984	TATA	SEXP		18-Mar-2017	KKD	53	66		61E84307664	MAT412202G0E03539	72
5609	ATC243	KL-15-A	1985	TATA	SEXP		18-Mar-2017	KKD	53	66		61B84288560	MAT412202G0D02676	72
5610	ATC244	KL-15-A	1986	TATA	SEXP		18-Mar-2017	KKD	53	66		61E84307724	MAT412202G0E03531	72
5611	ATC245	KL-15-A	1987	TATA	SEXP		18-Mar-2017	KKD	53	66		61B84288554	MAT412202G0D02677	72
5612	ATC246	KL-15-A	1988	TATA	SEXP		18-Mar-2017	KKD	53	66		61B84288562	MAT412202G0D02679	72
5613	ATC247	KL-15-A	1989	TATA	SEXP		18-Mar-2017	KKD	53	66		61E84307850	MAT412202G0E03538	72
5614	ATC248	KL-15-A	1990	TATA	SEXP		18-Mar-2017	KKD	53	66		61D84299616	MAT412202G0E03565	72
5615	ATA 78	KL-15-A	1991	LL	FP		20-Mar-2017	MDY	53	66		GFEZ402605	MB1PEYD4GEEU3449	76
5616	ATA 79	KL-15-A	1992	LL	FP		20-Mar-2017	MDY	53	66		GEEZ403548	MB1PBEYD2GEEU4308	76
5617	ATC250	KL-15-A	1993	TATA	SEXP		21-Mar-2017	KKD	53	66		61E84307676	MAT412202G0E03530	72
5618	ATC251	KL-15-A	1994	TATA	SEXP		21-Mar-2017	KKD	53	66		61D84301021	MAT412202G0E03532	72
5619	ATC148	KL-15-A	1995	TATA	SEXP		21-Mar-2017	KGD	53	66		61B84283596	MAT412202G0B01027	84
5620	ATC149	KL-15-A	1996	TATA	SDLX		21-Mar-2017	TVM	53	66		61A84281014	MAT412202G0B00885	27
5621	ATC258	KL-15-A	1997	TATA	SEXP		21-Mar-2017	TVM	53	66		51K84262588	MAT412202F0P08416	27
5622	ATC297	KL-15-A	1998	LL	FP		21-Mar-2017	NDM	53	66		GDEZ406516	MB1PBEYD1GEDU7293	110
5623	ATC298	KL-15-A	1999	LL	FP		21-Mar-2017	CTR	53	66		GEEZ405858	MB1PBEYD8GEDU7064	70
5624	ATA175	KL-15-A	2010	LL	FP		21-Mar-2017	PKD	53	66		GEEZ404619	MB1PBEYD2GEEU5751	65
5625	ATA176	KL-15-A	2011	LL	FP		21-Mar-2017	TVM	53	66		GDEZ405939	MB1PBEYD3GEDU6436	27
5626	ATM108	KL-15-A	2012	LL	FP		21-Mar-2017	PLR	53	66		GEEZ404528	MB1PBEYD6GEDU7029	36
5627	ATM109	KL-15-A	2013	LL	FP		21-Mar-2017	TVM	53	66		GDEZ406393	MB1PBEYD4GEDU7031	27
5628	ATM113	KL-15-A	2014	LL	FP		21-Mar-2017	MKD	53	66		GEEZ404933	MB1PBEYD2GEDU7061	08
5629	ATM114	KL-15-A	2015	LL	FP		21-Mar-2017	TVM	53	66		GEEZ405533	MB1PBEYD4GEDU7059	27
5630	ATM115	KL-15-A	2016	LL	FP		21-Mar-2017	KPA	53	66		GDEZ406518	MB1PBEYD0GEDU7222	74
5631	ATM116	KL-15-A	2017	LL	FP		21-Mar-2017	KPA	53	66		GDEZ406506	MB1PBEYD6GEDU7225	74
5632	ATM117	KL-15-A	2018	LL	FP		21-Mar-2017	TSR	53	66		GDEZ406519	MB1PBEYD8GEDU7226	63
5633	ATM118	KL-15-A	2019	LL	FP		21-Mar-2017	PLKD	53	66		GDEZ406572	MB1PBEYD5GEDU7295	69
5634	ATM212	KL-15-A	2020	LL	FP		21-Mar-2017	PLKD	53	66		GEEZ405306	MB1PBEYD6GEDU7791	69
5635	ATM213	KL-15-A	2021	LL	FP		21-Mar-2017	PLR	53	66		GEEZ400087	MB1PBEYD1GEDU6662	36
5636	ATM214	KL-15-A	2022	LL	FP		21-Mar-2017	PSL	53	66		GDEZ405958	MB1PBEYD2GEDU6489	21
5637	ATM215	KL-15-A	2023	LL	FP		21-Mar-2017	TSY	53	66		GEEZ405824	MB1PBEYD3GEDU6484	73
5638	ATM216	KL-15-A	2024	LL	FP		21-Mar-2017	ETPA	53	66		GEEZ405468	MB1PBEYD3GEEU6049	48
5639	ATM217	KL-15-A	2025	LL	FP		21-Mar-2017	KLM	53	66		GEEZ405705	MB1PBEYD0GEDU6488	34
5640	ATM264	KL-15-A	2026	LL	FP		21-Mar-2017	KLM	53	66		GEEZ404951	MB1PBEYD7GEEU6068	34
5641	ATM265	KL-15-A	2027	LL	FP		21-Mar-2017	KKD	53	66		GEEZ405883	MB1PBEYD5GEDU6437	72

SI.NO	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5642	ATM282	KL-15-A	2028	LL	FP		21-Mar-2017	KKD	53	66		GEEZ405801	MB1PBEYD1GEDU6354	72
5643	ATM283	KL-15-A	2029	LL	FP		21-Mar-2017	TSR	53	66		GEEZ405940	MB1PBEYD1GEDU6435	63
5644	ATM284	KL-15-A	2030	LL	FP		21-Mar-2017	PNI	53	66		GEEZ405882	MB1PBEYD8GEDU6965	67
5645	ATM285	KL-15-A	2031	LL	FP		21-Mar-2017	KLM	53	66		GEEZ405631	MB1PBEYDXGEDU6966	34
5646	ATM286	KL-15-A	2032	LL	FP		21-Mar-2017	KGD	53	66		GEEZ406329	MB1PBEYD5GEDU6969	84
5647	ATM291	KL-15-A	2033	LL	FP		21-Mar-2017	KGD	53	66		GDEZ406326	MB1PBEYD3GEDU6968	84
5648	ATM292	KL-15-A	2034	LL	FP		21-Mar-2017	VDA	53	66		GDEZ406325	MB1PBEYD1GEDU6967	92
5649	ATM293	KL-15-A	2035	LL	FP		21-Mar-2017	VDA	53	66		GEEZ404942	MB1PBEYD2GEDU7030	92
5650	ATM294	KL-15-A	2036	LL	FP		21-Mar-2017	VDA	53	66		GEEZ405684	MB1PBEYD1GEDU6970	92
5651	ATM295	KL-15-A	2037	LL	FP		21-Mar-2017	CHRY	53	66		GEEZ405686	MB1PBEYD3GEDU6971	44
5652	ATK168	KL-15-A	2038	EML	SFP		21-Mar-2017	TPLM	53	66		E613CDGC74477	MC2RINRTOGC048246	94
5653	ATK182	KL-15-A	2039	LL	SFP		21-Mar-2017	PKD	53	66		GDEZ406656	MB1PBEYD8GEDU7324	65
5654	ATK183	KL-15-A	2040	LL	SFP		21-Mar-2017	TVM	53	66		GDEZ406505	MB1PBEYD2GEDU7299	27
5655	ATK184	KL-15-A	2041	LL	SFP		21-Mar-2017	CTLA	53	66		GFEZ402467	MB1PBEYD9GEDU7753	46
5656	ATK185	KL-15-A	2042	LL	SFP		21-Mar-2017	KTR	53	66	HBS 111	GDEZ407002	MB1PBEYD5GEDU7751	35
5657	ATK186	KL-15-A	2043	LL	SFP		21-Mar-2017	KTR	53	66	HBS 111	GDEZ406533	MB1PBEYDXGEDU7325	35
5658	ATK259	KL-15-A	2044	LL	SFP		21-Mar-2017	SBY	53	66		GFEZ402124	MB1PBEYD5GEDU7331	75
5659	ATK260	KL-15-A	2045	LL	SFP		21-Mar-2017	TSR	53	66		GDEZ405959	MB1PBEYD8GEDU7730	63
5660	ATK261	KL-15-A	2046	LL	SFP		21-Mar-2017	TSR	53	66		GDEZ406960	MB1PBEYD3GEDU7733	63
5661	ATK262	KL-15-A	2047	LL	SFP		21-Mar-2017	KKD	53	66		GDEZ406980	MB1PBEYD0GEDU7768	72
5662	ATK263	KL-15-A	2048	LL	SFP		21-Mar-2017	KKD	53	66		GDEZ407049	MB1PBEYD5GEDU7765	72
5663	ATK301	KL-15-A	2049	LL	SFP		21-Mar-2017	PNI	53	66		GDEZ405912	MB1PBEYD9GEDU6439	67
5664	ATK302	KL-15-A	2050	LL	SFP		21-Mar-2017	MPM	53	66		GEEZ405751	MB1PBEYD4GEDU6364	71
5665	ATK303	KL-15-A	2051	LL	SFP		21-Mar-2017	KKD	53	66		GEEZ405815	MB1PBEYDXGEDU6434	72
5666	ATK304	KL-15-A	2052	LL	SFP		21-Mar-2017	KKD	53	66		EDEZ400533	MB1PBEYD5GEEU6070	72
5667	ATK305	KL-15-A	2053	LL	SFP		21-Mar-2017	TSR	53	66		GEEZ405803	MB1PBEYD7GEDU6357	63
5668	ATK306	KL-15-A	2054	LL	SFP		21-Mar-2017	TSR	53	66		GEEZ405717	MB1PBEYD0GEDU6362	63
5669	ATK307	KL-15-A	2055	LL	SFP		21-Mar-2017	TSR	53	66		GEEZ405722	MB1PBEYD6GEDU6365	63
5670	ATA177	KL-15-A	2056	LL	FP		22-Mar-2017	PNKM	53	66		GEEZ404953	MB1PBEYD4GEEU5752	49
5671	ATA178	KL-15-A	2057	LL	FP		22-Mar-2017	TVM	53	66		GEEZ404878	MB1PBEYD5GEEU6067	27
5672	ATA179	KL-15-A	2058	LL	FP		22-Mar-2017	MVPA	53	66	LL BS 111	GEEZ405686	MB1PBEYDXGEDU6904	52
5673	ATA180	KL-15-A	2059	LL	FP		22-Mar-2017	MVK	53	66		GDEZ406090	MB1PBEYD1GEDU6905	88
5674	ATA181	KL-15-A	2060	LL	FP		22-Mar-2017	MVK	53	66		GEEZ405831	MB1PBEYD3GEDU6906	88
5675	ATA266	KL-15-A	2061	LL	FP		22-Mar-2017	KNPY	53	66		GFEZ402545	MB1PBEYD7GEDU6908	87
5676	ATA267	KL-15-A	2062	LL	FP		22-Mar-2017	KNPY	53	66		GDEZ406328	MB1PBEYD0GEDU6961	87
5677	ATA268	KL-15-A	2063	LL	FP		22-Mar-2017	CGNR	53	66		GEEZ405823	MB1PBEYD5GEDU6907	40
5678	ATA269	KL-15-A	2064	LL	FP		22-Mar-2017	MVPA	53	66		GDEZ407396	MB1PBEYD4GEDU6963	52
5679	ATA270	KL-15-A	2065	LL	FP		22-Mar-2017	PNKM	53	66		GDEZ406327	MB1PBEYD9GEDU6960	49
5680	ATA271	KL-15-A	2066	LL	FP		22-Mar-2017	KDLR	53	66		FYEZ429017	MB1PBEYD2GEDU6962	90
5681	ATA272	KL-15-A	2067	LL	FP		22-Mar-2017	NDM	53	66		FYEZ414384	MB1PBEYD6GEDU6964	110
5682	ATA296	KL-15-A	2068	LL	FP		22-Mar-2017	KMGM	53	66		GDEZ406507	MB1PBEYD3GEDU7294	55
5683	ATM110	KL-15-A	2069	LL	FP		23-Mar-2017	ETPA	53	66		GDEZ406395	MB1PBEYD6GEDU7032	48
5684	ATM112	KL-15-A	2070	LL	FP		23-Mar-2017	EDT	53	66		GDEZ406396	MB1PBEYD8GEDU7033	98
5685	ATK102	KL-15-A	2071	LL	SFP		23-Mar-2017	MLPY	53	66		GDEZ406394	MB1PBEYD4GEDU7062	96
5686	ATK103	KL-15-A	2072	LL	SFP		23-Mar-2017	ANK	53	66	LL HINO BS111	GEEZ405721	MB1PBEYD2GEDU6363	57

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5687	ATK308	KL-15-A	2073	LL	SFP		23-Mar-2017	NDD	53	66		GEEZ405772	MB1PBEYD7GEDU6360	31
5688	ATK309	KL-15-A	2074	LL	SFP		23-Mar-2017	PTPM	53	66		GEEZ405541	MB1PBEYDOGEDU7060	15
5689	ATE171	KL-15-A	2075	LL	SFP		23-Mar-2017	PTPM	53	66		GEEZ404861	MB1PBEYD9GEEU5746	15
5690	ATE172	KL-15-A	2076	LL	SFP		23-Mar-2017	TSY	53	66		GEEZ404857	MB1PBEYD2GEEU5748	73
5691	ATE173	KL-15-A	2077	LL	SFP		23-Mar-2017	PNI	53	66		GEEZ405127	MB1PBEYD4GEEU5749	67
5692	ATE174	KL-15-A	2078	LL	SFP		23-Mar-2017	CDLM	53	66		GEEZ404768	MB1PBEYD0GEEU5750	80
5693	ATE218	KL-15-A	2079	EML	SFP		23-Mar-2017	KPA	53	66		E613CDGB071180	MC2RINRTOGB047709	74
5694	ATE219	KL-15-A	2080	EML	SFP		23-Mar-2017	GVR	53	66		E613CDGB071151	MC2RINRTOGB047710	66
5695	ATE220	KL-15-A	2081	EML	SFP		23-Mar-2017	PLR	53	66		E613CDGB071160	MC2RINRTOGB047711	36
5696	ATE221	KL-15-A	2082	EML	SFP		23-Mar-2017	KPA	53	66		E613CDGB071201	MC2RINRTOGB047717	74
5697	ATE222	KL-15-A	2083	EML	SFP		23-Mar-2017	TSY	53	66		E613CDGB070535	MC2RINRTOGB047641	73
5698	ATE223	KL-15-A	2084	EML	SFP		23-Mar-2017	TSR	53	66		E613CDGB070883	MB1PBEYD0GB047678	63
5699	ATE224	KL-15-A	2085	EML	SFP		23-Mar-2017	MPM	53	66		E613CDGB071019	MB1PBEYD0GB047690	71
5700	ATE225	KL-15-A	2086	EML	SFP		23-Mar-2017	TVL	53	66		E613CDGB071164	MB1PBEYD0GB047705	43
5701	ATE226	KL-15-A	2087	EML	SFP		23-Mar-2017	KKD	53	66		E613CDGB071176	MB1PBEYD0GB047712	72
5702	ATE227	KL-15-A	2088	EML	SFP		23-Mar-2017	MDY	53	66		E613CDGC073127	MC2RINRTOGCO48071	76
5703	ATE273	KL-15-A	2089	EML	SFP		23-Mar-2017	TDP	53	66		E613CDGC073420	MC2RINRTOGCO48101	53
5704	ATE274	KL-15-A	2090	EML	SFP		23-Mar-2017	KTR	53	66		E613CDGC073440	MC2RINRTOGCO48102	35
5705	ATE275	KL-15-A	2091	EML	SFP		23-Mar-2017	GVR	53	66		E613CDGC073444	MC2RINRTOGCO48103	66
5706	ATE276	KL-15-A	2092	EML	SFP		23-Mar-2017	CTR	53	66		E613CCDG073424	MC2RINRTOGCO48107	70
5707	ATE277	KL-15-A	2093	EML	SFP		23-Mar-2017	EKM	53	66		E613CDGC073119	MC2RINRTOGCO48070	56
5708	ATE278	KL-15-A	2094	EML	SFP		23-Mar-2017	TVM	53	66		E613CDGC073297	MC2RINRTOGCO48085	27
5709	ATE279	KL-15-A	2095	EML	SFP		23-Mar-2017	KTM	53	66		E613CDGC073289	MC2RINRTOGCO48090	47
5710	ATE280	KL-15-A	2096	EML	SFP		23-Mar-2017	TVM	53	66		E613CDGC073436	MC2RINRTOGCO48104	27
5711	ATE281	KL-15-A	2097	EML	SFP		23-Mar-2017	ALP	53	66		E613CDGC073448	MC2RINRTOGCO48105	45
5712	ATE287	KL-15-A	2098	LL	SFP		23-Mar-2017	PNR	53	66		GEEZ405605	MB1PBEYD8GEDU6903	78
5713	ATE288	KL-15-A	2099	LL	SFP		23-Mar-2017	KGD	53	66		GDEZ406398	MB1PBEYD2GEDU7058	84
5714	ATE289	KL-15-A	2100	LL	FP		23-Mar-2017	KKD	53	66		GEEZ404956	MB1PBEYD6GEDU7063	72
5715	ATE290	KL-15-A	2101	LL	FP		23-Mar-2017	NDM	53	66		GDEZ406570	MB1PBEYDXGEDU7227	110
5716	ATK104	KL-15-A	2102	LL	SFP		24-Mar-2017	KTDA	53	66	BS 111	GDEZ405934	MB1PBEYD8GEDU6433	25
5717	ATK105	KL-15-A	2103	LL	SFP		24-Mar-2017	KDLR	53	66		GDEZ406508	MB1PBEYD7GEDU7296	90
5718	ATK106	KL-15-A	2104	LL	SFP		24-Mar-2017	CGNR	53	66		GEEZ404923	MB1PBEYD7GEDU6438	40
5719	ATK107	KL-15-A	2105	LL	SFP		24-Mar-2017	MPM	53	66		GEEZ405880	MB1PBEYD7GEDU6441	71
5720	ATC147	KL-15-A	2106	TATA	SEXP		25-Mar-2017	TVM	53	66		51K84262587	MAT412202FOPO8429	27
5721	ATC150	KL-15-A	2107	TATA	SDLX		25-Mar-2017	KHD	53	66		51K84259802	MAT412202FOPO8422	106
5722	ATC163	KL-15-A	2108	TATA	SDLX		25-Mar-2017	KHD	53	66		61A84281006	MAT412202GOBO0884	106
5723	ATC193	KL-15-A	2109	TATA	SDLX		25-Mar-2017	TLY	53	66	BS 111	51J84257378	MAT412202F0P07993	18
5724	ATC252	KL-15-A	2110	TATA	SDLX		25-Mar-2017	PNI	53	66		61D84299602	MAT412202GOEO3564	67
5725	ATC253	KL-15-A	2111	TATA	SDLX		25-Mar-2017	PNI	53	66		61D84299643	MAT412202G0F03572	67
5726	ATC254	KL-15-A	2112	TATA	SDLX		25-Mar-2017	PVM	53	66		61D84303209	MAT412202G0FO3581	83
5727	ATC255	KL-15-A	2113	TATA	SDLX		25-Mar-2017	TVM	53	66		61D84299626	MAT412202G0FO3582	27
5728	ATC256	KL-15-A	2114	TATA	SDLX		25-Mar-2017	PALA	53	66		61D84304466	MAT412202G0FO3647	50
5729	ATC257	KL-15-A	2115	TATA	SDLX		25-Mar-2017	PALA	53	66		61E84308355	MAT412202G0FO3648	50
5730	ATC151	KL-15-A	2116	TATA	SDLX		25-Mar-2017	ALP	53	66		61A84275918	MAT412202GOA00261	45
5731	ATC152	KL-15-A	2117	TATA	SDLX		27-Mar-2017	ALP	53	66		51K84259796	MAT412202FOPO8434	45

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5732	ATC154	KL-15-A	2118	TATA	SDLX		27-Mar-2017	KDLR	53	66		61A84278715	MAT412202GOBO1033	90
5733	ATC155	KL-15-A	2119	TATA	SDLX		27-Mar-2017	KDLR	53	66		61A84275954	MAT412202GOA00267	90
5734	ATC156	KL-15-A	2120	TATA	SDLX		27-Mar-2017	TVM	53	66		61A84275950	MAT412202GOA00266	27
5735	ATC157	KL-15-A	2121	TATA	SDLX		27-Mar-2017	TVM	53	66		61A84278709	MAT412202GOBO1034	27
5736	ATC202	KL-15-A	2122	TATA	SDLX		27-Mar-2017	TSR	53	66		61A84278718	MAT412202GOBO1029	63
5737	ATC236	KL-15-A	2123	TATA	SEXP		27-Mar-2017	PNR	53	66		61B84283598	MAT412202GOBO1292	78
5738	ATC237	KL-15-A	2124	TATA	SEXP		27-Mar-2017	PNR	53	66		61B84283800	MAT412202GOBO1293	78
5739	ATC238	KL-15-A	2125	TATA	SEXP		27-Mar-2017	TVM	53	66		61A84281000	MAT412202GOBO0882	27
5740	ATC153	KL-15-A	2126	TATA	SDLX		28-Mar-2017	TSR	53	66		61A84275939	MAT412202GOA00263	63
5741	ATC158	KL-15-A	2127	TATA	SDLX		28-Mar-2017	TSR	53	66		61A84275941	MAT412202GOA00264	63
5742	ATC159	KL-15-A	2128	TATA	SDLX		28-Mar-2017	TSR	53	66		61A84278269	MAT412202GOBO1036	63
5743	ATC160	KL-15-A	2129	TATA	SDLX		28-Mar-2017	TSR	53	66		61A84275946	MAT412202GOA00259	63
5744	ATC161	KL-15-A	2130	TATA	SDLX		28-Mar-2017	PTA	53	66		61A84275553	MAT412202GOA00260	37
5745	ATC162	KL-15-A	2131	TATA	SDLX		28-Mar-2017	PTA	53	66		61A84275008	MAT412202GOA00258	37
5746	ATC187	KL-15-A	2132	TATA	SDLX		28-Mar-2017	PVM	53	66		51K84262561	MAT412202FOPO8431	83
5747	ATC188	KL-15-A	2133	TATA	SDLX		28-Mar-2017	EKM	53	66		51484262574	MAT412202FOPO8430	56
5748	ATC189	KL-15-A	2134	TATA	SDLX		28-Mar-2017	CWS	53	66		61A84279064	MAT412202FOPO1072	09
5749	ATC190	KL-15-A	2135	TATA	SDLX		28-Mar-2017	CWS	53	66		61A84281027	MAT412202GOBO1094	09
5750	ATC191	KL-15-A	2136	TATA	SDLX		28-Mar-2017	GVR	53	66		61B84283816	MAT412202GOBO1074	66
5751	ATC192	KL-15-A	2137	TATA	SDLX		28-Mar-2017	PTA	53	66		61A84279142	MAT412202GOBO1071	37
5752	ATC249	KL-15-A	2138	TATA	SDLX		28-Mar-2017	KPA	53	66		61E84307656	MAT412202GOEO3522	74
5753	ATC194	KL-15-A	2139	TATA	SDLX		28-Mar-2017	PTA	53	66		61A84281022	MAT412202GOBO1095	37
5754	ATC195	KL-15-A	2140	TATA	SDLX		28-Mar-2017	PLKD	53	66		61A84279147	MAT412202GOBO0881	69
5755	ATC196	KL-15-A	2141	TATA	SDLX		28-Mar-2017	PLKD	53	66		61B84283600	MAT412202GOBO1026	69
5756	ATC197	KL-15-A	2142	TATA	SDLX		28-Mar-2017	ALP	53	66		61A84279131	MAT412202GOBO1035	45
5757	ATC198	KL-15-A	2143	TATA	SDLX		28-Mar-2017	TVM	53	66		61B84283595	MAT412202GOBO1028	27
5758	ATC199	KL-15-A	2144	TATA	SDLX		28-Mar-2017	TVM	53	66		61B84283818	MAT412202GOBO1244	27
5759	ATC200	KL-15-A	2145	TATA	SDLX		28-Mar-2017	PLR	53	66		61A84281008	MAT412202GOBO1070	36
5760	ATC201	KL-15-A	2146	TATA	SDLX		28-Mar-2017	TVM	53	66		61A84278724	MAT412202GOBO1075	27
5761	ATC203	KL-15-A	2147	TATA	SDLX		28-Mar-2017	TVM	53	66		61B84283604	MAT412202GOBO1037	27
5762	ATC204	KL-15-A	2148	TATA	SDLX	MINL	28-Mar-2017	TVM	53	66		61B84283807	MAT412202GOBO1073	27
5763	ATC205	KL-15-A	2149	TATA	SDLX	MINL	28-Mar-2017	TVM	53	66		61A84279051	MAT412202GOBO1030	27
5764	ATC206	KL-15-A	2150	TATA	SDLX	MINL	28-Mar-2017	TVM	53	66		61A84281016	MAT412202GOBO1031	27
5765	ATC207	KL-15-A	2151	TATA	SDLX	MINL	28-Mar-2017	TVM	53	66		61A84275263	MAT412202GOBO1032	27
5766	ATC208	KL-15-A	2152	TATA	SDLX	MINL	28-Mar-2017	SBY	53	66		61A84279139	MAT412202GOBO1096	75
5767	ATC209	KL-15-A	2153	TATA	SDLX	MINL	28-Mar-2017	SBY	53	66		61A84279140	MAT412202GOBO1097	75
5768	ATC210	KL-15-A	2154	TATA	SDLX	MINL	28-Mar-2017	MDY	53	66		61A84278725	MAT412202GOBO1098	76
5769	ATC211	KL-15-A	2155	TATA	SDLX	MINL	28-Mar-2017	MDY	53	66		61B84283801	MAT412202GOBO1140	76
5770	ATC228	KL-15-A	2156	TATA	SDLX	MINL	28-Mar-2017	KNR	53	66		61A84278280	MAT412202GOBO1093	77
5771	ATC229	KL-15-A	2157	TATA	SDLX	MINL	28-Mar-2017	KNR	53	66		61B84283613	MAT412202GOBO1178	77
5772	ATC230	KL-15-A	2158	TATA	SDLX	MINL	28-Mar-2017	PLKD	53	66		61B84283812	MAT412202GOBO1220	69
5773	ATC231	KL-15-A	2159	TATA	SDLX	MINL	28-Mar-2017	KGD	53	66		61B84283607	MAT412202GOBO1179	84
5774	ATC232	KL-15-A	2160	TATA	SDLX	MINL	28-Mar-2017	KGD	53	66		61B84283799	MAT412202GOBO1219	84
5775	ATC233	KL-15-A	2161	TATA	SDLX	MINL	28-Mar-2017	CWS	53	66		61B84283806	MAT412202GOBO1141	09
5776	ATC234	KL-15-A	2162	TATA	SDLX	MINL	28-Mar-2017	CWS	53	66		61A84281002	MAT412202GOBO1221	09

SI.No	VHLNO	REGLTR	REGNO	MAKE	TYPE	TYPE1	COMDATE	UNIT	SC	CC	ENG_TYPE	ENG_NO	CHA_NO	DEPO
5777	ATC235	KL-15-A	2163	TATA	SDLX	MINL	28-Mar-2017	TVM	53	66		61A84281001	MAT412202GOBO1243	27
5778	TP 704	KL-15	4882	LL	ORD		4-Jul-2003	PNR	48	60	HINO EURO		JVE 502651	78
5779	ATC299	KL-15	2000	LL	FP		21-Mar-2017	PKD	53	66		GDEZ406630	MB1PBED0GEDU7298	65
5780	RAC176	KL-15	7317	LL	ORD	SWB	29-Dec-2008	EKM	48	60	HINO BSII ALPSV 4/100	ZNE 104101Z	ZNE 666525	56
5781	RT 548	KL-15	5726	TATA	ORD		1-Dec-2004	PBVR	48	60	CUMMINS	62140367	HVZ 127212	59